

Prepared for:
National Research Council Canada

Victoria, BC V9A 1B3

Hazardous Materials Survey

**1916 Wing Building
Victoria, BC
NWEG Project 20120**



Prepared by



**North West
Environmental Group Ltd.**

210-2950 Douglas Street
Victoria, British Columbia
NWEG Project: 20120

EXECUTIVE SUMMARY

Introduction

North West Environmental Group Ltd. was retained by NRC - National Research Council of Canada to conduct a Hazardous Materials Assessment at the NRC Research Facilities, 1916 Wing of the Admin Building.

The surveys were conducted on various dates between May 27th 2013 and - June 28th 2013.

No previous Hazardous Building Materials Assessment reports and documentation were available. Non-destructive floor-by-floor, room-by-room assessments of all building areas were conducted in order to identify hazardous materials and their condition.

Identification of all sampling locations were made on detailed floor plans, and a summary of remedial recommendations made by priority.

FINDINGS AND RECOMMENDATIONS

Asbestos

Asbestos was not identified in the samples collected at the time of the survey.

Table 0.1: Asbestos Containing Materials Summary-

Asbestos containing materials were identified to be in the following materials/locations:			
Sample ID	Building	Material	Recommendation
<i>No asbestos found in materials sampled</i>			

As per the clients request, non-invasive investigative techniques were used. Even with the most invasive survey techniques, however, it should be noted that the possibility remains for other concealed materials to be found during a renovation or demolition.

Warning: in the event any additional suspect materials are encountered during demolition or renovation activities, work on those materials must stop immediately and remain undisturbed until testing confirms the presence or absence of asbestos or other hazardous material. If this any materials suspected of containing asbestos or another hazardous material are disturbed during the work, all work shall stop until the area is contained, the hazard evaluated by a qualified professional and the hazardous materials, if indeed present, is safely managed by a qualified contractor.

Lead

Table 0.2: Paint Chip Sampling Results by Flame AAS (SW 846 3050B*/7000B)

Sample #	Date Tested	Location	Lead Concentration % by Weight	Lead Concentration (mg/kg)
20120-14	12/6/2013	Room 316 – Beige Paint Chips	0.059	590

Paint

Analysis of paint samples indicated that lead is present within paint at a concentration of 590 mg/kg. Samples were found to have lead concentrations in excess of the threshold specified in the federal *Surface Coatings Material Regulation SCMR* of 90 mg/kg for new paint acceptable for use in residential applications.

Overall, paint coatings were found to be in good condition, with the exception of Room 316 where the ceiling was damaged. Where damaged and deteriorating, paint should be removed following procedures designed to protect the workers from heavy metal exposure and to avoid the spread of contamination. Lead content of painted materials should not increase their disposal costs however; concentrated paint chips would need to be disposed as hazardous waste. Routine removal of lead paint is not recommended; rather it should be managed in place and removed on an “as needed” basis.

Elemental Lead

No sources of elemental lead were observed in the way of planned work. If lead materials are found they are typically recognized as having significant salvage value, disposal therefore should not be a major concern. Workers should exercise caution if heat is to be used to melt any lead found as means of facilitating its extraction. Molten lead can produce significant quantities of inhalable lead fume which can pose a severe health hazard. The BC Occupational Health and Safety Regulation requires that worker exposure to airborne lead be kept below 0.05 mg/m³.

Lead within the copper water pipes/fittings was not tested for lead content however lead content in solder, especially from buildings of this vintage, is known to reach levels up to 98% lead.

Mercury Containing Equipment

Mercury-containing equipment was observed at the subject site during the survey. This equipment includes: fluorescent light tubes. Specific locations are outlined within Section 9.0.

Mercury-containing equipment should be removed prior to any demolition activities and be packaged for transport and storage or disposal/destruction at a licensed facility. Alternatively, if functional, these units could be re-used for their original

intended purpose. Caution should be exercised to ensure that mercury-containing equipment is not broken, releasing droplets of mercury or mercury vapor.

Ozone Depleting Substances

Ozone depleting substances (ODS) were not observed within the subject site.

Crystalline Silica

Testing for crystalline silica in dust was not completed/conducted as part of this survey however it is known to be a component of concrete dust. All concrete, plaster and stucco is suspected of containing silica in crystalline and non-crystalline forms. Many of the removal techniques (grinding, cutting, chipping etc.) for these materials can generate high levels of crystalline silica in the air.

Use wetting techniques and/or HEPA equipped extraction systems attached to drills and other power equipment where possible in order to decrease dust levels.

Mould

Mould was not observed within the building.

Polychlorinated Biphenyls (PCB) in Electrical Equipment

Fluorescent light fixtures were observed and appeared to be of varying vintages often found to contain ballasts which Environment Canada (EC) has developed a guideline called - *Identification of Lamp Ballasts Containing PCBs –Environment Canada 1991*.

Manufacturers of ballasts and capacitors use distinct catalogue and date codes to identify their product, its date of manufacture, and, for some capacitors, its dielectric fluid. Fluorescent lamp ballasts are usually mounted between the fluorescent tubes on the light fixture and are shielded with a metal protective device which reduces heat radiation. Due to the fact the covers are easily broken and the risk of electrical shock when accessing the ballast, it is standard practice to make the observation that there is a potential for PCBs to be present and have the ballasts inspected prior to disposal.

NRC maintains an active halocarbon inventory. Inspect all light ballasts for the presence of PCB prior to disposal. PCB containing ballasts must be disposed as hazardous waste.

Hantavirus-Animal Droppings

Droppings suspected of containing Hantavirus were observed during the survey.

Workers accessing areas where rodent or other animal droppings are present must be informed of the potential risk of Hantavirus exposure and employ suitable precautions for personal protection and control of the spread of contamination.

Urea-formaldehyde Foam Insulation (UFFI)

No materials suspected of containing urea-formaldehyde foam insulation were observed during the survey.



NWEG #20120

See General Notes

Warning: in the event any additional suspect materials are encountered during renovation/repair activities, work on those materials should stop immediately and remain undisturbed until testing confirms the presence or absence of asbestos or other hazardous material

TABLE OF CONTENTS

EXECUTIVE SUMMARY II
 INTRODUCTION II
 FINDINGS AND RECOMMENDATIONS II
LIST OF ACRONYMS III
1.0 INTRODUCTION 1
2.0 SCOPE OF WORK 2
3.0 SITE DESCRIPTION 3
 3.1 SITE LOCATION 3
4.0 REGULATORY FRAMEWORK, GUIDELINES AND CODES 4
 4.1 FEDERAL OCCUPATIONAL HEALTH AND SAFETY 4
 4.2 BC OCCUPATIONAL HEALTH AND SAFETY REGULATION 4
 4.3 ENVIRONMENTAL MANAGEMENT ACT 4
 4.4 BC OCCUPATIONAL HEALTH AND SAFETY REGULATION 5
 4.5 HAZARDOUS PRODUCTS ACT, SURFACE COATING MATERIALS REGULATION 5
5.0 SPECIFIC HAZARDOUS MATERIALS 6
6.0 METHODOLOGY 12
7.0 FINDINGS AND RISK ASSESSMENT 16
 7.1 ASBESTOS IN BULK BUILDING MATERIAL SAMPLES 16
 7.2 LEAD 19
 7.3 MERCURY CONTAINING EQUIPMENT 20
 7.4 OZONE DEPLETING SUBSTANCES 21
 7.5 CRYSTALLINE SILICA 21
 7.6 MOULD 21
 7.7 POLYCHLORINATED BIPHENYLS (PCB) IN ELECTRICAL EQUIPMENT 21
 7.8 HANTAVIRUS-ANIMAL DROPPINGS 22
 7.9 UFFI 22
 7.10 ARSENIC 22
 7.11 RADIOACTIVE MATERIALS 22
 7.12 ABOVE GROUND STORAGE TANKS 22
8.0 ABATEMENT COST ESTIMATE 23
9.0 BULK SAMPLES 24
 BUILDING: ROOF AND EXTERIOR 25
 BUILDING: FLOOR 4.5, ROOM ATTIC 27
 BUILDING: FLOOR 4, ROOM 406 28
 BUILDING: FLOOR 4, ROOM 405 30
 BUILDING: FLOOR 4, ROOM 404 31
 BUILDING: FLOOR 4, ROOM 403 32
 BUILDING: FLOOR 4, ROOM 402 33
 BUILDING: FLOOR 4, ROOM 401 34
 BUILDING: FLOOR 4, ROOM HALLWAY 35
 BUILDING: FLOOR 4, ROOM STAIRWELL 36
 BUILDING: FLOOR 3, ROOM 316 38



NWEG #20120

See General Notes

Warning: in the event any additional suspect materials are encountered during renovation/repair activities, work on those materials should stop immediately and remain undisturbed until testing confirms the presence or absence of asbestos or other hazardous material

BUILDING: FLOOR 3, ROOM 315	39
BUILDING: FLOOR 3, ROOM 314	40
BUILDING: FLOOR 3, ROOM 313	41
BUILDING: FLOOR 3, ROOM 303	42
BUILDING: FLOOR 3, ROOM 302	43
BUILDING: FLOOR 3, ROOM 301.5	44
BUILDING: FLOOR 3, ROOM 301	45
BUILDING: FLOOR 3, ROOM HALLWAY	46
BUILDING: FLOOR 2, ROOM 201	47
BUILDING: FLOOR 2, ROOM 202	48
BUILDING: FLOOR 2, ROOM 203	49
BUILDING: FLOOR 2, ROOM 204	50
BUILDING: FLOOR 2, ROOM 205	51
BUILDING: FLOOR 2, ROOM 206	52
BUILDING: FLOOR 2, ROOM 207	53
BUILDING: FLOOR 2, ROOM 208	54
BUILDING: FLOOR 1, ROOM 101	55
BUILDING: FLOOR 1, ROOM 102	56
BUILDING: FLOOR 1, ROOM 103	57
BUILDING: FLOOR 1, ROOM 104	58
BUILDING: FLOOR 1, ROOM 105	59
BUILDING: FLOOR 1, ROOM 106	60
BUILDING: FLOOR 1, ROOM 107	61
BUILDING: FLOOR 1, ROOM 108	62
BUILDING: FLOOR 1, ROOM 109	63
BUILDING: FLOOR 1, ROOM 110	64
BUILDING: FLOOR 1, ROOM HALLWAY	65
BUILDING: HALLWAY	66
10.0 LIMITATION OF SURVEY.....	67
APPENDICES.....	69
APPENDIX A: SITE MAP.....	70
APPENDIX B: SAMPLE RESULTS.....	71
APPENDIX C: SAMPLE LOCATIONS.....	72
TABLES AND FIGURES	
Table 0.1: Asbestos Containing Materials Summary-.....	ii
Table 0.2: Paint Chip Sampling Results by Flame AAS (SW 846 3050B*/7000B).....	iii
Table 4.4.1: ACGIH / WorkSafeBC Exposure Limits.....	5
Table 7.1.1: Asbestos Containing Materials Summary-Current Survey.....	17
Figure 7.1.1: Action Matrix from DP 057.....	17
Figure 7.1.2: Action Key.....	18
Table 7.2.1: Paint Chip Sampling Results by Flame AAS (SW 846 3050B*/7000B).....	20



LIST OF ACRONYMS

ACM	asbestos-containing materials
ALARA	As Low As Reasonably Achievable
AMP	Asbestos Management Program
CFCs	chlorofluorocarbons
EC	Environment Canada
EMA	Environmental Management Act
HCFCs	hydrochlorofluorocarbons
HFCs	hydrofluorocarbons
HPA	Hazardous Products Act
HWR	Hazardous Waste Regulation
NRC	National Research Council
NWEG	North West Environmental Group
ODS	ozone-depleting substances
PCBs	Polychlorinated biphenyls (PCBs)
SCMR	Surface Coating Materials Regulation
SOW	Statement of Work
WMO	United Nations World Meteorological Organization



NWEG #20120

See General Notes

Warning: in the event any additional suspect materials are encountered during renovation/repair activities, work on those materials should stop immediately and remain undisturbed until testing confirms the presence or absence of asbestos or other hazardous material

1.0 INTRODUCTION

North West Environmental Group Ltd. was retained by NRC - National Research Council of Canada to conduct a Hazardous Materials Assessment Survey at the Research Facilities, 1916 Wing Build. The facility is referred to as the "subject site" or "site" throughout this document. The site location is shown on Drawing 1.

The surveys were conducted between May 27th 2013 and - June 28th 2013 by Julie Scott-Moncrieff, Will Roff, and Dan Morton, Industrial Hygienists from North West Environmental Group Ltd.

Note: this document is a detailed review of hazardous materials found within the building fabric of the site; however, it cannot be considered an absolute listing of all hazardous materials present within the structure. Occupant supplies and processes were not generally considered except where they may have contaminated the building fabric and some materials may have been concealed within enclosed areas of the building structure and not visible to the inspectors at the time of the survey. In the event that materials suspected of containing asbestos, heavy metals or other hazardous components are uncovered or impacted during operations, maintenance, renovation, construction or demolition activities, all work must stop until such time as the materials can be evaluated by a qualified person and appropriate precautions are employed to protect workers and building occupants.



2.0 SCOPE OF WORK

- Non-destructive, room-by-room assessment of all building areas, identifying the location, accessibility to personnel, type of material (e.g. vinyl floor tiles, wall paint, thermostat) and condition of all asbestos-containing materials (including vermiculite insulation), lead materials, mercury containing equipment, ozone depleting substances (ODS), crystalline silica, mould, polychlorinated biphenyl's (PCBs), Hantavirus, urea formaldehyde foam insulation (UFFI), arsenic, radioactive materials, above ground storage tanks (AGST), and other chemical hazards.

1916 Wing Admin was assessed:

- Sampling and subsequent analysis to ascertain the amount of hazardous materials within the subject site using a laboratory accredited by the National Voluntary Laboratory Accreditation Program (NVLAP).
- Identification of all sampling locations on detailed floor plans, distinguishing between those that are confirmed to be hazardous and those that are not.
- Preparation of a separate summary of costs for repair, encapsulation or removal of the asbestos containing materials and other hazardous materials, presented as remedial options and report detailing the results, conclusions and recommendations as well as an abatement cost estimate, if necessary.

3.0 SITE DESCRIPTION

3.1 Site Location

The NRC - National Research Council of Canada is located in Victoria, BC, on the southern tip of Vancouver Island. The site is located as shown in Appendix A.

See Appendix A for map of Site Location and Plan.

4.0 REGULATORY FRAMEWORK, GUIDELINES AND CODES

4.1 Federal Occupational Health and Safety

In Federal jurisdictions, asbestos-containing materials (ACM) are regulated under the *Canada Labour Code, Part II*. Specifically, *Part X, Hazardous Substances*, provides the direction for the control of exposure to potentially toxic substances in the workplace. Under this regulation, employers are required to:

- Maintain a record of all hazardous materials;
- Undertake a hazard investigation by competent persons;
- Ensure materials are properly stored and handled;
- Post warning signs;
- Inform and educate employees regarding hazards; and
- Control exposure through substitution, engineering or protective equipment.

4.2 BC Occupational Health and Safety Regulation

Most of the employees working in the dockyard buildings are Federal employees and are subject to the federal OHSA. However the majority of contractors and some site tenants Workplace health and safety is regulated in British Columbia by WorkSafeBC under the *Workers' Compensation Act* (effective April 15, 1998), as amended by *Workers' Compensation (Occupational Health and Safety) Amendment Act* (effective October 1, 1999). The Act defines the general duties and obligations of the employer, employees and others at the work site.

Under this regulation, employers are required to:

- Maintain a record of all hazardous materials;
- Undertake a hazard investigation by competent persons;
- Ensure materials are properly stored and handled;
- Post warning signs;
- Inform and educate employees regarding hazards; and
- Control exposure through substitution, engineering or protective equipment

WorkSafeBC Regulations apply to the handling of materials containing designated substances and the prevention of possible worker exposures. Permissible exposure limits to these designated substances, which include asbestos, lead, mercury and arsenic, are established by the American Conference of Governmental Industrial Hygienists (ACGIH) and adopted by WorkSafeBC.

4.3 Environmental Management Act

The *Environmental Management Act* (EMA), brought into force in July 2004, is the principle environmental statute in British Columbia. The EMA prohibits the introduction of waste into the environment in such a manner or quantity as to cause pollution, except in accordance with a regulation, permit, approval or code of practice issued under the Act. The Hazardous Waste Regulation (HWR) addresses the proper handling, transport and disposal of hazardous wastes, under provisions of the EMA.

While the Provincial Regulations do not apply directly to the sites operated by the Federal Government, they do apply when the materials are removed from the site for disposal.

4.4 BC Occupational Health and Safety Regulation

WorkSafeBC Regulations apply to the handling of materials containing designated substances and the prevention of possible worker exposures. These designated substances, which include lead, mercury and arsenic, are established by the American Conference of Governmental Industrial Hygienists (ACGIH) and adopted by WorkSafeBC.

Where worker exposure to a designated substance may exceed 50% of the threshold limit value for a substance, WorkSafeBC requires that the employer establish an exposure control plan. All routes of entry must be considered when establishing the extent of worker exposure. Exposure limits are summarized in Table 4.4.1.

Table 4.4.1: ACGIH / WorkSafeBC Exposure Limits

Substance [CAS No.]	Time Weighted Average (TWA)
Asbestos - All forms [1332-21-4]	0.1 f/cc (F)
Lead - elemental and inorganic compounds, as Pb [7439-92-1]	0.05 mg/m ³
Silica, Crystalline - alpha quartz [14808-60-7; 1317-95-9] and Cristobalite, Respirable [14464-46-1] Revised 2006	0.025 mg/m ³

4.5 Hazardous Products Act, Surface Coating Materials Regulation

The *Hazardous Products Act (HPA), Surface Coating Materials Regulation (SOR/2005-109) (SCMR)* permits the advertising, sale and labeling of surface coatings (including paint) that meet the following criteria set out below. Quantities of lead and mercury are specifically limited. Other heavy metals are not addressed in this regulation.

There has been confusion in the past regarding the limits for lead and mercury in paint and how that relates to worker safety and disposal. An explanation of the SCMR limits for paint and mercury are included in this report to help alleviate this confusion. Although a given paint sample may have concentrations of lead and mercury lower than the limits specified within the SCMR, worker exposure may still occur if sufficient quantities of lead and/or mercury are inhaled, ingested or absorbed through the skin. The risk to workers posed by heavy metal containing coatings is proportional to the work undertaken. Heavy metal laden coatings that are not disturbed pose little risk to non-pre-school aged building occupants.

5.0 SPECIFIC HAZARDOUS MATERIALS

Asbestos

Projects that will result in the disturbance of asbestos-containing materials (ACMs) must satisfy WorkSafeBC's regulations and conform to the guidance document Safe Work Practices for Handling of Asbestos. WorkSafeBC's Occupational Health and Safety Regulation defines an asbestos-containing material as "any manufactured article or other material, other than vermiculite insulation, that would be determined to contain at least 0.5% or more asbestos if tested in accordance with one of the following methods:

METHOD 1

- I. Asbestos, Chrysotile by XRD, Method 9000 (Issue 2, dated August 15, 1994) in the NIOSH Manual of Analytical Methods, published by the United States National Institute for Occupational Safety and Health, Centre for Disease Control;
- II. Asbestos (bulk) by PLM, Method 9002 (Issue 2, dated August 15, 1994) in the NIOSH Manual of Analytical Methods, published by the United States National Institute for Occupational Safety and Health, Centre for Disease Control;
- III. Test Method for the Determination of Asbestos in Bulk Building Materials (EPA/600/R-93/116, dated July 1993) published by the United States Environmental Protection Agency;

METHOD 2

- I. Vermiculite insulation that would be determined to contain any asbestos if tested in accordance with the Research Method for Sampling and Analysis of Fibrous Amphibole in Vermiculite Attic Insulation (EPA/600/R-04/004, dated January 2004) published by the United States Environmental Protection Agency;

The asbestos-containing material can also be characterized as friable and non-friable. Friable asbestos "means any material which, when dry, can be easily crumbled or powdered by hand pressure, or a material that is crumbled or powdered" as defined under the BC Occupational Health and Safety Regulation. The condition of the asbestos and classifications would be used in assessing the level of action required with respect to re-use of the building.

Worker exposure to asbestos fibres is also regulated by the BC Occupational Health and Safety Regulation. The WorkSafeBC eight-hour time-weighted average (TWA) for asbestos fibres (all forms) is 0.1 fibre/cm³. Exposure to these substances must be kept as close to zero as is reasonably practicable.

Bulk samples are collected in accordance with NIOSH Analytical Method 9002 and the WorkSafeBC guideline document, Safe Work Practices for Handling Asbestos.

Asbestos is designated as an ALARA substance; worker exposure to this product must be kept “as low as reasonably achievable” (ALARA). Employers are required under Section 5.54 (Exposure control plan) of the Occupational Health and Safety Regulation (OHSR) to develop an exposure control plan (ECP) when workers are or may be exposed to airborne concentrations of these materials in excess of 50% of the exposure limit.

Lead

Paints containing lead may be advertised, sold or imported into Canada when under standardized testing conducted on a dried sample of the coating indicates that lead concentrations do not exceed 600 mg/kg.

In 2005 the federal Surface Coating Materials Regulation was amended to reduce this threshold from 5,000 mg/kg to 600 mg/kg and then to 90 mg/kg in 2010. As paints under this concentration of lead are acceptable for use in residential settings today, such coatings do not pose a significant hazardous material issue unless rendered airborne within a worker’s breathing zone by fine dust generating processes.

Paints that exceed this concentration threshold are prohibited to be advertised, sold or imported into Canada unless they meet certain conditions of use and labeling.

Permitted uses include:

- as an anti-corrosive or an anti-weathering coating applied on the interior or exterior surface of any building or equipment that is used for an agricultural or industrial purpose;
- as an anti-corrosive or an anti-weathering coating applied on any structure, other than a building, that is used for an agricultural, industrial or public purpose;
- as a touch-up coating for metal surfaces;
- on traffic signs;
- for graphic art on billboards or similar displays;
- for identification marks in industrial buildings; or
- as material for the purposes of arts, crafts or hobbies, other than material for use by children.

Paint

Paints often contain heavy metals as pigments and/or preservatives. Common heavy metal additives to paints are lead, mercury, and arsenic. Under specific circumstances, persons may be exposed to these metals by ingestion, skin absorption and/or inhalation.

Other than during the application process, the primary mechanism of exposure for workers would be the inhalation of dusts through activities such as sanding, scraping, drilling, crushing, heating, burning or other processes likely to damage the coatings themselves. Paints containing heavy metals pose little risk to workers when in good condition and when undisturbed.

Although limits are currently imposed in the quantities of lead permitted in paints intended for specific uses, lead content below these limits may still pose a health hazard if rendered airborne and inhaled, ingested or absorbed through the skin. The same applies to mercury. The Hazardous Products Act, Surface Coating Materials Regulation (SOR/2005-109) (SCMR) permits the advertising, sale and labeling of surface coatings (including paint) that meet the following criteria set out below. Quantities of lead and mercury are specifically limited. Other heavy metals are not addressed in this regulation.

In 1976, the amount of lead that could be added to interior paints was limited by law, but exterior paints could still contain higher amounts of lead, provided they carried a warning label. Under the Surface Coating Materials Regulations, which came into effect in 2005, the lead limit was further reduced (from Health Canada). The 600 mg/kg maximum total lead standard is the same as that proposed for paints and other liquid coating materials used for furniture, household products, children's products, and exterior and interior surfaces of any building frequented by children, under the recent amendment to the Hazardous Products Act Liquid Coating Materials Regulations. It is also the same standard prescribed by the U.S. Consumer Product Safety Commission Regulation 16 CFR Part 1303, for paint and other liquid coatings for residential use, toys and furniture (97). This limit was determined by a risk assessment which calculated that 600 mg/kg of lead in paint was the threshold level, at or below which there would be no significant lead exposure if a child consumed a one square inch paint chip each day.

When lead is present in paint, there is a potential for airborne exposure of lead to workers. Airborne exposure can occur if the material is disturbed (especially if the lead containing materials are hand sanded); hand demolished and/or any other disturbances are made to the coating. An exposure control plan is necessary if workers are, or may be, exposed to lead in excess of 50 % of the exposure limit established by the Workers' Compensation Board (WorkSafeBC) for an 8 hours total weighted average exposure, or if exposure through any route of entry could cause elevated levels of lead in the blood. Lead precautions during demolition or renovation may be required, including the use of personal protective equipment for workers and/or dust suppression methods.

Mercury Containing Equipment

Mercury is hazardous substance, and any maintenance or abatement involving materials containing mercury or mercury compounds must be done in compliance with the BC Occupational Health and Safety Regulations (BCOHSR).

Employers with workers who have a risk of exposure must have an exposure control plan (ECP) in place prior to allowing their workers to come into contact with this material. As with all other hazardous substances, all personnel working around or with such materials must be made aware of their presence and be supplied with training in the potential health effects and means of avoiding exposures.

As a hazardous substance, transportation and disposal of this substance must be done in compliance with the federal Transportation of Dangerous Goods (TDG) Regulations and the BC Hazardous Waste Regulation. Mercury is found in

fluorescent light bulbs, thermostats, manometers, and equipment such as electrical switches.

Mercury is designated as an ALARA substance whereby worker exposure to this product must be kept “as low as reasonably achievable”. Employers are required under Section 5.54 (Exposure control plan) of the Occupational Health and Safety Regulation (OHSR) to develop an exposure control plan (ECP) when workers are or may be exposed to airborne concentrations of this material in excess of 50% of the exposure limit.

Ozone-depleting Substances (CFCs/ODS)

Chlorofluorocarbons (CFCs) are ozone-depleting substances (ODS) and a type of halocarbon. ODS are regulated by the *Canadian Environmental Protection Act* under the *Ozone-Depleting Substances Regulations 1998 SOR/99-7* and the *Federal Halocarbon Regulations (FHR) SOR/99-225*. Compounds that contain only chlorine, fluorine and carbon are called CFCs. These materials are used in refrigeration systems and in fire suppression systems. The other main refrigerants are hydrochlorofluorocarbons (HCFCs), hydrofluorocarbons (HFCs) and blends of fluorocarbons (designated by “R”).

In BC these substances are regulated under the BC Ozone Depleting Substances and Other Halocarbons Regulation.

While the regulations allow the continued use of halocarbon refrigerants, they strictly prohibit any person from releasing any halocarbons into the environment.

In the case of demolition, ODS will require proper recovery and disposal. The BC Ozone-Depleting Substances Regulations would also apply to any CFC/ODS abatement procedures. These regulations require that all ODS be collected, stored and recycled, or collected and disposed of accordingly.

Crystalline Silica

Crystalline silica is a substance which is considered hazardous by inhalation and can result in serious and sometimes fatal lung disease. The ACGIH and WorkSafeBC, under the Occupational Health and Safety Regulation and the Canada Labour Code specify an exposure limit of 0.025 mg/m³.

Mould

Within the BC Occupational Health and Safety Regulations, there are no established permissible exposure levels for mould spores in air. This means that there are no published concentrations above which worker exposure is deemed to be hazardous and under which workers would not need respiratory protection. WorkSafeBC does, however, provide guidance on protocols for protecting workers from the hazards of airborne mould and bacteria within the section(s) of the Regulation guidelines addressing Indoor Air Quality.

Various other many guidelines are provided for addressing mould in Canada including:

- The Institute of Inspection, Cleaning and Restoration and Certification (IICRC) standard S500 governing both water damage restoration and entitled: Standard for Professional Water Damage Restoration – S500. This document is approved by the American National Standards Institute (ANSI)
- Health Canada: Fungal contamination in public buildings: A guide to recognition and management, 1995
- Health Canada. Fungal Contamination in Public Buildings: Health Effects and Investigation Methods, 2004

These guidelines also state that any non-porous (metal, glass and hard plastics) and semi-porous (wood and concrete) materials that are structurally sound and visibly mouldy can be cleaned and re-used. However, porous materials such as ceiling tiles, wallpaper, insulation, drywall, and sometimes carpets with more than a small area of contamination should be removed and discarded.

Polychlorinated Biphenyls

Polychlorinated biphenyls (PCBs) are regulated under both Federal (*Canadian Environmental Protection Act*) and Provincial (*BC Hazardous Waste Regulation*) legislation and must be treated as PCB waste and be stored and disposed of accordingly.

Each fluorescent light fixture removed during facility renovation or demolition should have the ballast checked to determine if it contains PCBs. Ballasts containing PCBs must be removed, sorted and transported to a licensed facility. Although rare, paints have been known to contain PCBs.

Hantavirus – Rodent Droppings

The Hantavirus is a virus associated with Hantavirus Pulmonary Syndrome, a disease caught through contact with the urine or droppings, or by being bitten or scratched by infected rodents. The disease starts off like a cold or flu (fever, sore muscles, headaches, nausea, vomiting), but progresses to pneumonia-like conditions within a few days. The change in intensity of the symptoms is very rapid and can result in fluid build-up in the lungs and respiratory failure.

Hantavirus is a hazardous substance and as such is regulated under the BC Occupational Health and Safety Regulation. Employers with workers who have a risk of exposure must have an exposure control plan (ECP) in place prior to allowing their workers to come into contact with this material. As with all other hazardous substances, all personnel working around or with such materials must be made aware of their presence and be supplied with training in the potential health effects and means of avoiding exposures.

Urea Formaldehyde Foam Insulation (UFFI)

UFFI was banned in 1978. All such material was to have been removed and replaced. Standard real estate agreements currently contain a “No UFFI” clause and as a best management practice, all buildings containing UFFI should have the material removed. UFFI is still found in many buildings in BC.

Arsenic

Arsenic is hazardous substance, and any maintenance or abatement involving materials containing arsenic or arsenic compounds must be done in compliance with the BC Occupational Health and Safety Regulations (BCOHSR).

Employers with workers who have a risk of exposure must have an exposure control plan (ECP) in place prior to allowing their workers to come into contact with this material. As with all other hazardous substances, all personnel working around or with such materials must be made aware of their presence and be supplied with training in the potential health effects and means of avoiding exposures.

Arsenic has long been used as a pesticide due to its toxic properties. Arsenical pesticides, often in the form of chromated copper arsenate (CCA), when applied with high pressure to wood, serve to extend the structural life of the material by making it resistant to mould, rot and insect infestation. Studies have shown that these materials have the ability to leach arsenic into the soil. Arsenic may also be found in paints. Although wood and wood dusts contaminated with arsenical pesticides do not require specialized disposal in BC, care must be exercised to minimize the potential for worker exposure to these materials through direct skin contact or through inhalation of dusts and fumes.

Radioactive Materials

Many buildings contain smoke alarms which contain small sealed radioactive sources in the form of ²⁴¹Americium. The Canadian Nuclear Safety Commission (CNSC) and the Canadian Nuclear Safety Act regulate radioactive materials. These materials are sealed into a metal case within the smoke detector and must not be damaged or tampered with. Smoke detectors intended for disposal must be handled in accordance with CNSC regulations.

Above Ground Storage Tanks (AGST)

Storage tanks containing fuels have the ability to leak over time and can result in soil and groundwater contamination. These tanks must be observed and checked over time to ensure they do not leak. Evidence of leaks must be investigated and any potential contamination remediated. The Canadian Council of Ministers of the Environment (CCME) publishes a Code of Practice for the safe management of aboveground and underground storage tanks.

Other Chemical Hazards

Storage and Handling of controlled products fall under the Hazardous Products Act and Workplace Hazardous Materials Information System (WHMIS).

6.0 METHODOLOGY

The methodology of the survey is summarized in the following sections.

Asbestos

The asbestos survey methodology and sampling procedure are outlined in the following sections.

Survey Methodology

The survey was designed to determine the type and extent of asbestos containing material (ACM) presence within the subject site. The survey was non-destructive and therefore did not include areas that were inaccessible at the time of the survey. Where practicable, sample volumes were minimized to avoid unnecessary damage to building systems. Specific building material components were examined within the building and include, where applicable:

- Structural – all visible structural components including walls, roofs and supporting members
- Mechanical systems - insulation, domestic hot and cold water, and caulks.
- Architectural – systems including: texture coats, sheet flooring, vinyl floor tile, ceiling tile, wall board, drywall joint compound, asbestos sheet products.

Where materials were observed that were suspected of containing asbestos, representative samples were collected. Thirty-two (32) samples of materials suspected of containing asbestos were collected and submitted with a chain of custody to the contract laboratory.

A complete listing of all materials suspected of containing asbestos that were sampled, including the results of analysis is found in Section 9 of this report.

Sampling Procedures

Bulk Samples

Sampling procedures for various building materials vary somewhat depending on the exact conditions at each site. In all cases standardized protocols are used for collecting samples for asbestos analysis. All accessible suspect materials that were visually unique were sampled. Visually similar materials were only sampled once unless known to be heterogeneous such as drywall joint compound.

Sampled materials were cut down to the base substrate to ensure that a representative sample was collected.

Paint

Painted surfaces were scraped down to the base substrate to ensure that all layers of paint were included. Paint samples were tested using the following analytical method:

- Lead: EMSL (SW 846 3050B*/7000B) Lead in Paint Chips by Flame Atomic Absorption Spectrophotometer

A total of one (1) paint chip sample was submitted to EMSL Analytical for analysis. The sample location is shown on the floor plans.

Mercury Containing Equipment

The subject site was inspected for the presence of mercury containing equipment. Devices suspected of containing mercury were documented so that they can be removed prior to demolition. These devices typically include fluorescent light tubes, thermostats, and manometers.

Ozone Depleting Substances (ODS) and Other Halocarbons

The subject building was inspected for the presence of devices that are known or suspected of containing to contain ODS or other halocarbons. Devices suspected of containing these materials were documented so that any hazardous materials can be removed prior to demolition or disposal of the equipment. These devices typically include refrigeration and air conditioning equipment.

Crystalline Silica

Testing for crystalline silica in dust was not completed/conducted as part of this survey however it is known to be a component of concrete dust. All concrete, plaster and stucco is suspected of containing silica in crystalline and non-crystalline forms. Many of the removal techniques (grinding, cutting, chipping etc) for these materials can generate high levels of crystalline silica in the air.

Mould

Within the BC Occupational Health and Safety Regulations, there are no established permissible exposure levels for mould spores in air. This means that there are no published concentrations above which worker exposure is deemed to be hazardous and under which workers would not need respiratory protection. WorkSafeBC does, however, provide guidance on protocols for protecting workers from the hazards of airborne mould and bacteria within the section(s) of the Regulation guidelines addressing Indoor Air Quality.

Various other guidelines are provided for addressing mould in Canada including:

- The Institute of Inspection, Cleaning and Restoration and Certification (IICRC) standard S500 governing both water damage restoration and entitled: Standard for Professional Water Damage Restoration – S500. This document is approved by the American National Standards Institute (ANSI)
- Health Canada: Fungal contamination in public buildings: A guide to recognition and management, 1995
- Health Canada. Fungal Contamination in Public Buildings: Health Effects and Investigation Methods, 2004

These guidelines also state that any non-porous (metal, glass and hard plastics) and semi-porous (wood and concrete) materials that are structurally sound and visibly

mouldy can be cleaned and re-used. However, porous materials such as ceiling tiles, wallpaper, insulation, drywall, and sometimes carpets with more than a small area of contamination should be removed and discarded.

Polychlorinated Biphenyls (PCB)

The Site was surveyed for the presence of PCBs in electrical equipment. The primary source of PCBs was identified in fluorescent light ballasts which were evaluated according to the guideline developed by Environment Canada (EC) - *Identification of Lamp Ballasts Containing PCBs –Environment Canada 1991*.

Manufacturers of ballasts and capacitors use distinct catalogue and date codes to identify their product, its date of manufacture, and, for some capacitors, its dielectric fluid. Fluorescent lamp ballasts are usually mounted between the fluorescent tubes on the light fixture and are shielded with a metal protective device which reduces heat radiation. In order to determine if fluorescent light ballasts contain PCB's the metal protective cover is removed while the power is off to the fixture. With the ballast exposed the date code is visible and can be referenced in the EC guideline.

For ballasts not stamped "no PCB", in most cases, fluorescent light ballasts need to be removed from the fixture before the date of manufacture can be determined. The date of manufacture is critical in establishing whether PCB may be present in the ballast capacitor.

Hantavirus

Observations were made by the technicians on site for the presence of rodent droppings and other evidence of rodent presence.

Urea-formaldehyde Foam Insulation

The subject site was inspected for the presence of UFFI. No sampling was undertaken for UFFI as materials suspected of containing UFFI were not observed.

Arsenic

The subject site was inspected for the presence of materials that are known or suspected of containing arsenic. Materials suspected of containing arsenic were documented so that they can be removed prior to demolition. These materials typically include wood likely to have been preserved with arsenical pesticides.

Radioactive Materials

Testing for radioactive materials was not included within the scope of the survey. However, smoke detectors are known to contain radioactive sources and other radioactive materials may have been used on the site in the past. Observations were made by the technician on site for the presence and locations of radioactive sources.

Above Ground Storage Tanks

Observations were made by the technician on site for the presence of aboveground or underground storage tanks that may be in the way of planned work. The conducting of a Stage 1 preliminary site assessment was beyond the scope of this report.

7.0 FINDINGS AND RISK ASSESSMENT

The findings of the survey are discussed in the following sections. Photographs of sample locations are provided in Section 8.0. The asbestos risk assessment and indicative cost estimates are provided in this section. The analytical reports are provided in Appendix B.

7.1 Asbestos in Bulk Building Material Samples

A total of thirty-two (32) samples of suspected asbestos containing materials were collected and submitted for analysis to the contract laboratory. The analytical results are provided in Appendix B.

Asbestos was not identified in the samples collected at the time of the survey.

Recommendations are based on Public Works and Government Services Canada Departmental Policy 057 – Asbestos Management (DP 057).

Asbestos Containing Materials must be managed under an Asbestos Management Plan (AMP). The purpose of the AMP is to assist the organization in managing ACM in a systematic fashion to ensure identified ACM are managed in a safe manner which complies with the Canada Labour Code and WorkSafeBC guidelines.

ACM in good condition may be managed in place in accordance with the implementation of the Asbestos Management Plan (AMP). Institute routine surveillance of the ACM. Trained workers or contractors must use appropriate asbestos precautions (Type 1, Type 2 or Type 3) during disturbance of the remaining ACM.

Inspect all identified asbestos containing materials annually to identify any damage and ensure proper labeling is present.

Any damaged ACM found during future inspections, as well as ACM that could be impacted by any demolition or renovation activity, should be removed following procedures outlined in the AMP.

Throughout any abatement activities, appropriate air monitoring and inspection should be conducted by qualified personnel to ensure all contamination is contained and ACM are disposed of appropriately. It is recommended that a proper scope of work and asbestos removal specifications be written to ensure the complete and proper removal of all ACM.

Table 7.1.1: Asbestos Containing Materials Summary-Current Survey

Asbestos containing materials were identified to be in the following materials/locations:			
Sample ID	Building	Material	Recommendation
<i>No asbestos found in materials sampled</i>			

Evaluation of asbestos containing materials is based on the condition of the material and its accessibility. Following are the guidelines used to evaluate ACMs and the action, if any, required to safely manage them.

Figure 7.1.1: Action Matrix from DP 057

ACCESS	CONDITION			
	GOOD	FAIR	POOR	DEBRIS
(A)	ACTION 5/7	ACTION 5/6	ACTION 3	ACTION 1
(B)	ACTION 7	ACTION 6/5	ACTION 3	ACTION 1
(C) exposed	ACTION 7	ACTION 6	ACTION 4	ACTION 2
(C) concealed	ACTION 7	ACTION 7	ACTION 4	ACTION 2
(D)	ACTION 7	ACTION 7	ACTION 7	ACTION 7

The following is excerpted from Public Works and Government Services Canada Departmental Policy 057 – Asbestos Management (DP 057).

Condition

Spray Applied Fireproofing, Insulation and Texture Finishes

In evaluating the condition of ACM spray applied as fireproofing, thermal insulation or texture, decorative or acoustic finishes, the following criteria apply;

GOOD	Surface of material shows no significant signs of damage, deterioration or delamination. Up to one percent visible damage to surface is allowed within range of GOOD. Evaluation of sprayed fireproofing requires the surveyor to be familiar with the irregular surface texture typical of sprayed asbestos products. GOOD condition includes unencapsulated or unpainted fireproofing or texture finishes, where no delamination or damage is observed, and encapsulated fireproofing or texture finishes where the encapsulation has been applied after the damage or fallout occurred.
POOR	Sprayed materials show signs of damage, delamination or deterioration. More than one percent damage to surface of ACM spray.

Mechanical Insulation

In evaluating the condition of mechanical insulation (on boilers, breeching, ductwork, piping, tanks, equipment etc.) the following criteria are used:

GOOD	Insulation is completely covered in jacketing and exhibits no evidence of damage or deterioration. No insulation is exposed. Includes conditions where the jacketing has minor surface damage (i.e., scuffs or stains), but the jacketing is not penetrated.
FAIR	Minor penetration damage to jacketed insulation (cuts, tears, nicks, deterioration or

	delamination) or undamaged insulation that has never been jacketed. Insulation is exposed but not showing surface disintegration. The extent of missing insulation ranges should be minor to none.
POOR	Original insulation jacket is missing, damaged, deteriorated or delaminated. Insulation is exposed and significant areas have been dislodged. Damage cannot be readily repaired.

Non-Friable and Potentially Friable Materials

Non-friable materials generally have little potential to release airborne fibres, even when damaged by mechanical breakage. However, some non-friable materials, i.e., exterior asbestos Concrete products, may have deteriorated so that the binder no longer effectively contains the asbestos fibres. In such cases of significantly deteriorated non-friable material, the material will be treated as a friable product.

Accessibility

The accessibility of building materials known or suspected of being ACM is rated according to the following criteria:

Access (A)	Areas of the building within reach (from floor level) of all building users. Includes areas such as gymnasiums, workshops, and storage areas where activities of the building users may result in disturbance of ACM not normally within reach from floor level.
Access (B)	Frequently entered maintenance areas within reach of maintenance staff, without need for a ladder. Includes: frequently entered pipe chases, tunnels and service areas or areas within reach from a fixed ladder or catwalk, i.e., tops of equipment, mezzanines.
Access (C) Exposed	Areas of the building above 8'0" where use of a ladder is required to reach the ACM. Only refers to ACM materials that are exposed to view, from the floor or ladder, without removing or opening other building components such as ceiling tiles, or service access doors or hatches. Does not include infrequently accessed service areas of the building.
Access (C) Concealed	Areas of the building which require removal of a building component including lay-in ceilings and access panels into solid ceiling systems. Includes rarely entered crawl spaces, attic spaces etc. Observations are limited to the extent visible from the access points.
Access (D)	Areas of the building behind inaccessible solid ceiling systems, walls, or mechanical equipment, etc., where demolition or the ceiling, wall or equipment etc., is required to reach the ACM. Evaluation of condition and extent of ACM is limited or impossible, depending on the surveyor's ability to visually examine the materials in Access D.

Figure 7.1.2: Action Key

Action 1	Immediate Clean Up of Debris That is Likely to be Disturbed Restrict access that is likely to cause a disturbance of the ACM DEBRIS and clean up ACM DEBRIS immediately. Utilize correct asbestos procedures. This action is required for compliance with regulatory requirements.
-----------------	--

Action 2	Entry Into Areas with ACM Debris At locations where ACM DEBRIS can be isolated in lieu of removal or clean up, use appropriate means to limit entry to the area. Restrict access to the area to persons utilizing Type 2 asbestos-work precautions. The precautions will be required until the ACM DEBRIS has been cleaned up, and the source of the DEBRIS has been stabilized or removed.
Action 3	ACM Removal Required for Compliance Remove ACM for compliance with regulatory requirements. Utilize asbestos procedures appropriate to the scope of the removal work.
Action 4	Access into Areas Where ACM is Present and Likely to be Disturbed by Access Use asbestos precautions when entry or access into an area likely to disturb the ACM. ACTION 4 must be used until the ACM is removed (Use ACTION 1 or 2 if DEBRIS is present).
Action 5	Proactive ACM Removal Remove ACM in lieu of repair, or at locations where the presence of asbestos in GOOD condition is not desirable.
Action 6	ACM Repair Repair ACM found in FAIR condition, and not likely to be damaged again or disturbed by normal use of the area or room. Upon completion of the repair work, treat ACM as material in GOOD condition and implement ACTION 7. If ACM is likely to be damaged or disturbed during normal use of the area or room, implement ACTION 5.
Action 7	Routine Surveillance Institute routine surveillance of the ACM. Trained workers or contractors must use appropriate asbestos precaution during disturbance of the remaining ACM.

Note: any additional suspect materials encountered during renovation or demolitions activities must be left undisturbed until testing determines the presence or absence of asbestos or other hazardous material. In the event they are damaged or otherwise impacted, all work shall stop until appropriate control can be put in place to protect workers and the public.

7.2

Lead

Lead Paint

Analysis of paint samples indicated that lead is present within paint at a concentration of 590 mg/kg. Samples were found to have lead concentrations in excess of the threshold specified in the federal *Surface Coatings Material Regulation SCMR* of 90 mg/kg for new paint acceptable for use in residential applications.

Table 7.2.1: Paint Chip Sampling Results by Flame AAS (SW 846 3050B*/7000B)

Sample #	Date Tested	Location	Lead Concentration % by Weight	Lead Concentration (mg/kg)
20120-14	12/6/2013	Room 316 – Beige Paint Chips	0.059	590

Overall, paint coatings were found to be in good condition, with the exception of Room 316 where the ceiling was damaged. Where damaged and deteriorating, paint should be removed following procedures designed to protect the workers from lead dust exposure and to avoid the spread of contamination. Lead content of painted materials should not increase their disposal costs however; concentrated paint chips would need to be disposed as hazardous waste. Routine removal of lead paint is not recommended; rather it should be managed in place and removed on an “as needed” basis.

Elemental Lead

Lead within the copper water pipes/fittings was not tested for lead content however lead content in solder, especially from buildings of this vintage, is known to reach levels up to 98% lead.

If lead materials are found they are typically recognized as having significant salvage value, disposal therefore should not be a major concern. Workers should exercise caution if heat is to be used to melt any lead found as means of facilitating its extraction. Molten lead can produce significant quantities of inhalable lead fume which can pose a severe health hazard. The BC Occupational Health and Safety Regulation require that worker exposure to airborne lead be kept below 0.05 mg/m³.

7.3 Mercury Containing Equipment

Mercury-containing equipment was observed at the subject site during the survey. This equipment includes: fluorescent light tubes. Specific locations are outlined within Section 9.0.

Mercury-containing equipment should be removed prior to any demolition activities and be packaged for transport and storage or disposal/destruction at a licensed facility. Alternatively, if functional, these units could be re-used for their original intended purpose. Caution should be exercised to ensure that mercury-containing equipment is not broken, releasing droplets of mercury or mercury vapor.

7.4 Ozone Depleting Substances

Ozone depleting substances (ODS) were not observed within the subject site.

7.5 Crystalline Silica

Testing for crystalline silica in dust was not completed/conducted as part of this survey however it is known to be a component of concrete dust. All concrete, plaster and stucco is suspected of containing silica in crystalline and non-crystalline forms. Many of the removal techniques (grinding, cutting, chipping etc) for these materials can generate high levels of crystalline silica in the air.

Use wetting techniques and/or HEPA equipped extraction systems attached to drills and other power equipment where possible in order to decrease dust levels.

7.6 Mould

Mould was not observed within the building.

7.7 Polychlorinated Biphenyls (PCB) in Electrical Equipment

Fluorescent light fixtures were observed and appeared to be of varying vintages often found to contain ballasts which Environment Canada (EC) has developed a guideline called - *Identification of Lamp Ballasts Containing PCBs –Environment Canada 1991*.

Manufacturers of ballasts and capacitors use distinct catalogue and date codes to identify their product, its date of manufacture, and, for some capacitors, its dielectric fluid. Fluorescent lamp ballasts are usually mounted between the fluorescent tubes on the light fixture and are shielded with a metal protective device which reduces heat radiation. Due to the fact the covers are easily broken and the risk of electrical shock when accessing the ballast, it is standard practice to make the observation that there is a potential for PCBs to be present and have the ballasts inspected prior to disposal.

NRC maintains an active halocarbon inventory. Inspect all light ballasts for the presence of PCB prior to disposal. PCB containing ballasts must be disposed as hazardous waste.

7.8 Hantavirus-Animal Droppings

Droppings suspected of containing Hantavirus were observed during the survey. Specific locations are detailed in Section 9.0.

Workers accessing areas where rodent or other animal droppings are present must be informed of the potential risk of Hantavirus exposure and employ suitable precautions for personal protection and control of the spread of contamination.

7.9 UFFI

No sampling was undertaken for Urea Formaldehyde Foam Insulation (UFFI) as materials suspected of containing UFFI were not observed in the way of planned work.

7.10 Arsenic

Wood likely to have been preserved with arsenical pesticides was not observed on the subject site.

Although wood and wood dusts contaminated with arsenical pesticides do not require specialized disposal in BC, care must be exercised to minimize the potential for worker exposure to these materials through direct skin contact or through inhalation of dusts and fumes. Caution must be taken to ensure this material is not burned or composted if removed during renovation or demolition.

7.11 Radioactive Materials

Smoke detectors were observed in the building.

Smoke detectors that may be removed during the demolition and/or renovations should be collected and disposed in accordance with Canadian Nuclear Safety Commission regulations. Alternatively, if still functional, they may be reused for their original intended purpose.

7.12 Above Ground Storage Tanks

Aboveground storage tanks were not observed on the subject site. The conducting of a Stage 1 Preliminary Site Investigation was beyond the scope of this report.

Warning: in the event any additional suspect materials are encountered during demolition or renovation activities, work on those materials must stop immediately and remain undisturbed until testing confirms the presence or absence of asbestos or other hazardous material. If this any materials suspected of containing asbestos or another hazardous material are disturbed during the work, all work shall stop until the area is contained, the hazard evaluated by a qualified professional and the hazardous materials, if indeed present, is safely managed by a qualified contractor.

8.0 ABATEMENT COST ESTIMATE

No asbestos was detected in the materials sampled during the survey.

9.0 BULK SAMPLES

The following photo plate is a summary of the room by room assessment including samples collected.

Building: Roof and Exterior

Room Details:

- Asphalt, Shingle
- Stucco
- Wood Siding

Hazardous Materials Observed:

Samples:

20120-28	Lower Shingle (no asbestos detected)
20120-29	Red Shingle (no asbestos detected)
20120-30	Stucco (no asbestos detected)
20120-31	Stucco (no asbestos detected)
20120-32	Stucco (no asbestos detected)
20120-33	Caulking (no asbestos detected)

Comments:
(No Access)



20120-28



20120-29



20120-30



20120-31

Building: Roof and Exterior



20120-32



20120-33

Building: Floor 4.5, Room Attic

Room Details:

- Ceiling: Wood
- Wall: Wood
- Floor: Wood

Hazardous Materials Observed:

Samples:

None

Comments:

Fibreglass insulation and pipe insulation



Building: Floor 4, Room 406

Room Details:


- Ceiling: Plaster, Drywall with Joint Compound
- Wall: Drywall with Joint Compound, Plaster, Wall Texture Coat 1
- Floor: Carpet, Wood

Hazardous Materials Observed:

- **PCB:**
Fluorescent light ballasts may contain PCBs, prior to modification, check ballast to determine if PCBs are present.
- **Mercury containing:** Fluorescent light tubes contain mercury.

Samples:

- | | |
|----------|---|
| 20120-18 | Drywall Joint Compound (no asbestos detected) |
| 20120-19 | Wall Texture Coat 1 (no asbestos detected) |
| 20120-20 | Wall Texture Coat 1 (no asbestos detected) |
| 20120-21 | Wall Texture Coat 1 (no asbestos detected) |



20120-18




20120-19

Building: Floor 4, Room 406



20120-20



20120-21

Building: Floor 4, Room 405

Room Details:


- Ceiling: Plaster
- Walls: Plaster, Drywall with Joint Compound
- Flooring: Carpet, Wood

Hazardous Materials Observed:

- **PCB:**
Fluorescent light ballasts may contain PCBs, prior to modification, check ballast to determine if PCBs are present.
- **Mercury containing:** Fluorescent light tubes contain mercury.

Samples:

None



Building: Floor 4, Room 404

Room Details:

- Ceiling: Plaster
- Walls: Plaster, Drywall with Joint Compound
- Flooring: Carpet, Wood

Hazardous Materials Observed:

- **PCB:**
- **Mercury containing:** Fluorescent light tubes contain mercury.

Samples:

None



Building: Floor 4, Room 403

Room Details:

- Ceiling: Plaster
- Walls: Plaster, Drywall with Joint Compound
- Flooring: Carpet, Wood

Hazardous Materials Observed:

- **PCB:**
Fluorescent light ballasts may contain PCBs, prior to modification, check ballast to determine if PCBs are present.
- **Mercury containing:** Fluorescent light tubes contain mercury.



Samples:

None

Building: Floor 4, Room 402

Room Details:

- Ceiling: Plaster
- Walls: Plaster, Drywall with Joint Compound
- Flooring: Carpet, Wood

Hazardous Materials Observed:

- **PCB:**
Fluorescent light ballasts may contain PCBs, prior to modification, check ballast to determine if PCBs are present.
- **Mercury containing:** Fluorescent light tubes contain mercury.

Samples:

None



Building: Floor 4, Room 401

Room Details:

- Ceiling: Plaster
- Walls: Plaster, Drywall with Joint Compound
- Flooring: Carpet, Wood

Hazardous Materials Observed:

- **PCB:**
Fluorescent light ballasts may contain PCBs, prior to modification, check ballast to determine if PCBs are present.
- **Mercury containing:** Fluorescent light tubes contain mercury.

Samples:

None



Building: Floor 4, Room Hallway

Room Details:

- Ceiling: Drywall with Joint Compound, Plaster
- Walls: Plaster, Drywall with Joint Compound
- Flooring: Grey Sheet Flooring, Wood

Hazardous Materials Observed:

- **PCB:**
Fluorescent light ballasts may contain PCBs, prior to modification, check ballast to determine if PCBs are present.
- **Mercury containing:** Fluorescent light tubes contain mercury.

Samples:

20120-22 Drywall Joint Compound (no asbestos detected)



20120-22

Building: Floor 4, Room Stairwell

Room Details:

- Ceiling: Concrete, Ceiling Texture Coat 1, Plaster
- Walls: Concrete Block
- Flooring: Rubber, Terrazzo

Hazardous Materials Observed:

- **Asbestos:**
May be present within concrete block.
- **PCB:**
Fluorescent light ballasts may contain PCBs, prior to modification, check ballast to determine if PCBs are present.
- **Mercury containing:** Fluorescent light tubes contain mercury.

Samples:

- | | |
|----------|---|
| 20120-23 | Ceiling Texture Coat 1 (no asbestos detected) |
| 20120-24 | CTX 1 (no asbestos detected) |
| 20120-25 | Layer 1, Plaster skim coat (no asbestos detected) |
| 20120-25 | Layer 2, Plaster base coat (no asbestos detected) |
| 20120-27 | Layer 1, Rubber Floor (no asbestos detected) |
| 20120-27 | Layer 2, Mastic (no asbestos detected) |



20120-23



20120-24



20120-25



20120-27



Building: Floor 4, Room Stairwell



Building: Floor 3, Room 316

Room Details:

- Above Ceiling: Plaster
- Ceiling: Acoustic Ceiling Tile1
- Walls: Plaster
- Flooring: Carpet, Wood

Hazardous Materials Observed:

- **PCB:**
Fluorescent light ballasts may contain PCBs, prior to modification, check ballast to determine if PCBs are present.
- **Mercury containing:** Fluorescent light tubes contain mercury.
- **Lead:** Flaking paint chips contain lead.

Samples:

- 20120-14** Paint Chips (**contains lead 590 mg/kg**)
- 20120-15** Layer 1, Plaster Skim Coat (no asbestos detected)
- 20120-15** Layer 2, Plaster Base Coat (no asbestos detected)

Comments:

Damage to plaster and paint



20120-14; 20120-15



Building: Floor 3, Room 315

Room Details:


- Above Ceiling: Plaster
- Ceiling: Acoustic Ceiling Tile1
- Walls: Plaster
- Flooring: Carpet, Wood

Hazardous Materials Observed:

- **PCB:**
Fluorescent light ballasts may contain PCBs, prior to modification, check ballast to determine if PCBs are present.
- **Mercury containing:** Fluorescent light tubes contain mercury.

Samples:

None



Building: Floor 3, Room 314

Room Details:

- Above Ceiling: Plaster
- Ceiling: Acoustic Ceiling Tile1
- Walls: Plaster, Panel
- Flooring: Carpet, Wood

Hazardous Materials Observed:

- **PCB:**
Fluorescent light ballasts may contain PCBs, prior to modification, check ballast to determine if PCBs are present.
- **Mercury containing:** Fluorescent light tubes contain mercury.

Samples:

None



Building: Floor 3, Room 313

Room Details:

- Above Ceiling: Drywall with Joint Compound Plaster,
- Ceiling: Acoustic Ceiling Tile 1
- Wall: Plaster, Drywall with Joint Compound
- Floor: Carpet, Wood

Hazardous Materials Observed:

- **PCB:**
Fluorescent light ballasts may contain PCBs, prior to modification, check ballast to determine if PCBs are present.
- **Mercury containing:** Fluorescent light tubes contain mercury.

Samples:

None



Building: Floor 3, Room 303

Room Details:

- Above Ceiling: Drywall with Joint Compound
- Ceiling: Acoustic Ceiling Tile 1
- Wall: Plaster, Drywall with Joint Compound
- Floor: Carpet, Wood

Hazardous Materials Observed:

- **PCB:**
Fluorescent light ballasts may contain PCBs, prior to modification, check ballast to determine if PCBs are present.
- **Mercury containing:** Fluorescent light tubes contain mercury.



Samples:

20120-17 Drywall with Joint Compound Above Ceiling



20120-17

Building: Floor 3, Room 302

Room Details:

- Ceiling: Plaster, Acoustic Ceiling Tile 1
- Wall: Plaster, Drywall with Joint Compound
- Floor: Carpet, Wood

Hazardous Materials Observed:

- **PCB:**
Fluorescent light ballasts may contain PCBs, prior to modification, check ballast to determine if PCBs are present.
- **Mercury containing:** Fluorescent light tubes contain mercury.



Samples:

None

Building: Floor 3, Room 301.5

Room Details:


- Ceiling: Donna Conna Tile 2
- Wall: Donna Conna Tile 2, Plaster
- Floor: Grey Sheet Flooring Wood
- Other: Glue dollops may be present

Hazardous Materials Observed:

- **Mercury containing:** Fluorescent light tubes contain mercury.

Samples:

20120-16 Donna Conna Tile 2(no asbestos detected)



20120-16


Building: Floor 3, Room 301

Room Details:

- Ceiling: Plaster, Acoustic Ceiling Tile 1
- Walls: Plaster, Wood
- Flooring: Carpet, Wood

Hazardous Materials Observed:

- **PCB:**
Fluorescent light ballasts may contain PCBs, prior to modification, check ballast to determine if PCBs are present.
- **Mercury containing:** Fluorescent light tubes contain mercury.



Samples:

None

Building: Floor 3, Room Hallway

Room Details:

- Above Ceiling: Drywall with Joint Compound, Plaster
- Ceiling: Acoustic Ceiling Tile 1
- Wall: Drywall with Joint Compound, Plaster
- Floor: Grey Sheet Flooring, Wood

Hazardous Materials Observed:

- **PCB:**
Fluorescent light ballasts may contain PCBs, prior to modification, check ballast to determine if PCBs are present.
- **Mercury containing:** Fluorescent light tubes contain mercury.

Samples:

None



Building: Floor 2, Room 201

Room Details:

- Above Ceiling: Drywall with Joint Compound, Plaster
- Ceiling: Acoustic Ceiling Tile 1
- Wall: Drywall with Joint Compound, Plaster
- Floor: Carpet, Wood

Hazardous Materials Observed:

- **PCB:**
Fluorescent light ballasts may contain PCBs, prior to modification, check ballast to determine if PCBs are present.
- **Mercury containing:** Fluorescent light tubes contain mercury.

Samples:

None

Comments:

Fibreglass pipe insulation



Building: Floor 2, Room 202

Room Details:

- Above Ceiling: Drywall with Joint Compound, Plaster
- Ceiling: Acoustic Ceiling Tile 1
- Wall: Drywall with Joint Compound
- Floor: Carpet, Wood

Hazardous Materials Observed:

- **PCB:**
Fluorescent light ballasts may contain PCBs, prior to modification, check ballast to determine if PCBs are present.
- **Mercury containing:** Fluorescent light tubes contain mercury.


Samples:

20120-11 Layer 1, Plaster, Skim Coat (no asbestos detected)

20120-11 Layer 2, Plaster, Base Coat (no asbestos detected)



20120-11



Building: Floor 2, Room 203

Room Details:

- Above Ceiling: Drywall with Joint Compound, Plaster
- Ceiling: Acoustic Ceiling Tile
- Wall: Drywall with Joint Compound
- Floor: Carpet, Wood

Hazardous Materials Observed:

- **PCB:**
Fluorescent light ballasts may contain PCBs, prior to modification, check ballast to determine if PCBs are present.
- **Mercury containing:** Fluorescent light tubes contain mercury.

Samples:

20120-12 Drywall with Joint Compound (no asbestos detected)

Comments:

Fibreglass pipe insulation above ceiling



Building: Floor 2, Room 204

Room Details:


- Above Ceiling: Drywall with Joint Compound, Plaster
- Ceiling: Acoustic Ceiling Tile 1
- Wall: Drywall with Joint Compound, Plaster
- Floor: Carpet, Wood

Hazardous Materials Observed:

- **PCB:**
Fluorescent light ballasts may contain PCBs, prior to modification, check ballast to determine if PCBs are present.
- **Mercury containing:** Fluorescent light tubes contain mercury.

Samples:

None



Building: Floor 2, Room 205

Room Details:

- Above Ceiling: Drywall with Joint Compound, Plaster
- Ceiling: Acoustic Ceiling Tile 1
- Wall: Drywall with Joint Compound, Plaster
- Floor: Carpet, Wood

Hazardous Materials Observed:

- **PCB:**
Fluorescent light ballasts may contain PCBs, prior to modification, check ballast to determine if PCBs are present.
- **Mercury containing:** Fluorescent light tubes contain mercury.

Samples:

None

Comments:

Fibreglass pipe insulation



Building: Floor 2, Room 206

Room Details:

- Above Ceiling: Plaster
- Ceiling: Acoustic Ceiling Tile 1
- Wall: Drywall with Joint Compound, Plaster
- Floor: Carpet, Wood

Hazardous Materials Observed:

- **PCB:**
Fluorescent light ballasts may contain PCBs, prior to modification, check ballast to determine if PCBs are present.
- **Mercury containing:** Fluorescent light tubes contain mercury.



Samples:

None

Comments:

Fibreglass Insulation (wall cavity)



Building: Floor 2, Room 207

Room Details:

- Above Ceiling: Drywall with Joint Compound, Plaster
- Ceiling: Acoustic Ceiling Tile 1
- Wall: Drywall with Joint Compound, Plaster
- Floor: Carpet, Wood

Hazardous Materials Observed:

- **PCB:**
Fluorescent light ballasts may contain PCBs, prior to modification, check ballast to determine if PCBs are present.
- **Mercury containing:** Fluorescent light tubes contain mercury.

Samples:

None



Building: Floor 2, Room 208

Room Details:

- Above Ceiling: Drywall with Joint Compound, Plaster
- Ceiling: Acoustic Ceiling Tile 1
- Wall: Drywall with Joint Compound, Plaster
- Floor: Carpet, Wood

Hazardous Materials Observed:

- **PCB:**
Fluorescent light ballasts may contain PCBs, prior to modification, check ballast to determine if PCBs are present.
- **Mercury containing:** Fluorescent light tubes contain mercury.

Samples:

20120-13 Layer 1,-Plaster Skim Coat (no asbestos detected)

20120-13 Layer 2,-Plaster Base Coat (no asbestos detected)

Comments:

Fibreglass pipe insulation



20120-13

Building: Floor 1, Room 101

Room Details:

- Ceiling: Ceiling Texture Coat 1
- Wall: Drywall with Joint Compound, Plaster
- Floor: Carpet, Concrete

Hazardous Materials Observed:

- **PCB:**
Fluorescent light ballasts may contain PCBs, prior to modification, check ballast to determine if PCBs are present.
- **Mercury containing:** Fluorescent light tubes contain mercury.

Samples:

None



Building: Floor 1, Room 102

Room Details:

- Ceiling: Acoustic Ceiling Tile, Drywall with Joint Compound
- Wall: Plaster, Drywall with Joint Compound
- Floor: Carpet, Concrete

Hazardous Materials Observed:

- **PCB:**
Fluorescent light ballasts may contain PCBs, prior to modification, check ballast to determine if PCBs are present.
- **Mercury containing:** Fluorescent light tubes contain mercury.

Samples:

None



Building: Floor 1, Room 103

Room Details:

- Ceiling: Acoustic Ceiling Tile, Drywall with Joint Compound, Plaster
- Wall: Plaster, Drywall with Joint Compound
- Floor: Grey Sheet Flooring, Concrete

Hazardous Materials Observed:

- **PCB:**
Fluorescent light ballasts may contain PCBs, prior to modification, check ballast to determine if PCBs are present.
- **Mercury containing:** Fluorescent light tubes contain mercury.



Samples:

None


Building: Floor 1, Room 104

Room Details:

- Ceiling: Ceiling Texture Coat Type 1, Plaster, Acoustic Ceiling Tile
- Wall: Ceiling Texture Coat 1, Drywall with Joint Compound Plaster,
- Floor: Carpet, Concrete

Hazardous Materials Observed:

- **PCB:**
Fluorescent light ballasts may contain PCBs, prior to modification, check ballast to determine if PCBs are present.
- **Mercury containing:** Fluorescent light tubes contain mercury.



20120-09



Samples:

20120-09 Ceiling Texture Coat 1 (no asbestos detected)

Building: Floor 1, Room 105

Room Details:

- Ceiling: Plaster,
- Wall: Plaster, Wood,
- Floor: Grey Sheet Flooring, Concrete

Hazardous Materials Observed:

- **Mercury containing:** Fluorescent light tubes contain mercury.

Samples:

- 20120-07 Layer 1, Plaster, Skim Coat (no asbestos detected)
- 20120-07 Layer 2, Plaster, Base Coat (no asbestos detected)
- 20120-08 Sheet Flooring (no asbestos detected)



20120-08



20120-07



Building: Floor 1, Room 106

Room Details:

- Ceiling: Acoustic Ceiling Tile, Drywall with Joint Compound Plaste,
- Wall: Drywall with Joint Compound
- Floor: Carpet, Concrete

Hazardous Materials Observed:

- **PCB:**
Fluorescent light ballasts may contain PCBs, prior to modification, check ballast to determine if PCBs are present.
- **Mercury containing:** Fluorescent light tubes contain mercury.

Samples:

None



Building: Floor 1, Room 107

Room Details:


- Ceiling: Drywall with Joint Compound, Acoustic Ceiling Tile
- Wall: Drywall with Joint Compound
- Floor: Carpet, Concrete

Hazardous Materials Observed:

- **PCB:**
Fluorescent light ballasts may contain PCBs, prior to modification, check ballast to determine if PCBs are present.
- **Mercury containing:** Fluorescent light tubes contain mercury.

Samples:

- 20120-04 Drywall Joint Compound (no asbestos detected)
20120-05 Acoustic Ceiling Tile (no asbestos detected)



20120-04



20120-05




Building: Floor 1, Room 108

Room Details:

- Ceiling: Wood, Plaster, Donna Conna Tile
- Wall: Plaster, Drywall with Joint Compound
- Floor: Concrete

Hazardous Materials Observed:

- **PCB:**
Fluorescent light ballasts may contain PCBs, prior to modification, check ballast to determine if PCBs are present.
- **Mercury containing:** Fluorescent light tubes contain mercury.



20120-01



20120-02

Samples:

- 20120-01 Layer 1, Plaster, Skim Coat (no asbestos detected)
- 20120-01 Layer 2, Plaster, Base Coat (no asbestos detected)
- 20120-02 Drywall with Joint Compound (no asbestos detected)
- 20120-03 Donna Conna Tile (no asbestos detected)

Comments:

Donna conna ceiling tile is stapled
Fibreglass Insulation



20120-03

Building: Floor 1, Room 109

Room Details:

- Ceiling: Acoustic Ceiling Tile, Drywall with Joint Compound
- Wall: Plaster, Drywall with Joint Compound
- Floor: Carpet, Concrete

Hazardous Materials Observed:

- **PCB:**
Fluorescent light ballasts may contain PCBs, prior to modification, check ballast to determine if PCBs are present.
- **Mercury containing:** Fluorescent light tubes contain mercury.

Samples:

None



Building: Floor 1, Room 110

Room Details:

- Ceiling: Acoustic Ceiling Tile, Drywall with Joint Compound
- Wall: Drywall with Joint Compound
- Floor: Carpet

Hazardous Materials Observed:

- **PCB:**
Fluorescent light ballasts may contain PCBs, prior to modification, check ballast to determine if PCBs are present.
- **Mercury containing:** Fluorescent light tubes contain mercury.

Samples:

20120-06 Drywall Joint Compound (no asbestos detected)



20120-06

Building: Floor 1, Room Hallway

Room Details:

- Ceiling: Drywall with Joint Compound, Plaster
- Wall: Drywall with Joint Compound, Plaster
- Floor: Grey Sheet Flooring, Concrete

Hazardous Materials Observed:


- **PCB:**
Fluorescent light ballasts may contain PCBs, prior to modification, check ballast to determine if PCBs are present.
- **Mercury containing:** Fluorescent light tubes contain mercury.

Samples:

20120-10 Firestop (Red) (No asbestos detected)

Comments:

Fibreglass pipes



20120-10

Building: Hallway

Room Details:

- Above Ceiling: Plaster, Drywall with Joint Compound
- Ceiling: Acoustic Ceiling Tile 1
- Wall: Drywall with Joint Compound, Plaster
- Floor: Grey Sheet Flooring, Wood
- Other: Sample 10 (Firestop- Red) present

Hazardous Materials Observed:

- **PCB:**
Fluorescent light ballasts may contain PCBs, prior to modification, check ballast to determine if PCBs are present.
- **Mercury containing:** Fluorescent light tubes contain mercury.

Samples:

20120-26 Layer 1, Plaster, Skim Coat (no asbestos detected)

20120-26 Layer 2, Plaster, Base Coat (no asbestos detected)

Comments:

Wood behind plaster



20120-26



10.0 Limitation of Survey

This document details the methodology, findings and conclusions of this survey and assessment conducted on the subject site in May and June 2013

Analytical results included in the report reflect the sampled materials at the specific sample locations. Visually similar materials were referenced to specific analyzed samples.

The survey of the buildings did not include destructive sampling which would permit an intrusive investigation of inaccessible wall and ceiling cavities. Limited access into interior and perimeter walls, voids, crawlspaces, and mechanical shafts was obtained for the investigation of insulation materials. It is possible that hazardous materials are present in these areas but were not identified. If materials suspected of containing asbestos or other hazardous materials are encountered during future renovations or demolition, they should be treated as hazardous proven otherwise. Locations and building materials that have not been surveyed should be considered potentially hazardous materials-containing until such time as they can be evaluated by a qualified person. Until such time as the material can be appropriately evaluated, all work that could impact the suspect materials shall cease in the affected areas until such time as appropriate precautions can be implemented to protect workers and others at the subject site.

Roofing materials may contain asbestos, however, due to the potential for damage to the building and its contents, full depth roofing core samples were not obtained from the roofing systems. Roofing materials should be sampled and analyzed for asbestos prior to disturbance in the event that roof repairs or replacement is required.

All vermiculite insulation should be considered as asbestos containing until such time as a comprehensive destructive testing sampling program is carried out within the building or structure. Asbestos containing vermiculite should be considered present within all concrete block walls, voids, and spaces including attics, walls, ceiling and floor voids.

Some materials cannot be reasonably surveyed without causing significant damage to the building structure or envelope systems. These materials should be assessed for risk specific to any planned renovations or demolition activities. Materials suspected of containing asbestos may be located in concealed locations on this site include:

- Materials inside double wall metal chimney sections,
- Concealed roofing, caulk and felts,
- Internal parts of appliances, equipment and white goods,
- Vermiculite in walls that do not have existing penetrations,
- Buried cement pipes,
- Gaskets in pipe flanges and valves and
- Fire Doors

Other materials were not sampled for fear of causing damage to building systems including vibration dampeners and electrical wiring.

An asbestos risk assessment must be completed prior to any removal and/or alteration work in or on a building. Removal and/or alteration work requires control measures to be implemented in accordance with WorkSafeBC. Regulations. Protective personal equipment is required during any work or major alteration that may disturb synthetic or asbestos insulation and/or dust that may be present.

Yours very truly,

North West Environmental Group Ltd.



Julie Scott-Moncrieff, B.Sc.,
Senior Occupational Hygienist

APPENDICES



APPENDIX A: Site Map




Figure A1: Overhead Map of NRC (Google Maps - ©2013 Google)




Figure A2: Provided map of NRC buildings (not an all inclusive list)

APPENDIX B: Sample Results



Bulk Sample Report

Asbestos Analysis of Bulk Materials using Polarized Light Microscopy

Client: National Research Council Canada

Date: June 13, 2013

Contractor: National Research Council Canada

Client Job or PO#:

Project: NRC - 1916 Wing Build

Project number: 20120

Sample No	Location	Date Analysed	Analyst	Description	Phase	%	Asbestos	%	Other Materials	%
20120-1 Layer 1	Room 108	Jun-13-2013	EMSL	Plaster	Skim Coat - White	30	None Detected	0	Non-Fibrous	100
20120-1 Layer 2	Room 108	Jun-13-2013	EMSL	Plaster	Base Coat - Grey	70	None Detected	0	Non-Fibrous	100
20120-2	Room 108	Jun-13-2013	EMSL	Drywall Joint Compound	White	100	None Detected	0	Non-Fibrous	100
20120-3	Room 108	Jun-13-2013	EMSL	Donna Conna Ceiling Tile Sm+Lg Pinhole	Brown	100	None Detected	0	Fibrous (Other) (98%) Non-Fibrous (2%)	100
20120-4	Room 107	Jun-13-2013	EMSL	Drywall Joint Compound	White	100	None Detected	0	Non-Fibrous	100
20120-5	Room 107	Jun-13-2013	EMSL	Acoustic Ceiling Tile (Pinhole + Random Fissure)	Grey	100	None Detected	0	Fibrous (Other) (80%) Non-Fibrous (20%)	100
20120-6	Room 110	Jun-13-2013	EMSL	Drywall Joint Compound	White	100	None Detected	0	Non-Fibrous	100
20120-7 Layer 1	Room 105	Jun-13-2013	EMSL	Plaster	Skim Coat - White	30	None Detected	0	Non-Fibrous	100
20120-7 Layer 2	Room 105	Jun-13-2013	EMSL	Plaster	Base Coat - Grey	70	None Detected	0	Non-Fibrous	100
20120-8	Room 105	Jun-13-2013	EMSL	Sheet Flooring - Grey	Grey	100	None Detected	0	Fibrous (Other) (20%) Non-Fibrous (80%)	100
20120-9	Room 104	Jun-13-2013	EMSL	Ceiling Texture Coat 1	Cream	100	None Detected	0	Non-Fibrous	100
20120-10	1st Floor Hallway - Adjacent to 110	Jun-13-2013	EMSL	Firestopping (Red)	Red	100	None Detected	0	Non-Fibrous	100
20120-11 Layer 1	Room 202 - Above Ceiling	Jun-13-2013	EMSL	Plaster	Skim Coat - White	30	None Detected	0	Non-Fibrous	100
20120-11 Layer 2	Room 202 - Above Ceiling	Jun-13-2013	EMSL	Plaster	Base Coat - Grey	70	None Detected	0	Non-Fibrous	100
20120-12	Room 203 - Above Ceiling	Jun-13-2013	EMSL	Drywall Joint Compound	White	100	None Detected	0	Non-Fibrous	100

Note: Samples were analyzed by method: EPA/600/R-93/116" Bulk Asbestos Analysis by Polarized Light Microscopy". For heterogenous materials the concentration may vary. No reproduction without permission.

Sample No	Location	Date Analysed	Analyst	Description	Phase	%	Asbestos	%	Other Materials	%
20120-13 Layer 1	Room 208	Jun-13-2013	EMSL	Plaster	Skim Coat - White	30	None Detected	0	Non-Fibrous	100
20120-13 Layer 2	Room 208	Jun-13-2013	EMSL	Plaster	Base Coat - Grey	70	None Detected	0	Non-Fibrous	100
20120-15 Layer 1	Room 316	Jun-13-2013	EMSL	Plaster	Skim Coat - White	30	None Detected	0	Non-Fibrous	100
20120-15 Layer 2	Room 316	Jun-13-2013	EMSL	Plaster	Base Coat - Grey	70	None Detected	0	Non-Fibrous	100
20120-16	Room 301.5	Jun-13-2013	EMSL	Donna Conna Tile 2 - Large Pinhole	Brown	100	None Detected	0	Fibrous (Other) (98%) Non-Fibrous (2%)	100
20120-17	Room 303 - Above Ceiling	Jun-13-2013	EMSL	Drywall Joint Compound	White	100	None Detected	0	Non-Fibrous	100
20120-18	Room 406	Jun-13-2013	EMSL	Drywall Joint Compound	White	100	None Detected	0	Non-Fibrous	100
20120-19	Room 406	Jun-13-2013	EMSL	Wall Texture Coat 1	Beige	100	None Detected	0	Non-Fibrous	100
20120-20	Room 406	Jun-13-2013	EMSL	Wall Texture Coat 1	Beige	100	None Detected	0	Non-Fibrous	100
20120-21	Room 406	Jun-13-2013	EMSL	Wall Texture Coat 1	Beige	100	None Detected	0	Non-Fibrous	100
20120-22	4th Floor Hallway - Adj. to 404	Jun-13-2013	EMSL	Drywall Joint Compound	White	100	None Detected	0	Non-Fibrous	100
20120-23	4th Floor Stairwell	Jun-13-2013	EMSL	Ceiling Texture Coat 1	Cream	100	None Detected	0	Non-Fibrous	100
20120-24	4th Floor Stairwell	Jun-13-2013	EMSL	Ceiling Texture Coat 1	Cream	100	None Detected	0	Non-Fibrous	100
20120-25 Layer 1	3rd Floor Stairwell	Jun-13-2013	EMSL	Plaster	Skim Coat - White	30	None Detected	0	Non-Fibrous	100
20120-25 Layer 2	3rd Floor Stairwell	Jun-13-2013	EMSL	Plaster	Base Coat - Grey	70	None Detected	0	Non-Fibrous	100
20120-26 Layer 1	2nd Floor Hallway - Adj. to 204	Jun-13-2013	EMSL	Plaster	Skim Coat - White	30	None Detected	0	Non-Fibrous	100
20120-26 Layer 2	2nd Floor Hallway - Adj. to 204	Jun-13-2013	EMSL	Plaster	Base Coat - Grey	70	None Detected	0	Non-Fibrous	100
20120-27 Layer 1	4th Floor Stairwell	Jun-13-2013	EMSL	Rubber Floor & Mastic	Flooring - Purple	90	None Detected	0	Non-Fibrous	100
20120-27 Layer 2	4th Floor Stairwell	Jun-13-2013	EMSL	Rubber Floor & Mastic	Mastic	10	None Detected	0	Non-Fibrous	100
20120-28	Roof	Jun-13-2013	EMSL	Black Asphalt Shingle	Black	100	None Detected	0	Fibrous (Other) (30%) Non-Fibrous (70%)	100
20120-29	Roof	Jun-13-2013	EMSL	Red Asphalt Shingle	Black	100	None Detected	0	Fibrous (Other) (25%) Non-Fibrous (75%)	100
20120-30	Exterior - 4th Floor	Jun-13-2013	EMSL	Stucco	Grey	100	None Detected	0	Non-Fibrous	100
20120-31	Exterior - 4th Floor	Jun-13-2013	EMSL	Stucco	Grey	100	None Detected	0	Non-Fibrous	100
20120-32	Exterior - 4th Floor	Jun-13-2013	EMSL	Stucco	Grey	100	None Detected	0	Non-Fibrous	100

Note: Samples were analyzed by method: EPA/600/R-93/116" Bulk Asbestos Analysis by Polarized Light Microscopy". For heterogenous materials the concentration may vary. No reproduction without permission.



Sample No	Location	Date Analysed	Analyst	Description	Phase	%	Asbestos	%	Other Materials	%
20120-33	Exterior - 4th Floor	Jun-13-2013	EMSL	Caulking - Flashing (White)	White	100	None Detected	0	Non-Fibrous	100

Note: Samples were analyzed by method: EPA/600/R-93/116" Bulk Asbestos Analysis by Polarized Light Microscopy". For heterogenous materials the concentration may vary. No reproduction without permission.



APPENDIX C: Sample Locations




North West
Environmental Group Ltd.


NWEG #20120


See General Notes

72

Warning: in the event any additional suspect materials are encountered during renovation/repair activities, work on those materials should stop immediately and remain undisturbed until testing confirms the presence or absence of asbestos or other hazardous material



LEGEND		DRAWING NOT TO SCALE	
123	None Detected	ADDRESS/LOCATION:	PROJECT NO.: 20120
123	Material Contains Asbestos	<u>Herzberg Institute of Astrophysics</u>	DATE: <u>05/06/2013</u>
123	Lead Sample	DRAWING TITLE:	SURVEYED BY: <u>WR/DM</u>
		<u>Administration Building</u>	DRAWING NO.: <u>001</u>
		<u>1916 Wing - Fourth Floor</u>	 North West Environmental Group Ltd. #210 – 2950 Douglas St. Victoria, BC V8T 4N4



DRAWING NOT TO SCALE

LEGEND

ASBESTOS

123	None Detected
123	Material Contains Asbestos
123	Lead Sample

ADDRESS/LOCATION:
Herzberg Institute of Astrophysics

DRAWING TITLE:
Administration Building
1916 Wing - Third Floor

PROJECT NO.: 20120


DATE: 05/06/2012

SURVEYED BY: WR/DM

DRAWING NO.: 002



#210 – 2950 Douglas St.
 Victoria, BC V8T 4N4



DRAWING NOT TO SCALE

LEGEND

ASBESTOS

123

None Detected

123

Material Contains Asbestos

123

Lead Sample

ADDRESS/LOCATION:

Herzberg Institute of Astrophysics

DRAWING TITLE:

Administration Building
1916 Wing - Second Floor

PROJECT NO.: 20120

DATE: 05/06/2012

SURVEYED BY: WR/DM


DRAWING NO.: 003



North West
 Environmental Group Ltd.

#210 – 2950 Douglas St.

Victoria, BC V8T 4N4



DRAWING NOT TO SCALE

LEGEND

ASBESTOS

123

None Detected

123

Material Contains Asbestos

123

Lead Sample

ADDRESS/LOCATION:

Herzberg Institute of Astrophysics

DRAWING TITLE:

Administration Building
1916 Wing - First Floor

PROJECT NO.: 20120

DATE: 05/06/2012

SURVEYED BY: WR/DM

DRAWING NO.: 004



North West
 Environmental Group Ltd.

#210 – 2950 Douglas St.

Victoria, BC V8T 4N4