

TAYLOR HAZELL ARCHITECTS
 333 Adelaide Street West, 5th Floor
 Toronto ON M5V 1R5 www.taylorhazell.com
 p. 416.862.2694 f. 416.862.8401



03	RE-ISSUED FOR TENDER	05.07.16
02	ISSUED FOR TENDER	03.05.16
01	ISSUED FOR 99%	06.04.16
revisions		date

project _____ project _____

MACHIAS SEAL ISLAND LIGHTHOUSE RESTORATION

SECTION DETAIL PHOTOS

designed TAYLOR HAZELL ARCHITECTS conçu
 date _____
 drawn N. ADDISON dessiné
 date _____
 approved C. HAZELL approuvé
 date _____

Tender _____ Soumission _____

PWGC Project Manager Administrateur de projets TPSCG

project number no. du projet

R.080316.001

drawing no. no. du dessin

A300





PHOTO 02 - DETAIL VIEW OF DAMAGE AT EXTERIOR LANTERN CONCRETE CURB. REPAIR CONCRETE; REFER TO STRUCTURAL.



PHOTO 01 - DETAIL VIEW OF INTERIOR LANTERN WINDOW ASSEMBLY.



PHOTO 06 - TYPICAL CONDITION OF GALLERY LEVEL SLAB. TO BE REBUILT AND NEW TRAFFIC COATING PROVIDED. NEW RAIL TO BE 125mm FROM GALLERY EDGE. REFER TO DETAIL 1/A500.



PHOTO 05 - TYPICAL CONDITION OF UNDERSIDE GALLERY LEVEL SLAB TO BE REBUILT. EXISTING METAL BRACKET TO BE DISASSEMBLED AND STORED. PENETRATIONS TO BE SEALED, REFER TO STRUCTURAL.



PHOTO 04 - DETAIL OF EXISTING RO5 BOOT TO BE REPLACED.



PHOTO 03 - DETAIL OF ANCHOR BOLTS TO BE REMOVED AND HAND PATCHED.



PHOTO 02 - EXTERIOR WALL PENETRATIONS AT FIRST LEVEL TO BE PROPERLY SEALED WITH FIRE PROTECTION AROUND EXHAUST. PROVIDE NEW DRYWALL FINISH, PRIME & PAINT.



PHOTO 01 - DETAIL OF TYPICAL DAMAGE AT CONCRETE COLLAR BASE. COLLAR TO BE CHIPPED BACK TO SOUND MATERIAL AND REBUILT. REFER TO STRUCTURAL.