



PHOTO 12 - DETAIL VIEW OF INTERIOR LANTERN TIE BAR TO BE REPLACED TO MATCH ORIGINAL. REFER TO STRUCTURAL.




PHOTO 15 - DETAIL OF EXISTING LANTERN VENT WITH FAILED RUBBER SEAL, INTERIOR. REMOVE SEAL, PAINT AND CORROSION. PROVIDE REPLACEMENT CAP WITH GASKET AND INSTALL IN "CLOSED" POSITION. MAKE-GOOD ANY DAMAGE TO CONCRETE SUSTAINED DURING REMOVAL.




PHOTO 14 - DETAIL OF EXISTING LANTERN VENT, INTERIOR. REMOVE CAP AND REMOVE PAINT AND CORROSION. PROVIDE GASKET FOR SEAL AND REINSTATE CAP IN "CLOSED" POSITION. MAKE-GOOD ANY DAMAGE TO CONCRETE SUSTAINED DURING REMOVAL OF CAP.



PHOTO 16 - INTERIOR OF GALLERY HATCH. SILL AND HEAD CASING ARE ORIGINAL AND ARE TO BE RETAINED. JAMBS AND DOOR TO BE REPLACED. REFER TO DETAIL 3/A500



PHOTO 13 - EXTERIOR GALLERY LADDER. PROVIDE NEW METAL BOLTED CONNECTIONS. REFER TO DETAIL 2/A501.

04	ISSUED FOR PH. 2 TENDER	07.26.17
03	RE-ISSUED FOR TENDER	05.07.16
02	ISSUED FOR TENDER	13.05.16
01	ISSUED FOR 99%	06.04.16
revisions		date

project project

MACHIAS SEAL ISLAND
LIGHTHOUSE
RESTORATION

drawing dessin

DETAIL PHOTOS

designed conçu

date

drawn dessiné

date

approved pspc approuvé

date July 2017

Tender Ian Sceles Soumission

PWGSC Project Manager Administrateur de projets TPSGC

project number no. du projet

R.080316.001

drawing no. no. du dessin

A301