

# ***ASI Marine*** | **REPORT**

Submitted to:

**Parsons Corporation  
625 Cochrane Drive, Suite 500  
Markham, ON L3R 9R9**

**Underwater Bridge Inspection  
Hamlet Swing Bridge  
Hamlet, ON**

**Inspection Dates:**

**November 2-3, 2016**

**ASI Marine Proposal DH16-066**

## Table of Contents

---

1.0	INTRODUCTION .....	1
2.0	SCOPE OF WORK .....	2
3.0	QUALIFICATIONS .....	2
4.0	METHODOLOGY .....	2
5.0	INSPECTION PROCEDURE .....	3
6.0	OBSERVATIONS .....	3
6.1	Rest Pier .....	4
6.1.1	East side (0+000E to 0+029E, 0+036.5E to 0+066.5E) excluding Pivot Pier .....	4
6.1.2	West side (0+000E to 0+029E, 0+039E to 0+069E) excluding Pivot Pier .....	6
6.1.3	North face (0+000N to 0+004.8N) .....	8
6.1.4	South face (0+000S to 0+005S) .....	8
6.2	Pivot Pier .....	8
6.2.1	East side (0+030E to 0+037.5E) .....	8
6.2.2	West side (0+030W to 0+039W) .....	9
6.3	East Pier .....	9

## List of Appendices

- Appendix 1: Site Photos
- Appendix 2: General Arrangement Drawing
- Appendix 3: Inspection Data Sheets
- Appendix 4: Inspection Video (USB)

## REPORT

**Parsons Corporation**

**Underwater Inspection – Hamlet Swing Bridge  
1641 Muskoka District Road 49  
Hamlet, ON**

**March 8, 2017**

### 1.0 INTRODUCTION

ASI Marine, a division of ASI Group Ltd. (ASI), has been retained by Parsons Corporation to perform an underwater condition inspection of the Hamlet Swing Bridge located in Hamlet, Ontario. The following report identifies defects, as well as general conditions, associated with swing bridge located at N44°46'58.62", W79°23'41.84".



**Figure 1: Hamlet Swing Bridge, Hamlet, Ontario**

## **2.0 SCOPE OF WORK**

The scope of services as described in the correspondence with Parson Corporation was as follows:

- Mobilization and demobilization
- Underwater inspection, Rest Pier (north and south limits), Pivot Pier and East Pier
- Compilation of detailed inspection report including images and edited video.

## **3.0 QUALIFICATIONS**

All commercial diving was performed in accordance with The Ministry of Labour (MOL) Diving Regulation O.Reg.629/94 amended to O. Reg. 32/14 and the Canadian Standards Association (CSA) Competency Standard for Diving Z275.4-12. A written 'Notice for Diving Operations' was submitted to the MOL prior to mobilizing to site.

ASI Commercial Divers are certified in accordance with Canadian Standards Association (CSA) Competency Standard for Diving Z275.4-12 and as legislated by The Ministry of Labour (MOL) Diving Regulation O.Reg.629/94 amended to O. Reg.32/14. Diving personnel hold a current Diver Certification Board of Canada (DCBC) recognition card.

## **4.0 METHODOLOGY**

ASI provided a four-man commercially qualified dive crew equipped with surface-supplied diving equipment, helmet-mounted video/LED lighting and underwater camera system (for real-time monitoring) to conduct all in-water task requirements. Daily verbal reports of project progress were supplied to Parsons Corporation via an underwater inspection data sheet. Two hard copies of the final inspection videos edited in electronic format will be delivered to Parsons Corporation upon completion of the project.

The diving supervisor was able to monitor the inspection progress in real-time. The client representative (on-site engineer) communicated with the diver to ensure project objectives were achieved. A 19-inch video monitor will be available topside to observe diving operations. Diving personnel were staged from a dive support vessel (ASI Niagara). Staging consisted of two complete surface supply diving systems along with high pressure/low pressure and redundant diver air supply, support equipment/tooling and first aid emergency response equipment. ASI ensured a means of diver extraction is at the dive site, allowing for prompt evacuation if required.





Figure 2: Diver performing underwater inspections

## 5.0 INSPECTION PROCEDURE

The inspection commenced at the north limit of the east side of the rest pier moving southward. Once the east limit was completed the dive crew began the inspection of the east pier moving in a clockwise direction. The inspection ended by inspecting the west side of the rest pier, commencing at the south limit moving north. The inspection of the piers included measurements and location of defects, as well as water depth, utilizing a measuring stick and 100' cloth measuring tape. As marine growth was found on the majority of the piers, isolated areas were cleaned off and inspected further. Utilizing a probing tool, penetration depths of the timber were measured and recorded in order to determine the level of cross-sectional loss and rot.

## 6.0 OBSERVATIONS

Upon arrival, the dive team conducted a safety talk to review all safety procedures before commencing the inspection. The inspection found the Rest Pier to be in fair condition. The timber cribbing on the west side of the rest pier was found to be in better condition than that of the cribbing on the east side. The rest pier was found to be constructed of timber cribbing with precast concrete blocks located above the cribbing. Spalling was evident on the majority of concrete blocks at the inner edges where the adjoining blocks meet. Located on top of the concrete block was mass concrete that extends the full length of the pier. Inspection of the mass concrete was generally not included in this report other than severe areas of deterioration that extended to water surface. Located at the centre of the rest pier was the pivot pier which was found to be constructed of concrete. The inspection found the east pier to be completely encased in grout bags. Reference material indicated the east pier to be constructed of wood sheeting and steel sheet pile with a concrete deck. Due to the fact the east pier was encased in grout bags, inspection of the pier was not possible. The grout bags were found to be generally intact and in fair condition. Below are general descriptions of the findings, highlighting the major observations.

## 6.1 Rest Pier

### 6.1.1 East side (0+000E to 0+029E, 0+036.5E to 0+066.5E) excluding Pivot Pier

Chainage	Observations
0+000E	Marine growth on crib, more extensive near bottom
	Tiebacks found to have 0.03 m gap around circumference
	21 rows of timbers, no undermining of crib found
	0.38 m x 0.38 m screw bolt w/ washers securing timbers in good condition
	Gap between 7 <sup>th</sup> and 8 <sup>th</sup> timber from top, 0.5 m of penetration
	12 <sup>th</sup> timber from top, end grain rotted
	14 <sup>th</sup> timber from top, 0.15 m of penetration at end of timber
	15 <sup>th</sup> timber from top, severely rotted corner tieback
	16 <sup>th</sup> timber from top, 0.025 of cross-section loss on face of timber 0.3 m in length
0+002E	0.48 m long x 0.25 m high x 0.06 m deep spall on concrete block at surface
	0.12 m long x 0.1 m high x 0.06 m deep spall
	Gap between blocks approximately 0.07 m wide
0+003E	Top 3 tiebacks approximately 0.1 m of penetration into timber
0+005E	Top tieback timber severely rotted
	2 <sup>nd</sup> timber from top 0.1 m penetration into timber
	3 <sup>rd</sup> timber from top, severely rotted
0+006E	Concrete block overhangs timber crib to the east by 0.76 m (extends to 0+011)
0+008E	2 <sup>nd</sup> tie back from the top, 20% cross-sectional loss
	No resistance at 0.76 m penetration between timbers
	3 <sup>rd</sup> timber from the top, 0.15 m penetration
	4 <sup>th</sup> timber from the top, rotted with 0.2 m penetration
	6 <sup>th</sup> timber from the top, 50% cross-sectional loss, 0.1 m penetration
	Lake bottom 0.3 m deep sediment, hard bottom below sediment
0+009E	Severe spall, 0.74 m long x 0.46 m high x 0.1 m deep spall, 0.41 m below surface
	Concrete blocks spalled at corners
0+011E	Bottom 1/3 of top timber disintegrated (through pin exposed)
0+011E to 0+012E	Severe spall with exposed rebar at surface, 0.97 m long x 0.74 m high x 0.03 m deep
0+012E	Top tieback timber rotted 0.5 m deep
	4 <sup>th</sup> timber from the top, 0.15 m penetration
	9 <sup>th</sup> timber from the top, 0.1 m penetration
	12 <sup>th</sup> timber from the top, 0.1 m penetration
	0.1 m penetration at lake bottom
0+015E	6 <sup>th</sup> timber from the top, 0.2 m penetration
	0.2 m penetration on lake bottom
0+017E	Spall on concrete block at surface, 0.9 m long x 0.38 m high x 0.1 m deep
0+018E	1 <sup>st</sup> tieback from top, 50% cross-sectional loss

Chainage	Observations
0+018E	7 <sup>th</sup> tieback from top, 0.18 m penetration
	0.03 m penetration into lake bottom
	Split timber from 0+018 to 0+020, 3.1 m off lake bottom
0+020E	Top timber, 10% cross-sectional loss
	2 <sup>nd</sup> timber from bottom, 0.15 m penetration
	Concrete from over pour found on bottom, 1.5 m long x 0.5 m high x 0.5 m high
	Severe rot just below waterline, 1 <sup>st</sup> timber from top
	7 <sup>th</sup> timber from top, excessive rot 0.61 m wide
	9 <sup>th</sup> timber from top offset 0.08 m offshore
	Block corners rounded and spalled
0+022E	2 <sup>nd</sup> tieback timber from top, sever rot, 0.3 m penetration
	Debris on lake bottom
0+023E	Pop out on concrete block, 0.9 m long x 0.3 m high x 0.56 m deep with exposed rebar
	Concrete spall, 3.5 m long x 0.15 m high x 0.1 m deep begins 0.13 m above waterline
0+038E	Spall and missing concrete on mass concrete, 2 m long x 0.18 m high x 0.46 m deep
	Concrete blocks overhand timber crib by 0.1 m
	Conduit protruding through timber crib then into lake bottom
	Concrete leaning against timber crib at lake bottom
0+040E	Spall on mass concrete ends
	Tieback timber flush with concrete blocks
	Bottom 4 timbers offset to the west by 0.1 m
0+041E	Spall on mass concrete 0.9 m long x 0.1 m high x 0.13 m deep
	5 timbers exposed, middle three offset towards west
0+047E	Spall on block corners
	Rip-rap on lake bottom
	Light sediment on lake bottom with cobbles
0+050E	Top timber 0.13 m offsets lower timbers to the west
	Lower timbers flush with blocks
0+052E to 0+053E	Top timber with severe rot for whole length of timber, 85% cross-sectional loss
0+053E	Crib joint in good condition
0+055E	Spalling on block corners continues
0+056E	Spall on blocks 0.3 m long x 0.38 m high x 0.18 m deep
	Spall on mass concrete continues
0+058E	Exposed steel on mass concrete 0.53 m long x 0.38 m high x 0.18 m deep

Chainage	Observations
0+058E	7 <sup>th</sup> tieback from top, 0.18 m penetration Rip rap on lake bottom
0+062E	Spall on blocks 0.15 m long x 0.25 m high x 2 m deep
0+063E to 0+065E	Severe spall between mass concrete and concrete blocks with exposed rebar, 1.98 m long x 0.48 m high x 0.96 m deep
0+066.5E	Concrete block proud of timber crib 0.1 m
	Steel angled face at end of pier with 0.66 m long x 0.48 m high x 0.76 m deep long void behind, continues 0.28 m below surface. Steel face extends 1.37 m below surface at a 45° angle, then plumb to 1.83 m below surface
	Undermining of timber crib, beginning at chainage 0+064, 2.5 m long x 0.3 m high x 0.45 m deep

#### 6.1.2 West side (0+000E to 0+029E, 0+039E to 0+069E) excluding Pivot Pier

Chainage	Observations
0+000W	Concrete spall on blocks with exposed aggregate 0.25 m long x 0.25 m high x 0.03 m deep, commencing 0.1 m below surface
0+001W	Top tieback timber, 10% cross-sectional loss
0+003W	Scour / spall on concrete block corners
0+004W	Spall on concrete block, 0.76 m long x 0.33 m high x 0.06 m deep
0+005W	Light scour and spalling on edge of concrete block corners
0+006W	Bottom timber, 50% cross-sectional loss
0+006W to 0+012W	Spalling on concrete block corners
0+012W	Top timber 30% cross-sectional loss
0+013W	Spall on bottom of concrete block, 0.33 m long x 0.13 m high x 0.04 m deep
0+014.5W	Spall at centre of concrete block, 0.45 m long to 0.43 m high x 0.06 m deep
0+015W to 0+020W	Spall at corner of blocks at bottom, 0.06 m wide separation of blocks
0+018W	Tie back timber missing approximately 0.3 m
0+021W	Top timber approx. 5% cross-sectional loss
0+024W	Spall on concrete blocks, 0.18 m long x 0.23 m high x 0.04 m deep
0+026W	Spall on corner of concrete blocks
0+027W	Top timber, 0.15 m rot at end of timber
0+030W	Spall on concrete block, 0.23 m long x 0.05 m high x 0.04 m deep, 0.05 m below surface

Chainage	Observations
0+030W	Spall on concrete block, 0.3 m long x 0.36 m high x 0.03 m deep, 0.05 m below surface extends 0.05 m above surface
	Spall mid-block, begins 0.18 m below surface, 0.66 m long x 0.2 m high x 0.04 m deep
0+039W to 0+043W	Severe spall above surface, 4 m long x 0.3 m high x 0.25 m deep Conduit protrudes from timber crib, extends into lake bottom
0+041W	Conduits protruding from timber crib, extends into lake bottom
0+043W	Top timber, 0.15 m penetration
0+045W	Concrete blocks overhang timber cribs by 0.11 m
0+046W	Top timber 20% cross-sectional loss
0+047W	Spall on corner of concrete block, 0.25 m long x 0.08 m high x 0.08 m deep
0+051W	Concrete blocks overhang timber crib by 0.15 m
0+055W	Top timber 30% missing
0+056W	Spall beginning at surface, 0.76 m long x 0.25 m high x 0.05 m deep
0+056.5W	Spall at bottom of concrete block, 0.23 m long x 0.15 m high x 0.05 m deep
0+059W	Spall above surface on concrete block adjacent to mass concrete, 0.36 m long x 0.43 m high x 0.076 m deep
0+062W	Scour at bottom of block
	Block overhangs timber crib by 0.17 m
0+064W	Block spall/ pop out, 0.18 m long x 0.28 m high x 0.2 m deep
0+064.3W	Spall on concrete block beginning at surface, 0.48 m long x 0.25 m high x 0.076 m deep
0+067W	Spall at surface, 0.53 m long x 0.41 m high x 0.05 m deep
	Top tieback timber, 50% rotted
	2 <sup>nd</sup> timber from the top, 50% rotted
0+069W	Top timber 0.05 m proud on timbers below
	Steel plate at end of pier extends into water at 45° angle, heavily corroded, terminates 1.2 m above lake bottom
	Void under steel plate (similar to void at north end of pier), 0.17 m long x 0.69 m high x 0.48 m deep
	Pop out at bottom of block, 0.36 m long x 0.2 m high x 0.43 m deep

### 6.1.3 North face (0+000N to 0+004.8N)

Chainage	Observations
0+000N	0.075 m gap between north/south timbers and east/west timbers Top timber offset north approx. 0.05 m
0+001N	15 <sup>th</sup> timber from top, 50% cross-sectional loss 0.76 m penetration into lake bottom
0+004N	Top timber offset 0.18 m to the north Top tieback severely rotted with exposed connection pin, begins to improve 0.45 m towards south
0+004.8N	1 m penetration into lake bottom

### 6.1.4 South face (0+000S to 0+005S)

Chainage	Observations
0+000S	Bottom timber missing for full extent of south face
0+002.5	Undermining, 0.56 m long x 0.3 m high, begins to decrease heading west
0+005	Debris and large rock on lake bottom 2 <sup>nd</sup> timber from bottom, severe rot, 0.3 m, penetration into timber 100% surface rust on steel plate, approx. 0.001 m pitting depth

## 6.2 Pivot Pier

### 6.2.1 East side (0+030E to 0+037.5E)

Chainage	Observations
0+030E	Concrete spall full length of pivot pier, starting at surface, 0.76 m high x 0.15 m deep
0+032	Vertical crack with efflorescence commencing above surface extends to lake bottom
0+037.8	0.2 m deep spall

### 6.2.2 West side (0+030W to 0+039W)

Chainage	Observations
0+030W	Concrete spall full length of pivot pier, starting at surface, 0.76 m high x 0.15 m deep
0+030.5W	0.18 m high crack with efflorescence, spall continues from 0+030W
0+033W	0.63 m below surface, 0.76 m long x 0.3 m high x 0.05 m deep, spall continues from 0+030.5W
0+034W	Spall, 1 m long x 0.28 m high x 0.05 m deep
0+035W	Spall, 1 m long x 0.36 m high x 0.05 m deep
0+036W	Spall, 1 m long x 0.18 m high x 0.05 m deep
0+039W	Spall continues from 0+036W, narrows to 0.08 m high

### 6.3 East Pier

The inspection of the east pier found the concrete cap to be subject to moderate spalling for the full circumference of the pier. The support structure was found to be encased by grout bags for the full circumference of the pier. The transition between the concrete cap and grout bags was found to range between 0.05 m to 0.25 m below surface. The grout bags continued to lake bottom with no undermining observed. As referenced in the previous inspection report, the grout bags were found to be brittle and easily broken therefore; the dive team did not penetrate the bags in order to avoid damage.

# Appendix 1:

## Site Photos





Image 1-1: East face of Rest Pier, looking west



Image 1-2: East face of Rest Pier, looking west

**PARSONS**



ASI Project No: DH16-066

Project Date: Nov 2-3, 2016

Drawn By: D. Vitucci

**Site Photos**

**Underwater Bridge Inspection  
Hamlet Swing Bridge**

Appendix  
Number:

**1**

Sheet 1 of 32





Image 1-3: East face of Pivot Pier, looking west



Image 1-4: East face of Rest Pier, looking west

**PARSONS**



ASI Project No: DH16-066

Project Date: Nov 2-3, 2016

Drawn By: D. Vitucci

**Site Photos**

**Underwater Bridge Inspection  
Hamlet Swing Bridge**

Appendix  
Number:

**1**

Sheet 2 of 32





Image 1-5: East face of Pivot Pier, looking west



Image 1-6: South face of Rest Pier, looking north, steel plates extending into water

**PARSONS**



ASI Project No: DH16-066

Project Date: Nov 2-3, 2016

Drawn By: D. Vitucci

**Site Photos**

**Underwater Bridge Inspection  
Hamlet Swing Bridge**

Appendix  
Number:

**1**

Sheet 3 of 32



Image 1-7: West face of Rest Pier, looking east



Image 1-8: West face of Rest Pier, looking east

**PARSONS**

**ASI Marine**

ASI Project No: DH16-066

Project Date: Nov 2-3, 2016

Drawn By: D. Vitucci

**Site Photos**

**Underwater Bridge Inspection  
Hamlet Swing Bridge**

Appendix  
Number:

**1**

Sheet 4 of 32





Image 1-9: West face of Pivot Pier, looking east



Image 1-10: West face of Pivot Pier, looking east

**PARSONS**



ASI Project No: DH16-066

Project Date: Nov 2-3, 2016

Drawn By: D. Vitucci

**Site Photos**

**Underwater Bridge Inspection  
Hamlet Swing Bridge**

Appendix  
Number:

**1**

Sheet 5 of 32



Image 1-11: West face of Rest Pier, looking east



Image 1-12: West face of Rest Pier, looking south east

**PARSONS**

**ASI Marine**

ASI Project No: DH16-066

Project Date: Nov 2-3, 2016

Drawn By: D. Vitucci

**Site Photos**

**Underwater Bridge Inspection  
Hamlet Swing Bridge**

Appendix  
Number:

**1**

Sheet 6 of 32





Image 1-13: South face of East Pier, looking north



Image 1-14: East face of East Pier, looking west

**PARSONS**

**ASI Marine**

ASI Project No: DH16-066

Project Date: Nov 2-3, 2016

Drawn By: D. Vitucci

**Site Photos**

**Underwater Bridge Inspection  
Hamlet Swing Bridge**

Appendix  
Number:

**1**

Sheet 7 of 32



Image 1-15: West face of East Pier, looking east



Image 1-16: South face of Pivot Pier, looking north

**PARSONS**

**ASI Marine**

ASI Project No: DH16-066

Project Date: Nov 2-3, 2016

Drawn By: D. Vitucci

**Site Photos**

**Underwater Bridge Inspection  
Hamlet Swing Bridge**

Appendix  
Number:

**1**

Sheet 8 of 32





Image 1-17: South face of Pivot Pier, looking north




Image 1-18: Top timber offset at north limit of Rest Pier

**PARSONS**

**ASI Marine**

ASI Project No: DH16-066

Project Date: Nov 2-3, 2016

Drawn By: D. Vitucci

**Site Photos**

**Underwater Bridge Inspection  
Hamlet Swing Bridge**

Appendix  
Number:

**1**

Sheet 9 of 32




Image 1-19: Top timber offset at north limit of Rest Pier



Image 1-20: North west corner of Rest Pier, looking south, gap between timbers

**PARSONS**

 **ASI Marine**

ASI Project No: DH16-066

Project Date: Nov 2-3, 2016

Drawn By: D. Vitucci

**Site Photos**

**Underwater Bridge Inspection  
Hamlet Swing Bridge**

Appendix  
Number:

**1**

Sheet 10 of 32






Image 1-21: Square head connection bolt, all bolts and washers in good condition, Rest Pier




Image 1-22: Tieback timber, north end of Rest Pier

**PARSONS**

**ASI Marine**

ASI Project No: DH16-066

Project Date: Nov 2-3, 2016

Drawn By: D. Vitucci

**Site Photos**

**Underwater Bridge Inspection  
Hamlet Swing Bridge**

Appendix  
Number:

**1**

Sheet 11 of 32




Image 1-23: Spall 1 m below surface at north end of Rest Pier, spall severity typical for Rest Pier



Image 1-24: Electrical conduit on east side of Rest Pier, extending into lake bottom

**PARSONS**



ASI Project No: DH16-066

Project Date: Nov 2-3, 2016

Drawn By: D. Vitucci

**Site Photos**

**Underwater Bridge Inspection  
Hamlet Swing Bridge**

Appendix  
Number:

**1**

Sheet 12 of 32





Image 1-25: Rip-rap on lake bottom at 0+024, east side of Rest Pier



Image 1-26: Interface between concrete base of Pivot Pier and lake bottom

**PARSONS**

 **ASI Marine**

ASI Project No: DH16-066

Project Date: Nov 2-3, 2016

Drawn By: D. Vitucci

**Site Photos**

**Underwater Bridge Inspection  
Hamlet Swing Bridge**

Appendix  
Number:

**1**

Sheet 13 of 32



Image 1-27: Gap between timber crib and Pivot Pier, east side of Rest Pier



Image 1-28: Gap between timbers, east side of Rest Pier

**PARSONS**

 **ASI Marine**

ASI Project No: DH16-066

Project Date: Nov 2-3, 2016

Drawn By: D. Vitucci

**Site Photos**

**Underwater Bridge Inspection  
Hamlet Swing Bridge**

Appendix  
Number:

**1**

Sheet 14 of 32





Image 1-29: End grain of tieback timber east side of Rest Pier



Image 1-30: Tieback timber in poor condition, east side of Rest Pier

**PARSONS**



ASI Project No: DH16-066

Project Date: Nov 2-3, 2016

Drawn By: D. Vitucci

**Site Photos**

**Underwater Bridge Inspection  
Hamlet Swing Bridge**

Appendix  
Number:

**1**

Sheet 15 of 32



Image 1-31: Tieback timber, gap size typical on east side of Rest Pier



Image 1-32: Horizontal timbers, gap typical on east side of Rest Pier

**PARSONS**

**ASI Marine**

ASI Project No: DH16-066

Project Date: Nov 2-3, 2016

Drawn By: D. Vitucci

**Site Photos**

**Underwater Bridge Inspection  
Hamlet Swing Bridge**

Appendix  
Number:

**1**

Sheet 16 of 32






Image 1-33: Gap between horizontal timbers, east side of Rest Pier




Image 1-34: Rotted tieback timber, east side of Rest Pier

**PARSONS**

 **ASI Marine**

ASI Project No: DH16-066

Project Date: Nov 2-3, 2016

Drawn By: D. Vitucci

**Site Photos**

**Underwater Bridge Inspection  
Hamlet Swing Bridge**

Appendix  
Number:

**1**

Sheet 17 of 32



Image 1-35: Joint between timbers, north limit of Rest Pier



Image 1-36: Joint between timbers, north limit of Rest Pier

**PARSONS**

**ASI Marine**

ASI Project No: DH16-066

Project Date: Nov 2-3, 2016

Drawn By: D. Vitucci

**Site Photos**

**Underwater Bridge Inspection  
Hamlet Swing Bridge**

Appendix  
Number:

**1**

Sheet 18 of 32





Image 1-37: Spall on concrete block, west side of Rest Pier. Gap/spall between blocks at corners typical throughout inspection




Image 1-38: Horizontal crack, west side of Rest Pier

**PARSONS**

**ASI Marine**

ASI Project No: DH16-066

Project Date: Nov 2-3, 2016

Drawn By: D. Vitucci

**Site Photos**

**Underwater Bridge Inspection  
Hamlet Swing Bridge**

Appendix  
Number:

**1**

Sheet 19 of 32




Image 1-39: Crack in concrete, west side of Rest Pier



Image 1-40: Tieback timber, end grain rotted, Rest Pier

**PARSONS**

 **ASI Marine**

ASI Project No: DH16-066

Project Date: Nov 2-3, 2016

Drawn By: D. Vitucci

**Site Photos**

**Underwater Bridge Inspection  
Hamlet Swing Bridge**

Appendix  
Number:

**1**

Sheet 20 of 32






Image 1-41: Spall at waterline, west side of Rest Pier



Image 1-42: Tieback timber, end grain rotted, west side of Rest Pier

**PARSONS**

**ASI Marine**

ASI Project No: DH16-066

Project Date: Nov 2-3, 2016

Drawn By: D. Vitucci

**Site Photos**

**Underwater Bridge Inspection  
Hamlet Swing Bridge**

Appendix  
Number:

**1**

Sheet 21 of 32



Image 1-43: Tieback timber end grain in good condition, Rest Pier



Image 1-44: Interface between timber crib and lake bottom, west side of Rest Pier

**PARSONS**

**ASI Marine**

ASI Project No: DH16-066

Project Date: Nov 2-3, 2016

Drawn By: D. Vitucci

**Site Photos**

**Underwater Bridge Inspection  
Hamlet Swing Bridge**

Appendix  
Number:

**1**

Sheet 22 of 32





Image 1-45: Severe spall commencing above surface with exposed rebar, Rest Pier



Image 1-46: Gap between concrete blocks west side of rest pier, gap/spall condition typical on west side of Rest Pier

**PARSONS**

 **ASI Marine**

ASI Project No: DH16-066

Project Date: Nov 2-3, 2016

Drawn By: D. Vitucci

**Site Photos**

**Underwater Bridge Inspection  
Hamlet Swing Bridge**

Appendix  
Number:

**1**

Sheet 23 of 32






Image 1-47: Spall on concrete blocks, west side of Rest Pier



Image 1-48: Spall on concrete blocks, west side of Rest Pier

**PARSONS**

 **ASI Marine**

ASI Project No: DH16-066

Project Date: Nov 2-3, 2016

Drawn By: D. Vitucci

**Site Photos**

**Underwater Bridge Inspection  
Hamlet Swing Bridge**

Appendix  
Number:

**1**

Sheet 24 of 32






Image 1-49: Spall on concrete blocks, west side of Rest Pier



Image 1-50: North face of East Pier, looking south

**PARSONS**

 **ASI Marine**

ASI Project No: DH16-066

Project Date: Nov 2-3, 2016

Drawn By: D. Vitucci

**Site Photos**

**Underwater Bridge Inspection  
Hamlet Swing Bridge**

Appendix  
Number:

**1**

Sheet 25 of 32



Image 1-51: North face of East Pier, looking south




Image 1-52: Grout bags, east side of East Pier

**PARSONS**

 **ASI Marine**

ASI Project No: DH16-066

Project Date: Nov 2-3, 2016

Drawn By: D. Vitucci

**Site Photos**

**Underwater Bridge Inspection  
Hamlet Swing Bridge**

Appendix  
Number:

**1**

Sheet 26 of 32






Image 1-53: Interface between concrete bag and concrete cap, East Pier



Image 1-54: Typical condition of grout bag, East Pier

**PARSONS**

**ASI Marine**

ASI Project No: DH16-066

Project Date: Nov 2-3, 2016

Drawn By: D. Vitucci

**Site Photos**

**Underwater Bridge Inspection  
Hamlet Swing Bridge**

Appendix  
Number:

**1**

Sheet 27 of 32




Image 1-55: Interface between grout bags and concrete cap, East Pier



Image 1-56: Grout bags at base of East Pier

**PARSONS**

**ASI Marine**

ASI Project No: DH16-066

Project Date: Nov 2-3, 2016

Drawn By: D. Vitucci

**Site Photos**

**Underwater Bridge Inspection  
Hamlet Swing Bridge**

Appendix  
Number:

**1**

Sheet 28 of 32






Image 1-57: Interface between grout bags and concrete cap at surface, East Pier




Image 1-58: Interface between grout bags and concrete cap at surface, East Pier

**PARSONS**

**ASI Marine**

ASI Project No: DH16-066

Project Date: Nov 2-3, 2016

Drawn By: D. Vitucci

**Site Photos**

**Underwater Bridge Inspection  
Hamlet Swing Bridge**

Appendix  
Number:

**1**

Sheet 29 of 32



Image 1-59: Interface between grout bags and concrete cap at surface, west side of East Pier




Image 1-60: Interface of grout bags and lakebed, East Pier

**PARSONS**



ASI Project No: DH16-066

Project Date: Nov 2-3, 2016

Drawn By: D. Vitucci

**Site Photos**

**Underwater Bridge Inspection  
Hamlet Swing Bridge**

Appendix  
Number:

**1**

Sheet 30 of 32






Image 1-61: Interface of grout bags and lakebed, East Pier



Image 1-62: Interface of grout bags and lakebed, East Pier

**PARSONS**

 **ASI Marine**

ASI Project No: DH16-066

Project Date: Nov 2-3, 2016

Drawn By: D. Vitucci

**Site Photos**

**Underwater Bridge Inspection  
Hamlet Swing Bridge**

Appendix  
Number:

**1**

Sheet 31 of 32



Image 1-63: Interface of grout bags and lakebed, East Pier

**PARSONS**



ASI Project No: DH16-066

Project Date: Nov 2-3, 2016

Drawn By: D. Vitucci

**Site Photos**

**Underwater Bridge Inspection  
Hamlet Swing Bridge**

Appendix  
Number:


**1**

Sheet 32 of 32



## Appendix 2:

### General Arrangement Drawings



**SITE PLAN AND DEPTH SOUNDING**  
(Not to Scale)

**LEGEND**

(0+000)E	DENOTES	CHAINAGE (EAST SIDE OF WEST PIER)
(0+000)W	"	CHAINAGE (WEST SIDE OF WEST PIER)
(0+000)N	"	CHAINAGE (NORTH SIDE OF WEST PIER)
(0+000)S	"	CHAINAGE (SOUTH SIDE OF WEST PIER)
-0.00 W/L	"	WATER DEPTH



Project No.: DH16-066

Date: February 28, 2016

Drawn By: D.V.

**GENERAL ARRANGEMENT**

**HAMLET SWING BRIDGE  
HAMLET, ONTARIO**

Appendix  
Number:

**2**

Sheet 1 of 1

## Appendix 3:

### Inspection Data Sheets



### Inspection Data Sheet

Date:	Nov 2-3, 2016	ASI Project #:	DH16-066
Client:	PARSONS		
Location:	HAMLET, ONT - WEST PIER (EAST SIDE)		
Facility:	HAMLET SWING BRIDGE		
Supervisor:	DAVE GEORGE	Diver:	COLE
Video:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Video Unit #:	
Digital Still Camera:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Camera Unit #:	
Visual Inspection:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		
Note: be specific and clear with location, direction and use objects of known size for scale as required			
<b>Observations</b>			
	Description		
04000	GROWTH ON CRIB, ALGAT AT BOTTOM. 0.03m SAW - TIEBACKS TIMBERS (21), NO W/IN SCREW BOLT W/ WASHERS, GOOD TIMBER SAW (7/8), 0.5m penetration 12-TIMBER - END ROT 14 - 0.5 PENETRATION 15 - ROTTEN TIEBACK 16 - SPONGY - 0.025m		
04002	SPALL 0.48 L x 0.25 H 0.06 D. 11 0.12 L x 0.1 H 0.06 D 0.07 GAP.		
04003	0.1m penet., TOP 3 TIEBACKS		
04005	TOP - ROT SEVERE 2 - 0.1m penetration 3 - ROT SEVERE		
04006	BLOCK OVERHANG CRIB 0.76m		
04008	2 tie back, approx. 20% c/s loss 0.76 penetration - NO RESISTANCE 3 - 0.15m Penet. 4 - 0.2m penet/rot 6 - 50% rot, 0.1m penet. 0.3m segment		

### Inspection Data Sheet

Date:	NOV 2-3, 2016	ASI Project #:	DH/6-066
Client:	PARSONS		
Location:	HAMLET, DNT - WEST PIER (EAST SIDE)		
Facility:	HAMLET SWING BRIDGE		
Supervisor:	DAVE GEORGE	Diver:	COLLE
Video:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Video Unit #:	
Digital Still Camera:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Camera Unit #:	
Visual Inspection:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		
Note: be specific and clear with location, direction and use objects of known size for scale as required			
<b>Observations</b>			
		Description	
01009		SPALL - 0.74 x .46 H x 0.1 H BLOCKS SPALLED AT CORNERS	
01011		BOTTOM 1/3 DISINTEGRATION	
01011 - 01012		SPALL w/ G.P. REBAR., 0.97 L x .74 H x 0.03 D	
01012		TOP - 0.5 ROT 4 - 0.15 pen. 9 - 0.1 pen. 12 - 0.1 pen. 0.1 penet. @ Bottom.	
01015		6 - 0.2m penet. 0.2m - Bottom penet.	
01017		SPALL - 0.9 L x .38 H x 0.1 deep	
01018		TOP - 50% loss 7 - 0.18 penet. 0.03 m penet. IN LACE TIMBER SPLIT, 01018 - 01020	
01020		TOP - 10% c/s loss 2 - 0.15 m penet. OVERPOUR - ON BOT., 1.5 L x .54 x .5 D ROT - SEVERE @ TOP 7 - 0.16 m wide ROT 9 - OFFSET .08 OFFSHORE BLOCKS - CORNERS ROUNDED	

### Inspection Data Sheet

Date: <u>Nov 2-3, 2016</u>	ASI Project #: <u>DA16-066</u>	
Client: <u>PARSON'S</u>		
Location: <u>HAMLET, ONT</u>		
Facility: <u>HAMLET SWINK BRIDGE - W. PIER, (EAST SIDE)</u>		
Supervisor: <u>DAVE GEORGE</u>	Diver: <u>COLE</u>	
Video: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Video Unit #:	
Digital Still Camera: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Camera Unit #:	
Visual Inspection: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		
<i>Note: be specific and clear with location, direction and use objects of known size for scale as required</i>		
<b>Observations</b>		
		Description
<u>0402</u>		<u>2 - TIEBARS, ROT / SEVERE, 0.3m long.</u> <u>DEBRIS ON BOTTOM</u>
<u>04023</u>		<u>BLOCK - POP OUTS, .9 L x .3 H x .56 DEEP</u> <u>SPALL - 3.5 L x .15 H x .1 D</u>
<u>04038</u>		<u>SPALL / MISSING CONC, 2 L x .18 H x .46 D</u> <u>BLOCKS OVERHANGING .1m</u> <u>CONDUIT THROUGH CRIB</u> <u>CONC. LUMEN AGAINST TIMBER.</u>
<u>04040</u>		<u>SPALL ON MASS ENDS</u> <u>TIEBAR FLUSH</u> <u>BOTTOM 4 OFFSET, 1 WEST</u>
<u>04041</u>		<u>SPALL, .9 L x .1 H x .13 D</u> <u>5 TIMBERS, MID-3 O/S TO WEST</u>
<u>04047</u>		<u>SPALL ON BLOCKS (CORNERS)</u> <u>RIP-RAVE</u> <u>SEDIMENT ON BOTTOM.</u>
<u>04050</u>		<u><del>13</del> TIMBER, 13 OFFSET (TOP)</u> <u>TIMBERS FLUSH W/ BLOCKS</u>
<u>04052</u>		
<u>04053</u>		<u>SEVERE ROT, TOP, 85% LOSS</u>
<u>04053</u>		<u>CRIB GOOD</u>



Date: Nov 2-3, 2016	ASI Project #: DH16-066	
Client: PARSONS		
Location: HAMLET, ONT → WEST PIER (EAST SIDE)		
Facility: HAMLET SWINK BRIDGE		
Supervisor: DAVID GEORGE	Diver: COLE	
Video: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Video Unit #:	
Digital Still Camera: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Camera Unit #:	
Visual Inspection: <input type="checkbox"/> Yes <input type="checkbox"/> No		
Note: be specific and clear with location, direction and use objects of known size for scale as required		
<b>Observations</b>		
	Description	
04055	SPALLS ON CORNERS	
04056	SPAN ON BLOCKS, .3 L x .38 H x .18 D SPAN ON MASS CONC. CONTIGUES	
04058	STEEL EXPOSED, .53 L x .38 H x .18 D 7- .18 penetration	
04062	SPAN ON BLOCKS, .15 L x .25 H x 2 DEEP.	
04063 - 065	SPAN BROWN CONC & BLOCKS w/ REBAR <del>1.98 L</del> 1.98 L x .48 H x .96 DEEP	
04066.5	Conc. proud of Timber (1m)	
	STEEL ANGLE @ END of PIER, VOID .66 L x .48 H x .76 D, EXTEND 1.37 BELOW SURFACE	
	U/LM OF CRIB, 2.5 L x .3 H x .45 DEEP.	

### Inspection Data Sheet

Date: <u>Nov 2-3, 2016</u>		ASI Project #: <u>DH16-066</u>	
Client: <u>PARSONS</u>			
Location: <u>HAMLET, ONT - WEST PIER (W. SIDE)</u>			
Facility: <u>HAMLET SWINK BRIDGE</u>			
Supervisor: <u>DAVE GEORGE</u>		Diver: <u>COLE</u>	
Video: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		Video Unit #:	
Digital Still Camera: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		Camera Unit #:	
Visual Inspection: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No			
<i>Note: be specific and clear with location, direction and use objects of known size for scale as required</i>			
<b>Observations</b>			
		Description	
01000		SPALL ON BRIDGE, ENP. AGGREG., • 25 L x • 25 H x • 03 D	
01001		TIEBACK, 10% LOSS	
01003		SCOUR / SPALL ON CONC.	
01004		SPALL, • 76 L x • 33 H x • 06 D	
01005		SCOUR & SPALL AT CONC. EXPOS.	
01006		TIMBER @ BOTTOM, 50% LOSS	
01006			
- 01012		SPALLING ON CORNERS	
01013		SPALL ON CONC. @ BOT. • 33 L x • 13 H x 0.04 D	
01014.5		SPALL, CONC., • 45 L x • 43 H x 0.06 D	
01015			
- 01020		SPALL @ CORN., 26 WIDE	
01018		TIEBACK TIMBER MISSING	
01021		TOP TIM. 5% LOSS	
01024		SPALL ON BLOCKS, • 18 L x • 23 H x 0.04 D	

### Inspection Data Sheet

Date: <b>Nov 2-3, 2016</b>		ASI Project #:	
Client: <b>PARSONS</b>			
Location: <b>HAMLET, ONT - WEST PIER (W. SIDE)</b>			
Facility: <b>HAMLET SWINN BRIDGE</b>			
Supervisor: <b>DAVE GEORGE</b>		Diver: <b>COLE</b>	
Video: <input type="checkbox"/> Yes <input type="checkbox"/> No		Video Unit #:	
Digital Still Camera: <input type="checkbox"/> Yes <input type="checkbox"/> No		Camera Unit #:	
Visual Inspection: <input type="checkbox"/> Yes <input type="checkbox"/> No			
<i>Note: be specific and clear with location, direction and use objects of known size for scale as required</i>			
<b>Observations</b>			
		Description	
040216		SPALL ON BLOCK CORNERS	
04027		TIMBER, .15m ROT AT END	
04030		SPALL ON CONC., .23L x .05H x .04D	
		" ON CONC. .3L x .36H x .03D	
		SPALL, MID-BLOCK, .66L x .2H x .04D	
04039			
-04043		SPALL, 4L x .3H x .25 DEEP, w/ CONDUIT PROTRUDING	
040411		CONDUIT PROTRUDING FROM CRIB	
04043		.15 PENETRATION, TOP	
04045		BLOCK OVERHANGS .11	
04046		TOP, 20% LOSS	
04047		SPALL ON CORN, .25L x .08H x .08D	
04051		CONC. OVERHANG .15	
04055		TOP, 30% MISSING	
04056		SPALL, FROM SURFACE, .76L x .25H x .05D	
04056.5		SPALL @ BOTTOM, .23L x .15H x .05D	



Date: <b>Nov 2-3, 2016</b>		ASI Project #:	
Client: <b>PARSONS</b>			
Location:			
Facility:			
Supervisor:		Diver:	
Video: <input type="checkbox"/> Yes <input type="checkbox"/> No		Video Unit #:	
Digital Still Camera: <input type="checkbox"/> Yes <input type="checkbox"/> No		Camera Unit #:	
Visual Inspection: <input type="checkbox"/> Yes <input type="checkbox"/> No			
Note: be specific and clear with location, direction and use objects of known size for scale as required			
<b>Observations</b>			
		Description	
01059		SPALL ABOVE SURFACE, .36L x .43 H x .076 D	
01062		SCOUR AT BOTTOM BLOCKS OVER HANA .17	
01064		SPALL / POP OUT, .18L x .28H x .2 D	
01064.3		SPALL, .48L x .25H x .076 D	
01067		SPALL, .53L x .41H x .05 D <del>TOP 20% ROT</del> TOP 50% ROT	
		2- 50% ROT	
01069		PLATE @ END of PIER AT 45°, STOPS 1.2 BELOW VOID UNDER PLATE, .17L x .69H x .48 D	
		POP OUT, .36L x .2H x .43 D	

Date:	NOV 2-3, 2016	ASI Project #:
Client:	PARSONS	
Location:	HAMLET, ONT - W. PIER (W. SIDE)	
Facility:	HAMLET SWIM BRIDGE	
Supervisor:	DAVE GEORGE	Diver: COLE
Video:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Video Unit #:
Digital Still Camera:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Camera Unit #:
Visual Inspection:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
<i>Note: be specific and clear with location, direction and use objects of known size for scale as required</i>		
<b>Observations</b>		
	Description	
NORTH FACE		
0+000	.075 GAP BTWN N/S - E/W TOP TIMBER d/s .05	
0+001	1 <sup>st</sup> - 50% LOSS .76 PENETRATION @ BOTTOM	
0+004	TIMBER D/S .18 NORTH TIE BACK ROTTEN w/ EXPOSED PIN	
0+004.5	1m PENETRATION	
SOUTH FACE		
0+000	BOTTOM TIMBER MISSING	
0+002.5	V/M .56L x .3H	
0+005	DEBRIS @ BOTTOM 2 ROT, .3M PENETRATION PLATE 100% CORROSION, .001 DEEP	

**Inspection Data Sheet**

Date:	Nov 3, 2016	ASI Project #:	DH16-066
Client:	PARSONS		
Location:	HAMLET, ONT - PIVOT PIER		
Facility:	HAMLET SWIMMING BRIDGE		
Supervisor:	DAVE GEORNE	Diver:	COLE
Video:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Video Unit #:	
Digital Still Camera:	<input type="checkbox"/> Yes <input type="checkbox"/> No	Camera Unit #:	
Visual Inspection:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		
<i>Note: be specific and clear with location, direction and use objects of known size for scale as required</i>			
<b>Observations</b>			
		Description	
EAST			
SIDE			
0+030		SPALL - FULL LENGTH, .76H x .15D	
0+032		CRACK w/ EFFLORESCENCE	
0+037.8		.2 D SPALL	
W. SIDE			
0+030		SPALL FOR FULL LENGTH, .76H x .15D	
0+030.5		CRACK, .18m w/ EFFLOR.	
0+033		.76L x .3H x .05D	
0+034		1mL x .28H x .05D	
0+035		1mL x .36H x .05D	
0+036		1m x .18H x .05D	
0+039		SPALL CONT'S FROM 0+036	



## Appendix 4:

Inspection Video (USB)