

Metal Based Paint and Supplemental Asbestos Assessment

Parks Canada Buildings and
Structures at Georgina Point
(Active Pass) Lightstation, East
Point (Saturna Island)
Lightstation; Portlock Point
Lightstation and Russell Island



Prepared for:
Parks Canada Agency

Prepared by:
Stantec Consulting Ltd.
500 - 4730 Kingsway
Burnaby, BC V5H 0C6

123220964

January 19, 2018

Table of Contents

| | |
|---|-----------|
| ABBREVIATIONS | I |
| 1.0 INTRODUCTION | 1 |
| 2.0 BACKGROUND | 2 |
| 2.1 DOCUMENT REVIEW | 2 |
| 2.1.1 Supplemental Documents | 2 |
| 3.0 SCOPE OF WORK | 3 |
| 3.1 METALS IN PAINT | 3 |
| 3.2 ASSESSMENT SCOPE | 4 |
| 4.0 REFERENCE STANDARDS AND ANALYTICAL METHODOLOGY | 4 |
| 4.1 LEAD IN PAINT | 4 |
| 4.1.1 Assessment of Paint Condition | 6 |
| 4.1.2 Building Materials—Leachable Lead Content | 6 |
| 4.2 ASBESTOS | 7 |
| 4.2.1 Sample Results Interpretation | 8 |
| 4.2.2 Asbestos Sampling Quality Assurance/Quality Control | 8 |
| 5.0 LIMITATIONS | 9 |
| 5.1 PHYSICAL AND SAMPLING LIMITATIONS | 9 |
| 5.1.1 Lead in Paint | 9 |
| 5.1.2 Asbestos | 10 |
| 5.2 AREAS NOT ACCESSED | 10 |
| 5.3 INFORMATION FROM PREVIOUS REPORTS | 11 |
| 6.0 FINDINGS | 11 |
| 6.1 LEAD | 11 |
| 6.1.1 Previously Identified LCPs | 11 |
| 6.1.2 Additional Suspected LCP Sampling | 12 |
| 6.1.3 Building Materials—Leachable Lead Content | 16 |
| 6.2 ASBESTOS | 19 |
| 6.2.1 Previously Identified ACMs | 19 |
| 6.2.2 Additional Suspected ACM Sampling | 19 |
| 7.0 GENERAL RECOMMENDATIONS | 21 |
| 7.1 LEAD | 21 |
| 7.2 ASBESTOS | 23 |
| 8.0 LCP CONDITION ASSESSMENT AND REMEDIAL OPTIONS | 24 |
| 9.0 CLOSURE | 34 |

METAL BASED PAINT AND SUPPLEMENTAL ASBESTOS ASSESSMENT

LIST OF TABLES

| | | |
|-----------|---|----|
| Table 4-1 | LCP Condition Categories..... | 7 |
| Table 5-1 | Additional Suspected LCP Sample Collection and Analysis Summary GINPR, BC | 12 |
| Table 5-2 | Summary of Additional Identified LCPs GINPR, BC | 14 |
| Table 5-3 | Painted Building Material Sample Collection and Lead Leachate Analysis Summary GINPR, BC | 17 |
| Table 5-4 | Summary of Lead Leachable Paints GINPR, BC | 18 |
| Table 5-5 | Suspected ACM Sample Collection and Analysis Summary GINPR, BC | 19 |
| Table 5-6 | Summary of Additional Identified ACMs GINPR, BC..... | 20 |
| Table 6-1 | Remedial Actions Summary GINPR, BC..... | 22 |
| Table 8-1 | Summary of Remedial Action Options GINPR, BC..... | 26 |

LIST OF APPENDICES

| | | |
|-------------------|--|------------|
| APPENDIX A | LABORATORY ANALYTICAL REPORT—LEAD: PAINT CHIP ANALYSIS | A.1 |
| APPENDIX B | LABORATORY ANALYTICAL REPORT—LEAD: TCLP | B.1 |
| APPENDIX C | LABORATORY ANALYTICAL REPORT—ASBESTOS: BULK MATERIAL ANALYSIS | C.1 |

Abbreviations

| | |
|-------|---|
| ACGIH | American Conference of Governmental Industrial Hygienists |
| ACM | asbestos-containing material |
| AIHA | American Industrial Hygiene Association |
| BAPAT | Bulk Asbestos Proficiency Analytical Testing |
| EMSL | EMSL Canada Inc. |
| GINPR | Gulf Islands National Park Reserve |
| HVAC | heating, ventilation and air conditioning |
| IHPAT | Industrial Hygiene Proficiency Analytical Testing |
| LCP | lead-containing paint |
| NVLAP | National Voluntary Laboratory Accreditation Program |
| OEL | occupational exposure limit |
| TCLP | toxicity characteristic leaching procedure |

METAL BASED PAINT AND SUPPLEMENTAL ASBESTOS ASSESSMENT

Introduction
January 19, 2018

1.0 INTRODUCTION

Stantec Consulting Ltd. (Stantec) was commissioned by the Parks Canada Agency (Parks Canada) to conduct a metal based paint and supplemental asbestos assessment of four sites (further referred to as the subject sites) and the associated structures (further referred to as the subject structures) located in Gulf Islands National Park Reserve (GINPR), British Columbia as follows:

| Site Name | Structure | FCSI # |
|---|--|----------|
| Georgina Point (Active Pass) Lightstation | Light Keepers House | 00023457 |
| | Weather Station (Radio/Engine Room) | 00023457 |
| | Beacon (Light Tower) | 00023457 |
| | Garage | 00023457 |
| | Shed (former Fuel Shed) | 00023457 |
| | Seasonal Washroom | 00023457 |
| | Outhouse | 00023457 |
| | NAV Canada Shed (Solar Panel/Battery Room) | 00023457 |
| | Gazebo | 00023457 |
| East Point (Saturna Island) Lightstation | Light Tower and Shed | 00023462 |
| | Garage | 00023462 |
| | Bunkhouse | 00023462 |
| | Fog Horn Building | 00023462 |
| Portlock Point | Lighthouse (Major Shorelight) | 00023458 |
| Russell Island | Mahoi House | 00024299 |
| | Caretakers Shed | 00024299 |
| | Water Tower | 00024299 |
| | Generator Shed | 00024299 |

The assessment was commissioned by Parks Canada in order to support the development of a remedial action plan (RAP) for metal based paint abatement and remediation at the subject sites.

The site work was conducted by Keith Irwin and Steve Chou on September 19, 20, and 21, 2017.

METAL BASED PAINT AND SUPPLEMENTAL ASBESTOS ASSESSMENT

Background
January 19, 2018

2.0 BACKGROUND

Stantec understands that contaminants including lead (Pb), mercury (Hg) and other metals in paint have been identified (or are potentially present) on various structural (building-related) components (both interior and exterior) and potentially in soils and groundwater, at the subject sites and associated with the subject structures. Stantec further understands that the Parks Canada Remediation and Risk Management Plan (currently in draft) recommends that the contaminated paint is abated and/or remediated as a means of removing the source of lead (and other metals) that may pose health and safety risks to visitors and staff at these sites, and that may contribute to potential environmental contamination at the subject sites.

In support of meeting the objectives of the Parks Canada Remediation and Risk Management Plan, this assessment was requested in support of the development of a remedial action plan (RAP) and tender package (including technical specifications) for Pb and other metal based paint abatement and remediation at the subject sites.

2.1 DOCUMENT REVIEW

The following report pertaining to hazardous building materials at the subject sites was reviewed prior to undertaking the assessment (further referred to herein as the "initial assessment"):

- Stantec Report No. 123220330 entitled *Hazardous Building Materials Assessment, 45 Buildings at the Gulf Islands National Park, BC* dated March 22, 2016, prepared for Public Works and Government Services Canada on behalf of Parks Canada (initial assessment)

The pertinent information from the documentation listed above has been incorporated into this report.

2.1.1 Supplemental Documents

The following additional documents were provided by Parks Canada, and were reviewed for background information related to various actual or potential sources of contamination at the subject sites (further referred to herein as the "previous environmental assessment reports"):

- Parks Canada Agency March 2016 DRAFT document *Portlock Point Major Shorelight, Prevost Island: Remediation and Risk Management Plan*
- Parks Canada Agency March 2016 document *Active Pass Lightstation Georgina Point, Mayne Island Remediation and Risk Management Plan*
- Parks Canada Agency July 2016 DRAFT document *Saturna Island (East Point) Lightstation: Remediation and Risk Management Plan*
- The Environmental Services Group Royal Military College of Canada August 2014 document *Gulf Islands National Park – 2014 Site Closure Review – Active Pass, East Point, Portlock Point*
- The Environmental Services Group Royal Military College of Canada July 2015 document *Summary Report for Gulf Islands National Park Reserve, British Columbia – Results and*

METAL BASED PAINT AND SUPPLEMENTAL ASBESTOS ASSESSMENT

Scope of Work
January 19, 2018

*Recommendations of the 2014 Sampling Program – Human Health Risk Assessment;
Ecological Risk Assessment Review; Site Closure Tool Initiation*

- The Environmental Services Group Royal Military College of Canada March 2015 document *Gulf Islands 2014 Sampling Report, Gulf Islands National Park Reserve, British Columbia – 2014 Additional Sampling Program*
- Canadian Coast Guard May 2005 document *Ecological Risk Assessment of Environmental Contamination at Six De-Staffed Lightstations*
- Morrow Environmental June 3, 2005 document *Human Health Risk Assessment of Environmental Contamination at the De-Staffed Active Pass Lightstation Site*
- Morrow Environmental June 3, 2005 document *Human Health Risk Assessment of Environmental Contamination at the De-Staffed East Point Lightstation Site*
- Golder Associates April 11, 2016 document *Supplemental Phase III Environmental Site Assessment and PQRA – Russell Island, BC*
- Franz Environmental Inc. March 2011 document *Remedial Options Evaluation – Russell Island, BC, Gulf Islands National Park Reserve of Canada*

3.0 SCOPE OF WORK

3.1 METALS IN PAINT

Although Pb, Hg and other metals may be present in paint, Pb is the constituent that was historically used to the greatest extent. The lead content of paint will typically significantly exceed that of Hg or other metals in paint.

Based on the above and on our experience in conducting hazardous building materials assessments throughout Canada, Pb is the paint constituent that Stantec believes poses the most significant risk from both a health (exposure) and an environmental (contamination) standpoint.

In addition, the ecological and human health risks associated with other metals such as mercury and arsenic are discussed in the previous environmental assessment reports, primarily as they pertain to significant site-related sources for these metals, such as mercury bath lamps (for mercury) and historic waste disposal practices (for arsenic). Contributions to ecological or human health risks from the presence of metals other than Pb in paint do not appear to have been considered as significant contamination sources.

As such, this report has been prepared to primarily assess for lead in paint, with the expectation that appropriately handling painted building materials to control risks associated with lead will also appropriately control the risks associated with Hg and other metals in paint.

METAL BASED PAINT AND SUPPLEMENTAL ASBESTOS ASSESSMENT

Reference Standards and Analytical Methodology
January 19, 2018

3.2 ASSESSMENT SCOPE

The scope of work completed by Stantec during this assessment involved the following:

- Review of previous reports and documents pertaining to Pb and other metal contamination in paint at the subject sites
- Site visits to collect additional information regarding the following:
 - Current condition of paints, including documentation of the various substrates to which paints are applied on the subject structures, and the condition as it relates to each separate substrate
 - Collection of samples to determine the Pb content of paints not previously sampled, if any
 - Collection of samples to determine the asbestos content of building materials that may be altered by the remediation work, for materials and buildings where such information was not on-file
 - Collection of samples to determine the leachable Pb content of materials with painted surfaces, where such bulk materials (paint and substrate) may be considered for removal and landfill disposal (as opposed to removal of the paint from the substrate) to determine whether the material may, in disposal form, be considered toxic waste
 - Soil or ground surface conditions as they relate to visible contamination from paint debris containing Pb or other metals, if necessary

It should be noted that the Georgina Point Gazebo and the East Point Garage were not included in the initial assessment. As such, an assessment for lead-containing paints (LCPs) and asbestos-containing materials (ACMs) that may require remediation or that may be disturbed during remediation was conducted at those additional sites as part of this assessment.

4.0 REFERENCE STANDARDS AND ANALYTICAL METHODOLOGY

4.1 LEAD IN PAINT

When discussing exposure risks associated with the lead content of paint that has been applied to building materials (and has dried to form a coating), it is important to understand the various ways in which the lead content of paint is measured and/or considered.

When painted building materials are disturbed, the various processes by which this occurs (e.g. torch-cutting, grinding, manual demolition, etc.) can create airborne, lead-containing particulate. In this respect, applicable regulations present their "allowable" limits for worker exposure in relation to the airborne concentration of lead particles, which is expressed in milligrams per cubic metre (mg/m^3). Both the *Canada Labour Code, Part II* (Canada Labour Code) and British Columbia's Occupational Health and Safety Regulation (BC Reg. 296/97) refer to an occupational exposure limit (OEL) for lead of $0.05 \text{ mg}/\text{m}^3$.

METAL BASED PAINT AND SUPPLEMENTAL ASBESTOS ASSESSMENT

Reference Standards and Analytical Methodology
January 19, 2018

When assessing how much a particular paint coating may contribute to lead exposure risks upon disturbance, the total lead content of the paint coating is considered. This is measured either in percent weight, or in milligrams per kilogram (mg/kg, which is equivalent to parts per million [ppm]). In this respect, the 2011 WorkSafeBC manual titled *Lead-Containing Paint and Coatings: Preventing Exposure in the Construction Industry*, indicates the following:

- Improper removal of lead paint containing 600 mg/kg lead results in airborne lead concentrations that exceed half of the exposure limit
 - This potential for exposure exceeding half of the occupational exposure limit would be the trigger for implementation of an exposure control plan
- Lead concentrations as low as 90 mg/kg may present a risk to pregnant women and children
 - Any risk assessment should include for the presence of high risk individuals within the workplace

In addition to the above, the 2017 WorkSafeBC publication *Safe Work Practices for Handling Lead* (Lead Guideline) indicates the following:

Unlike for asbestos-containing material, WorkSafeBC does not numerically define what would be considered a lead-containing paint or coating. All suspected paints or coatings should be tested for lead because, depending on the nature of the work, even a small amount could pose a risk to workers. In order to determine which controls and personal protective equipment would be required for a particular job, a qualified person must consider this information as part of the risk assessment.

When reviewing the above, although “high risk” individuals may be present at the subject sites periodically as users, such individuals are not expected to be present in situations associated with building material alteration activities (i.e., remediation) that would create significant disturbance to paint and airborne, inhalable particulate matter (i.e., typical exposure risks) with such individuals present. As such, and as the risk of ingestion of paint debris can reasonably be deemed low for periodic users, Stantec will reference a value of greater than 600 ppm in defining paints as “lead-containing”, such that appropriate risk assessments can be completed for the RAP.

Based on the above, samples of potential LCPs were collected from major paint applications (either previously un-sampled paints, or to confirm previous results), in sufficient quantity to conduct analysis for total lead content. The sampling of paint applications involved the collection of paint chip samples of paint layers to the substrate, where possible. A minimum volume of 5 cc or a half teaspoon of paint chips was typically collected. Wherever necessary and possible, paint was separated from any backing material such as paper, concrete or wood and placed in a sealed, clearly labelled plastic bag.

METAL BASED PAINT AND SUPPLEMENTAL ASBESTOS ASSESSMENT

Reference Standards and Analytical Methodology
January 19, 2018

Samples collected were submitted to EMSL Analytical, Inc. in Indianapolis, Indiana (EMSL) for analysis of total lead content using EPA Method SW 846 3050B*/7000B. EMSL's analytical laboratory is accredited by the AIHA Environmental Lead Laboratory Approval Program (ELLAP).

4.1.1 Assessment of Paint Condition

The criteria for condition evaluation pertaining to LCPs described herein are generally based on the United States Housing and Urban Development (HUD) 2012 *Guidelines for the Evaluation and Control of Lead-Based Paint Hazards in Housing*.

When evaluating the condition of LCPs, an attempt should be made to determine whether the deterioration is due to a moisture problem or some other existing building deficiency.

"Poor" surfaces are considered to be a hazard and should be corrected. **"Fair"** surfaces should be repaired, but are not yet considered to be a hazard; if not repaired, they should be monitored frequently. **"Good/intact"** surfaces should be monitored to ensure that they remain in a nonhazardous condition.

In addition, the presence of paint debris must be considered in evaluating condition. Given the variety of paint uses, there are many applications that can have a tendency for the paint to "wear" from the surface slowly, over an extended period of time. Conditions where paint has worn from a surface are worth noting for maintenance discussions (i.e., related to re-coating the surface should, for example, the coating provide weather protection), however, in the absence of loose paint chip debris/dust, such conditions would not represent a potential exposure situation related to lead.

The condition evaluation criteria for LCPs are summarized in Table 4-1.

4.1.2 Building Materials—Leachable Lead Content

Once the exposure risks associated with generating airborne particulate when disturbing building materials coated with LCPs have been addressed, and the painted building materials become waste, we must also consider disposal options.

According to the British Columbia Hazardous Waste Regulation (BC Reg. 63/88), lead waste (including building material waste coated with LCPs) may be considered a toxic leachate (and require special disposal) if lead is in a dispersible form and its leachate contains greater than 5.0 mg/L lead.

METAL BASED PAINT AND SUPPLEMENTAL ASBESTOS ASSESSMENT

Reference Standards and Analytical Methodology
January 19, 2018

Table 4-1 LCP Condition Categories

| Type of Building Component ¹ | Total Area of Deteriorated Paint on Each Component | | |
|--|--|---|--|
| | Good/Intact | Fair ² | Poor ³ |
| Exterior components with large surface areas. | Entire surface is intact. | Less than or equal to 10 ft ² | More than 10 ft ² |
| Interior components with large surface areas (walls, ceilings, floors, doors). | Entire surface is intact. | Less than or equal to 2 ft ² | More than 2 ft ² |
| Interior and exterior components with small surface areas (window sills, baseboards, soffits, trim). | Entire surface is intact. | Less than or equal to 10% of the total surface area of the component. | More than 10% of the total surface area of the component |
| NOTES: ¹ Building component in this table refers to each individual component or side of building, not the combined surface area of all similar components in a room (e.g., a wall with 1 ft ² of deteriorated paint is in "fair" condition, even if the other three walls in a room are intact). ² Surfaces in "fair" condition should be repaired and/or monitored, but are not considered to be "LCP hazards". ³ Surfaces in "poor" condition are considered to be "LCP hazards" and should be addressed through abatement or interim controls. | | | |

Based on the above, bulk samples of painted building materials that would be expected to be disposed-of via landfill were collected in a form presumed to be representative of waste generated during renovation or demolition, each sample containing over 50 g in weight. The samples were submitted to EMSL for leachate analysis through Toxicity Characteristic Leaching Procedure (TCLP), using US EPA Method SW846, 1311/7420.

4.2 ASBESTOS

The presence of asbestos in federal workplaces, and pertaining to federally regulated workers is governed by the Canada Labour Code. The presence of asbestos in the workplace in British Columbia pertaining to provincially regulated workers is governed by BC Reg. 296/97. As both federally regulated workers and provincially regulated workers (e.g., contractors) are expected to carry out work activities within the subject structures, and as the provincial regulations are generally more prescriptive pertaining to asbestos (and generally include the requirements noted in the Canada Labour Code), this assessment was conducted to meet the requirements of BC Reg. 296/97.

According to the current version of BC Reg. 296/97, ACM means any material containing at least 0.5% asbestos, or vermiculite insulation with any asbestos.

METAL BASED PAINT AND SUPPLEMENTAL ASBESTOS ASSESSMENT

Reference Standards and Analytical Methodology
January 19, 2018

Based on these criteria, a visual assessment of accessible areas was undertaken in order to check for the presence of additional materials suspected of containing asbestos (those that were not assessed or sampled per the initial assessment) that may be disturbed during the remediation work. Locations to collect discrete bulk asbestos samples of suspect building materials were identified. Samples of representative materials were then collected at these locations.

Multiple samples were collected from each "homogenous application" of observed suspected ACMs (materials suspected to contain asbestos that are uniform in material type, colour, texture application and estimated installation date) and submitted to EMSL Canada Inc. in Burnaby, BC for analysis of asbestos content using polarized light microscopy (PLM) with dispersion staining, in accordance with the United States Environmental Protection Agency (EPA) 600/R-93/116 method. EMSL Canada Inc.'s analytical laboratory is accredited by the National Voluntary Laboratory Accreditation Program (NVLAP).

The number of samples to be collected for each homogenous application of a suspected ACM was based on the recommendations provided in the WorkSafeBC 2017 publication *Safe Work Practices for Handling Asbestos* (Asbestos Guide), along with the assessor's experience and understanding of the consistency of that building material's application.

4.2.1 Sample Results Interpretation

When asbestos is detected in concentrations greater than 0.5% in one of the samples within a set that was collected to represent a "homogenous application" of a particular material (or detected in any concentration, in a set of samples collected for applications of vermiculite), the entire sample set and the entire application of that material was then considered to be an ACM.

In addition to the above, a "positive stop" option was used during the laboratory analysis of the building material samples submitted for asbestos analysis. The "positive stop" option is utilized by the laboratory when asbestos is detected at a concentration of greater than one percent in one of the samples within a set that was collected to represent a "homogenous application" of that material. At this point, further analysis of subsequent samples within the set is deemed to be unnecessary (as the entire set will be considered an ACM, per above), and the remainder of the samples within the set are not analyzed.

4.2.2 Asbestos Sampling Quality Assurance/Quality Control

Sampling activities pertaining to asbestos were conducted in accordance with Stantec's SWPs, which take into account current provincial regulations pertaining to such work (i.e., sampling procedures, required number of samples, and laboratory analytical procedures).

METAL BASED PAINT AND SUPPLEMENTAL ASBESTOS ASSESSMENT

Limitations
January 19, 2018

Representative bulk samples were collected of accessible suspect ACMs in sufficient quantities for laboratory analyses. Suspect ACM samples were sealed in polyethylene zip-lock bags labeled with the sample number, suspect material description, and sample location. As part of sampling procedures, sampling tools were cleaned between sample collection events to avoid the potential for cross-contamination of samples.

Sample bags were compiled in order and placed into a single container accompanied with a Chain of Custody form outlining the project information, date, building location, number of samples, and sample description. Samples were submitted to the analytical laboratory in a sealed container via courier.

5.0 LIMITATIONS

In preparation of this report, Stantec used professional judgment based on experience. The work was conducted in accordance with generally accepted professional standards. Stantec relied on information gathered during the site investigation and laboratory analytical reports.

This report reflects the observations made within accessible and accessed areas of the subject structures, and the results of analyses performed on the specific material sampled during the assessment or previously sampled by Stantec. Analytical results reflect the sampled materials at the specific sample locations.

This report has been prepared for the exclusive use of the Parks Canada for the purpose of assessing general conditions in the subject building. Any use that a third party makes of this report, or reliance on, or decisions to be made on it, are the responsibility of such third parties. Stantec accepts no responsibility for damages, if any, suffered by any third party as a result of decisions made or actions based on this report.

5.1 PHYSICAL AND SAMPLING LIMITATIONS

Sampling was conducted pertaining to suspected LCPs and suspected ACMs only. Sampling for metals other than lead that may be present in paint was not conducted. Concealed spaces were inspected via existing access panels, where present. Interior and exterior finishes, solid ceilings, walls, flooring and structural elements were not removed to access concealed areas.

5.1.1 Lead in Paint

Although the painted surfaces where samples were collected may be covered with more than one coat of paint, the paint samples are described by the surface (visible) colour only. Attempts were made to represent all layers of paint in the samples collected. As analytical results are referenced to the surface paint colour only, the lead content of all painted surfaces similar to that represented by the surface paint colour were presumed to be the same, regardless of differing sub surface paints, if any.

METAL BASED PAINT AND SUPPLEMENTAL ASBESTOS ASSESSMENT

Limitations
January 19, 2018

Sampling for analysis of lead leachate was conducted such that building material samples were collected in a form presumed to be representative of waste generated during demolition. The lead leachate samples are meant to represent the general waste that would be created when painted surfaces are demolished, without having paint removed.

5.1.2 Asbestos

Assessment for asbestos was conducted only pertaining to buildings or materials that had not previously been assessed and sampled (per the initial assessment). Suspected ACMs that were not sampled included, but were not limited to, the following (where present, based on building construction or as otherwise noted):

- Interior components of mechanical equipment (e.g., inner linings or gaskets in boilers)
- Interior components of HVAC units
- Heat protection materials inside mechanical installations (e.g., gaskets) and light fixtures (e.g., paper backing in sealed incandescent fixtures)
- Drywall and/or wall plaster and associated finish materials concealed behind new and/or additional walls or ceilings
- Woven tape inside duct connection joints or inner ducting insulation
- Materials within sealed/hard wall cavities or hard ceiling cavities without appropriate access points
- Insulation materials inside fire doors

If encountered during remediation activities, any suspected ACMs not identified within this report or the initial assessment should be presumed to contain asbestos and handled as such until otherwise proven, through analytical testing.

5.2 AREAS NOT ACCESSED

The following areas were not accessed, for the reasons indicated:

- Georgina Point Light Keeper's House:
 - Attic space ("Do not enter" sign on door access, unsafe due to the presence of mercury vapour)
 - Second floor hallway closet ("Do not enter" sign on door access, unsafe due to the presence of mercury vapour)
 - Second floor north bedroom and closet (locked bedroom, key didn't work)
- Georgina Point Weather Station:
 - Interior of the weather turret on the roof (no safe roof access)
 - The fenced off antenna area (high voltage warning)
- Interior of the Georgina Point Shed (a key for the padlock was not provided)
- Bedroom 1 within the East Point Bunkhouse (locked bedroom—access not provided by tenant)

METAL BASED PAINT AND SUPPLEMENTAL ASBESTOS ASSESSMENT

Findings
January 19, 2018

As such, limited comments, if any, will be provided regarding the presence, quantity or condition of LCPs or ACMs within the above-noted areas.

5.3 INFORMATION FROM PREVIOUS REPORTS

Stantec reviewed the previous report(s) outlined herein for information purposes, and the information provided was considered in developing the current assessment and sampling plan.

Supplemental sampling of previously sampled materials was not conducted. Where previous sampling and analytical data indicated the presence of an LCP or ACM the material was considered to be an LCP or ACM.

6.0 FINDINGS

6.1 LEAD

6.1.1 Previously Identified LCPs

The initial assessment (Stantec 2016) indicated the presence of the following LCPs:

- Georgina Point Light Keeper's House
 - Grey colored paint on the basement floor
 - White colored paint on the exterior siding
 - Grey colored paint on the exterior trim
 - Red colored paint on the exterior under the porch
- Georgina Point Weather Station
 - Grey colored paint on the electrical room floor
 - Grey colored paint on the HVAC ducting
 - Red colored paint on the exterior trim
- Georgina Point Beacon
 - White colored paint on the interior walls and ceiling of the upper level
 - Red colored paint on the upper level floor and staircase
 - Red colored paint on the upper level exterior
 - White colored paint on the exterior of the tower
 - Grey colored paint on the exterior of the tower base and stairs
- Georgina Point Garage
 - Grey colored paint on the interior floor
 - Grey colored paint on the exterior doors
 - White colored paint on the exterior trim
- Georgina Point Shed
 - White colored paint on the exterior
 - Grey colored paint on the exterior floor
- East Point Light Tower and Shed
 - White colored paint on the interior walls and ceiling of the Shed
 - Red colored paint on the light tower

METAL BASED PAINT AND SUPPLEMENTAL ASBESTOS ASSESSMENT

Findings

January 19, 2018

- East Point Bunkhouse
 - White colored paint on the exterior walls
 - Light brown colored paint on the interior doors and trim
- East Point Fog Horn Building
 - White coloured paint on the interior walls
 - Grey coloured paint on the interior trim
 - White coloured paint on the exterior walls
- Portlock Point Lighthouse
 - White colored paint on the exterior trim
 - Grey colored paint on the interior light post and floors
 - White colored paint on the interior upper level walls and ceiling
 - Red colored paint on the exterior upper walls and railings
- Mahoi House
 - Cream colored paint on the interior bedroom
 - White colored paint on the exterior
 - Green colored paint on the exterior window trim
 - Gold colored paint on the exterior window frame
- Russell Island Caretaker's Shed
 - White colored paint on the exterior
 - Green colored paint on the exterior trim
- Russell Island Water Tower
 - Beige colored paint on the exterior trim
- Russell Island Generator Shed
 - Green colored paint on the exterior walls

6.1.2 Additional Suspected LCP Sampling

Paint chip samples were obtained from the various applications which had not been previously sampled within the subject structures. A summary of the sample types, locations and analytical results is presented in Table 5-1, below. A copy of the certificate of analysis provided by EMSL for the suspected LCP samples submitted is attached to this Appendix A.

**Table 5-1 Additional Suspected LCP Sample Collection and Analysis Summary
GINPR, BC**

| Sample Number | Paint Description | Location | Result (PPM Lead) |
|------------------------------------|-------------------------------------|-------------------------------|-----------------------------|
| Georgina Point Light Keepers House | | | |
| GPH-P-06 | White on concrete deck edge | Exterior southeast under deck | 37,000 |
| GPH-P-07 | Red on wood hand railing | Exterior southeast deck | 2,000 |
| N/A | Red paint on flagpole concrete base | Flagpole concrete base | Presumed LCP See 6.1.2.1 |
| Georgina Point Weather Station | | | |
| GPB-PB-04 | White on concrete exterior walls | South wall | 110 |

METAL BASED PAINT AND SUPPLEMENTAL ASBESTOS ASSESSMENT

Findings
January 19, 2018

**Table 5-1 Additional Suspected LCP Sample Collection and Analysis Summary
GINPR, BC**





| Sample Number | Paint Description | Location | Result (PPM Lead) |
|---|---|---------------------------|-------------------|
| GPB-PB-06 | Grey on concrete exterior slab | Northeast exterior | 700 |
| Georgina Point Beacon | | | |
| GPL-PB-06 | Cream on metal door (Interior?) | Tower base | 2,300 |
| GPL-PB-07 | Grey on interior concrete floor | Tower base | 2,400 |
| Georgina Point Gazebo | | | |
| GG-PB-01 | Brown wood | Exterior | <100 |
| East Point Light Tower and Shed | | | |
| EL-PB-04 | White on concrete tower footing | Tower base | 1,100 |
| East Point Garage | | | |
| EPG-PB-01 | White interior drywall | Meeting room | 320 |
| EPG-PB-02 | Beige interior drywall | Garage 2 | 860 |
| EPG-PB-03 | Grey interior wood trim | Office | <140 |
| EPG-PB-04 | Grey exterior concrete foundation wall | Northeast exterior | <100 |
| East Point Bunkhouse | | | |
| EB-PB-07 | Beige on concrete foundation walls | East basement | <100 |
| EB-PB-08 | Grey on structural steel posts and beams | West basement | 2,000 |
| EB-PB-00 | Red on structural steel posts and beams | West basement | <100 |
| Mahoi House | | | |
| MH-PB-07 | White/grey exterior plywood deck | North exterior | 1,200 |
| NOTE: Bold, orange highlighted text indicates confirmed LCP (paint with lead content >600 ppm) | | | |

Based on our observations and on our interpretations of suspected LCP sample analytical results, the additional paints presented in Table 5-2, below are also considered LCPs:

METAL BASED PAINT AND SUPPLEMENTAL ASBESTOS ASSESSMENT

Findings
January 19, 2018

**Table 6-2 Summary of Additional Identified LCPs
GINPR, BC**

| Additional Identified LCP Description | | Photo |
|---------------------------------------|---|---|
| Site/Structure | Georgina Point Light Keeper's House |  |
| Paint colour | White | |
| Substrate | Concrete | |
| Location/approx. extent | Deck edge | |
| Lead content | 37,000 ppm | |
| Condition | Poor | |
| Site/Structure | Georgina Point Light Keeper's House |  |
| Paint colour | Red | |
| Substrate | Wood | |
| Location/approx. extent | Deck hand railing | |
| Lead content | 2,000 ppm | |
| Condition | Good | |
| Site/Structure | Georgina Point Light Keeper's House – detached flagpole |  |
| Paint colour | Red | |
| Substrate | Concrete | |
| Location/approx. extent | Flagpole base | |
| Lead content | Presumed LCP – see 6.1.2.1 | |
| Condition | Good (reported) | |
| Site/Structure | Georgina Point Weather Station |  |
| Paint colour | Grey | |
| Substrate | Concrete | |
| Location/approx. extent | Exterior concrete slab | |
| Lead content | 700 ppm | |
| Condition | Paint worn from surface | |

METAL BASED PAINT AND SUPPLEMENTAL ASBESTOS ASSESSMENT

Findings
January 19, 2018


**Table 6-2 Summary of Additional Identified LCPs
GINPR, BC**

| Additional Identified LCP Description | | Photo |
|---------------------------------------|-------------------------|--|
| Site/Structure | Georgina Point Beacon |  |
| Paint colour | Cream | |
| Substrate | Metal | |
| Location/approx. extent | Door and door frame | |
| Lead content | 2,300 ppm | |
| Condition | Poor | |
| Site/Structure | Georgina Point Beacon |  |
| Paint colour | Grey | |
| Substrate | Concrete | |
| Location/approx. extent | Tower base | |
| Lead content | 2,400 ppm | |
| Condition | Poor | |
| Site/Structure | East Point light tower |  |
| Paint colour | White | |
| Substrate | Concrete | |
| Location/approx. extent | Footings | |
| Lead content | 1,100 ppm | |
| Condition | Poor | |
| Site/Structure | East Point Garage | No Photo |
| Paint colour | Beige | |
| Substrate | Drywall | |
| Location/approx. extent | Garage 2 interior walls | |
| Lead content | 860 ppm | |
| Condition | Good | |

METAL BASED PAINT AND SUPPLEMENTAL ASBESTOS ASSESSMENT

Findings
January 19, 2018

**Table 6-2 Summary of Additional Identified LCPs
GINPR, BC**

| Additional Identified LCP Description | | Photo |
|---------------------------------------|---|---|
| Site/Structure | East Point Bunkhouse | No Photo |
| Paint colour | Grey | |
| Substrate | Steel | |
| Location/approx. extent | Basement structural steel posts and beams | |
| Lead content | 2,000 ppm | |
| Condition | Good | |
| Site/Structure | Mahoi House |  |
| Paint colour | White/grey | |
| Substrate | Plywood | |
| Location/approx. extent | Exterior north deck | |
| Lead content | 1,200 ppm | |
| Condition | Poor | |

6.1.2.1 Red Paint on Flagpole Base

Although the flagpole was not listed as a structure to be included in our assessment, it has been reported that the red paint on the base of the flagpole, adjacent to the Georgina Point Light Keeper's House, is suspected to be LCP and is in good condition having been recently repainted. Given that various other visually similar red paints on other structures at the subject site have been tested and confirmed to be lead-containing, the red paint on the concrete base of the flagpole should also be presumed to be lead-containing.

6.1.3 Building Materials—Leachable Lead Content

Bulk (full-thickness, where possible) samples of building materials that are coated with the LCPs identified both through the initial assessment and through this assessment were collected. The samples were collected only from those materials that could potentially be removed with paint on them, and disposed of via landfill.

Each sample was collected in a form presumed to be representative of waste generated during the remediation project, and submitted to EMSL for analysis of leachable lead content.

METAL BASED PAINT AND SUPPLEMENTAL ASBESTOS ASSESSMENT

Findings
January 19, 2018

A summary of the sample types, locations and analytical results is presented in Table 5-3, below. A copy of the certificate of analysis provided by EMSL for the bulk painted building material samples submitted is included in Appendix B.

**Table 5-3 Painted Building Material Sample Collection and Lead Leachate Analysis Summary
GINPR, BC**


| Sample Number | Paint Description and Application | Initial Result (Total Lead, ppm) | Leachate Result (mg/L) |
|--|--|----------------------------------|------------------------|
| Georgina Point Light Keeper's House | | | |
| GPH-LL-03 | White exterior wood trim (basement door) | 1,800 | <0.40 |
| GPH-LL-04 | Grey exterior wood trim (wooden slats around the southwest deck) | 91,000 | <0.40 |
| GPH-LL-07 | Red on exterior wood hand railing | 2,000 | <0.40 |
| East Point Light Tower and Shed | | | |
| EL-LL-03 | Red steel frame of tower | 39,000 | 0.89 |
| East Point Bunkhouse | | | |
| EB-LL-02 | White exterior wood siding | 2,000 | <0.40 |
| East Point Fog Horn Building | | | |
| EF-LL-02 | Grey interior wood trim | 1,200 | 1.4 |
| EF-LL-03 | White exterior wood siding | 3,300 | <0.40 |
| Portlock Point Lighthouse | | | |
| PP-LL-01 | White exterior wood trim | 72,000 | 0.58 |
| PP-LL-02 | Grey interior wood stairs | 5,400 | <0.40 |
| PP-LL-04 | Red exterior wood trim | 110,000 | 2.9 |
| Maho'i House | | | |
| MH-LL-03 | White exterior wood siding | 56,000 | 6.8 |
| Russell Island Caretaker's Shed | | | |
| MHCS-LL-01 | White exterior wood siding | 1,700 | <0.40 |
| Russell Island Generator Shed | | | |
| MHGS-LL-01 | Green wood exterior | 6,500 | 1.1 |
| NOTE: Bold highlighted text indicates material that contains lead in a dispersible form such that its leachate contains greater than 5.0 mg/L lead . | | | |

As indicated above, analytical results indicate that the paint presented in Table 5-4, below contains lead in a dispersible form such that its leachate contains greater than 5.0 mg/L lead, and will require segregation and special disposal during renovation or demolition.

METAL BASED PAINT AND SUPPLEMENTAL ASBESTOS ASSESSMENT

Findings
January 19, 2018

**Table 5-4 Summary of Lead Leachable Paints
GINPR, BC**

| Identified LCP Description | | Photo |
|----------------------------|--|--|
| Site/Structure | Mahoi House |  |
| Paint colour | White | |
| Substrate | Wood | |
| Location/approx. extent | Exterior siding | |
| Leachate Result | 6.8 mg/L | |
| Condition | Generally good with localized areas of flaking and peeling | |

With the exception of the above-noted white paint on the wood siding of the Mahoi House, the other LCPs identified through this assessment and the initial assessment would not appear to be posing a significant environmental contamination hazard, in their current condition.

6.1.3.1 Metal or Concrete Materials Coated with LCPs

Materials such as metal and concrete that are coated with LCPs are typically not tested for leachable lead content for the following reasons:

- If removed with paint in-tact, these materials are expected to be recycled, not disposed of via landfill. As such, the leachable lead content will not impact the "disposal" option, as recycling facilities will typically accept metal or concrete with lead-containing paint.
- If removal of the paint from the substrate is considered, the waste associated with that process (paint chips and removal substrate – sand, beads, etc.) is typically presumed to be hazardous waste (leachable for lead in excess of 5.0 mg/L), or must be tested in its actual form (once removed, with the removal substrate) to confirm.
 - In most cases, during an initial assessment, it is not practical to try to remove sufficient paint from the substrate in order to appropriately analyze for lead leachate, as a significant area would have to be "scraped" (100 g of sample is required).

During our assessment, and pertaining to the red paint on the steel frame of the East Point light tower, this paint was significantly flaking and delaminating such that a sufficient amount was available for lead leachate sampling. Although paint waste from this structure would not appear to be hazardous waste (0.89 mg/L lead detected in leachate for the paint alone), the expected paint chip waste that would result in removal of LCP from metal or concrete surfaces from any other structures considered herein will be presumed to be hazardous (i.e., presumed to contain leachable lead in excess of 5 mg/L).

METAL BASED PAINT AND SUPPLEMENTAL ASBESTOS ASSESSMENT

Findings
January 19, 2018

6.2 ASBESTOS

6.2.1 Previously Identified ACMs

The initial assessment (Stantec 2016) indicated the presence of the following ACMs:

- Georgina Point Light Keeper's House
 - White woven tape on seams of furnace ducting throughout
 - Heat shields in round incandescent light fixtures throughout
 - Joint compound on drywall walls and ceilings throughout
 - Black window pane caulking on the windows throughout
- Georgina Point Weather Station
 - Brown 12 in. x 12 in. vinyl floor tile in the Weather room
 - Joint compound on drywall walls and ceilings
- Georgina Point Beacon
 - Black window pane caulking on the windows throughout
- Georgina Point NAV Canada Shed
 - Black window pane caulking on the window
- East Point Light Tower and Shed
 - Black window pane caulking on the window in the east wall of the Shed
- East Point Bunkhouse
 - Drywall joint compound on walls and ceilings throughout
- Portlock Point Lighthouse
 - Black building tar on the interior walls
 - Black window pane caulking on the north side window

6.2.2 Additional Suspected ACM Sampling

Stantec identified and sampled various additional suspected ACMs that may be disturbed by the remediation work. The samples collected were submitted to EMSL for analysis of asbestos content and nature.

A summary of the sampled materials, sample locations and analytical results is presented in Table 6-5, below. A copy of the certificate of analysis provided by EMSL for the suspected ACM samples submitted is attached at the end of this Appendix C.

**Table 6-5 Suspected ACM Sample Collection and Analysis Summary
GINPR, BC**

| Sample Number | Material Description | Sample Location | Result (%/type asbestos) |
|--------------------------------|-------------------------|-----------------|-----------------------------|
| Georgina Point Weather Station | | | |
| GPB-VFT-01 | Black floor tile mastic | Weather room | <0.25% Chrysotile |
| East Point Garage | | | |
| EPG-DJC-01A | Drywall joint compound | Garage 1 | None Detected |
| EPG-DJC-01B | Drywall joint compound | Garage 2 | None Detected |

METAL BASED PAINT AND SUPPLEMENTAL ASBESTOS ASSESSMENT


Findings
January 19, 2018

**Table 6-5 Suspected ACM Sample Collection and Analysis Summary
GINPR, BC**

| Sample Number | Material Description | Sample Location | Result (%/type asbestos) |
|---|-----------------------------------|---------------------------|-------------------------------------|
| EPG-DJC-01C | Drywall joint compound | Garage 2 | None Detected |
| EPG-WPC-01A | Black window pane caulking | Office | 0.72% Chrysotile |
| EPG-WPC-01B | Black window pane caulking | Meeting room | Positive Stop (Not Analyzed) |
| EPG-WPC-01C | Black window pane caulking | Office | Positive Stop (Not Analyzed) |
| Russell Island Caretakers Shed | | | |
| MHCS-CP-01 | Cement panel | Northwest exterior | 20% Chrysotile |
| NOTE: Bold, highlighted text indicates confirmed >0.5% ACM | | | |

Based on our observations of building construction (estimated vintage of interior finishes and uniformity of building material use) and on our interpretations of suspected ACM sample analytical results, the additional materials presented in Table 6-6, below were also identified as ACMs.


**Table 6-6 Summary of Additional Identified ACMs
GINPR, BC**

| Identified ACM Description and Condition Information | | Photo |
|---|--------------------------------|--|
| East Point Garage – Black window pane caulking | |  |
| Friability | Non-friable | |
| Condition | Good | |
| Total Quantity | Approximately 15 linear meters | |
| Content | 0.72% Chrysotile | |

METAL BASED PAINT AND SUPPLEMENTAL ASBESTOS ASSESSMENT

General Recommendations
January 19, 2018

**Table 6-6 Summary of Additional Identified ACMs
GINPR, BC**

| Identified ACM Description and Condition Information | | Photo |
|---|--------------------------------|--|
| Russell Island Caretakers Shed – Cement panel stored outside | |  |
| Friability | Non-friable | |
| Condition | Good | |
| Total Quantity | Approximately 1 m ² | |
| Content | 20% Chrysotile | |

6.2.2.1 Non-Friable Materials Containing Less Than 0.5% Asbestos

One sample of black floor tile mastic was collected from the Georgina Point Weather Station Weather room. The analytical result for that sample indicates its asbestos content to be less than 0.25%. The number of samples collected for this material would be adequate to appropriately characterize its asbestos content based on its extent and published standards for sampling of homogenous applications of suspected ACMs (e.g., the Asbestos Guide). Given the analytical result and the non-friable nature of this material, it would not be considered an ACM. Note that the overlying vinyl floor tile in the Weather room was identified as an ACM by the initial assessment.

7.0 GENERAL RECOMMENDATIONS

7.1 LEAD

LCPs can be managed in place, where in good condition, and where well adhered to substrates. Health and safety and/or environmental contamination risks posed by LCPs in good condition are expected to be negligible, with the possible exception of exposure risks associated with children that may chew on surfaces (e.g., window ledges/trim) coated with LCPs.

Where paints are in poor condition, health and safety risks may be present and as such, remedial action should be undertaken. Remedial action can include various options, including, but not limited to those summarized in Table 7-1 below.

METAL BASED PAINT AND SUPPLEMENTAL ASBESTOS ASSESSMENT

General Recommendations

January 19, 2018

Note that we have assumed that in all instances where paint will be removed, new paint would be installed.

Table 7-1 Remedial Actions Summary
GINPR, BC

| Action Description | Advantages | Disadvantages |
|---|---|---|
| Localized removal of LCP from substrate: Removal of damaged/poor condition LCP from surfaces only, with or without re-painting | Simplest, most cost-effective solution | LCP remains on the structure for the most part. Further damage/delamination can occur in the future, requiring repeated remediation in other areas. Would require regular surveillance of remaining LCP to address future damage as it happens. |
| Comprehensive removal of LCP from substrate: Removal of all LCP from a particular substrate (regardless of LCP condition – both good and poor condition paint), with or without re-painting | Exposure risks associated with LCP are removed. Residual that remains will not pose exposure risk as it will be extremely well adhered to the substrate. Often effective for substrates like concrete or metal that may not otherwise require full removal. | Residual LCP will remain, for most removal methods. Cost can be high depending on the amount of substrate, and some paint that would otherwise not require action for many years may also be removed – incurring additional costs for re-painting that may not have otherwise been necessary. |
| Localized substrate removal: Removal of substrates (with LCP intact) in only those areas where damaged/poor condition LCPs are present, with re-installation of new substrates (painted to match existing) in those locations only. | Often can be easier/more efficient to remove the substrates than just removing the paint. Typically effective for discrete substrates like trim. | Significant “patchwork” can be required, if substrates are present (for example) in the middle of a wall – carrying additional risks associated with building envelope failure at remediation points. |
| Comprehensive substrate removal: Removal of substrates (with LCP intact) throughout a structure (regardless of LCP condition – substrates with both good and poor condition paint), with re-installation of new substrates (painted to match existing) | Exposure risks associated with LCP are removed. | Cost can be high depending on the amount of substrate, and some substrates that would otherwise not require action for many years may also be removed – incurring additional costs for re-installation that may not have otherwise been necessary. Not practical for some substrates (e.g., concrete foundations) |

When undertaking remedial actions on LCPs, ensure compliance with the following:

- Exposure protection requirements of BC Reg. 296/97, including the provisions of the Lead Guideline
- Transportation and disposal requirements of BC Reg. 63/88
- Transportation requirements of the Federal Transportation of Dangerous Goods Regulation

METAL BASED PAINT AND SUPPLEMENTAL ASBESTOS ASSESSMENT

General Recommendations
January 19, 2018

Corrective action or remedial work on paint applications containing any concentration of lead should be undertaken in a manner so as to avoid generating fine particulate matter or dust (i.e., avoid sanding). Airborne lead dust or fumes should not exceed the Canada Labour Code and BC Reg. 296/97 8-hour OEL of 0.05 mg/m³ during the removal of paints and products containing any concentration of lead. The use of personal protective equipment is recommended to reduce the potential for over-exposure to lead dust. This can be achieved by:

- Providing workers with protective clothing and PPE or devices as necessary to protect the worker against the hazards to which the worker may be exposed
- Providing workers with adequate and training in the care and use of clothing, equipment or device before wearing or using it
- Wetting the surface of the materials to prevent dust emissions
- Providing workers with washing facilities with clean water, soap and individual towels to properly wash prior to exiting the work area

To avoid the inhalation of lead, it is essential to have the following control methods in place:

- Engineering controls
- Work practices and hygiene practices
- Respirators and personal protective equipment
- Training

The work tasks required and the ways in which LCPs will be impacted will determine the appropriate respirators, measures and procedures that should be followed to protect workers from lead exposure.

7.2 ASBESTOS

For buildings with identified ACMs, Stantec recommends the following with regards to meeting the requirements of the Canada Labour Code and BC Reg. 296/97 as they pertain to managing asbestos in the workplace:

- Identified ACMs in good condition can be managed in place
- Suspected ACMs deemed visually similar to the ACMs identified in this report (on a building-by-building basis) should be considered ACMs and handled as such, unless proven otherwise, through analytical testing
- ACMs that may be impacted during LCP remediation should be removed by appropriately trained personnel (e.g., asbestos abatement contractor personnel), in accordance with the requirements of BC Reg. 296/97 and the Asbestos Guide, and prior to the initiation of project work that will disturb them
- Should a material suspected to contain asbestos fibres become uncovered during LCP remediation or other activities, all work in the areas that may disturb the material should be stopped. Samples of the suspect material should be submitted for laboratory analysis to

METAL BASED PAINT AND SUPPLEMENTAL ASBESTOS ASSESSMENT

LCP Condition Assessment and Remedial Options
January 19, 2018




determine if asbestos fibres are present. Confirmed asbestos materials should be handled in accordance with applicable guidelines and regulations.

- Asbestos-containing cement pipe may be present below ground—caution should be used at any time when excavation is required
- Ensure asbestos containing waste is handled, stored, and disposed of in accordance with the requirements of the Federal Transportation of Dangerous Goods Regulation and the British Columbia Hazardous Waste Regulation (BC Reg. 63/88)

8.0 LCP CONDITION ASSESSMENT AND REMEDIAL OPTIONS

Table 8-1 below summarizes the findings and recommendations of this assessment with regards to each identified LCP present at the subject sites, including options for remedial actions, based on current condition of LCPs and the substrates to which they are applied.

With respect to the remedial actions, the various options have been highlighted as follows:

| | |
|--|---|
|  | Option recommended by Stantec |
|  | Other option available for consideration by Parks Canada |
|  | Option not recommended due to health and safety risks or practicality |

Preliminary cost estimates have also been included in Table 8-1 below, on a task-by-task basis. Regarding these cost estimates, the following notes are provided:

- The cost estimates were derived through providing general descriptions of the required work to an experienced abatement contractor, who offered “order of magnitude” costs for each task, given appropriate information about general site location and materials to be addressed. The contractor estimated costs using their knowledge of the man-days required to complete the work, as well as associated logistics for travel, living-out and waste disposal.
 - The contractors was NOT provided with site-specific information that would preclude them from bidding on the resulting remediation project.
- The cost estimates, as provided, are task-specific, and have not considered completion of multiple tasks at the same site (or in the same building) simultaneously.
- Cost savings would likely be realized by combining tasks.
- The overall cost for addressing paints in poor condition at each of the subject sites will be dependent on the final scope to be completed.
- Cost estimates have not been provided for options deemed “not recommended”.
- Cost estimates do not include consulting fees associated with on-site monitoring that may be required. The costs for such services cannot be determined until the overall scope for abatement work is understood, as well as the methods that will be employed by the contractor that completes the abatement work. For example, limited monitoring may be required for situations where substrates will be removed (with paint in-tact), while projects that will involve removal of paints from substrates may require a more significant level of involvement of a consultant to conduct monitoring.

METAL BASED PAINT AND SUPPLEMENTAL ASBESTOS ASSESSMENT

LCP Condition Assessment and Remedial Options
January 19, 2018

- Cost estimates include abatement tasks only. These estimates do not include tasks such as re-painting or reinstatement of removed building materials. Such estimates can be provided as part of the Class A Cost Estimate for the final Remedial Action Plan, which will be provided under separate cover.
- Cost estimates do not include for addressing other issues that may arise due to abatement work conducted (e.g. compromised structural integrity if all siding is removed; alteration of siding and/or siding removal/replacement required to remove windows/frames; etc.).
- Cost estimates provided herein were intended to provide PSPC and Parks Canada with additional context to assist them in distinguishing between the various remedial options. Through preliminary review of this document, PSPC and Parks Canada have evaluated the options and indicated their chosen option, in the "Proceed with RAP" column.

METAL BASED PAINT AND SUPPLEMENTAL ASBESTOS ASSESSMENT

LCP Condition Assessment and Remedial Options
January 19, 2018

Table 8-1 Summary of Remedial Action Options
GINPR, BC

| Building | Paint Description/ Condition/Quantity | Paint Lead Concentration (ppm) | Leachate Concentration (mg/L) | Remedial Action Options | Preliminary Cost Estimate | Proceed with RAP |
|---|---|--------------------------------------|----------------------------------|---|---------------------------|---------------------|
| Georgina Point Light Keeper's House | Grey on concrete basement floor is in poor condition, flaking and peeling throughout—approximately 33 m² | 41,000 | Leachate sampling not practical | Manage in place | | |
| | | | | Localized LCP removal from substrate | \$6,900 | |
| | | | | Comprehensive removal of LCP from substrate | \$6,900 | Yes |
| | | | | Localized substrate removal | | |
| | | | | Comprehensive substrate removal | | |
| | White on wood exterior siding is in good condition except for localized flaking on the rear basement door—approximately 1.5 m² in poor condition | 1,800 | <0.40 | Manage in place | | |
| | | | | Localized LCP removal from substrate | \$2,500 | Yes |
| | | | | Comprehensive removal of LCP from substrate | \$10,700 | |
| | | | | Localized substrate removal | \$2,500 | |
| | | | | Comprehensive substrate removal | \$9,000 | |
| | Grey on wood and stucco exterior trim is in good condition throughout except for the surface of the decks where some paint is worn from the surface—approximately 33 m² in poor condition | 91,000 | <0.40 | Manage in place | \$0 | Agree |
| | | | | Localized LCP removal from substrate | \$6,900 | |
| | | | | Comprehensive removal of LCP from substrate | \$10,000 | |
| | | | | Localized substrate removal | \$9,000 | |
| | | | | Comprehensive substrate removal | \$15,000 | |
| Georgina Point Light Keeper's House (cont'd) | Red on concrete exterior foundation wall under porch is in poor condition, flaking and peeling throughout - Approximately 14.5 m² Note that some flaking paint was observed to be present on the surface of the soil below | 6,700 | Leachate sampling not practical | Manage in place | | |
| | | | | Localized LCP removal from substrate | | |
| | | | | Comprehensive removal of LCP from substrate | \$12,500 | Yes |
| | | | | • Remove the top inch of soil along the wall where flaking paint is present | | |
| | | | | Localized substrate removal | | |
| | White on concrete edge of deck under porch is in poor condition, flaking and peeling throughout - Approximately 1 m² | 37,000 | Leachate sampling not practical | Manage in place | | |
| | | | | Localized LCP removal from substrate | | |
| | | | | Comprehensive removal of LCP from substrate | \$2,500 | Yes |
| | | | | Localized substrate removal | | |
| | | | | Comprehensive substrate removal | | |
| | Red on wood exterior handrails is in good condition throughout | 2,000 | <0.40 | Manage in place | \$0 | Agree |
| | | | | Localized LCP removal from substrate | \$2,500 | |
| | | | | Comprehensive removal of LCP from substrate | \$2,500 | |
| | | | | Localized substrate removal | \$2,500 | |
| | | | | Comprehensive substrate removal | \$2,500 | |
| | Red paint on concrete base of detached flagpole is in poor condition throughout – Approximately 1 m² | Presumed LCP | Leachate sampling not practical | Manage in place | | |
| | | | | Localized LCP removal from substrate | | |
| | | | | Comprehensive removal of LCP from substrate | \$2,500 | Yes |
| | | | | Localized substrate removal | | |
| | | | | Comprehensive substrate removal | | |

METAL BASED PAINT AND SUPPLEMENTAL ASBESTOS ASSESSMENT

LCP Condition Assessment and Remedial Options
January 19, 2018

Table 8-1 Summary of Remedial Action Options
GINPR, BC

| Building | Paint Description/ Condition/Quantity | Paint Lead Concentration (ppm) | Leachate Concentration (mg/L) | Remedial Action Options | Preliminary Cost Estimate | Proceed with RAP |
|--|--|---|------------------------------------|--|--|---------------------|
| Georgina Point Weather Station | Grey on concrete floor in the electrical room is in poor condition, flaking and peeling throughout - Approximately 37 m² | 2,200 | Leachate sampling not practical | Manage in place | | |
| | | | | Localized LCP removal from substrate | \$7,000 | |
| | | | | Comprehensive removal of LCP from substrate | \$7,000 | Yes |
| | | | | Localized substrate removal | | |
| | | | | Comprehensive substrate removal | | |
| | Grey on metal exterior vent is in good condition throughout | 1,700 | Leachate sampling not practical | Manage in place | \$0 | Agree |
| | | | | Localized LCP removal from substrate | \$2,500 | |
| | | | | Comprehensive removal of LCP from substrate | \$2,500 | |
| | | | | Localized substrate removal | \$2,500 | |
| | | | | Comprehensive substrate removal | \$2,500 | |
| | Red on concrete exterior trim is in poor condition, flaking and peeling throughout - Approximately 5.5 m² | 56,000 | Leachate sampling not practical | Manage in place | | |
| | | | | Localized LCP removal from substrate | | |
| | | | | Comprehensive removal of LCP from substrate | \$2,500 | Yes |
| | | | | Localized substrate removal | | |
| | | | | Comprehensive substrate removal | | |
| | Grey on concrete exterior slab is worn from the surface throughout - Approximately 36.5 m² | 700 | Leachate sampling not practical | Manage in place | \$0 | Agree |
| | | | | Localized LCP removal from substrate | | |
| | | | | Comprehensive removal of LCP from substrate | \$7,000 | |
| | | | | Localized substrate removal | | |
| | | | | Comprehensive substrate removal | | |
| Georgina Point Weather Station (cont'd) | Red and white on metal antenna is in poor condition, flaking and peeling throughout - Approximately 11 m² | Not sampled as it could not be safely accessed (high voltage warning) | Leachate sampling not practical | Undertake sampling prior to developing an action plan | \$8,500, assuming paint is lead-containing and scope would be to remove paint throughout. | Yes |
| Georgina Point Beacon | White on metal interior of upper level walls and ceiling is in poor condition, flaking and peeling throughout - Approximately 2.5 m² | 7,500 | Leachate sampling not practical | Manage in place | | |
| | | | | Localized LCP removal from substrate | | |
| | | | | Comprehensive removal of LCP from substrate • If ACM window caulking will be disturbed it should be removed prior to LCP remediation | \$2,500 if ACM not disturbed; \$5,000 if ACM disturbed | Yes |
| | | | | Localized substrate removal | | |
| | | | | Comprehensive substrate removal • If ACM window caulking will be disturbed it should be removed prior to LCP remediation | \$5,000, assuming ACM will be disturbed | |
| | Red on metal upper level floor and staircase is in poor condition, flaking and peeling throughout - Approximately 10 m² | 67,000 | Leachate sampling not practical | Manage in place | | |
| | | | | Localized LCP removal from substrate | | |
| | | | | Comprehensive removal of LCP from substrate | \$10,000 | Yes |
| | | | | Localized substrate removal | | |
| | | | | Comprehensive substrate removal | \$60,000 | |

METAL BASED PAINT AND SUPPLEMENTAL ASBESTOS ASSESSMENT

LCP Condition Assessment and Remedial Options
January 19, 2018

Table 8-1 Summary of Remedial Action Options
GINPR, BC

| Building | Paint Description/ Condition/Quantity | Paint Lead Concentration (ppm) | Leachate Concentration (mg/L) | Remedial Action Options | Preliminary Cost Estimate | Proceed with RAP |
|-----------------------------------|---|--------------------------------------|------------------------------------|--|---------------------------|---------------------|
| Georgina Point Beacon (cont'd) | Red on metal upper level exterior and railing is in poor condition, flaking and peeling throughout - Approximately 10 m ² | 100,000 | Leachate sampling not practical | Manage in place | | |
| | | | | Localized LCP removal from substrate | | |
| | | | | Comprehensive removal of LCP from substrate • If ACM window caulking will be disturbed it should be removed prior to LCP remediation | \$10,000 | Yes |
| | | | | Localized substrate removal | | |
| | | | | Comprehensive substrate removal • If ACM window caulking will be disturbed it should be removed prior to LCP remediation | \$60,000 | |
| | White on exterior of tower is in good condition throughout | 2,700 | Leachate sampling not practical | Manage in place | \$0 | Agree |
| | | | | Localized LCP removal from substrate | | |
| | | | | Comprehensive removal of LCP from substrate | \$75,000 | |
| | | | | Localized substrate removal | | |
| | | | | Comprehensive substrate removal | | |
| | Grey on concrete exterior foundation and steps is mostly worn from the surface of the concrete (reportedly previously abated) - Approximately 7.5 m ² | 1,300 | Leachate sampling not practical | Manage in place | \$0 | |
| | | | | Localized LCP removal from substrate | | |
| | | | | Comprehensive removal of LCP from substrate (to remove amounts left behind by previous abatement) | \$8,000 | Yes |
| | | | | Localized substrate removal | | |
| | | | | Comprehensive substrate removal | | |
| | Cream on the interior side of the metal door and frame is in poor condition, flaking and peeling throughout - Approximately 2.5 m ² | 2,300 | Leachate sampling not practical | Manage in place | | |
| | | | | Localized LCP removal from substrate | | |
| | | | | Comprehensive removal of LCP from substrate | \$3,000 | Yes |
| | | | | Localized substrate removal | | |
| | | | | Comprehensive substrate removal | \$2,500 | |
| | Grey on interior? concrete floor base is in poor condition, flaking and peeling throughout - Approximately 2.5 m ² | 2,400 | Leachate sampling not practical | Manage in place | | |
| | | | | Localized LCP removal from substrate | | |
| | | | | Comprehensive removal of LCP from substrate | \$2,500 | Yes |
| | | | | Localized substrate removal | | |
| | | | | Comprehensive substrate removal | | |
| Georgina Point Garage | Grey on concrete floor is in poor condition, flaking and peeling throughout - Approximately 23.5 m ² | 1,200 | Leachate sampling not practical | Manage in place | | |
| | | | | Localized LCP removal from substrate | | |
| | | | | Comprehensive removal of LCP from substrate | \$7,500 | Yes |
| | | | | Localized substrate removal | | |
| | | | | Comprehensive substrate removal | | |
| | Grey on metal doors is in good condition throughout | 2,900 | Leachate sampling not practical | Manage in place | \$0 | Agree |
| | | | | Localized LCP removal from substrate | \$2,500 | |
| | | | | Comprehensive removal of LCP from substrate | \$3,000 | |
| | | | | Localized substrate removal | | |
| | | | | Comprehensive substrate removal | \$2,500 | |

METAL BASED PAINT AND SUPPLEMENTAL ASBESTOS ASSESSMENT

LCP Condition Assessment and Remedial Options
January 19, 2018

Table 8-1 Summary of Remedial Action Options
GINPR, BC

| Building | Paint Description/ Condition/Quantity | Paint Lead Concentration (ppm) | Leachate Concentration (mg/L) | Remedial Action Options | Preliminary Cost Estimate | Proceed with RAP |
|-----------------------------------|--|--------------------------------------|--|--|--|---------------------|
| Georgina Point Garage (cont'd) | White on wood exterior fascia is in poor condition, flaking and peeling throughout - Approximately 4 m² | 1,100 | No sample collected as no discrete location was identified | Manage in place | | |
| | | | | Localized LCP removal from substrate | | |
| | | | | Comprehensive removal of LCP from substrate | \$2,500 | |
| | | | | Localized substrate removal | | |
| | | | | Comprehensive substrate removal • Although it is unlikely that this material is lead leachable waste based on the lead concertation of the paint TCLP testing may be required prior to its disposal at a landfill | \$2,500 Add \$2,500 if material is leachable (unlikely) | Yes |
| Georgina Point Shed | White on wood exterior siding is in good condition except for localized flaking on the door – Approximately 3 m² in poor condition | 190,000 | No sample collected as no discrete location was identified | Manage in place | | |
| | | | | Localized LCP removal from substrate | | |
| | | | | Comprehensive removal of LCP from substrate | \$3,000 | Yes |
| | | | | Localized substrate removal • TCLP testing will be required prior to disposal at a landfill | \$2,500 Add \$2,500 if material is leachable | |
| | | | | Comprehensive substrate removal • TCLP testing will be required prior to disposal at a landfill | \$3,000 Add \$2,500 if material is leachable | |
| | Grey on concrete front step is in poor condition, flaking and peeling throughout - Approximately 1 m2 | 4,400 | Leachate sampling not practical | Manage in place | | |
| | | | | Localized LCP removal from substrate | | |
| | | | | Comprehensive removal of LCP from substrate | \$2,500 | Yes |
| | | | | Localized substrate removal | | |
| | | | | Comprehensive substrate removal | | |
| Georgina Point Seasonal Washroom | No LCPs have been identified for this building. | | | | | |
| Georgina Point Outhouse | No LCPs have been identified for this building. | | | | | |
| Georgina Point NAV Canada Shed | No LCPs have been identified for this building. | | | | | |
| Georgina Point Gazebo | No LCPs have been identified for this building. | | | | | |
| East Point Light Tower and Shed | White on wood interior and exterior shed walls is in good condition throughout | 1,200 | No sample collected as no discrete location was identified and the paint does not require remedial action based on condition | Manage in place | \$0 | Agree |
| | | | | Localized LCP removal from substrate | | |
| | | | | Comprehensive removal of LCP from substrate | \$10,000 | |
| | | | | Localized substrate removal | | |
| | | | | Comprehensive substrate removal | \$5,000 | |
| | Red on the steel tower structure is in poor condition, flaking and peeling throughout - Approximately 120 m2s | 39,000 | 0.89 | Manage in place | | |
| | | | | Localized LCP removal from substrate | | |
| | | | | Comprehensive removal of LCP from substrate | \$75,000 | Yes |
| | | | | Localized substrate removal | | |
| | | | | Comprehensive substrate removal | | |

METAL BASED PAINT AND SUPPLEMENTAL ASBESTOS ASSESSMENT

LCP Condition Assessment and Remedial Options
January 19, 2018

Table 8-1 Summary of Remedial Action Options
GINPR, BC

| Building | Paint Description/ Condition/Quantity | Paint Lead Concentration (ppm) | Leachate Concentration (mg/L) | Remedial Action Options | Preliminary Cost Estimate | Proceed with RAP |
|---|--|--------------------------------------|---|---|---------------------------|---------------------|
| East Point Light Tower and Shed (cont'd) | White on concrete tower footings is in poor condition, flaking and peeling throughout - Approximately 18 m² | 1,100 | Leachate sampling not practical | Manage in place | | |
| | | | | Localized LCP removal from substrate | | |
| | | | | Comprehensive removal of LCP from substrate | \$5,000 | Yes |
| | | | | Localized substrate removal | | |
| | | | | Comprehensive substrate removal | | |
| East Point Garage | Beige on interior drywall is in good condition throughout | 860 | No sample collected as no discrete location was identified and the paint does not require remedial action based on condition | Manage in place | \$0 | Agree |
| | | | | Localized LCP removal from substrate | | |
| | | | | Comprehensive removal of LCP from substrate | | |
| | | | | Localized substrate removal | | |
| | | | | Comprehensive substrate removal | \$10,000 | |
| East Point Bunkhouse | White on wood exterior siding is in poor condition flaking and peeling over a significant portion of the building - Approximately 70 m² in poor condition | 2,000 | <0.40 | Manage in place | | |
| | | | | Localized LCP removal from substrate | \$17,500 | |
| | | | | Comprehensive removal of LCP from substrate | \$43,750 | |
| | | | | Localized substrate removal | \$7,500 | |
| | | | | Comprehensive substrate removal | \$15,000 | Yes |
| | Light brown on wood interior doors and trim is in good condition throughout | 2,800 | No sample collected as no discrete location was identified and the paint does not require remedial action based on condition | Manage in place | \$0 | Agree |
| | | | | Localized LCP removal from substrate | | |
| | | | | Comprehensive removal of LCP from substrate | | |
| | | | | Localized substrate removal | \$2,500 | |
| | | | | Comprehensive substrate removal | \$5,000 | |
| | Grey on structural steel posts and beams in the basement is in good condition throughout | 2,000 | Leachate sampling not practical | Manage in place | \$0 | Agree |
| | | | | Localized LCP removal from substrate | | |
| | | | | Comprehensive removal of LCP from substrate | \$5,000 | |
| | | | | Localized substrate removal | | |
| | | | | Comprehensive substrate removal | \$3,000 | |
| East Point Fog Horn Building | White on wood interior walls is in good condition throughout | 1,400 | No sample collected as no discrete location was identified and the paint does not require remedial action based on condition | Manage in place | \$0 | Agree |
| | | | | Localized LCP removal from substrate | | |
| | | | | Comprehensive removal of LCP from substrate | | |
| | | | | Localized substrate removal | | |
| | | | | Comprehensive substrate removal | \$10,000 | |
| | Grey on wood interior trim is in good condition throughout | 1,200 | 1.4 | Manage in place | \$0 | Agree |
| | | | | Localized LCP removal from substrate | | |
| | | | | Comprehensive removal of LCP from substrate | | |
| | | | | Localized substrate removal | | |
| | | | | Comprehensive substrate removal | \$2,500 | |

METAL BASED PAINT AND SUPPLEMENTAL ASBESTOS ASSESSMENT

LCP Condition Assessment and Remedial Options
January 19, 2018

Table 8-1 Summary of Remedial Action Options
GINPR, BC

| Building | Paint Description/ Condition/Quantity | Paint Lead Concentration (ppm) | Leachate Concentration (mg/L) | Remedial Action Options | Preliminary Cost Estimate | Proceed with RAP |
|--|--|--------------------------------------|---|---|---------------------------|---------------------|
| East Point Fog Horn Building (cont'd) | White on wood exterior siding is generally in good condition with minor flaking and peeling in some locations - Approximately 5 m² Note that some flaking paint was observed to be present on the surface of the soil below | 3,300 | <0.40 | Manage in place | | |
| | | | | Localized LCP removal from substrate • Remove the top inch of soil along the wall where flaking paint is present | \$6,500 | Yes |
| | | | | Comprehensive removal of LCP from substrate • Remove the top inch of soil along the wall where flaking paint is present | \$21,150 | |
| | | | | Localized substrate removal • Remove the top inch of soil along the wall where flaking paint is present | \$6,500 | |
| | | | | Comprehensive substrate removal • Remove the top inch of soil along the wall where flaking paint is present | \$9,000 | |
| Portlock Point Lighthouse | White on wood exterior is flaking and peeling in some locations (window trim and door) - Approximately 4.5 m² Note that some of the wood window trim is deteriorating due to moisture | 72,000 | 0.58 | Manage in place | | |
| | | | | Localized LCP removal from substrate | | |
| | | | | Comprehensive removal of LCP from substrate • If ACM building tar and/or window caulking will be disturbed it should be removed prior to LCP remediation | \$3,500 | Yes |
| | | | | Localized substrate removal | | |
| | | | | Comprehensive substrate removal • If ACM building tar and/or window caulking will be disturbed it should be removed prior to LCP remediation | \$3,500 | |
| | Grey on metal and wood interior trim and stairs is generally in good condition with minor flaking and peeling around the base of the metal light post - Approximately 1 m² | 5,400 | <0.40 | Manage in place | | |
| | | | | Localized LCP removal from substrate | \$3,500 | |
| | | | | Comprehensive removal of LCP from substrate | \$3,500 | Yes |
| | White on interior metal walls and ceiling on the upper level is flaking and peeling throughout - Approximately 15 m² | 2,900 | Leachate sampling not practical | Localized substrate removal | | |
| | | | | Comprehensive substrate removal | | |
| | | | | Manage in place | | |
| | | | | Localized LCP removal from substrate | | |
| | | | | Comprehensive removal of LCP from substrate • If ACM building tar and/or window caulking will be disturbed it should be removed prior to LCP remediation | \$9,000 | Yes |
| Portlock Point Lighthouse (cont'd) | Red on exterior metal walls and roof on the upper level is flaking and peeling throughout - Approximately 30 m² Note that wood trim is present directly below the windows and that the window trim is deteriorating due to moisture | 110,000 | 2.9 for the wood trim which is present directly below the windows No metal sample as leachate sampling not practical | Localized substrate removal | | |
| | | | | Comprehensive substrate removal | | |
| | | | | Manage in place | | |
| | | | | Localized LCP removal from substrate | | |
| | | | | Comprehensive removal of LCP from substrate • Remove and replace wood trim • If ACM building tar and/or window caulking will be disturbed it should be removed prior to LCP remediation | \$18,000 | Yes |
| | | | | Localized substrate removal | | |
| | | | | Comprehensive substrate removal | | |

METAL BASED PAINT AND SUPPLEMENTAL ASBESTOS ASSESSMENT

LCP Condition Assessment and Remedial Options
January 19, 2018

Table 8-1 Summary of Remedial Action Options
GINPR, BC

| Building | Paint Description/ Condition/Quantity | Paint Lead Concentration (ppm) | Leachate Concentration (mg/L) | Remedial Action Options | Preliminary Cost Estimate | Proceed with RAP |
|-------------|---|--------------------------------------|--|---|---------------------------|---------------------|
| Mahoi House | Cream on wood panel interior walls is in good condition throughout | 3,700 | No sample collected as no discrete location was identified and the paint does not require remedial action based on condition | Manage in place | \$0 | Agree |
| | | | | Localized LCP removal from substrate | | |
| | | | | Comprehensive removal of LCP from substrate | | |
| | | | | Localized substrate removal | | |
| | | | | Comprehensive substrate removal | \$5,500 | |
| | White on wood exterior siding is generally in good condition with minor flaking and peeling in some locations - Approximately 40 m² in poor condition | 56,000 | 6.8 | Manage in place | | |
| | | | | Localized LCP removal from substrate | \$20,000 | Yes |
| | | | | Comprehensive removal of LCP from substrate | \$80,000 | |
| | | | | Localized substrate removal • Note that wood exterior siding will require disposal as lead leachable waste based on the TCLP results | \$40,000 | |
| | | | | Comprehensive substrate removal • Note that wood exterior siding will require disposal as lead leachable waste based on the TCLP results | \$50,000 | |
| | Green on wood exterior window trim is in good condition throughout | 15,000 | No sample collected as no discrete location was identified and the paint does not require remedial action based on condition | Manage in place | \$0 | Agree |
| | | | | Localized LCP removal from substrate | | |
| | | | | Comprehensive removal of LCP from substrate | \$7,000 | |
| | | | | Localized substrate removal | | |
| | | | | Comprehensive substrate removal | \$7,000 | |
| | Gold on wood exterior window frame is in good condition throughout | 42,000 | No sample collected as no discrete location was identified and the paint does not require remedial action based on condition | Manage in place | \$0 | Agree |
| | | | | Localized LCP removal from substrate | | |
| | | | | Comprehensive removal of LCP from substrate | \$7,000 | |
| | | | | Localized substrate removal | | |
| | | | | Comprehensive substrate removal | \$7,000 | |
| | White/grey on plywood exterior north deck is worn from the surface throughout - Approximately 10 m² | 1,200 | No sample collected as no discrete location was identified | Manage in place | \$0 | Agree |
| | | | | Localized LCP removal from substrate | | |
| | | | | Comprehensive removal of LCP from substrate | \$10,000 | |
| | | | | Localized substrate removal • Although it is unlikely that this material is lead leachable waste based on the lead concentration of the paint TCLP testing may be required prior to its disposal at a landfill | | |
| | | | | Comprehensive substrate removal • Although it is unlikely that this material is lead leachable waste based on the lead concentration of the paint TCLP testing may be required prior to its disposal at a landfill | \$8,000 | |

METAL BASED PAINT AND SUPPLEMENTAL ASBESTOS ASSESSMENT

LCP Condition Assessment and Remedial Options
January 19, 2018

Table 8-1 Summary of Remedial Action Options
GINPR, BC

| Building | Paint Description/ Condition/Quantity | Paint Lead Concentration (ppm) | Leachate Concentration (mg/L) | Remedial Action Options | Preliminary Cost Estimate | Proceed with RAP |
|-----------------------------------|---|--------------------------------------|---|---|---------------------------|---------------------|
| Russel Island Caretaker's Shed | White on wood exterior siding is in flaking and peeling over a significant portion of the building - Approximately 20 m² in poor condition | 1,700 | <0.40 | Manage in place | | |
| | | | | Localized LCP removal from substrate | \$12,000 | |
| | | | | Comprehensive removal of LCP from substrate | \$20,000 | |
| | | | | Localized substrate removal | \$6,000 | |
| | | | | Comprehensive substrate removal | \$10,000 | Yes |
| | Green on wood exterior trim is in good condition throughout | 2,100 | No sample collected as no discrete location was identified and the paint does not require remedial action based on condition | Manage in place | \$0 | Agree |
| | | | | Localized LCP removal from substrate | | |
| | | | | Comprehensive removal of LCP from substrate | \$7,000 | |
| | | | | Localized substrate removal | | |
| | | | | Comprehensive substrate removal | \$3,500 | |
| Russel Island Water Tower | Beige on wood exterior trim is flaking and peeling throughout - Approximately 2 m² | 1,800 | No sample collected as no discrete location was identified | Manage in place | | |
| | | | | Localized LCP removal from substrate | | |
| | | | | Comprehensive removal of LCP from substrate | \$3,500 | |
| | | | | Localized substrate removal | | |
| | | | | Comprehensive substrate removal • Although it is unlikely that this material is lead leachable waste based on the lead concentration of the paint TCLP testing may be required prior to its disposal at a landfill | \$3,500 | Yes |
| | | | | | | |
| Russel Island Generator Shed | Green on wood exterior walls is in good condition throughout | 6,500 | 1.1 | Manage in place | \$0 | Agree |
| | | | | Localized LCP removal from substrate | | |
| | | | | Comprehensive removal of LCP from substrate | \$10,000 | |
| | | | | Localized substrate removal | | |
| | | | | Comprehensive substrate removal | \$5,000 | |

NOTES:
"Leachate sampling not practical" – Indicates substrates that were either not anticipated to be removed for landfill disposal (e.g., metal, concrete); substrates that could not be removed for structural reasons (e.g., concrete floors or foundations); or paints that could not be removed in sufficient quantity to allow for leachate testing of the paint only.
"No sample collected as no discrete location was identified" – Indicates a building with heritage value where the sampling process would effectively create visible damage to the building.

Closure
January 19, 2018

9.0 CLOSURE

This report has been prepared for the sole benefit of the Parks Canada Agency. Any use which a third party makes of this report, or any reliance on decisions based on it, is the responsibility of such third parties. Stantec Consulting Ltd. accepts no responsibility for damages, if any, suffered by any third party as a result of decisions made or actions based on this report.

The information and conclusions contained in this report are based upon work undertaken by trained professionals and technical staff in accordance with generally accepted engineering, scientific and occupational health and safety practices current at the time the work was performed. Conclusions presented in this report should not be construed as legal advice.

The conclusions presented in this report represent the best technical judgment of Stantec Consulting Ltd. based on the data obtained from the work. The conclusions are based on the site conditions encountered by Stantec Consulting Ltd. at the time the work was performed at the specific assessment and/or sampling locations, and can only be extrapolated to an undefined limited area around these locations. The extent of the limited area depends on building construction and conditions, weather, building usage and other factors. Due to the nature of the investigation and the limited data available, Stantec Consulting Ltd. cannot warrant against undiscovered environmental or health and safety liabilities.

If any conditions become apparent that differ significantly from our understanding of conditions as presented in this report, we request that we be notified immediately to reassess the conclusions provided herein.

METAL BASED PAINT AND SUPPLEMENTAL ASBESTOS ASSESSMENT

Closure
January 19, 2018

We trust that the above is satisfactory for your purposes at this time. Should you have any questions or concerns, or require additional information, please do not hesitate to contact the Stantec Project Manager at your convenience.

Regards,

STANTEC CONSULTING LTD.

Keith Irwin, Dipl.Tech.
Technologist
Phone: (604) 412-3016
Keith.Irwin@stantec.com

Tiffany Waite, B.Sc.
Associate
Phone: (250) 470-4498
Tiffany.Waite@stantec.com

This report was approved for transmittal by:

Sean Brigden, B.Sc., P.B.Dipl, CRSP
Senior Associate
Phone: (250) 655-6062
Sean.Brigden@stantec.com

APPENDIX A
LABORATORY ANALYTICAL REPORT—
LEAD: PAINT CHIP ANALYSIS

**EMSL Analytical, Inc.**

6340 CastlePlace Dr., Indianapolis, IN 46250

Phone/Fax: (317) 803-2997 / (317) 803-3047

<http://www.EMSL.com>indianapolislab@emsl.com

EMSL Order: 161718958

CustomerID: JACQ30L

CustomerPO:

ProjectID:


Attn: **Keith Irwin**
Stantec Consulting, LTD
500 - 4730 Kingsway
Burnaby, BC V5H 0C6

Phone: (604) 412-3004
Fax:
Received: 10/05/17 10:00 AM
Collected:

Project: 123220964

Test Report: Lead in Paint Chips by Flame AAS (SW 846 3050B/7000B)*

| <i>Client SampleDescription</i> | <i>Collected</i> | <i>Analyzed</i> | <i>RDL</i> | <i>Lead Concentration</i> |
|---------------------------------|------------------|---|------------|---------------------------|
| GPB-PB-04 161718958-0001 | | 10/5/2017 Site: S Wall - White on Concrete Exterior Walls | 100 ppm | 110 ppm |
| GPB-PB-06 161718958-0002 | | 10/5/2017 Site: NE Exterior - Grey on Concrete Exterior Slab | 100 ppm | 700 ppm |
| GPL-PB-06 161718958-0003 | | 10/5/2017 Site: Tower Base - Cream on Metal Door | 100 ppm | 2300 ppm |
| GPL-PB-07 161718958-0004 | | 10/5/2017 Site: Tower Base - Grey on Concrete Floor | 100 ppm | 2400 ppm |
| GPH-P-06 161718958-0005 | | 10/5/2017 Site: Exterior SE Under Deck - White on Concrete Deck Edge | 2500 ppm | 37000 ppm |
| GPH-P-07 161718958-0006 | | 10/5/2017 Site: Exterior SE Deck - Red on Wood Hand Railing | 100 ppm | 2000 ppm |
| EB-PB-07 161718958-0007 | | 10/5/2017 Site: E Basement - Beige on Concrete Foundation Walls | 100 ppm | <100 ppm |
| EB-PB-08 161718958-0008 | | 10/5/2017 Site: W Basement - Grey on Structural Steel Posts & Beams | 100 ppm | 2000 ppm |
| EB-PB-00 161718958-0009 | | 10/5/2017 Site: W Basement - Red on Structural Steel Posts & Beams | 100 ppm | <100 ppm |
| EL-PB-04 161718958-0010 | | 10/5/2017 Site: Tower Base - White on Concrete Tower Footing | 100 ppm | 1100 ppm |
| EPG-PB-01 161718958-0011 | | 10/5/2017 Site: Meeting Room - White Interior Drywall | 100 ppm | 320 ppm |


Doug Wiegand, Laboratory Manager
or other approved signatory

*Analysis following Lead in Paint by EMSL SOP/Determination of Environmental Lead by FLAA. Reporting limit is 0.010 % wt based on the minimum sample weight per our SOP. Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities. Samples received in good condition unless otherwise noted. "<" (less than) result signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc. Indianapolis, IN AIHA-LAP, LLC--ELLAP 157245, OH E10040

Initial report from 10/05/2017 15:17:01

**EMSL Analytical, Inc.**

6340 CastlePlace Dr., Indianapolis, IN 46250

Phone/Fax: (317) 803-2997 / (317) 803-3047

<http://www.EMSL.com>indianapolislab@emsl.com

EMSL Order: 161718958

CustomerID: JACQ30L

CustomerPO:

ProjectID:

Attn: **Keith Irwin**
Stantec Consulting, LTD
500 - 4730 Kingsway
Burnaby, BC V5H 0C6

Phone: (604) 412-3004
Fax:
Received: 10/05/17 10:00 AM
Collected:

Project: 123220964

Test Report: Lead in Paint Chips by Flame AAS (SW 846 3050B/7000B)*

| <i>Client SampleDescription</i> | <i>Collected</i> | <i>Analyzed</i> | <i>RDL</i> | <i>Lead Concentration</i> |
|---------------------------------|------------------|---|------------|---------------------------|
| EPG-PB-02 161718958-0012 | | 10/5/2017 Site: Garage 2 - Beige Interior Drywall | 100 ppm | 860 ppm |
| EPG-PB-03 161718958-0013 | | 10/5/2017 Site: Office - Grey Interior Wood Trim | 140 ppm | <140 ppm |
| EPG-PB-04 161718958-0014 | | 10/5/2017 Site: NE Exterior - Grey Exterior Concrete Foundation Wall | 100 ppm | <100 ppm |
| GG-PB-01 161718958-0015 | | 10/5/2017 Site: Exterior - Brown Wood | 100 ppm | <100 ppm |
| MH-PB-07 161718958-0016 | | 10/5/2017 Site: N Exterior White/Grey Exterior Plywood Deck | 100 ppm | 1200 ppm |

Doug Wiegand, Laboratory Manager
or other approved signatory

*Analysis following Lead in Paint by EMSL SOP/Determination of Environmental Lead by FLAA. Reporting limit is 0.010 % wt based on the minimum sample weight per our SOP. Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities. Samples received in good condition unless otherwise noted. "<" (less than) result signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc. Indianapolis, IN AIHA-LAP, LLC--ELLAP 157245, OH E10040

Initial report from 10/05/2017 15:17:01

APPENDIX B
LABORATORY ANALYTICAL REPORT—
LEAD: TCLP

**EMSL Analytical, Inc.**

6340 CastlePlace Dr., Indianapolis, IN 46250

Phone/Fax: (317) 803-2997 / (317) 803-3047

<http://www.EMSL.com>indianapolislab@emsl.com

EMSL Order: 161718978
CustomerID: JACQ30L
CustomerPO: 123220964
ProjectID:


Attn: **Keith Irwin**
Stantec Consulting, LTD
500 - 4730 Kingsway
Burnaby, BC V5H 0C6

Phone: (604) 412-3004
Fax:
Received: 10/05/17 10:00 AM
Collected:

Project: 123220964

Test Report: Toxicity Characteristic Leaching Procedure (SW846, 1311/7420)

| <i>Client SampleDescription</i> | <i>Collected</i> | <i>Analyzed</i> | <i>RDL</i> | <i>Lead Concentration</i> |
|---------------------------------|------------------|--|------------|---------------------------|
| EL-LL-03 161718978-0001 | | 10/6/2017 Site: Tower Base - Red Steel Frame | 0.40 mg/L | 0.89 mg/L |
| MHGS-LL-01 161718978-0002 | | 10/6/2017 Site: Exterior Green Wood | 0.40 mg/L | 1.1 mg/L |
| GPH-LL-03 161718978-0003 | | 10/6/2017 Site: Exterior North - White Exterior Wood Siding | 0.40 mg/L | <0.40 mg/L |
| GPH-LL-04 161718978-0004 | | 10/6/2017 Site: Exterior SE - Grey Exterior Wood Trim | 0.40 mg/L | <0.40 mg/L |
| GPH-LL-07 161718978-0005 | | 10/6/2017 Site: Exterior SE - Red on Wood Hand Railing | 0.40 mg/L | <0.40 mg/L |
| EB-LL-02 161718978-0006 | | 10/6/2017 Site: Exterior W - White Exterior Wood Siding | 0.40 mg/L | <0.40 mg/L |
| MHCS-LL-01 161718978-0007 | | 10/6/2017 Site: Exterior NW - White Exterior Wood Siding | 0.40 mg/L | <0.40 mg/L |
| EF-LL-02 161718978-0008 | | 10/6/2017 Site: Stairs at Attic - Grey Interior Wood Trim | 0.40 mg/L | 1.4 mg/L |
| EF-LL-03 161718978-0009 | | 10/6/2017 Site: Exterior N - White Exterior Wood Siding | 0.40 mg/L | <0.40 mg/L |
| PP-LL-01 161718978-0010 | | 10/6/2017 Site: Window - White Exterior Wood Trim | 0.40 mg/L | 0.58 mg/L |
| PP-LL-02 161718978-0011 | | 10/6/2017 Site: Stairs - Grey Interior Wood Stairs | 0.40 mg/L | <0.40 mg/L |


Doug Wiegand, Laboratory Manager
or other approved signatory

This report relates only to those items tested. Samples received in good condition unless otherwise noted. Quality Control Data associated with this sample set is within acceptable limits, unless otherwise noted
Samples analyzed by EMSL Analytical, Inc. Indianapolis, IN

Initial report from 10/06/2017 16:22:14

**EMSL Analytical, Inc.**

6340 CastlePlace Dr., Indianapolis, IN 46250

Phone/Fax: (317) 803-2997 / (317) 803-3047

<http://www.EMSL.com>indianapolislaboratory@emsl.com

EMSL Order: 161718978
CustomerID: JACQ30L
CustomerPO: 123220964
ProjectID:

Attn: **Keith Irwin**
Stantec Consulting, LTD
500 - 4730 Kingsway
Burnaby, BC V5H 0C6

Phone: (604) 412-3004
Fax:
Received: 10/05/17 10:00 AM
Collected:

Project: **123220964****Test Report: Toxicity Characteristic Leaching Procedure (SW846, 1311/7420)**

| <i>Client SampleDescription</i> | <i>Collected</i> | <i>Analyzed</i> | <i>RDL</i> | <i>Lead Concentration</i> |
|---------------------------------|------------------|---|------------|---------------------------|
| PP-LL-04 161718978-0012 | | 10/6/2017 Site: Light Tower Exterior - Red Exterior Wood | 0.40 mg/L | 2.9 mg/L |
| MH-LL-03 161718978-0013 | | 10/6/2017 Site: Exterior SE - White Exterior Wood Siding | 0.40 mg/L | 6.8 mg/L |

Doug Wiegand, Laboratory Manager
or other approved signatory

This report relates only to those items tested. Samples received in good condition unless otherwise noted. Quality Control Data associated with this sample set is within acceptable limits, unless otherwise noted

Samples analyzed by EMSL Analytical, Inc. Indianapolis, IN

Initial report from 10/06/2017 16:22:14

APPENDIX C
LABORATORY ANALYTICAL REPORT—
ASBESTOS: BULK MATERIAL ANALYSIS



EMSL Canada Inc.

4506 Dawson Street Burnaby, BC V5C 4C1
 Phone/Fax: 604-757-3158 / (604) 757-4731
<http://www.EMSL.com> / vancouverlab@EMSL.com

EMSL Canada Order 691702357
 Customer ID: 55JACQ30L
 Customer PO:
 Project ID:

Attn: Keith Irwin
 Stantec Consulting, Ltd.
 500 - 4730 Kingsway
 Burnaby, BC V5H 0C6

Phone: (604) 412-3004
Fax:
Collected:
Received: 10/04/2017
Analyzed: 10/05/2017

Proj: 123220964 - GEORGINA POINT WEATHER STATION, MAHOI HOUSE CARETAKERS SHED, EAST POINT GARAGE

Test Report: Asbestos Analysis in Bulk Material for Occupational Health and Safety British Columbia Regulation 188/2011 via EPA 600/R-93/116 Method

Client Sample ID: GPB-VFT-01 **Lab Sample ID:** 691702357-0001

Sample Description: BLACK FLOOR TILE MASTIC/WEATHER ROOM

| TEST | Analyzed | Color | Non-Asbestos | | Asbestos | Comment |
|-------------------------|------------|-------|--------------|-------------|-------------------|---------|
| | Date | | Fibrous | Non-Fibrous | | |
| 400 PLM PtCt Grav. Red. | 10/05/2017 | Brown | 0.0% | 100% | <0.25% Chrysotile | |

Client Sample ID: MHCS-CP-01 **Lab Sample ID:** 691702357-0002

Sample Description: CEMENT PANEL/NORTHWEST EXTERIOR

| TEST | Analyzed | Color | Non-Asbestos | | Asbestos | Comment |
|------|------------|-------|--------------|-------------|----------------|---------|
| | Date | | Fibrous | Non-Fibrous | | |
| PLM | 10/05/2017 | Gray | 0% | 80% | 20% Chrysotile | |

Client Sample ID: EPG-DJC-01A **Lab Sample ID:** 691702357-0003

Sample Description: DRYWALL JOINT COMPOUND/GARAGE 1

| TEST | Analyzed | Color | Non-Asbestos | | Asbestos | Comment |
|------|------------|-------|--------------|-------------|---------------|---------|
| | Date | | Fibrous | Non-Fibrous | | |
| PLM | 10/05/2017 | White | 0% | 100% | None Detected | |

Client Sample ID: EPG-DJC-01B **Lab Sample ID:** 691702357-0004

Sample Description: DRYWALL JOINT COMPOUND/GARAGE 2

| TEST | Analyzed | Color | Non-Asbestos | | Asbestos | Comment |
|------|------------|-------|--------------|-------------|---------------|---------|
| | Date | | Fibrous | Non-Fibrous | | |
| PLM | 10/05/2017 | White | 0% | 100% | None Detected | |

Client Sample ID: EPG-DJC-01C **Lab Sample ID:** 691702357-0005

Sample Description: DRYWALL JOINT COMPOUND/GARAGE 3

| TEST | Analyzed | Color | Non-Asbestos | | Asbestos | Comment |
|------|------------|-------|--------------|-------------|---------------|---------|
| | Date | | Fibrous | Non-Fibrous | | |
| PLM | 10/05/2017 | White | 0% | 100% | None Detected | |

Client Sample ID: EPG-WPC-01A **Lab Sample ID:** 691702357-0006

Sample Description: BLACK WINDOW PANE CAULKING/OFFICE

| TEST | Analyzed | Color | Non-Asbestos | | Asbestos | Comment |
|---------------------|------------|-------|--------------|-------------|------------------|---------|
| | Date | | Fibrous | Non-Fibrous | | |
| PLM Grav. Reduction | 10/05/2017 | Black | 0.0% | 99.3% | 0.72% Chrysotile | |

Client Sample ID: EPG-WPC-01B **Lab Sample ID:** 691702357-0007

Sample Description: BLACK WINDOW PANE CAULKING/MEETING ROOM

| TEST | Analyzed | Color | Non-Asbestos | | Asbestos | Comment |
|---------------------|------------|-------|--------------|-------------|----------|------------------------------|
| | Date | | Fibrous | Non-Fibrous | | |
| PLM Grav. Reduction | 10/05/2017 | | | | | Positive Stop (Not Analyzed) |



EMSL Canada Inc.

4506 Dawson Street Burnaby, BC V5C 4C1
Phone/Fax: 604-757-3158 / (604) 757-4731
<http://www.EMSL.com> / vancouverlab@EMSL.com

EMSL Canada Order 691702357
Customer ID: 55JACQ30L
Customer PO:
Project ID:

Test Report: Asbestos Analysis in Bulk Material for Occupational Health and Safety British Columbia Regulation 188/2011 via EPA 600/R-93/116 Method

Client Sample ID: EPG-WPC-01C

Lab Sample ID: 691702357-0008

Sample Description: BLACK WINDOW PANE CAULKING/OFFICE

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|---------------------|------------------|-------|--------------|-------------|------------------------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM Grav. Reduction | 10/05/2017 | | | | Positive Stop (Not Analyzed) | |

Analyst(s):

Kathleen Cruz PLM (4)
400 PLM PtCt Grav. Red (1)
PLM Grav. Reduction (1)

Reviewed and approved by:

Nicole Yeo, Laboratory Manager
or Other Approved Signatory

None Detected = <0.1%. EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. Samples received in good condition unless otherwise noted. This report must not be used to claim product endorsement by NVLAP of any agency of the U.S. Government.

Samples analyzed by EMSL Canada Inc. Burnaby, BC

Initial report from: 10/06/2017 09:36:43