



4	⊿ .				
		:	$\bigtriangleup$	$\therefore$	
		•••			
	EXISTING CONCRETE				
	PILE CA	P AND	DEC	K	




- 1. THICKNESS AND REINFORCING OF EXISTING SLAB AND TRENCH IS UNKNOWN.
- 2. MINIMUM 400mm LENGTH OF TRANSVERSE REINFORCING TO REMAIN IN PLACE. DAMAGED TRANSVERSE REBAR TO BE REPLACED WITH NEW 10M DOWELS INSTALLED WITH HILTI HY200 EPOXY AND 150mm EMBEDMENT (SPACING OF DOWELS TO MATCH EXISTING REBAR).
- SECTION EXISTING TRENCH REMOVALS























ot Scale: