



REVISED

Asbestos Reassessment

CCGS Limnos
Vessel Number 328088
370 Dalhousie Street,
Amherstburg, Ontario

Prepared for:

Canadian Coast Guard
520 Exmouth Street
Sarnia, Ontario, N7T 8B1

Attention: Leslie Anne Veldman
Project Officer, Marine Engineering, Central and Arctic

July 16, 2019

Pinchin File: 241027



Asbestos Reassessment

Vessel Number 328088, 370 Dalhousie Street, Amherstburg, Ontario
Canadian Coast Guard

July 16, 2019
Pinchin File: 241027
REVISED

Issued to: Canadian Coast Guard
Contact: Leslie Anne Veldman
Project Officer, Marine Engineering, Central and Artic
Issued on: July 16, 2019
Pinchin File: 241027
Issuing Office: Tilbury, ON
Pinchin Contact: Graham Rogers
519.682.4492 ext. 3302
grogers@pinchin.com

Author:

Dylan Melo, B.Sc.
Project Technologist
519.682.4492 ext. 3307
dmelo@pinchin.com

Reviewer:

Tina Manning, CRSP, PMP, LEED AP
Operations Manager
519.682.4492 ext. 3301
tmanning@pinchin.com



EXECUTIVE SUMMARY

Canadian Coast Guard (Client) retained Pinchin Ltd. (Pinchin) to conduct an asbestos building materials reassessment in the CCGS Limnos docked at 370 Dalhousie Street, Amherstburg, Ontario. The reassessment was performed on May 13, 2019. Pinchin collected additional samples on July 2, 2019 when the vessel was docked at Hamilton Harbour, 47 Discovery Drive, Hamilton, Ontario.

The objective of the reassessment was to evaluate the condition and quantity of previously reported asbestos-containing materials (ACM), and develop corrective action plans as required for the purposes of long term management. The results of this assessment are not intended for construction, renovation, demolition or project tendering purposes.

The assessed area consisted of the entire vessel, excluding the exterior finishes, as shown on the drawings in Appendix I.

SUMMARY OF FINDINGS

Asbestos-containing materials (ACM) are present as follows:

- 9"x9" beige vinyl floor tiles with a brown fleck pattern in the Corridor and Boot Room Old Incinerator Room (Locations 3 and 31), observed in good condition.
- Transite cement paneling behind the electrical panel in the Wheelhouse (Location 1).

SUMMARY OF RECOMMENDATIONS

The following is a summary of significant recommendations; refer to the body of the report for detailed recommendations.

1. Prepare an Asbestos Management program (AMP).
2. Perform a reassessment of asbestos materials on an annual basis.
3. Prior to renovations or demolition, perform a pre-construction assessment to identify any hazardous materials that may be disturbed by the work.
4. Follow appropriate safe work procedures when handling or disturbing asbestos.

This Executive Summary is subject to the same standard limitations as contained in the report and must be read in conjunction with the entire report.



TABLE OF CONTENTS

| | | |
|------|--|----|
| 1.0 | INTRODUCTION AND SCOPE | 1 |
| 1.1 | Scope of Assessment..... | 1 |
| 2.0 | BACKGROUND INFORMATION | 1 |
| 2.1 | Vessel Description | 1 |
| 2.2 | Existing Reports and Summary of Asbestos Abatement | 2 |
| 3.0 | FINDINGS | 3 |
| 3.1 | Spray-Applied Insulation..... | 3 |
| 3.2 | Texture Finishes (Decorative) | 3 |
| 3.3 | Pipe Insulation | 3 |
| 3.4 | Duct Insulation and Mastic | 4 |
| 3.5 | Mechanical Equipment Insulation..... | 4 |
| 3.6 | Vermiculite | 5 |
| 3.7 | Acoustic Ceiling Tiles | 5 |
| 3.8 | Plaster..... | 5 |
| 3.9 | Drywall Joint Compound..... | 5 |
| 3.10 | Asbestos Cement Products (Transite) | 5 |
| 3.11 | Vinyl Sheet Flooring | 6 |
| 3.12 | Vinyl Floor Tile and Mastic | 6 |
| 3.13 | Firestopping..... | 7 |
| 3.14 | Levelling Compound..... | 7 |
| 3.15 | Sealants, Caulking, and Putty | 7 |
| 3.16 | Paper and Textile Products | 8 |
| 3.17 | Other Building Materials | 8 |
| 3.18 | Presumed Asbestos Materials..... | 9 |
| 4.0 | RECOMMENDATIONS..... | 10 |
| 4.1 | General | 10 |
| 4.2 | On-going Management and Maintenance | 10 |
| 5.0 | TERMS AND LIMITATIONS | 10 |
| 6.0 | REFERENCES..... | 10 |

APPENDICES

| | |
|---------------|------------------------------------|
| APPENDIX I | Drawings |
| APPENDIX II | Asbestos Analytical Certificates |
| APPENDIX III | Methodology |
| APPENDIX IV | Additional Photographs |
| APPENDIX V | Location Summary Report |
| APPENDIX VI | Asbestos Material Summary Report |
| APPENDIX VII | All Data Report |
| APPENDIX VIII | TEM Air Sample Lab Analysis Report |



1.0 INTRODUCTION AND SCOPE

Canadian Coast Guard (Client) retained Pinchin Ltd. (Pinchin) to conduct an asbestos building materials reassessment in the CCGS Limnos docked at 370 Dalhousie Street, Amherstburg, Ontario. Pinchin collected additional samples on July 2, 2019 when the vessel was docked at Hamilton Harbour, 47 Discovery Drive, Hamilton, Ontario.

The reassessment was performed by Dylan Melo, B.Sc., Project Technologist on May 13, 2019 and the additional sample collection was completed by Stephen Holmquist on July 2, 2019. The surveyor was accompanied by Leslie Veldman during the assessment. The vessel was occupied at the time of the assessment.

The objectives of the reassessment were to document the locations, quantities and conditions of previously identified asbestos containing building materials, and develop corrective action plans as required. This reassessment is only to be used for the purposes of long term management and routine maintenance. The results of this reassessment are not to be used for construction, renovation, demolition or project tendering purposes.

1.1 Scope of Assessment

The objective of the reassessment was to evaluate the condition and quantity of previously reported asbestos-containing materials (ACM), and develop corrective action plans as required.

Additional objectives included the following:

- Document any asbestos abatement that was performed since the last assessment.
- Collect additional samples as necessary to comply with provincial sampling requirements
- Collect three occupied air samples (and one field blank) for Phase Contrast Microscopy (PCM) and Transmission Electron Microscopy (TEM) analysis. Locations of air samples were indicated by the Client; and shown on the attached drawing.

Please refer to Appendix III for a detailed description of the methodology used for this assessment.

Please refer to Appendix VIII for the TEM air sample lab analysis report.

2.0 BACKGROUND INFORMATION

2.1 Vessel Description

| Description Item | Details |
|------------------|--------------------|
| Use | Coast Guard vessel |



| Description Item | Details |
|----------------------|--|
| Number of Floors | The vessel is 3 stories plus 1 levels below. |
| Total Area | The total assessed area is approximately 5000 square feet. |
| Year of Construction | The vessel was constructed in 1968. |
| Structure | Metal |
| Exterior Cladding | Metal |
| HVAC | N/A |
| Roof | N/A |
| Flooring | Vinyl floor tiles, vinyl sheet flooring, ceramic tile, metal, concrete, and terrazzo |
| Interior Walls | Metal, plastic, fibrous board, and wood |
| Ceilings | Metal, plastic, lay-in ceiling tiles, and wood |

2.2 Existing Reports and Summary of Asbestos Abatement

2.2.1 Review of Previous Reports

Pinchin was provided with the following reports, which have been reviewed as part of this reassessment:

- “Asbestos Materials Report Canadian Coast Guard Ship *Limnos*”, prepared March 21, 2005, Pinchin project number 28432.
- “Asbestos Materials Survey Report for Canadian Coast Guard Services, Vessel Name: CCGS *Limnos*, Vessel NO:328088”, prepared April 19, 2006, Pinchin project number 01-6116.
- “Letter of Findings from Investigation in Mechanical Room on a Canadian Coast Guard *Limnos Ship*”, August 11, 2006, Pinchin project number 36403.

2.2.2 Summary of Asbestos Abatement since the Previous Assessment

Abatement work has been completed since the last assessment. Based on observations made during the reassessment, the following abatement work has been conducted, since completion of the previous report:

- Approximately 500 square feet of the 9”x9” beige vinyl floor tiles with a white stripes pattern (previous sample 0001, lab report reference 2556478-2556450), from Locations 1, 2, 26, 29.



- Approximately five parging cement pipe fittings from the Utility Locker (Location 16).
- Door with mag-block insulation (samples 0005A-C, lab report reference 2556490-2556492) from the Showers and Washroom (Location 20).
- A fire door, containing amosite asbestos core, was reported as being removed in previous 2005 report.

3.0 FINDINGS

The following section summarizes the findings of the reassessment and provides a general description of the asbestos materials identified and their locations.

For details on quantities, condition and locations of ACM; refer to the Asbestos Material Summary Report and All Data Report in Appendix VI and VII.

Refer to the drawing in Appendix I for the locations of all known ACMs indicated via hatching or symbols. The locations of samples from both the current assessment, and historical assessments performed by Pinchin, have been included on the drawings.

Appendix II presents the asbestos bulk sample analytical results.

3.1 Spray-Applied Insulation

Spray applied insulation was not observed during the assessment.

3.2 Texture Finishes (Decorative)

No texture finishes were observed during the assessment.

3.3 Pipe Insulation

Parging cement, containing chrysotile asbestos (sample 0004A-C, lab report reference 2556487-2556489), was previously noted on the fittings (elbows, tees, valves, hangers, etc.) in the Utility Locker and Dry Storage Area (Location 16). Parging cement was not observed during this assessment.

All observed piping was either uninsulated, or are insulated with fibreglass, or other non-asbestos insulation such as mineral fibre or elastomeric foam insulation (Armaflex).

Pipes insulated with friable asbestos insulations may be present in inaccessible spaces such as above solid ceilings, in chases, in column enclosures and within shafts.



Uninsulated piping Utility and Dry storage Area (Location 16)

3.4 Duct Insulation and Mastic

All observed ducting was either uninsulated or insulated with non-asbestos fibreglass (foil-faced or canvas) and Armaflex.

The white lagging compound covering the canvas and fiberglass on ductwork in the Engine Room (Location 29) was sampled and does not contain asbestos (sample S0016A-C, lab reference 71912988).

The client identified yellow suspect insulation covering the fiberglass on ductwork in the Engine Room (Location 29) was sampled and does not contain asbestos (sample S0017A-C, lab reference 71912988)



Client identified lagging compound and suspect insulation.

3.5 Mechanical Equipment Insulation

Mechanical equipment is either uninsulated or insulated with non-asbestos fibreglass.

3.6 Vermiculite

Loose fill vermiculite debris was not observed in the spaces or areas inspected. Destructive testing was not performed and vermiculite may be present within masonry block walls, above solid ceilings or other void spaces.

3.7 Acoustic Ceiling Tiles

Acoustic ceiling tile are present in the assessed area, as follows:

| Size, Type, Pattern | Location Name (Location #); Quantity | Sample Number or Date Code | Asbestos Type |
|------------------------------------|--------------------------------------|--|---------------|
| 24"x48", white fissured | Engine Room (Location 29) | 0006-C, lab report reference 2556493-2556495 | None Detected |
| 24"x48", white with small pinholes | Corridor (Location 17) | S0018A-C, lab reference 71912988 | None Detected |

3.8 Plaster


Plaster was not observed in the assessed area.

3.9 Drywall Joint Compound

Drywall and joint compound was not observed during the assessment.

3.10 Asbestos Cement Products (Transite)

Transite cement board, containing chrysotile asbestos (samples S0021A-C, lab reference 71912988), is present behind the electrical panel in the Wheel House (Location 1). Transite is a non-friable material and was observed in good condition.



Asbestos-containing transite

**Asbestos Reassessment**

Vessel Number 328088, 370 Dalhousie Street, Amherstburg, Ontario
Canadian Coast Guard

July 16, 2019
Pinchin File: 241027
REVISED

3.11 Vinyl Sheet Flooring

Vinyl sheet flooring is present in the vessel as follows:

| Pattern, Colour | Location Name (Location #); Quantity | Sample Number | Asbestos Type |
|--|--|-----------------------------------|---------------|
| Grey with grey and white smear pattern | Scientists and Officer Mess (Location 19) | S0010 A-C, lab reference 71912988 | None Detected |
| Faux brick pattern | Utility Locker and Dry Storage (Location 16) | S0009 A-C, lab reference 71912988 | None Detected |
| Orange | Crew's Mess (Location 21) | Client installed in last 10 years | N/A |

3.12 Vinyl Floor Tile and Mastic

Vinyl floor tiles are present as follows:

| Size, Pattern, Colour | Location Name (Location #); Quantity | Sample Number | Asbestos Type (tile) | Asbestos Type (mastic) |
|-------------------------------------|---|---|----------------------|------------------------|
| 9"x9" beige with brown speck | Corridor (Location 3) – 200SF Boot Room Old Incinerator Room (Location 31) – 10 SF | 0003A-C; lab report reference 25566484-25564686). | Chrysotile | None Detected |
| 12"x12" off-white with brown streak | Focle Deck (Location 32) | S0011 A-C, lab reference 71912988 | None Detected | None Detected |

The asbestos-containing vinyl floor tiles are a non-friable material and were observed in good condition.



Asbestos-containing 9"x9" beige vinyl floor tiles; depicting painted and not painted conditions.

3.13 Firestopping

The red firestopping sealant covering the pipe and conduit penetrations throughout the vessel was sampled and does not contain asbestos (samples S0013A-C; lab report reference 71912988).



Non-asbestos red fire stopping


3.14 Levelling Compound

Levelling compound is often used in random and isolated areas and without removing all flooring may not always be detected.


3.15 Sealants, Caulking, and Putty

The following table presents a summary of caulking, sealants and putties present:

| Material and Colour | Location (Location #) | Quantity | Sample Number | Asbestos Type |
|---------------------|--|----------|---|---------------|
| Caulking, brown | Window frames in the Lab (Location 6) | 80 LF | S0014A-C, lab report reference 71912988 | None Detected |
| Caulking, white | Window frames in the Engine Room (Location 29) | 80 LF | S0015A-C, lab report reference 71912988 | None Detected |



Non-asbestos brown window caulking.



Non-asbestos white window caulking.

3.16 Paper and Textile Products

Fibrous board (millboard), containing amosite and chrysotile asbestos (previous samples 0007A-C; lab report reference 2556496-2556498), previously noted in the Engine Room (Location 29) was abated and no longer exists in the vessel. New plastic wall panelling was observed in the Engine Room (Location 29).

The laminate fibreboard present on the walls in the Diesel Generator Room (Location 30) and in the Lamp Locker (Locations 33) was sampled and does not contain asbestos (sample S022A-C, lab report reference B213116).

3.17 Other Building Materials

The black antisweat mastic present on the underside of the sink in the Lab (Location 6) was sampled and does not contain asbestos (samples S0008A-C, lab report reference 71912988).

The core insulation present inside both the A and B fire doors throughout the vessel was sampled and does not contain asbestos (samples S0019A-C, lab report reference 71912988).

Both the 1/2" and 1/8" cable insulation present throughout the vessel was sampled and do not contain asbestos (samples S0012A-C and S0020A-C, lab report reference 71912988).

The white mineral fibre insulation present on the structure of the vessel was previously sampled and does not contain asbestos (samples 0002A-C, lab report reference 25566481-2556883).



Non-asbestos black sink mastic.

3.18 Presumed Asbestos Materials

The methodology identifies a list of materials which may contain asbestos, which were not to be sampled, based on limitations of the scope. The following is a list of materials which may contain asbestos, which were not observed during the assessment, but based on site conditions may be present. If discovered, these materials are presumed to contain asbestos until otherwise proven by sampling and analysis:

- Floor levelling compound
- Ceramic tile setting compound
- Electrical components
- Refractory materials and insulations in boilers, incinerators and stacks
- Insulation under metal clad boilers and vessels
- Mechanical packing, ropes and gaskets
- Vermiculite in wall and ceiling cavities
- Fibre-reinforced paints and coatings
- Metal clad finishes
- Materials outside the assessed area



4.0 RECOMMENDATIONS

4.1 General

Perform a detailed intrusive assessment prior to building renovation or demolition operations. The assessment should include; destructive testing (i.e. coring and/or removal of building finishes and components), sampling of other hazardous materials (lead, mercury, PCBs, mould, etc.), and materials not tested in this study (i.e. roofing materials, caulking, mastics).

4.2 On-going Management and Maintenance

The following recommendations are made regarding on-going management and maintenance work involving the asbestos materials identified:

- Prepare an Asbestos Management program (AMP). The AMP should address and document; written work practices, worker training requirements, notifications, policies and responsibilities.
- Perform a reassessment of asbestos materials on an annual basis.
- Remove asbestos-containing materials (ACM) prior to alteration or maintenance work if ACM may be disturbed by the work. Follow appropriate asbestos precautions for the classification of work being performed.
- Update the asbestos inventory report for the building upon completion of any abatement of ACM.

5.0 TERMS AND LIMITATIONS

This work was performed subject to the Terms and Limitations presented or referenced in the proposal for this project.

Information provided by Pinchin is intended for Client use only. Pinchin will not provide results or information to any party unless disclosure by Pinchin is required by law. Any use by a third party of reports or documents authored by Pinchin or any reliance by a third party on or decisions made by a third party based on the findings described in said documents, is the sole responsibility of such third parties. Pinchin accepts no responsibility for damages suffered by any third party as a result of decisions made or actions conducted. No other warranties are implied or expressed.

6.0 REFERENCES

The following legislation and documents were referenced in completing the assessment and this report:

Federal

1. Canada Occupational Health and Safety Regulation, SOR/86-304.



Asbestos Reassessment

Vessel Number 328088, 370 Dalhousie Street, Amherstburg, Ontario
Canadian Coast Guard

July 16, 2019
Pinchin File: 241027
REVISED


Ontario

1. Asbestos on Construction Projects and in Buildings and Repair Operations, Ontario Regulation 278/05.
2. Designated Substances, Ontario Regulation 490/09.

J:\241000s\0241027.000 CanadianCoastGuard,CCGSLimnos,HAZ,REASST\Deliverables\241027 CGS Limno Vessel Asbestos Reassessment Report, June 2019.docx

Template: Master Report for Asbestos Reassessment, HAZ, April 23, 2019

APPENDIX I
Drawings




- LEGEND:
- PINCHIN LOCATION NUMBER
 - ASBESTOS BULK SAMPLE
 - AIR SAMPLE LOCATION
 - ACM VINYL FLOOR TILES
 - ACM TRANSITE PANEL

NOT ALL KNOWN OR SUSPECTED HAZARDOUS BUILDING MATERIALS MAY BE DEPICTED ON THE DRAWING. REFER TO THE HAZARDOUS BUILDING MATERIALS ASSESSMENT REPORT FOR A COMPLETE LIST OF KNOWN AND SUSPECTED HAZARDOUS BUILDING MATERIALS.

LEGEND IS COLOUR DEPENDENT. NON-COLOUR COPIES MAY ALTER INTERPRETATION.

BASE PLAN PROVIDED BY CLIENT.

| | | | |
|-------------|------------|--|--------|
| CLIENT: | | CCGS LIMNOS VESSEL 328088 | |
| LOCATION: | | 370 DALHOUSIE ST. AMHERSTBURG, ONTARIO | |
| TITLE: | | ASBESTOS REASSESSMENT SHIP OVERVIEW | |
| DATE: | 2019/05/29 | PROJECT # : | 241027 |
| DRAWN BY: | DM | 1 OF 5 | |
| CHECKED BY: | TM | | |
| SCALE: | NTS | | |



- LEGEND:
- PINCHIN LOCATION NUMBER
 - ASBESTOS BULK SAMPLE
 - AIR SAMPLE LOCATION
 - ACM VINYL FLOOR TILES
 - ACM TRANSITE PANEL

NOT ALL KNOWN OR SUSPECTED HAZARDOUS BUILDING MATERIALS MAY BE DEPICTED ON THE DRAWING. REFER TO THE HAZARDOUS BUILDING MATERIALS ASSESSMENT REPORT FOR A COMPLETE LIST OF KNOWN AND SUSPECTED HAZARDOUS BUILDING MATERIALS.

LEGEND IS COLOUR DEPENDENT. NON-COLOUR COPIES MAY ALTER INTERPRETATION.

BASE PLAN PROVIDED BY CLIENT.


CLIENT: CCGS
LIMNOS
VESSEL 328088






LOCATION: 370 DALHOUSIE ST.
AMHERSTBURG, ONTARIO

TITLE: ASBESTOS REASSESSMENT

BRIDGE/ WHEELHOUSE

| | |
|---------------------|------------------------|
| DATE: 2019/05/29 | PROJECT # : 241027 |
| DRAWN BY: DM | DRAWING: 2 OF 5 |
| CHECKED BY: TM | |
| SCALE: NTS | |



- LEGEND:
-  PINCHIN LOCATION NUMBER
 -  ASBESTOS BULK SAMPLE
 -  AIR SAMPLE LOCATION
 -  ACM VINYL FLOOR TILES
 -  ACM TRANSITE PANEL

NOT ALL KNOWN OR SUSPECTED HAZARDOUS BUILDING MATERIALS MAY BE DEPICTED ON THE DRAWING. REFER TO THE HAZARDOUS BUILDING MATERIALS ASSESSMENT REPORT FOR A COMPLETE LIST OF KNOWN AND SUSPECTED HAZARDOUS BUILDING MATERIALS.

LEGEND IS COLOUR DEPENDENT. NON-COLOUR COPIES MAY ALTER INTERPRETATION.

BASE PLAN PROVIDED BY CLIENT.

CLIENT: CCGS
LIMNOS
VESSEL 328088

LOCATION: 370 DALHOUSIE ST.
AMHERSTBURG, ONTARIO

TITLE: ASBESTOS REASSESSMENT

FORECASTLE DECK

| | |
|---------------------|------------------------|
| DATE: 2019/05/29 | PROJECT # : 241027 |
| DRAWN BY: DM | DRAWING: 3 OF 5 |
| CHECKED BY: TM | |
| SCALE: NTS | |



LEGEND:
(X) PINCHIN LOCATION NUMBER

◎ ASBESTOS BULK SAMPLE

PCM AIR SAMPLE LOCATION

ACM VINYL FLOOR TILES

ACM TRANSITE PANEL

NOT ALL KNOWN OR SUSPECTED HAZARDOUS BUILDING MATERIALS MAY BE DEPICTED ON THE DRAWING. REFER TO THE HAZARDOUS BUILDING MATERIALS ASSESSMENT REPORT FOR A COMPLETE LIST OF KNOWN AND SUSPECTED HAZARDOUS BUILDING MATERIALS.

LEGEND IS COLOUR DEPENDENT. NON-COLOUR COPIES MAY ALTER INTERPRETATION.

BASE PLAN PROVIDED BY CLIENT.

CLIENT: CCGS
LIMNOS
VESSEL 328088

LOCATION: 370 DALHOUSIE ST.
AMHERSTBURG, ONTARIO

TITLE: ASBESTOS REASSESSMENT
MAIN DECK

DATE: 2019/05/29


PROJECT # : 241027

DRAWN BY: DM

CHECKED BY: TM

SCALE: NTS

DRAWING:
4 OF 5





- LEGEND:
- PINCHIN LOCATION NUMBER
 - ASBESTOS BULK SAMPLE
 - AIR SAMPLE LOCATION
 - ACM VINYL FLOOR TILES
 - ACM TRANSITE PANEL

NOT ALL KNOWN OR SUSPECTED HAZARDOUS BUILDING MATERIALS MAY BE DEPICTED ON THE DRAWING. REFER TO THE HAZARDOUS BUILDING MATERIALS ASSESSMENT REPORT FOR A COMPLETE LIST OF KNOWN AND SUSPECTED HAZARDOUS BUILDING MATERIALS.

LEGEND IS COLOUR DEPENDENT. NON-COLOUR COPIES MAY ALTER INTERPRETATION.

BASE PLAN PROVIDED BY CLIENT.

CLIENT: CCGS
LIMNOS
VESSEL 328088

LOCATION: 370 DALHOUSIE ST.
AMHERSTBURG, ONTARIO

TITLE: ASBESTOS REASSESSMENT

LOWER DECK

| | |
|---------------------|------------------------|
| DATE: 2019/05/29 | PROJECT # : 241027 |
| DRAWN BY: DM | DRAWING: 5 OF 5 |
| CHECKED BY: TM | |
| SCALE: NTS | |

APPENDIX II
Asbestos Analytical Certificates



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 40 CFR, Part 763, Subpart E,
App.E



Customer: Pinchin Ltd.
5 Superior Street
Tilbury, Ontario N0P 2L0

Attn: Dylan Melo
Graham Rogers
Tayler Deweerd

Lab Order ID: 71912988
Analysis ID: 71912988_PLM
Date Received: 5/15/2019
Date Reported: 5/20/2019

Project: 241027,370 Dalhousie St, Amherstburg, On,Coast Guard,CCGS Limnos

| Sample ID | Description | Asbestos | Fibrous Components | Non-Fibrous Components | Attributes |
|----------------|---|---------------|-----------------------------------|------------------------|--------------------------------------|
| Lab Sample ID | Lab Notes | | | | Treatment |
| S0008A | Mastic, Black,Loc:6,Lab | None Detected | | 100% Other | Black Non Fibrous Homogeneous |
| 71912988PLM_1 | | | | | Dissolved |
| S0008B | Mastic, Black,Loc:6,Lab | None Detected | | 100% Other | Black Non Fibrous Homogeneous |
| 71912988PLM_2 | | | | | Dissolved |
| S0008C | Mastic, Black,Loc:6,Lab | None Detected | | 100% Other | Black Non Fibrous Homogeneous |
| 71912988PLM_3 | | | | | Dissolved |
| S0009A - A | Wall Covering,Brick Pattern Vinyl Sheet Flooring,Loc:16,Utility Locke | None Detected | 20% Cellulose 10% Wollastonite | 70% Other | Brown Non Fibrous Homogeneous |
| 71912988PLM_4 | vinyl sheet flooring | | | | Ashed, Dissolved |
| S0009A - B | Wall Covering,Brick Pattern Vinyl Sheet Flooring,Loc:16,Utility Locke | None Detected | | 100% Other | Yellow Non Fibrous Homogeneous |
| 71912988PLM_43 | mastic | | | | Dissolved |
| S0009B - A | Wall Covering,Brick Pattern Vinyl Sheet Flooring,Loc:16,Utility Locke | None Detected | 20% Cellulose 10% Wollastonite | 70% Other | Brown Non Fibrous Homogeneous |
| 71912988PLM_5 | vinyl sheet flooring | | | | Ashed, Dissolved |
| S0009B - B | Wall Covering,Brick Pattern Vinyl Sheet Flooring,Loc:16,Utility Locke | None Detected | | 100% Other | Yellow Non Fibrous Homogeneous |
| 71912988PLM_44 | mastic | | | | Dissolved |
| S0009C - A | Wall Covering,Brick Pattern Vinyl Sheet Flooring,Loc:16,Utility Locke | None Detected | 20% Cellulose 10% Wollastonite | 70% Other | Brown Non Fibrous Homogeneous |
| 71912988PLM_6 | vinyl sheet flooring | | | | Ashed, Dissolved |

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Philip Szabo (51)

Analyst

Approved Signatory



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 40 CFR, Part 763, Subpart E,
App.E



Customer: Pinchin Ltd.
5 Superior Street
Tilbury, Ontario N0P 2L0

Attn: Dylan Melo
Graham Rogers
Tayler Deweerd

Lab Order ID: 71912988
Analysis ID: 71912988_PLM
Date Received: 5/15/2019
Date Reported: 5/20/2019

Project: 241027,370 Dalhousie St, Amherstburg, On,Coast Guard,CCGS Limnos

| Sample ID | Description | Asbestos | Fibrous Components | Non-Fibrous Components | Attributes |
|----------------|--|---------------|--------------------|------------------------|--------------------------------|
| Lab Sample ID | Lab Notes | | | | Treatment |
| S0009C - B | Wall Covering,Brick Pattern Vinyl Sheet Flooring,Loc:16,Utility Locke | None Detected | | 100% Other | Yellow Non Fibrous Homogeneous |
| 71912988PLM_45 | mastic | | | | Dissolved |
| S0010A - A | Vinyl Sheet Flooring,Grey With Grey And White Smear Pattern,Loc:19,Scientist &Offi | None Detected | | 100% Other | Gray Non Fibrous Homogeneous |
| 71912988PLM_7 | vinyl sheet flooring | | | | Ashed, Dissolved |
| S0010A - B | Vinyl Sheet Flooring,Grey With Grey And White Smear Pattern,Loc:19,Scientist &Offi | None Detected | | 100% Other | Yellow Non Fibrous Homogeneous |
| 71912988PLM_46 | mastic | | | | Dissolved |
| S0010B - A | Vinyl Sheet Flooring,Grey With Grey And White Smear Pattern,Loc:19,Scientist &Offi | None Detected | | 100% Other | Gray Non Fibrous Homogeneous |
| 71912988PLM_8 | vinyl sheet flooring | | | | Ashed, Dissolved |
| S0010B - B | Vinyl Sheet Flooring,Grey With Grey And White Smear Pattern,Loc:19,Scientist &Offi | None Detected | | 100% Other | Yellow Non Fibrous Homogeneous |
| 71912988PLM_47 | mastic | | | | Dissolved |
| S0010C - A | Vinyl Sheet Flooring,Grey With Grey And White Smear Pattern,Loc:19,Scientist &Offi | None Detected | | 100% Other | Gray Non Fibrous Homogeneous |
| 71912988PLM_9 | vinyl sheet flooring | | | | Ashed, Dissolved |
| S0010C - B | Vinyl Sheet Flooring,Grey With Grey And White Smear Pattern,Loc:19,Scientist &Offi | None Detected | | 100% Other | Yellow Non Fibrous Homogeneous |
| 71912988PLM_48 | mastic | | | | Dissolved |
| S0011A - A | Vinyl Floor Tile And Mastic, 12"x 12" Off White With Brown Streak Pattern, Loc:32, | None Detected | | 100% Other | White Non Fibrous Homogeneous |
| 71912988PLM_10 | tile | | | | Dissolved |

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Philip Szabo (51)

Analyst

Approved Signatory



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 40 CFR, Part 763, Subpart E,
App.E



Customer: Pinchin Ltd.
5 Superior Street
Tilbury, Ontario N0P 2L0

Attn: Dylan Melo
Graham Rogers
Tayler Deweerd

Lab Order ID: 71912988
Analysis ID: 71912988_PLM
Date Received: 5/15/2019
Date Reported: 5/20/2019

Project: 241027,370 Dalhousie St, Amherstburg, On,Coast Guard,CCGS Limnos

| Sample ID | Description | Asbestos | Fibrous Components | Non-Fibrous Components | Attributes |
|----------------|--|---------------|--------------------|------------------------|--------------------------------------|
| Lab Sample ID | Lab Notes | | | | Treatment |
| S0011A - B | Vinyl Floor Tile And Mastic, 12"x 12" Off White With Brown Streak Pattern, Loc:32, | None Detected | | 100% Other | Yellow Non Fibrous Homogeneous |
| 71912988PLM_49 | mastic | | | | Dissolved |
| S0011B - A | Vinyl Floor Tile And Mastic, 12"x 12" Off White With Brown Streak Pattern, Loc:32, | None Detected | | 100% Other | White Non Fibrous Homogeneous |
| 71912988PLM_11 | tile | | | | Dissolved |
| S0011B - B | Vinyl Floor Tile And Mastic, 12"x 12" Off White With Brown Streak Pattern, Loc:32, | None Detected | | 100% Other | Yellow Non Fibrous Homogeneous |
| 71912988PLM_50 | mastic | | | | Dissolved |
| S0011C - A | Vinyl Floor Tile And Mastic, 12"x 12" Off White With Brown Streak Pattern, Loc:32, | None Detected | | 100% Other | White Non Fibrous Homogeneous |
| 71912988PLM_12 | tile - ashed | | | | Ashed, Dissolved |
| S0011C - B | Vinyl Floor Tile And Mastic, 12"x 12" Off White With Brown Streak Pattern, Loc:32, | None Detected | | 100% Other | Yellow Non Fibrous Homogeneous |
| 71912988PLM_51 | mastic | | | | Dissolved |
| S0012A | 1/2" Cable,Loc:3,Corridor | None Detected | 10% Cellulose | 90% Other | Black Non Fibrous Homogeneous |
| 71912988PLM_13 | | | | | Dissolved |
| S0012B | 1/2" Cable,Loc:3,Corridor | None Detected | 10% Cellulose | 90% Other | Black Non Fibrous Homogeneous |
| 71912988PLM_14 | | | | | Dissolved |
| S0012C | 1/2" Cable,Loc:3,Corridor | None Detected | 10% Cellulose | 90% Other | Black Non Fibrous Homogeneous |
| 71912988PLM_15 | | | | | Dissolved |

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Philip Szabo (51)

Analyst

Approved Signatory



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 40 CFR, Part 763, Subpart E,
App.E



Customer: Pinchin Ltd.
5 Superior Street
Tilbury, Ontario N0P 2L0

Attn: Dylan Melo
Graham Rogers
Tayler Deweerd

Lab Order ID: 71912988
Analysis ID: 71912988_PLM
Date Received: 5/15/2019
Date Reported: 5/20/2019

Project: 241027,370 Dalhousie St, Amherstburg, On,Coast Guard,CCGS Limnos

| Sample ID | Description | Asbestos | Fibrous Components | Non-Fibrous Components | Attributes |
|----------------|---|---------------|--------------------|------------------------|-------------------------------|
| Lab Sample ID | Lab Notes | | | | Treatment |
| S0013A | Firestopping Red (mastic),Loc:16,Utility Locker And dry Storage | None Detected | 5% Fiber Glass | 95% Other | Red Non Fibrous Homogeneous |
| 71912988PLM_16 | | | | | Ashed, Dissolved |
| S0013B | Firestopping Red (mastic),Loc:1,Wheel House | None Detected | 5% Fiber Glass | 95% Other | Red Non Fibrous Homogeneous |
| 71912988PLM_17 | | | | | Ashed, Dissolved |
| S0013C | Firestopping Red (mastic),Loc:3,Corridor | None Detected | 5% Fiber Glass | 95% Other | Red Non Fibrous Homogeneous |
| 71912988PLM_18 | | | | | Ashed, Dissolved |
| S0014A | Brown Window Caulking,Loc:6,Lab | None Detected | | 100% Other | Brown Non Fibrous Homogeneous |
| 71912988PLM_19 | | | | | Ashed, Dissolved |
| S0014B | Brown Window Caulking,Loc:6,Lab | None Detected | | 100% Other | Brown Non Fibrous Homogeneous |
| 71912988PLM_20 | | | | | Ashed, Dissolved |
| S0014C | Brown Window Caulking,Loc:6,Lab | None Detected | | 100% Other | Brown Non Fibrous Homogeneous |
| 71912988PLM_21 | | | | | Ashed, Dissolved |
| S0015A | White Window Caulking,Loc:29,Engine Room | None Detected | | 100% Other | White Non Fibrous Homogeneous |
| 71912988PLM_22 | | | | | Ashed, Dissolved |
| S0015B | White Window Caulking,Loc:29,Engine Room | None Detected | | 100% Other | White Non Fibrous Homogeneous |
| 71912988PLM_23 | | | | | Ashed, Dissolved |

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAL. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Philip Szabo (51)

Analyst

Approved Signatory



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 40 CFR, Part 763, Subpart E,
App.E



Customer: Pinchin Ltd.
5 Superior Street
Tilbury, Ontario N0P 2L0

Attn: Dylan Melo
Graham Rogers
Tayler Deweerd

Lab Order ID: 71912988
Analysis ID: 71912988_PLM
Date Received: 5/15/2019
Date Reported: 5/20/2019

Project: 241027,370 Dalhousie St, Amherstburg, On,Coast Guard,CCGS Limnos

| Sample ID | Description | Asbestos | Fibrous Components | Non-Fibrous Components | Attributes |
|----------------|---|---------------|-----------------------------------|--------------------------|-------------------------------|
| Lab Sample ID | Lab Notes | | | | Treatment |
| S0015C | White Window Caulking, Loc:29, Engine Room | None Detected | | 100% Other | White Non Fibrous Homogeneous |
| 71912988PLM_24 | | | | | Ashed, Dissolved |
| S0016A | Lagging Compound on Ductwork, Loc:29, Engine Room | None Detected | 95% Fiber Glass | 5% Other | White Fibrous Homogeneous |
| 71912988PLM_25 | | | | | Teased, Dissolved |
| S0016B | Lagging Compound on Ductwork, Loc:29, Engine Room | None Detected | 95% Fiber Glass | 5% Other | White Fibrous Homogeneous |
| 71912988PLM_26 | | | | | Teased, Dissolved |
| S0016C | Lagging Compound on Ductwork, Loc:29, Engine Room | None Detected | 95% Fiber Glass | 5% Other | White Fibrous Homogeneous |
| 71912988PLM_27 | | | | | Teased, Dissolved |
| S0017A | Client Identified Yellow Suspect Insulation, Loc:29, Engine Roo | None Detected | 98% Fiber Glass | 2% Other | Yellow Fibrous Homogeneous |
| 71912988PLM_28 | | | | | Teased, Dissolved |
| S0017B | Client Identified Yellow Suspect Insulation, Loc:29, Engine Roo | None Detected | 98% Fiber Glass | 2% Other | Yellow Fibrous Homogeneous |
| 71912988PLM_29 | | | | | Teased, Dissolved |
| S0017C | Client Identified Yellow Suspect Insulation, Loc:29, Engine Roo | None Detected | 98% Fiber Glass | 2% Other | Yellow Fibrous Homogeneous |
| 71912988PLM_30 | | | | | Teased, Dissolved |
| S0018A | Ceiling Tiles (lay-in), 2x4 Lay In Tile Small Pinhole Pattern, Loc:17, Corridor | None Detected | 45% Cellulose 35% Mineral Wool | 10% Perlite 10% Other | White Fibrous Homogeneous |
| 71912988PLM_31 | | | | | Ashed, Dissolved |

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAL. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Philip Szabo (51)

Analyst

Approved Signatory



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 40 CFR, Part 763, Subpart E,
App.E



Customer: Pinchin Ltd.
5 Superior Street
Tilbury, Ontario N0P 2L0

Attn: Dylan Melo
Graham Rogers
Tayler Deweerd

Lab Order ID: 71912988
Analysis ID: 71912988_PLM
Date Received: 5/15/2019
Date Reported: 5/20/2019

Project: 241027,370 Dalhousie St, Amherstburg, On,Coast Guard,CCGS Limnos

| Sample ID | Description | Asbestos | Fibrous Components | Non-Fibrous Components | Attributes |
|----------------|--|---------------|-----------------------------------|--------------------------|-----------------------------|
| Lab Sample ID | Lab Notes | | | | Treatment |
| S0018B | Ceiling Tiles (lay-in),2x4 Lay In Tile Small Pinhole Pattern,Loc:17,Corridor | None Detected | 45% Cellulose 35% Mineral Wool | 10% Perlite 10% Other | White Fibrous Homogeneous |
| 71912988PLM_32 | | | | | Ashed, Dissolved |
| S0018C | Ceiling Tiles (lay-in),2x4 Lay In Tile Small Pinhole Pattern,Loc:17,Corridor | None Detected | 45% Cellulose 35% Mineral Wool | 10% Perlite 10% Other | White Fibrous Homogeneous |
| 71912988PLM_33 | | | | | Ashed, Dissolved |
| S0019A | Suspect Door Core Insulation, Loc:17,Corridor | None Detected | 98% Fiber Glass | 2% Other | Yellow Fibrous Homogeneous |
| 71912988PLM_34 | | | | | Teased, Dissolved |
| S0019B | Suspect Door Core Insulation, Loc:17,Corridor | None Detected | 98% Fiber Glass | 2% Other | Yellow Fibrous Homogeneous |
| 71912988PLM_35 | | | | | Teased, Dissolved |
| S0019C | Suspect Door Core Insulation, Loc:17,Corridor | None Detected | 98% Fiber Glass | 2% Other | Yellow Fibrous Homogeneous |
| 71912988PLM_36 | | | | | Teased, Dissolved |
| S0020A | 1/8" Cable,Loc:1,Wheel House | None Detected | 30% Cellulose | 70% Other | Red Non Fibrous Homogeneous |
| 71912988PLM_37 | | | | | Dissolved |
| S0020B | 1/8" Cable,Loc:1,Wheel House | None Detected | 30% Cellulose | 70% Other | Red Non Fibrous Homogeneous |
| 71912988PLM_38 | | | | | Dissolved |
| S0020C | 1/8" Cable,Loc:1,Wheel House | None Detected | 30% Cellulose | 70% Other | Red Non Fibrous Homogeneous |
| 71912988PLM_39 | | | | | Dissolved |

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAL. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Philip Szabo (51)

Analyst

Approved Signatory



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 40 CFR, Part 763, Subpart E,
App.E



Customer: Pinchin Ltd.
5 Superior Street
Tilbury, Ontario N0P 2L0

Attn: Dylan Melo
Graham Rogers
Tayler Deweerd

Lab Order ID: 71912988
Analysis ID: 71912988_PLM
Date Received: 5/15/2019
Date Reported: 5/20/2019

Project: 241027,370 Dalhousie St, Amherstburg, On,Coast Guard,CCGS Limnos

| Sample ID | Description | Asbestos | Fibrous Components | Non-Fibrous Components | Attributes |
|----------------|--|----------------|--------------------|------------------------|------------------------------------|
| Lab Sample ID | Lab Notes | | | | Treatment |
| S0021A | Asbestos-cement (transite),Loc:1,Wheel House | 20% Chrysotile | | 80% Other | Gray Non Fibrous Homogeneous |
| 71912988PLM_40 | | | | | Dissolved |
| S0021B | Asbestos-cement (transite),Loc:1,Wheel House | Not Analyzed | | | |
| 71912988PLM_41 | | | | | |
| S0021C | Asbestos-cement (transite),Loc:1,Wheel House | Not Analyzed | | | |
| 71912988PLM_42 | | | | | |

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.


Philip Szabo (51)

Analyst

Approved Signatory

71912988

Version 1-15-2012

| | | | |
|------------------------|--|---|--|
| Client: | Pinchin Ltd. | *Instructions: Use Column "B" for your contact info | Invoice to: |
| Contact: | Dylan Melo | | |
| Address: | 30 Queen Street South, PO Box 339, Tilbury, ON N0P 2L0 | To See an Example Click the bottom Example Tab. | Contact name here |
| Phone: | 519-682-4492 | | Email address here |
| Fax: | 519-682-4493 | Enter samples between "<<" and ">>" |  Scientific Analytical Institute 4604 Dundas Dr. Greensboro, NC 27407 Phone: 336.292.3888 Fax: 336.292.3313 Email: lab@sailab.com |
| Email: | dmelo@pinchin.com | | |
| Project: | grogers@pinchin.com; tdeweerd@pinchin.com 241027,370 Dalhousie St, Amherstburg, On,Coast Guard,CCGS Limnos | Begin Samples with a "<<" above the first sample and end with a ">>" below the last sample. Only Enter your data on the first sheet "Sheet1" | |
| Client Notes: | | | |
| P.O. #: | 241027 | Note: Data 1 and Data 2 are optional fields that do not show up on the official report, however they will be included in the electronic data returned to you to facilitate your reintegration of the report data. | |
| Date Submitted: | May 14,2019 | | |
| Analysis: | PLM - Stop Positive | | |
| TurnAroundTime: | 4days | | |

| Sample Number | Data 1 (Lab use only) | Sample Description | Data 2 (Lab use only) |
|---------------|-----------------------|--|-----------------------|
| << | | | |
| S0008A | | Mastic, Black,Loc:6,Lab | |
| S0008B | | Mastic, Black,Loc:6,Lab | |
| S0008C | | Mastic, Black,Loc:6,Lab | |
| S0009A | | Wall Covering,Brick Pattern Vinyl Sheet Flooring,Loc:16,Utility Locker And dry Storage | |
| S0009B | | Wall Covering,Brick Pattern Vinyl Sheet Flooring,Loc:16,Utility Locker And dry Storage | |
| S0009C | | Wall Covering,Brick Pattern Vinyl Sheet Flooring,Loc:16,Utility Locker And dry Storage | |
| S0010A | | Vinyl Sheet Flooring,Grey With Grey And White Smear Pattern,Loc:19,Scientist &Officers Mes: | |
| S0010B | | Vinyl Sheet Flooring,Grey With Grey And White Smear Pattern,Loc:19,Scientist &Officers Mes: | |
| S0010C | | Vinyl Sheet Flooring,Grey With Grey And White Smear Pattern,Loc:19,Scientist &Officers Mes: | |
| S0011A | | Vinyl Floor Tile And Mastic, 12"x 12" Off White With Brown Streak Pattern, Loc:32,Focle Hallw: | |
| S0011B | | Vinyl Floor Tile And Mastic, 12"x 12" Off White With Brown Streak Pattern, Loc:32,Focle Hallw: | |
| S0011C | | Vinyl Floor Tile And Mastic, 12"x 12" Off White With Brown Streak Pattern, Loc:32,Focle Hallw: | |

Accepted



Rejected



M. Ives-Futelle 5-15 10:30

| | |
|--------|--|
| S0012A | 1/2" Cable,Loc:3,Corridor |
| S0012B | 1/2" Cable,Loc:3,Corridor |
| S0012C | 1/2" Cable,Loc:3,Corridor |
| S0013A | Firestopping Red (mastic),Loc:16,Utility Locker And dry Storage |
| S0013B | Firestopping Red (mastic),Loc:1,Wheel House |
| S0013C | Firestopping Red (mastic),Loc:3,Corridor |
| S0014A | Brown Window Caulking,Loc:6,Lab |
| S0014B | Brown Window Caulking,Loc:6,Lab |
| S0014C | Brown Window Caulking,Loc:6,Lab |
| S0015A | White Window Caulking,Loc:29,Engine Room |
| S0015B | White Window Caulking,Loc:29,Engine Room |
| S0015C | White Window Caulking,Loc:29,Engine Room |
| S0016A | Lagging Compoud on Ductwork, Loc:29,Engine Room |
| S0016B | Lagging Compoud on Ductwork, Loc:29,Engine Room |
| S0016C | Lagging Compoud on Ductwork, Loc:29,Engine Room |
| S0017A | Client Identified Yellow Suspect Insulation,Loc:29,Engine Room |
| S0017B | Client Identified Yellow Suspect Insulation,Loc:29,Engine Room |
| S0017C | Client Identified Yellow Suspect Insulation,Loc:29,Engine Room |
| S0018A | Ceiling Tiles (lay-in),2x4 Lay In Tile Small Pinhole Pattern,Loc:17,Corridor |
| S0018B | Ceiling Tiles (lay-in),2x4 Lay In Tile Small Pinhole Pattern,Loc:17,Corridor |
| S0018C | Ceiling Tiles (lay-in),2x4 Lay In Tile Small Pinhole Pattern,Loc:17,Corridor |
| S0019A | Suspect Door Core Insulation, Loc:17,Corridor |
| S0019B | Suspect Door Core Insulation, Loc:17,Corridor |
| S0019C | Suspect Door Core Insulation, Loc:17,Corridor |
| S0020A | 1/8" Cable,Loc:1,Wheel House |
| S0020B | 1/8" Cable,Loc:1,Wheel House |
| S0020C | 1/8" Cable,Loc:1,Wheel House |
| S0021A | Asbestos-cement (transite),Loc:1,Wheel House |
| S0021B | Asbestos-cement (transite),Loc:1,Wheel House |
| S0021C | Asbestos-cement (transite),Loc:1,Wheel House |

>>



Pinchin Ltd. Asbestos Laboratory Certificate of Analysis

Project Name: Canadian Coast Guard, CCG Limnos. Vessel Number 328088,
Hamilton Harbour - 47 Discovery Drive, Hamilton, Ontario

Project No.: 0241027.000

Prepared For: S. Holmquist / T. Manning

Lab Reference No.: b213116

Analyst(s): T. Lam / K. Cockburn

Date Received: July 3, 2019

Date Analyzed: July 10, 2019

Samples submitted: 3

Phases analyzed: 8

Method of Analysis:

EPA 600/R-93/116 - Method for the Determination of Asbestos in Bulk Building Materials dated July, 1993

Bulk samples are checked visually and scanned under a stereomicroscope. Slides are prepared and observed under a Polarized Light Microscope (PLM) at magnifications of 40X, 100X or 400X as appropriate. Asbestos fibres are identified by a combination of morphology, colour, refractive index, extinction, sign of elongation, birefringence and dispersion staining colours. A visual estimate is made of the percentage of asbestos present. A reported concentration of less than (<) the regulatory threshold (see chart below) indicates the presence of confirmed asbestos in trace quantities, limited to only a few fibres or fibre bundles in an entire sample. This method complies with provincial regulatory requirements where applicable. Multiple phases within a sample are analyzed and reported separately.

| Provincial Jurisdiction | Regulatory Threshold | Provincial Jurisdiction | Regulatory Threshold |
|--|----------------------|-------------------------|-----------------------------|
| Ontario, British Columbia, Nova Scotia | 0.5% | Alberta | Undefined |
| Quebec | 0.1% | Saskatchewan | 0.5% friable 1% non-friable |
| PEI, NWT, Yukon, Nunavut, Newfoundland and Labrador, and New Brunswick | 1% | Manitoba | 0.1% friable 1% non-friable |

All bulk samples submitted to this laboratory for asbestos analysis are retained for a minimum of three months. Samples may be retrieved, upon request, for re-examination at any time during that period.

The Pinchin Ltd. Mississauga asbestos laboratory is accredited by the National Institute of Standards and Technology, National Voluntary Laboratory Accreditation Program (NVLAP Lab Code 101270-0) for the 'EPA-600/M4-82-020: Interim Method for the Determination of Asbestos in Bulk Insulation Samples,' and the 'EPA 600/R-93/116: Method for the Determination of Asbestos in Bulk Building Materials'; and meets all requirements of ISO/IEC 17025:2005.

This report relates only to the items tested.

NOTE: *This test report may not be reproduced, except in full, without the written approval of the laboratory. The client may not use this report to claim product endorsement by NVLAP or any agency of the U.S. Government. This report is valid only when signed in blue ink by the analyst. Vinyl asbestos floor tiles contain very fine fibres of asbestos and may be missed by some laboratories using the PLM method. Internal verification studies performed by Pinchin indicate that the chance of missing asbestos in floor tiles is no higher than about 2%. The vinyl tile study and laboratory documentation on measurement uncertainty is available upon request. The analysis of dust samples by PLM cannot be used as an indicator of past or present airborne asbestos fibre levels.*



Pinchin Ltd. Asbestos Laboratory Certificate of Analysis

Project Name: Canadian Coast Guard, CCG Limnos. Vessel Number 328088,
Hamilton Harbour - 47 Discovery Drive, Hamilton, Ontario
Project No.: 0241027.000
Prepared For: S. Holmquist / T. Manning
Lab Reference No.: b213116
Date Analyzed: July 10, 2019

BULK SAMPLE ANALYSIS

| SAMPLE IDENTIFICATION | SAMPLE DESCRIPTION | % COMPOSITION (VISUAL ESTIMATE) | |
|---|--|---|--|
| | | ASBESTOS | OTHER |
| S022A Laminate fibreboard wall, Location 30 | 3 Phases: a) Homogeneous, black, consolidated, fibrous material. b) Non-homogeneous, beige and brown, soft, sticky material. c) Homogeneous, brown, consolidated, fibrous material. | None Detected None Detected None Detected | Cellulose > 75% Non-Fibrous Material 10-25% Non-Fibrous Material > 75% Cellulose > 75% Non-Fibrous Material 10-25% |
| Comments: | Cellulose is present on the surface of this sample. | | |
| S022B Laminate fibreboard wall, Location 30 | 3 Phases: a) Homogeneous, black, consolidated, fibrous material. b) Non-homogeneous, beige and brown, soft, sticky material. c) Homogeneous, brown, consolidated, fibrous material. | None Detected None Detected None Detected | Cellulose > 75% Non-Fibrous Material 10-25% Non-Fibrous Material > 75% Cellulose > 75% Non-Fibrous Material 10-25% |
| Comments: | Cellulose is present on the surface of this sample. | | |
| S022C Laminate fibreboard wall, Location 30 | 2 Phases: a) Homogeneous, black, consolidated, fibrous material. b) Non-homogeneous, red and brown, soft, sticky material. | None Detected None Detected | Cellulose > 75% Non-Fibrous Material 10-25% Non-Fibrous Material > 75% |
| Comments: | Cellulose is present on the surface of this sample. | | |

Reviewed by:

Reporting Analyst:

Analyzed by: TTL
 Reviewed by: [Signature]
 Report Sent by: [Signature]

Instructions:

Pinchin Ltd. - Asbestos Laboratory Internal Asbestos Bulk Sample Chain of Custody

| | | | |
|---|----------------------------------|-------------------------|--|
| Client Name: | Canadian Coast Guard | Project Address: | Hamilton Harbour - 47 Discovery Drive, Hamilton, Ontario |
| Portfolio/Building No: | CCG Limnos, Vessel Number 328088 | Pinchin File: | 241027 |
| Submitted by: | Stephen Holmquist | Email: | sholmquist@pinchin.com |
| CC Results to: | Tina Manning | CC Email: | tmanning@pinchin.com |
| Invoice to: | Tina Manning | Invoice Email: | tmanning@pinchin.com |
| Date Submitted: | July 2 2019 | Required by: | July 9 2019 |
| # of Samples: | 3 | Priority: | 5 Day Turnaround |
| Year of Building Construction (Mandatory Field): | | | |
| Do NOT Stop on Positive (Sample Numbers): | | | |
| Pinchin Group Company (Mandatory Field): | | Pinchin | |

To be Completed by Lab Personnel Only:

| Lab Reference #: | 0213116 | | Time: | 24 hour clock | | |
|-------------------------------|----------------|---------------|--|---------------|-----|------|
| Received by: | JUL 03 2019 JL | | Date: | Month | Day | Year |
| Name(s) of Analyst(s): | TTL / KC | | July 10 2019 | | | |
| Sample Prefix | Sample No. | Sample Suffix | Sample Description/Location (Mandatory) | | | |
| | S022 | A | Laminate fibreboard wall, Location 30 a) ND b) ND c) ND | | | |
| | S022 | B | Laminate fibreboard wall, Location 30 a) ND b) ND c) ND | | | |
| | S022 | C | Laminate fibreboard wall, Location 33 a) ND b) ND | | | |

APPENDIX III
Methodology

1.0 METHODOLOGY

Pinchin conducts an inspection of previously identified asbestos-containing materials (ACM) to evaluate the current condition of all accessible identified in the most recent assessment. The surveyor makes reference to any existing assessment or abatement reports (as provided by the Client).

1.1 Limitations on Scope

The re-assessment excludes the following:

- Articles belonging to the owner, tenant or occupant (e.g. stored items, furniture, appliances, etc.);
- Underground materials or equipment (e.g. vessels, drums, underground storage tanks, pipes, etc.);
- Building envelope, structural components, inaccessible or concealed materials or other items where sampling may cause consequential damage to the property.
- Energized systems (e.g. internal boiler components, elevators, mechanical or electrical components);
- Controlled products (e.g. stored chemicals, operational or process-related substances); and
- Materials not typically associated with construction (e.g. settled dust, spills, residual contamination from prior spills, etc.).

As per the original scope of work, concealed locations such as ceiling spaces above solid ceilings, shafts and chases are accessed via existing access panels. Our investigation does not include demolition of drywall or plaster walls to view concealed conditions. Structural items or exterior building finishes are not removed to determine the presence of concealed materials.

1.2 Methodology

Existing sampling data is reviewed and relied upon. If sampling is conducted, samples are collected at a rate that is in compliance with the requirements of local regulations and guidelines. The sampling strategy is also based on known ban dates and phase out dates of the use of asbestos; sampling of certain building materials is not conducted after specific construction dates. In addition, to be conservative, several years past these dates are added to account for some uncertainty in the exact start / finish date of construction and associated usage of ACM.

Materials listed as exclusions in the previous reports remain as exclusions. Sampling, assessment or verification of excluded materials was not conducted.

If present, the following materials are presumed to be asbestos-containing and are best sampled immediately prior to commencing renovation/disturbance:

- Roofing felts and tar, including repair mastics
- Concrete floor levelling compound, including ceramic tile thin set
- Elevator and lift brakes
- Electrical components or wiring within control centers, breakers, motors or lights, insulation on wiring
- Moulded plastic components (laboratory bench tops)
- Refractory materials and insulations in boilers, incinerators and stacks
- Insulation under metal clad boilers and vessels
- Mechanical packing, ropes and gaskets
- Adhesives and duct mastics
- Caulking and putties
- Paints and coatings
- Paper products under wood flooring or metal or slate roofing
- Soffit and fascia boards at elevated heights
- Exterior cladding
- Stucco, plaster or other cementitious parge coatings
- Vibration dampers on HVAC equipment
- Materials outside the assessed area

2.0 ANALYSIS AND IDENTIFICATION OF ASBESTOS MATERIALS

Pinchin relies on the analytical results of prior surveys. Asbestos bulk samples (if required) are analyzed at an independent NVLAP accredited laboratory. Preliminary identification of asbestos fibres is made using polarized light microscopy, with confirmation of the presence and type of asbestos made by dispersion staining optical microscopy. The analysis is performed in accordance with Test Method EPA/600/R-93/116: Method for the Determination of Asbestos in Bulk Building Materials, June 1993. All independent laboratories used by Pinchin, including our laboratory, are certified under the National Voluntary Laboratory Accreditation Program (NVLAP) to perform asbestos analysis of bulk samples.

Analytical results are compared to the following criteria.

| Jurisdiction | Friable | Non-Friable |
|---------------------------------------|------------------------|------------------------|
| BC | 0.5% ¹ | 0.5% |
| Alberta | Undefined ² | Undefined ² |
| Saskatchewan | >0.5% ¹ | >1% |
| Manitoba | 0.1% ¹ | 1% |
| Ontario | 0.5% | 0.5% |
| Yukon, Nunavut, Northwest Territories | 1% | 1% |
| Federal | 1% | 1% |

The asbestos analysis is completed using a stop positive approach. Only one result meeting the above regulated criteria is required to determine that a material is asbestos-containing, but all samples must be analyzed to conclusively determine that a material is non-asbestos. The laboratory stops analyzing samples from a homogeneous material once a result equal to or greater than the regulated criteria is detected in any of the samples of that material. All samples of a homogeneous material are analyzed if no asbestos is detected. In some cases, all samples are analyzed in the sample set regardless of result.

Where building materials are described in the report as “non-asbestos” or “does not contain asbestos”, this means that either no asbestos was detected by the analytical method utilized in any of the multiple samples or, if detected, it is below the lower limit of an asbestos-containing material in the applicable regulation.

Asbestos materials are evaluated in order to make recommendations regarding remedial work. The priority for remedial action is based on several factors:

- Friability (friable or non-friable).
- Condition (good, fair, poor, debris).
- Accessibility (ranking from accessible to all building users to inaccessible).
- Visibility (whether the material is obscured by other building components).
- Efficiency of the work (for example, if damaged ACM is being removed in an area, it may be most practical to remove all ACM in the area even if it is in good condition).

For a complete description of the Evaluation Criteria and Basis of Recommendations, refer to Annex A.

Template: Methodology for Asbestos Re-Assessment, HAZ, April 3, 2019

¹ Or any amount if vermiculite

² There is no criteria established for defining an asbestos-containing material by Alberta OHS Regulations. Historically, the accepted threshold was 1%, however materials that contain any asbestos will now need to be assessed before disturbance to determine the potential for fibre release based on the planned work activity.

METHODOLOGY ANNEX A EVALUATION CRITERIA

1.0 EVALUATION CRITERIA AND BASIS OF RECOMMENDATIONS

The detailed asbestos assessment provides information regarding the location, condition, accessibility and friability of the asbestos-containing materials (ACM). In order to make recommendations for compliance with current regulations, Pinchin developed the following criteria.

2.0 EVALUATION OF CONDITION

2.1 Friable Sprayed or Trowelled Fireproofing, Thermal Insulation and Texture Finishes (Surfacing Materials)

To evaluate the condition of ACM sprayed or trowelled on fireproofing, sprayed or trowelled thermal insulation (non-mechanical), or texture, decorative or acoustic finishes, the following criteria are applied:

| | |
|-------------|---|
| Good | Surface of material shows no significant signs of damage, deterioration or delamination. Good condition includes unencapsulated or unpainted fireproofing or texture finishes, where no or limited delamination or damage is observed, or encapsulated fireproofing or texture finishes where the encapsulant or paint has been applied after the damage or fallout occurred. |
| Poor | A sprayed material that shows signs of significant damage or is significantly delaminating or deteriorating. This may be limited to surface delamination or some portion of the substrate may be exposed. |

In Locations where damage exists in isolated areas, both good and poor condition may be applicable. The extent of each condition will be recorded. Fair condition is not utilized in the evaluation of ACM sprayed or trowelled fireproofing, sprayed or trowelled thermal insulation (non-mechanical), or texture, decorative or acoustic finishes.

The evaluation of the above products above ceilings may be limited by the number of observations and by building components such as ducts or full height walls that obstruct the above ceiling observations.

2.2 Friable Mechanical or Thermal System Insulation (TSI)

To evaluate the condition of mechanical insulation on vessels, boilers, breeching, ducts, pipes, fan units, equipment etc. the following criteria are applied:

| | |
|-------------|---|
| Good | Insulation is completely covered in jacketing and exhibits no evidence of damage or deterioration. No insulation is exposed. Includes conditions where the jacketing has minor damage (i.e. scuffs or stains), but the jacketing is not penetrated. |
| Fair | Minor penetrating damage to jacketed insulation (cuts, tears, nicks, deterioration or delamination) or undamaged insulation that has never been jacketed. Insulation is exposed but not showing surface disintegration. The extent of missing insulation ranges from minor to none. Damage can be repaired. |

| | |
|-------------|---|
| Poor | Original insulation jacket is missing, damaged, deteriorated or delaminated. Insulation is exposed and significant areas have been dislodged. Damage cannot be readily repaired. Includes components where insulation may have been removed incompletely. |
|-------------|---|

The evaluation of mechanical insulation may be limited by the number of observations made and building components such as ducts or full height walls that obstruct observations. It is often not possible to observe each foot of mechanical insulation from all angles.

2.3 Potentially Friable Materials and Miscellaneous Friable Materials

Potentially friable ACM are products that are basically non-friable while in place, but have the potential to generate friable dust upon removal or if significantly disturbed without appropriate procedures. These products may become friable if damaged. Potentially friable materials include materials such as acoustic ceiling tiles and plaster. To evaluate the condition of potentially friable materials, the following criteria are applied:

| | |
|-------------|--|
| Good | No significant damage or deterioration. Still serving its intended use as a building material or finish. |
| Fair | Showing signs of some cracking or breakage, but is not deteriorating (e.g. cracked plaster, broken but in place ceiling tile, missing tile or section of plaster etc.). The condition is such that it is still serving its intended use as a building material or finish but may require repair for mainly cosmetic purposes. |
| Poor | Significant deterioration or breaking apart of the material. Material has deteriorated to the point it is not serving its intended use as building material or finish. Material has deteriorated to a point it has become friable. Normally potentially friable ACM in Poor condition is not repairable and requires at least localized removal and replacement. |

2.4 Non-Friable Materials

Non-friable ACM cover a wide range of products with a wide variation in their tendency to release dust or asbestos fibres to the air. Many of these materials, (particularly where the matrix is an unweathered bitumen, asphalt or tar material) do not release fibres except in very unusual circumstances or during significant disturbance (e.g. use of abrasive power tools). Others with a cementitious matrix (asbestos-cement products) can more readily release dust due to abrasion, demolition, weathering, etc. The potential for asbestos release from non-friable ACM is always lower than from friable ACM. To evaluate the condition of non-friable Materials, the following criteria are applied:

| | |
|-------------|--|
| Good | No significant damage or deterioration. Still serving its intended use as a building material or finish. |
|-------------|--|

| | |
|-------------|--|
| Fair | Showing signs of some cracking or breakage, but is not deteriorating (e.g. cracked vinyl floor tile, missing piece of tile or transite, etc.). The condition is such that it is still serving its intended use as a building material or finish but may require repair for mainly cosmetic purposes. |
| Poor | Significant deterioration or breaking apart of the material to the point at which it cannot be repaired and it will require at least local removal. Material has deteriorated to the point it is not serving its intended use as building material or finish. Material may have deteriorated to a point where traffic or disturbance may cause it to become friable. |

2.5 Evaluation of ACM Debris

The identification of the exact location or presence of debris on the top of ceiling tiles is limited by the number of observations made and the presence of building components such as ducts or full height walls that obstruct observations.

The presence of fallen or dislodged ACM is noted separately from the ACM source and is referred to as Debris. Debris may be friable if from a friable ACM source or a badly deteriorated non-friable ACM source. Debris may also be non-friable (such as fallen pieces of transite sheet or mastic fittings, or broken, dislodged floor tiles).

| | |
|---------------|---|
| Debris | Debris may be friable or non-friable, but is always identified as debris. |
|---------------|---|

2.6 Evaluation of Presumed Asbestos-Containing Material (PACM)

Presumed asbestos-containing materials (PACM), are building materials that may contain asbestos but were not sampled or analyzed due to inaccessibility or the need to perform destructive testing to obtain a reasonable sample set. Evaluation of these materials is based on the assumption that these PACM are asbestos-containing.

A list of PACM is provided in the report and they are generally not included in the detailed room by room reports. Typically they are excluded because they are inaccessible or present in very small quantities. If PACM are evaluated, Pinchin uses the criteria that correspond with the type (and friability) of the material listed above.

3.0 EVALUATION OF ACCESSIBILITY

The accessibility of building materials known or suspected of being ACM is rated according to the following criteria:

| | |
|-----------------------------------|--|
| Access (A) | Common areas of the building within reach of all building users (approximately 8' - 9' from floor or standard ceiling height). Includes other areas where occupant activities may result in disturbance of material that is not normally within reach from floor level, but may be disturbed by common activities (e.g. gymnasiums, workshops, warehouses) |
| Access (B) | Areas of the building accessed primarily by Maintenance/Caretaking/Janitorial Staff and within reach without use of a ladder. Includes areas within reach in Boiler Rooms, Electrical Rooms, Janitors Closets, Elevator Rooms, Mechanical Rooms, etc. Includes materials within reach from fixed ladders or catwalks, mezzanines, and accessible pipe chases. |
| Access (C) and Visible | Areas of the building above 8' - 9' where use of a ladder or scaffold is required to reach the ACM. Only includes ACM that are visible to view without the removal or opening of other building components such as ceiling tiles or service access panels. Visible column on HMIS sheets will say YES. |
| Access (C) and not Visible | Areas of the building above 8' - 9' where use of a ladder or scaffold is required to reach the ACM. Includes ACM that are not visible to view and require the removal of a building component to see, such as ceilings tiles or access panels to view and access. Includes rarely entered crawl spaces, attic spaces, etc. Observations will be limited to the extent visible from the access points. Visible column on HMIS sheets will say NO. |
| Access (D) | Areas of the building behind inaccessible solid ceiling systems, walls or equipment etc. where demolition of the ceiling, wall or equipment etc. is required to reach the ACM. Material inaccessible due to height or location or is only accessed under unusual situations. Evaluation of condition and extent of ACM is limited or impossible, depending on the surveyor's ability to visually examine materials in Access D. |

4.0 ACTION MATRIX AND DEFINITIONS

Pinchin's evaluation of the viability of a specific asbestos control option is based on the consideration of the friability, condition, accessibility and visibility of a material. The logic used is that damaged ACM located in an area frequently accessed by all building occupants is of a higher priority than damaged ACM located in an infrequently accessed service area. The action matrix considers the potential for fibre release (primarily from friable ACM) and the possible concerns from regulatory bodies and many building occupants to all damaged ACM (including non-friable).

In any building with asbestos, many current regulations require an Asbestos Management Program be implemented. Depending on the condition and the accessibility, more active measures such as repair or removal may be recommended. The following matrix provides guidance for recommended Actions in the absence of renovation or demolition. In the event of construction or maintenance activity which will disturb ACM more aggressive control or removal will be required.

4.1 Action Matrix

The following tables outline the action decisions based on the relationship of assessed factors. Table I applies to friable ACM. Table II applies to non-friable ACM.

Table I Decision Matrix for Friable ACM

| Access | Condition | | | Debris |
|-----------------|-----------------------|-----------------------|----------|----------|
| | Good | Fair | Poor | |
| (A) | Action 5 ¹ | Action 5 ² | Action 3 | Action 1 |
| (B) | Action 7 | Action 6 ³ | Action 3 | Action 1 |
| (C) Visible | Action 7 | Action 6 | Action 3 | Action 2 |
| (C) Not Visible | Action 7 | Action 7 | Action 4 | Action 2 |
| (D) | Action 7 | Action 7 | Action 7 | Action 7 |

Table II Decision Matrix for Potentially Friable and Non-Friable ACM

| Access | Condition | | | Debris |
|-----------------|-----------|-----------------------|----------|----------|
| | Good | Fair | Poor | |
| (A) | Action 7 | Action 7 ⁴ | Action 3 | Action 1 |
| (B) | Action 7 | Action 7 | Action 3 | Action 1 |
| (C) Visible | Action 7 | Action 7 | Action 4 | Action 2 |
| (C) Not Visible | Action 7 | Action 7 | Action 4 | Action 2 |
| (D) | Action 7 | Action 7 | Action 7 | Action 7 |

4.2 Action Definitions

The following are the definitions in the Action Matrix Table presented above:

Action Definitions

| | |
|-----------------|--|
| Action 1 | Clean-Up of ACM Debris Restrict access that is likely to cause a disturbance of the ACM Debris and clean up ACM Debris. Utilize appropriate asbestos precautions. |
|-----------------|--|

¹ If friable ACM in access (A)/Good condition is not proactively removed Action 7 (Manage) is recommended.

² If friable ACM in access (A)/Fair condition is not proactively removed repair is recommended.

³ If friable ACM in access (B)/Fair condition is likely to be disturbed after repair proactive removal is recommended.

⁴ Action 7 is recommended for all non-friable ACM in Fair condition however some clients may wish to repair or take some action primarily for cosmetic reasons

Action Definitions


| | |
|-----------------|--|
| Action 2 | <p>Precautions for Access Which may Disturb ACM Debris</p> <p>Use appropriate means to isolate the debris or to limit entry to the area which may disturb the material. At locations where ACM Debris can remain in place in lieu of removal or clean-up (e.g. Debris on top of ceiling tiles or behind lockable door), Utilize appropriate asbestos precautions to enter the area if this will disturb debris. The precautions will be required until the ACM Debris has been cleaned up.</p> |
| Action 3 | <p>ACM Removal</p> <p>Remove ACM. Utilize asbestos procedures appropriate to the scope of the removal work. Until it is removed, restrict access to the material so it is not disturbed.</p> |
| Action 4 | <p>Precautions for Work Which may Disturb ACM in Poor Condition. Utilize appropriate asbestos precautions if ACM may be disturbed by work on or near ACM. This does not require restricting access to the area, only control of work which may contact or disturb the ACM. Removal is the only viable option if work will disturb ACM.</p> |
| Action 5 | <p>Proactive ACM Removal</p> <p>Remove friable ACM where the presence of friable asbestos in Good condition is not desirable. If friable ACM in Fair condition is not removed then Repair friable ACM.</p> |
| Action 6 | <p>ACM Repair</p> <p>Repair friable ACM in Fair condition which is not likely to be damaged again or disturbed by normal use of the area or room. Pinchin recommends proactive removal if friable ACM is likely to be damaged or disturbed during normal use of the area or room</p> |
| Action 7 | <p>Asbestos Management Program with Routine Surveillance Implement an Asbestos Management Program, including routine surveillance of ACM. Reassess materials regularly (typically once per year).</p> |

Master Template: Methodology Annex A to Appendix I Evaluation Criteria, HAZ, April 3, 2019

APPENDIX IV
Additional Photographs



Vinyl Floor Tile and Mastic, In closet 9x9 grey painted brown with brown streak, V9000, Corridor (Loc. 3)



Wall covering, Brick pattern vinyl sheet flooring, S0009C, Utility Locker And dry Storage (Loc. 16)



Vinyl Sheet Flooring, Grey with grey and white smear pattern, S0010A, Scientist & Officers Mess (Loc. 19)



Vinyl Sheet Flooring, New install, , Crew's Mess (Loc. 21)

APPENDIX V
Location Summary Report

ASBESTOS SUMMARY REPORT

Client: Canadian Coast Guard

Site: , , ON

Surveyor: Pinchin

Building Name: CCGS Limnos

Survey Date:

Reassessment Surveyor: Dylan Melo

Last Re-Assessment: 2019-05-13

| System | Asbestos | Friable | ACM Materials | Locations where ACM materials are present - Location(Room Number) | Recommended Actions | Quantity |
|--------------------------|----------|---------|-----------------------------|---|---------------------|----------|
| C - Ceiling | No | No | | | | |
| | | Yes | | | | |
| D - Duct | No | No | | | | |
| | | Yes | | | | |
| F - Floor | Yes | No | | | | |
| | | No | Vinyl Floor Tile and Mastic | 3, 31 | 7 | 120 SF |
| M - Mechanical Equipment | No | No | | | | |
| | | Yes | | | | |
| O - Other | No | No | | | | |
| | | Yes | | | | |
| P - Piping | No | No | | | | |
| | | Yes | | | | |
| S - Structure | No | No | | | | |
| | | Yes | | | | |
| W - Wall | Yes | No | | | | |
| | | No | Asbestos-cement (Transite) | 1 | 7 | 18 SF |

APPENDIX VI
Asbestos Material Summary Report

Client: Canadian Coast Guard
Site: , , ON

Building Name: CCGS Limnos

Surveyor: Pinchin

Survey Date:

| HAZMAT | Sample No | System/Material/Sample Description | Locations | LF | SF | EA | % | Type | Positive |
|----------|-----------|---|-------------------------|----|-----|----|-----|--------------------|----------|
| Asbestos | S0002 | STRUCTURE | 1,2,3,4,5,6,12,13,14,32 | 0 | 700 | 0 | 100 | None Detected | No |
| Asbestos | S0003 | FLOOR VINYL FLOOR TILE AND MASTIC | 3,31 | 0 | 90 | 0 | 0 | Chrysotile | Yes |
| Asbestos | S0008 ABC | OTHER MASTIC, BLACK | 6 | 0 | 20 | 0 | 0 | None Detected | No |
| Asbestos | S0009 ABC | WALL WALL COVERING BRICK PATTERN VINYL SHEET FLOORING | 16 | 0 | 45 | 0 | 0 | None Detected | No |
| Asbestos | S0010 ABC | FLOOR VINYL SHEET FLOORING GREY WITH GREY AND WHITE SMEAR PATTERN | 19 | 0 | 675 | 0 | 0 | None Detected | No |
| Asbestos | S0011 ABC | FLOOR VINYL FLOOR TILE AND MASTIC | 32 | 0 | 0 | 0 | 33 | None Detected | No |
| Asbestos | S0012 ABC | OTHER CONDUIT | 3 | 0 | 0 | 0 | 33 | None Detected | No |
| Asbestos | S0013 ABC | OTHER FIRESTOPPING (MASTIC) | 1,3,16 | 0 | 7 | 0 | 0 | None Detected | No |
| Asbestos | S0014 ABC | OTHER CAULKING | 6 | 30 | 0 | 0 | 0 | None Detected | No |
| Asbestos | S0015 ABC | OTHER CAULKING | 29 | 60 | 0 | 0 | 0 | None Detected | No |
| Asbestos | S0016 ABC | DUCT | 29 | 0 | 0 | 0 | 100 | None Detected | No |
| Asbestos | S0017 ABC | OTHER, WALL FIBREGLOSS | 16,29 | 0 | 0 | 2 | 100 | None Detected | No |
| Asbestos | S0018 ABC | CEILING CEILING TILES (LAY-IN) 2X4 LAY IN TILE SMALL PINHOLE | 17 | 0 | 8 | 0 | 0 | None Detected | No |
| Asbestos | S0019 ABC | OTHER, WALL THERMAL INSULATION | 17,20,32 | 0 | 26 | 5 | 0 | None Detected | No |
| Asbestos | S0020 ABC | OTHER CONDUIT | 1 | 0 | 0 | 0 | 100 | None Detected | No |
| Asbestos | S0021 ABC | WALL ASBESTOS-CEMENT (TRANSITE) | 1 | 0 | 18 | 0 | 0 | Chrysotile | Yes |
| Asbestos | S0022 ABC | CEILING, WALL FIBROUS BOARD LAMINATE FIBERBOARD WALL | 30,33 | 0 | 40 | 0 | 100 | None Detected | No |
| Asbestos | V9000 | FLOOR VINYL FLOOR TILE AND MASTIC | 3 | 0 | 30 | 0 | 0 | Confirmed Asbestos | Yes |
| Asbestos | V0000 | CEILING METAL | 1,2,3,4,5,6,12,13,14 | 0 | 730 | 0 | 100 | Non Asbestos | No |
| Asbestos | V0000 | FLOOR ABATED MATERIAL | 1,2,26,29 | 0 | 350 | 0 | 100 | Non Asbestos | No |
| Asbestos | V0000 | PIPING NOT INSULATED | 16,31 | 0 | 0 | 0 | 0 | Non Asbestos | No |

APPENDIX VII
All Data Report

ALL DATA REPORT

Client: Canadian Coast Guard
Location: #1 : Wheel House
Surveyor: Pinchin

Site: Vessels
Floor: NA
Survey Date: 2019-05-13

Building Name: 328088 : CCGS Limnos
Room #:
Reassessment Surveyor: Dylan Melo

Area (sqft): 200
Last Re-Assessment: 2019-05-13

| ASBESTOS | | | | | | | | | | | | | | | |
|-----------|-----------|----------------------------|------|----------|----|----|-----|------|------|------|------|----------|---------------|--------|------------------------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard |
| Ceiling | | Metal | | | A | Y | | 100 | | | % | V0000 | Non-Asbestos | | None |
| Duct | | Fibreglass | | | D | N | | 6 | | | LF | | | | |
| Floor | | Carpet | | | A | Y | | 200 | | | SF | | | | |
| Floor | | Abated Material | | | A | N | | 200 | | | SF | V0000 | Non-Asbestos | | None |
| Other | Cable | Conduit | | | B | N | | 300 | | | % | S0020ABC | None Detected | N.D. | None |
| Other | Conduit | Firestopping (mastic) | | | C | Y | | 2 | | | SF | S0013B | None Detected | N.D. | None |
| Structure | | | | | D | N | | 200 | | | SF | S0002 | None Detected | N.D. | None |
| Structure | | Steel | | | D | N | | 200 | | | SF | | | | |
| Wall | | Steel | | | B | N | | 260 | | | SF | | | | |
| Wall | | Wood | | | A | Y | | 260 | | | SF | | | | |
| Wall | | Asbestos-cement (Transite) | | | B | N | | 18 | | | SF | S0021ABC | Chrysotile | 10-25% | Confirmed Asbestos(NF) |
| Wall | | Fibreglass | | | B | Y | | 260 | | | SF | | | | |

Ceiling - Fiberglass with White Textile Covering

ALL DATA REPORT

Client: Canadian Coast Guard
Location: #2 : Cabin 3
Surveyor: Pinchin

Site: Vessels
Floor: Forecastle
Survey Date: 2019-05-13

Building Name: 328088 : CCGS Limnos
Room #:
Reassessment Surveyor: Dylan Melo

Area (sqft): 200
Last Re-Assessment: 2019-05-13

| ASBESTOS | | | | | | | | | | | | | | | |
|--------------------|------------|-----------------|------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard |
| Ceiling | | Metal | | | A | Y | | 100 | | | % | V0000 | Non-Asbestos | | None |
| Duct | | Fibreglass | | | D | N | | 6 | | | LF | | | | |
| Duct | Return Air | Not Insulated | | | A | Y | | 10 | | | LF | | | | |
| Floor | | Carpet | | | A | Y | | 100 | | | % | | | | |
| Floor | | Abated Material | | | A | N | | 100 | | | % | V0000 | Non-Asbestos | | None |
| Other ¹ | Sink | | | | | | | | | | | | | | |
| Piping | | Armaflex | | | B | N | | 5 | | | LF | | | | |
| Piping | | Not Insulated | | | A | Y | | 3 | | | LF | | | | |
| Structure | | | | | D | N | | 200 | | | SF | V0002 | None Detected | N.D. | None |
| Structure | | Steel | | | D | N | | 200 | | | SF | | | | |
| Structure | | Fibreglass | | | B | N | | 200 | | | SF | V0002 | None Detected | N.D. | None |
| Wall | | Steel | | | B | N | | 260 | | | SF | | | | |
| Wall | | Wood | | | | | | | | | | | | | |
| Wall | | Fibreglass | | | B | Y | | 260 | | | SF | | | | |

Floor abated 2010
1 - Uninsulated and painted

ALL DATA REPORT

Client: Canadian Coast Guard
Location: #3 : Corridor
Surveyor: Pinchin

Site: Vessels
Floor: Forecastle
Survey Date: 2019-05-13

Building Name: 328088 : CCGS Limnos
Room #:
Reassessment Surveyor: Dylan Melo

Area (sqft): 120
Last Re-Assessment: 2019-05-13

| ASBESTOS | | | | | | | | | | | | | | | |
|-----------|-----------|---|------|----------|----|----|-----|------|------|------|------|----------|--------------------|--------|------------------------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard |
| Ceiling | | Metal | | | A | Y | | 100 | | | % | V0000 | Non-Asbestos | | None |
| Floor | | Vinyl Floor Tile and Mastic | | | A | Y | | 90 | | | SF | S0003 | Chrysotile | 5-10% | Confirmed Asbestos(NF) |
| Floor | | Vinyl Floor Tile and Mastic, In closet 9x9 grey painted brown with brown streak | | Paint | A | N | | 30 | | | SF | V9000 | Confirmed Asbestos | | Confirmed Asbestos(NF) |
| Other | Conduit | Conduit | | | B | Y | | 100 | | | % | S0012ABC | None Detected | N.D. | None |
| Other | Conduit | Caulking | | | B | Y | | 2 | | | SF | S0013C | None Detected | N.D. | None |
| Structure | | Steel | | | B | N | | 100 | | | % | | | | |
| Structure | | Fibreglass | | | B | N | | 100 | | | % | V0002 | None Detected | N.D. | None |
| Wall | | Steel | | | | | | | | | | | | | |

Client: Canadian Coast Guard
Location: #4 : Cabin 1
Surveyor: Pinchin

Site: Vessels
Floor: Forecastle
Survey Date: 2019-05-13

Building Name: 328088 : CCGS Limnos
Room #:
Reassessment Surveyor: Dylan Melo

Area (sqft): 160
Last Re-Assessment: 2019-05-13

| ASBESTOS | | | | | | | | | | | | | | | |
|-----------|-----------|------------|------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard |
| Ceiling | | Metal | | | A | Y | | 160 | | | SF | V0000 | Non-Asbestos | | None |
| Duct | | Fibreglass | | | D | N | | 6 | | | LF | | | | |
| Floor | | Carpet | | | A | Y | | 160 | | | SF | | | | |
| Structure | | | | | D | N | | 100 | | | % | V0002 | None Detected | N.D. | None |
| Structure | | Steel | | | D | N | | 100 | | | % | | | | |
| Wall | | Wood | | | | | | | | | | | | | |

ALL DATA REPORT

Client: Canadian Coast Guard
Location: #5 : Cabin 2
Surveyor: Pinchin

Site: Vessels
Floor: Forecastle
Survey Date: 2019-05-13

Building Name: 328088 : CCGS Limnos
Room #:
Reassessment Surveyor: Dylan Melo

Area (sqft): 110
Last Re-Assessment: 2019-05-13

| ASBESTOS | | | | | | | | | | | | | | | |
|-----------|-----------|------------|------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard |
| Ceiling | | Metal | | | A | Y | | 110 | | | SF | V0000 | Non-Asbestos | | None |
| Duct | | Fibreglass | | | B | N | | 6 | | | LF | | | | |
| Floor | | Carpet | | | A | Y | | 110 | | | SF | | | | |
| Structure | | Steel | | | B | N | | 100 | | | % | | | | |
| Structure | | Fibreglass | | | B | N | | 100 | | | % | V0002 | None Detected | N.D. | None |
| Wall | | Wood | | | | | | | | | | | | | |

Client: Canadian Coast Guard
Location: #6 : Lab
Surveyor: Pinchin

Site: Vessels
Floor: Main Deck
Survey Date: 2019-05-13

Building Name: 328088 : CCGS Limnos
Room #:
Reassessment Surveyor: Dylan Melo

Area (sqft): 400
Last Re-Assessment: 2019-05-13

| ASBESTOS | | | | | | | | | | | | | | | |
|-----------|------------|---------------|------|----------|----|----|-----|------|------|------|------|----------|---------------|--------|--------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard |
| Ceiling | | Metal | | | A | Y | | 200 | | | SF | V0000 | Non-Asbestos | | None |
| Duct | Supply Air | Fibreglass | | | B | N | | 10 | | | LF | | | | |
| Floor | | Terrazzo | | | A | Y | | 400 | | | SF | | | | |
| Other | Sink | Mastic, Black | | | A | N | | 20 | | | SF | S0008ABC | None Detected | N.D. | None |
| Other | Window | Caulking | | | A | Y | | 30 | | | LF | S0014ABC | None Detected | N.D. | None |
| Piping | | Not Insulated | | | B | N | | 10 | | | LF | | | | |
| Structure | | Steel | | | B | N | | 100 | | | % | | | | |
| Structure | | Fibreglass | | | B | N | | 100 | | | % | V0002 | None Detected | N.D. | None |
| Wall | | Laminate | | | A | Y | | 100 | | | % | | | | |

ALL DATA REPORT

Client: Canadian Coast Guard
Location: #7 : Storage
Surveyor: Pinchin

Site: Vessels
Floor: Main Deck
Survey Date: 2019-05-13

Building Name: 328088 : CCGS Limnos
Room #:
Reassessment Surveyor: Dylan Melo

Area (sqft): 240
Last Re-Assessment: 2019-05-13

| ASBESTOS | | | | | | | | | | | | | | | |
|-----------|-----------|-------------------|------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard |
| Ceiling | | Fibreglass | | | C | Y | | 240 | | | SF | | | | |
| Duct | | Armaflex | | | A | Y | | 20 | | | LF | | | | |
| Floor | | Concrete (poured) | | | A | Y | | 240 | | | SF | | | | |
| Piping | | Not Insulated | | | B | Y | | 50 | | | LF | | | | |
| Piping | | Not Insulated | | | A | Y | | 10 | | | LF | | | | |
| Piping | | Not Insulated | | | A | Y | | 10 | | | LF | | | | |
| Structure | | Steel | | | | | | | | | | | | | |
| Wall | | Steel | | | A | Y | | 160 | | | SF | | | | |
| Wall | | Fibreglass | | | A | Y | | 100 | | | % | | | | |
| Wall | | Laminate | | | A | Y | | 100 | | | % | | | | |

Client: Canadian Coast Guard
Location: #8 : 2 Technicians - Cabin 16
Surveyor: Pinchin

Site: Vessels
Floor: Main Deck
Survey Date: 2019-05-13

Building Name: 328088 : CCGS Limnos
Room #:
Reassessment Surveyor: Dylan Melo

Area (sqft): 70
Last Re-Assessment: 2019-05-13

| ASBESTOS | | | | | | | | | | | | | | | |
|----------|------------|---------------|------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard |
| Ceiling | | Fibreglass | | | C | Y | | 70 | | | SF | | | | |
| Duct | Supply Air | Fibreglass | | | C | Y | | 3 | | | LF | | | | |
| Floor | | Carpet | | | A | Y | | 70 | | | SF | | | | |
| Piping | | Not Insulated | | | A | Y | | 16 | | | LF | | | | |
| Wall | | Fibreglass | | | A | Y | | 80 | | | SF | | | | |
| Wall | | Laminate | | | A | Y | | 80 | | | SF | | | | |

ALL DATA REPORT

Client: Canadian Coast Guard
Location: #9 : Cabin 15
Surveyor: Pinchin

Site: Vessels
Floor: Main Deck
Survey Date: 2019-05-13

Building Name: 328088 : CCGS Limnos
Room #:
Reassessment Surveyor: Dylan Melo

Area (sqft): 70
Last Re-Assessment: 2019-05-13

| ASBESTOS | | | | | | | | | | | | | | | |
|----------|------------|---------------|------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard |
| Ceiling | | Fibreglass | | | C | Y | | 70 | | | SF | | | | |
| Duct | Supply Air | Fibreglass | | | C | Y | | 3 | | | LF | | | | |
| Floor | | Carpet | | | A | Y | | 70 | | | SF | | | | |
| Piping | | Not Insulated | | | A | Y | | 16 | | | LF | | | | |
| Wall | | Fibreglass | | | A | Y | | 80 | | | SF | | | | |
| Wall | | Laminate | | | A | Y | | 80 | | | SF | | | | |

Client: Canadian Coast Guard
Location: #10 : Tank/Pump Compartment
Surveyor: Pinchin

Site: Vessels
Floor: Below Main
Survey Date: 2019-05-13

Building Name: 328088 : CCGS Limnos
Room #:
Reassessment Surveyor: Dylan Melo

Area (sqft): 250
Last Re-Assessment: 2019-05-13

| ASBESTOS | | | | | | | | | | | | | | | |
|----------------------|-----------|-------------------|------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard |
| Ceiling | | Steel | | | C | Y | | 250 | | | SF | | | | |
| Floor | | Steel | | | A | Y | | 125 | | | SF | | | | |
| Floor | | Concrete (poured) | | | A | Y | | 125 | | | SF | | | | |
| Mechanical Equipment | Tank | Not Insulated | | | A | Y | | 50 | | | SF | | | | |
| Mechanical Equipment | Tank | Not Insulated | | | A | Y | | 400 | | | SF | | | | |
| Mechanical Equipment | Tank | Not Insulated | | | A | Y | | 100 | | | SF | | | | |
| Mechanical Equipment | Tank | Not Insulated | | | A | Y | | 200 | | | SF | | | | |
| Piping | | Fibreglass | | | A | Y | | 25 | | | LF | | | | |
| Piping | | Fibreglass | | | A | Y | | 50 | | | LF | | | | |
| Piping | | Fibreglass | | | A | Y | | 50 | | | LF | | | | |
| Piping | | Not Insulated | | | A | Y | | 100 | | | LF | | | | |
| Piping | | Not Insulated | | | A | Y | | 100 | | | LF | | | | |
| Piping | | Not Insulated | | | A | Y | | 10 | | | LF | | | | |
| Structure | | Steel | | | C | Y | | 250 | | | SF | | | | |
| Wall | | Fibreglass | | | A | Y | | 500 | | | SF | | | | |

ALL DATA REPORT

Client: Canadian Coast Guard
Location: #11 : Head
Surveyor: Pinchin

Site: Vessels
Floor: Main Deck
Survey Date: 2019-05-13

Building Name: 328088 : CCGS Limnos
Room #:
Reassessment Surveyor: Dylan Melo

Area (sqft): 65
Last Re-Assessment: 2019-05-13

| ASBESTOS | | | | | | | | | | | | | | | |
|-----------|-----------|--------------------|------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard |
| Ceiling | | Steel | | | A | Y | | 65 | | | SF | | | | |
| Duct | | Armaflex | | | A | Y | | 12 | | | SF | | | | |
| Floor | | Concrete (precast) | | | A | Y | | 65 | | | SF | | | | |
| Piping | | Not Insulated | | | A | Y | | 12 | | | SF | | | | |
| Structure | | Steel | | | C | Y | | 65 | | | SF | | | | |
| Wall | | Steel | | | A | Y | | 260 | | | SF | | | | |

Client: Canadian Coast Guard
Location: #12 : OIC
Surveyor: Pinchin

Site: Vessels
Floor: Under Main
Survey Date: 2019-05-13

Building Name: 328088 : CCGS Limnos
Room #:
Reassessment Surveyor: Dylan Melo

Area (sqft): 120
Last Re-Assessment: 2019-05-13

| ASBESTOS | | | | | | | | | | | | | | | |
|-----------|-----------|---------------|---------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard |
| Ceiling | | Metal | | | A | Y | | 130 | | | SF | V0000 | Non-Asbestos | | None |
| Duct | | Fibreglass | | | C | N | | 10 | | | LF | | | | |
| Floor | | Ceramic Tiles | | | | | | | | | | | | | |
| Floor | | Carpet | | | A | Y | | 120 | | | SF | | | | |
| Piping | | Fibreglass | | | A | Y | | 10 | | | LF | | | | |
| Piping | | Not Insulated | | | C | N | | 10 | | | LF | | | | |
| Structure | | Steel | | | B | N | | 100 | | | % | | | | |
| Structure | | Fibreglass | | | B | N | | 100 | | | % | V0002 | None Detected | N.D. | None |
| Wall | | Steel | | | A | Y | | 120 | | | SF | | | | |
| Wall | | Wood | | | A | Y | | 140 | | | SF | | | | |
| Wall | | Fibreglass | Fitting | | A | Y | | 5 | | | EA | | | | |

Fiberglass Behind Wall, Firedoor at Corridor and Washroom

ALL DATA REPORT

Client: Canadian Coast Guard
Location: #13 : Chief Eng. Cabin
Surveyor: Pinchin

Site: Vessels
Floor: Under Main
Survey Date: 2019-05-13

Building Name: 328088 : CCGS Limnos
Room #:
Reassessment Surveyor: Dylan Melo

Area (sqft): 100
Last Re-Assessment: 2019-05-13

| ASBESTOS | | | | | | | | | | | | | | | |
|-----------|-----------|---------------|------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard |
| Ceiling | | Metal | | | A | Y | | 130 | | | SF | V0000 | Non-Asbestos | | None |
| Duct | | Fibreglass | | | C | N | | 10 | | | LF | | | | |
| Floor | | Ceramic Tiles | | | | | | | | | | | | | |
| Floor | | Carpet | | | A | Y | | 120 | | | SF | | | | |
| Piping | | Fibreglass | | | A | Y | | 10 | | | LF | | | | |
| Piping | | Not Insulated | | | C | N | | 10 | | | LF | | | | |
| Structure | | Steel | | | B | N | | 100 | | | SF | | | | |
| Structure | | Fibreglass | | | B | N | | 100 | | | SF | V0002 | None Detected | N.D. | None |
| Wall | | Steel | | | A | Y | | 120 | | | SF | | | | |
| Wall | | Wood | | | A | Y | | 140 | | | SF | | | | |

Fiberglass Behind Wall, Firedoor at Corridor and Washroom

ALL DATA REPORT

Client: Canadian Coast Guard
Location: #14 : Engineer (2) Cabin 6
Surveyor: Pinchin

Site: Vessels
Floor: NA
Survey Date: 2019-05-13

Building Name: 328088 : CCGS Limnos
Room #:
Reassessment Surveyor: Dylan Melo

Area (sqft): 100
Last Re-Assessment: 2019-05-13

| ASBESTOS | | | | | | | | | | | | | | | |
|-----------|-----------|---------------|------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard |
| Ceiling | | Metal | | | A | Y | | 100 | | | % | V0000 | Non-Asbestos | | None |
| Duct | | Fibreglass | | | C | N | | 10 | | | LF | | | | |
| Floor | | Ceramic Tiles | | | | | | | | | | | | | |
| Floor | | Carpet | | | A | Y | | 120 | | | SF | | | | |
| Piping | | Fibreglass | | | A | Y | | 10 | | | LF | | | | |
| Piping | | Not Insulated | | | C | N | | 10 | | | LF | | | | |
| Structure | | Steel | | | B | N | | 100 | | | % | | | | |
| Structure | | Fibreglass | | | B | N | | 100 | | | % | V0002 | None Detected | N.D. | None |
| Wall | | Steel | | | A | Y | | 120 | | | SF | | | | |
| Wall | | Wood | | | A | Y | | 140 | | | SF | | | | |

Fiberglass Behind Wall, Firedoor at Corridor and Washroom

ALL DATA REPORT

Client: Canadian Coast Guard
Location: #15 : Cabin 7
Surveyor: Pinchin

Site: Vessels
Floor: NA
Survey Date: 2019-05-13

Building Name: 328088 : CCGS Limnos
Room #:
Reassessment Surveyor: Dylan Melo

Area (sqft): 100
Last Re-Assessment: 2019-05-13

| ASBESTOS | | | | | | | | | | | | | | | |
|-----------|-----------|--------------------|------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard |
| Ceiling | | Steel | | | A | Y | | 100 | | | SF | | | | |
| Duct | | Armaflex | | | A | Y | | 12 | | | SF | | | | |
| Floor | | Concrete (precast) | | | A | Y | | 100 | | | SF | | | | |
| Piping | | Not Insulated | | | A | Y | | 12 | | | SF | | | | |
| Structure | | Steel | | | C | Y | | 65 | | | SF | | | | |
| Wall | | Steel | | | A | Y | | 260 | | | SF | | | | |

Client: Canadian Coast Guard
Location: #16 : Utility Locker And dry Storage
Surveyor: Pinchin

Site: Vessels
Floor: Under Main
Survey Date: 2019-05-13

Building Name: 328088 : CCGS Limnos
Room #:
Reassessment Surveyor: Dylan Melo

Area (sqft): 6
Last Re-Assessment: 2019-05-13

| ASBESTOS | | | | | | | | | | | | | | | |
|-------------------|-----------|---|---------|----------|----|----|-----|------|------|------|------|----------|---------------|--------|--------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard |
| Ceiling | | Steel | | | A | Y | | 6 | | | SF | | | | |
| Duct | | Armaflex | | | A | Y | | 12 | | | SF | | | | |
| Floor | | Concrete (precast) | | | A | Y | | 6 | | | SF | | | | |
| Other | Conduit | Firestopping (mastic) | | | C | Y | | 3 | | | SF | S0013A | None Detected | N.D. | None |
| Other | Door | Thermal Insulation | | | D | N | | 2 | | | EA | V0017 | None Detected | N.D. | None |
| Piping | | Fibreglass | | | B | N | | 3 | | .5 | LF | | | | |
| Piping | | Not Insulated | | | A | Y | | 12 | | | SF | | | | |
| Piping | All | Fibreglass | | Plastic | A | Y | | | | | | | | | |
| Piping | All | Not Insulated | | | B | N | | | | | | V0000 | Non-Asbestos | | None |
| Structure | | Steel | | | C | Y | | 65 | | | SF | | | | |
| Wall | | Steel | | | A | Y | | 260 | | | SF | | | | |
| Wall | | Wall covering, Brick pattern vinyl sheet flooring | | | B | N | | 45 | | | SF | S0009ABC | None Detected | N.D. | None |
| Wall ¹ | | Abated Material | Fitting | | B | N | | .5 | | | | S0004 | Chrysotile | 10-25% | None |

1 - No parping cement observed all fittings plastic covering fiberglass

ALL DATA REPORT

Client: Canadian Coast Guard
Location: #17 : Corridor
Surveyor: Pinchin

Site: Vessels
Floor: NA
Survey Date: 2019-05-13

Building Name: 328088 : CCGS Limnos
Room #:
Reassessment Surveyor: Dylan Melo

Area (sqft): 180
Last Re-Assessment: 2019-05-13

| ASBESTOS | | | | | | | | | | | | | | | |
|-----------|-----------|---|------|----------|----|----|-----|------|------|------|------|----------|---------------|--------|--------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard |
| Ceiling | | Steel | | | A | Y | | 65 | | | SF | | | | |
| Ceiling | | Ceiling Tiles (lay-in), 2x4 lay in tile small pinhole | | | B | Y | | 8 | | | SF | S0018ABC | None Detected | N.D. | None |
| Duct | | Armaflex | | | A | Y | | 12 | | | SF | | | | |
| Floor | | Steel | | | A | Y | | 40 | | | SF | | | | |
| Floor | | Carpet | | | A | Y | | 100 | | | % | | | | |
| Other | Door | Thermal Insulation | | | D | N | | 4 | | | EA | S0019AB | None Detected | N.D. | None |
| Piping | | Not Insulated | | | A | Y | | 12 | | | SF | | | | |
| Structure | | Steel | | | C | Y | | 65 | | | SF | | | | |
| Wall | | Steel | | | | | | | | | | | | | |

Client: Canadian Coast Guard
Location: #18 : Galley
Surveyor: Pinchin

Site: Vessels
Floor: NA
Survey Date: 2019-05-13

Building Name: 328088 : CCGS Limnos
Room #:
Reassessment Surveyor: Dylan Melo

Area (sqft): 200
Last Re-Assessment: 2019-05-13

| ASBESTOS | | | | | | | | | | | | | | | |
|----------|-----------|---------------|------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard |
| Ceiling | | Steel | | | A | Y | | 200 | | | SF | | | | |
| Floor | | Ceramic Tiles | | | A | Y | | 200 | | | SF | | | | |
| Wall | | Steel | | | A | Y | | 420 | | | SF | | | | |

ALL DATA REPORT

Client: Canadian Coast Guard
Location: #19 : Scientist & Officers Mess
Surveyor: Pinchin

Site: Vessels
Floor: NA
Survey Date: 2019-05-13

Building Name: 328088 : CCGS Limnos
Room #:
Reassessment Surveyor: Dylan Melo

Area (sqft): 225
Last Re-Assessment: 2019-05-13

| ASBESTOS | | | | | | | | | | | | | | | |
|-----------|-----------|--|------|----------|----|----|-----|------|------|------|------|----------|---------------|--------|--------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard |
| Ceiling | | Steel | | | A | Y | | 225 | | | SF | | | | |
| Duct | | Armaflex | | | A | Y | | 12 | | | SF | | | | |
| Floor | | Vinyl Sheet Flooring, Grey with grey and white smear pattern | | | A | Y | | 675 | | | SF | S0010ABC | None Detected | N.D. | None |
| Piping | | Not Insulated | | | A | Y | | 12 | | | SF | | | | |
| Structure | | Steel | | | C | Y | | 65 | | | SF | | | | |
| Wall | | Wood | | | A | Y | | 240 | | | SF | | | | |
| Wall | | Drywall and joint compound | | | A | Y | | 240 | | | SF | | | | |

Dry Wall Covered with Wallpaper and Wood Strip at Joints

Client: Canadian Coast Guard
Location: #20 : 2 Showers & 2 Washrooms
Surveyor: Pinchin

Site: Vessels
Floor: NA
Survey Date: 2019-05-13

Building Name: 328088 : CCGS Limnos
Room #:
Reassessment Surveyor: Dylan Melo

Area (sqft): 150
Last Re-Assessment: 2019-05-13

| ASBESTOS | | | | | | | | | | | | | | | |
|----------|-----------|--------------------|------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard |
| Ceiling | | Steel | | | A | Y | | 150 | | | SF | | | | |
| Duct | | Armaflex | | | A | Y | | 4 | | | LF | | | | |
| Floor | | Ceramic Tiles | | | A | Y | | 150 | | | SF | | | | |
| Piping | | Fibreglass | | | A | Y | | 6 | | | LF | | | | |
| Piping | | Armaflex | | | A | Y | | 10 | | | LF | | | | |
| Wall | | Steel | | | A | Y | | 250 | | | SF | | | | |
| Wall | Door | Thermal Insulation | | Metal | A | Y | | 21 | | | SF | S0019 | None Detected | N.D. | None |

4 Doors, 1 Damaged at Washroom

ALL DATA REPORT

Client: Canadian Coast Guard
Location: #21 : Crew's Mess
Surveyor: Pinchin

Site: Vessels
Floor: NA
Survey Date: 2019-05-13

Building Name: 328088 : CCGS Limnos
Room #:
Reassessment Surveyor: Dylan Melo

Area (sqft): 250
Last Re-Assessment: 2019-05-13

| ASBESTOS | | | | | | | | | | | | | | | |
|-----------|-----------|-----------------------------------|------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard |
| Ceiling | | Steel | | | A | Y | | 250 | | | SF | | | | |
| Duct | | Armaflex | | | A | Y | | 12 | | | SF | | | | |
| Floor | | Vinyl Sheet Flooring, New install | | | A | Y | | 250 | | | SF | | | | |
| Piping | | Not Insulated | | | A | Y | | 12 | | | SF | | | | |
| Structure | | Steel | | | C | Y | | 65 | | | SF | | | | |
| Wall | | Steel | | | A | Y | | 260 | | | SF | | | | |

Client: Canadian Coast Guard
Location: #22 : Cabin 9
Surveyor: Pinchin

Site: Vessels
Floor: NA
Survey Date: 2019-05-13

Building Name: 328088 : CCGS Limnos
Room #:
Reassessment Surveyor: Dylan Melo

Area (sqft): 100
Last Re-Assessment: 2019-05-13

| ASBESTOS | | | | | | | | | | | | | | | |
|-----------|-----------|--------------------|------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard |
| Ceiling | | Steel | | | A | Y | | 100 | | | SF | | | | |
| Duct | | Armaflex | | | A | Y | | 12 | | | SF | | | | |
| Floor | | Concrete (precast) | | | A | Y | | 100 | | | SF | | | | |
| Piping | | Not Insulated | | | A | Y | | 12 | | | SF | | | | |
| Structure | | Steel | | | C | Y | | 100 | | | % | | | | |
| Wall | | Steel | | | A | Y | | 260 | | | SF | | | | |

ALL DATA REPORT

Client: Canadian Coast Guard
Location: #23 : Cabin 8
Surveyor: Pinchin

Site: Vessels
Floor: NA
Survey Date: 2019-05-13

Building Name: 328088 : CCGS Limnos
Room #:
Reassessment Surveyor: Dylan Melo

Area (sqft): 100
Last Re-Assessment: 2019-05-13

| ASBESTOS | | | | | | | | | | | | | | | |
|-----------|-----------|--------------------|------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard |
| Ceiling | | Steel | | | A | Y | | 100 | | | SF | | | | |
| Duct | | Armaflex | | | A | Y | | 12 | | | SF | | | | |
| Floor | | Concrete (precast) | | | A | Y | | 100 | | | SF | | | | |
| Piping | | Not Insulated | | | A | Y | | 12 | | | SF | | | | |
| Structure | | Steel | | | C | Y | | 65 | | | SF | | | | |
| Wall | | Steel | | | A | Y | | 260 | | | SF | | | | |

Client: Canadian Coast Guard
Location: #24 : Cabin 11
Surveyor: Pinchin

Site: Vessels
Floor: NA
Survey Date: 2019-05-13

Building Name: 328088 : CCGS Limnos
Room #:
Reassessment Surveyor: Dylan Melo

Area (sqft): 100
Last Re-Assessment: 2019-05-13

| ASBESTOS | | | | | | | | | | | | | | | |
|-----------|-----------|--------------------|------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard |
| Ceiling | | Steel | | | A | Y | | 100 | | | SF | | | | |
| Duct | | Armaflex | | | A | Y | | 12 | | | SF | | | | |
| Floor | | Concrete (precast) | | | A | Y | | 100 | | | SF | | | | |
| Piping | | Not Insulated | | | A | Y | | 12 | | | SF | | | | |
| Structure | | Steel | | | C | Y | | 65 | | | SF | | | | |
| Wall | | Steel | | | A | Y | | 260 | | | SF | | | | |

ALL DATA REPORT

Client: Canadian Coast Guard
Location: #25 : Cabin 13
Surveyor: Pinchin

Site: Vessels
Floor: NA
Survey Date: 2019-05-13

Building Name: 328088 : CCGS Limnos
Room #:
Reassessment Surveyor: Dylan Melo

Area (sqft): 100
Last Re-Assessment: 2019-05-13

| ASBESTOS | | | | | | | | | | | | | | | |
|-----------|-----------|--------------------|------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard |
| Ceiling | | Steel | | | A | Y | | 100 | | | SF | | | | |
| Duct | | Armaflex | | | A | Y | | 12 | | | SF | | | | |
| Floor | | Concrete (precast) | | | A | Y | | 100 | | | SF | | | | |
| Piping | | Not Insulated | | | A | Y | | 12 | | | SF | | | | |
| Structure | | Steel | | | C | Y | | 65 | | | SF | | | | |
| Wall | | Steel | | | A | Y | | 260 | | | SF | | | | |

Steel Door

Client: Canadian Coast Guard
Location: #26 : Cabin 10
Surveyor: Pinchin

Site: Vessels
Floor: NA
Survey Date: 2019-05-13

Building Name: 328088 : CCGS Limnos
Room #:
Reassessment Surveyor: Dylan Melo

Area (sqft): 100
Last Re-Assessment: 2019-05-13

| ASBESTOS | | | | | | | | | | | | | | | |
|-----------|-----------|-----------------|------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard |
| Ceiling | | Steel | | | A | Y | | 100 | | | SF | | | | |
| Duct | | Armaflex | | | A | Y | | 12 | | | SF | | | | |
| Floor | | Abated Material | | | A | Y | | 100 | | | SF | V0000 | Non-Asbestos | | None |
| Piping | | Not Insulated | | | A | Y | | 12 | | | SF | | | | |
| Structure | | Steel | | | C | Y | | 65 | | | SF | | | | |
| Wall | | Steel | | | A | Y | | 260 | | | SF | | | | |

ALL DATA REPORT

Client: Canadian Coast Guard
Location: #27 : Cabin 12
Surveyor: Pinchin

Site: Vessels
Floor: NA
Survey Date: 2019-05-13

Building Name: 328088 : CCGS Limnos
Room #:
Reassessment Surveyor: Dylan Melo

Area (sqft): 100
Last Re-Assessment: 2019-05-13

| ASBESTOS | | | | | | | | | | | | | | | |
|-----------|-----------|--------------------|------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard |
| Ceiling | | Steel | | | A | Y | | 100 | | | SF | | | | |
| Duct | | Armaflex | | | A | Y | | 12 | | | SF | | | | |
| Floor | | Concrete (precast) | | | A | Y | | 100 | | | SF | | | | |
| Piping | | Not Insulated | | | A | Y | | 12 | | | SF | | | | |
| Structure | | Steel | | | C | Y | | 65 | | | SF | | | | |
| Wall | | Steel | | | A | Y | | 260 | | | SF | | | | |

Client: Canadian Coast Guard
Location: #28 : Cabin 14
Surveyor: Pinchin

Site: Vessels
Floor: NA
Survey Date: 2019-05-13

Building Name: 328088 : CCGS Limnos
Room #:
Reassessment Surveyor: Dylan Melo

Area (sqft): 0
Last Re-Assessment: 2019-05-13

| ASBESTOS | | | | | | | | | | | | | | | |
|-----------|-----------|--------------------|------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard |
| Ceiling | | Steel | | | A | Y | | 65 | | | SF | | | | |
| Duct | | Armaflex | | | A | Y | | 12 | | | SF | | | | |
| Floor | | Concrete (precast) | | | A | Y | | 65 | | | SF | | | | |
| Piping | | Not Insulated | | | A | Y | | 12 | | | SF | | | | |
| Structure | | Steel | | | C | Y | | 65 | | | SF | | | | |
| Wall | | Steel | | | A | Y | | 260 | | | SF | | | | |

ALL DATA REPORT

Client: Canadian Coast Guard
Location: #29 : Engine Room
Surveyor: Pinchin

Site: Vessels
Floor: NA
Survey Date: 2019-05-13

Building Name: 328088 : CCGS Limnos
Room #:
Reassessment Surveyor: Dylan Melo

Area (sqft): 600
Last Re-Assessment: 2019-05-13

| ASBESTOS | | | | | | | | | | | | | | | |
|----------------------|-------------------|-----------------|------|------------------|----|----|-----|------|------|------|------|----------|---------------|--------|--------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard |
| Ceiling | | Steel | | | C | Y | | 600 | | | SF | | | | |
| Duct | | | | Sacking compound | A | Y | | 300 | | | % | S0016ABC | None Detected | N.D. | None |
| Duct | | Fibreglass | | Canvas | A | Y | | 100 | | | | | | | |
| Duct | | Not Insulated | | | A | Y | | 50 | | | LF | | | | |
| Floor | | Steel | | | A | Y | | 600 | | | SF | | | | |
| Floor | | Abated Material | | | B | Y | | 50 | | | SF | V0000 | Non-Asbestos | | None |
| Mechanical Equipment | Generator Exhaust | Fibreglass | | Textile | A | Y | | 30 | | | LF | | | | |
| Other ¹ | Door | | | Metal | D | N | | 100 | | | | V0000 | Non-Asbestos | | None |
| Other | Window | Caulking | | | B | Y | | 60 | | | LF | S0015ABC | None Detected | N.D. | None |
| Piping | | Fibreglass | | | A | Y | | 60 | | | LF | | | | |
| Piping | | Not Insulated | | | A | Y | | 100 | | | LF | | | | |
| Structure | | Steel | | | C | Y | | 600 | | | SF | | | | |
| Wall | | Steel | | | A | Y | | 400 | | | SF | | | | |
| Wall | | Fibreglass | | Canvas | A | N | | 300 | | | % | S0017ABC | None Detected | N.D. | None |

Door to Engine Room, Control Room Fire Door

1 - Door was said to be replaced in 2005 according to Former Report, Pinchin file 28432

ALL DATA REPORT

Client: Canadian Coast Guard
Location: #30 : Diesel Generator Room
Surveyor: Pinchin

Site: Vessels
Floor: NA
Survey Date: 2019-05-13

Building Name: 328088 : CCGS Limnos
Room #:
Reassessment Surveyor: Dylan Melo

Area (sqft): 100
Last Re-Assessment: 2019-05-13

| ASBESTOS | | | | | | | | | | | | | | | |
|-----------|-----------|---|------|----------|----|----|-----|------|------|------|------|---------|---------------|--------|--------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard |
| Ceiling | | Steel | | | A | Y | | 100 | | | SF | | | | |
| Floor | | Steel | | | A | Y | | 100 | | | SF | | | | |
| Piping | | Fibreglass | | | A | Y | | 2 | | | LF | | | | |
| Structure | | Steel | | | A | Y | | 100 | | | SF | | | | |
| Wall | | Steel | | | A | Y | | 280 | | | SF | | | | |
| Wall | | Fibrous Board, Laminate fiberboard wall | | | A | Y | | 200 | | | % | S0022AB | None Detected | N.D. | None |

Client: Canadian Coast Guard
Location: #31 : Boot Room Old Incinerator Room
Surveyor: Pinchin

Site: Vessels
Floor: LOWER DECK
Survey Date: 2019-05-13

Building Name: 328088 : CCGS Limnos
Room #:
Reassessment Surveyor: Dylan Melo

Area (sqft): 10
Last Re-Assessment: 2019-05-13

| ASBESTOS | | | | | | | | | | | | | | | |
|--------------------|-----------|-----------------------------|------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|------------------------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard |
| Ceiling | | Steel | | | A | Y | | 6 | | | SF | | | | |
| Duct | | Armaflex | | | A | Y | | 12 | | | SF | | | | |
| Floor ¹ | | Vinyl Floor Tile and Mastic | | | A | Y | | | | | | V0003 | Chrysotile | 5-10% | Confirmed Asbestos(NF) |
| Piping | | Fibreglass | | Canvas | B | N | | | | | LF | | | | |
| Piping | All | Not Insulated | | | B | N | | | | | | V0000 | Non-Asbestos | | None |
| Structure | | Steel | | | C | Y | | 65 | | | SF | | | | |
| Wall | | Steel | | | A | Y | | 260 | | | SF | | | | |

1 - 9x9 painted grey

ALL DATA REPORT

Client: Canadian Coast Guard
Location: #32 : Focle Hallway
Surveyor: Pinchin

Site: Vessels
Floor: MID
Survey Date: 2019-05-13

Building Name: 328088 : CCGS Limnos
Room #:
Reassessment Surveyor: Dylan Melo

Area (sqft): 25
Last Re-Assessment: 2019-05-13

| ASBESTOS | | | | | | | | | | | | | | | |
|-----------|-----------|-----------------------------|------|----------|----|----|-----|------|------|------|------|----------|---------------|--------|--------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard |
| Floor | | Vinyl Floor Tile and Mastic | | | A | Y | | 100 | | | % | S0011ABC | None Detected | N.D. | None |
| Other | Door | Thermal Insulation | | | D | N | | 1 | | | EA | S0019C | None Detected | N.D. | None |
| Structure | | Steel | | | B | N | | 100 | | | % | | | | |
| Structure | | Fibreglass | | | B | N | | 100 | | | % | V0002 | None Detected | N.D. | None |
| Wall | | Steel | | | | | | | | | | | | | |

Client: Canadian Coast Guard
Location: #33 : Lamp Locker
Surveyor: Pinchin

Site: Vessels
Floor:
Survey Date:

Building Name: 328088 : CCGS Limnos
Room #:
Reassessment Surveyor: Dylan Melo

Area (sqft): 0
Last Re-Assessment: 2019-05-13

| ASBESTOS | | | | | | | | | | | | | | | |
|----------|-----------|---|------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard |
| Ceiling | | Fibrous Board, Laminate fiberboard | | | C | Y | | 40 | | | SF | V0022 | None Detected | N.D. | None |
| Floor | | Metal | | | A | Y | | | | | | | | | |
| Piping | | Metal | | | A | Y | | | | | | | | | |
| Wall | | Fibrous Board, Laminate fiberboard wall | | | A | Y | | 100 | | | % | S0022C | None Detected | N.D. | None |

Legend:

| Sample number | | Units | | Other | |
|---------------|--|-------|-------------|-------|-----------------------|
| S#### | Sample collected. | SF | Square feet | SVM | Suspect Visible Mould |
| V#### | Material is visually identified to be identical to S#### | LF | Linear feet | A | Access |
| V0000 | Known non hazardous material. | EA | Each | V | Visible |
| V9000 | Material is visually identified to contain hazardous material. | % | Percentage | AP | Air Plenum |
| V9500 | Material is presumed to contain hazardous material. | | | F | Friable material. |
| | | | | NF | Non Friable material. |

| Access | | Condition | |
|--------|--|-----------|--|
| A | Accessible to all building occupants | Good | No visible damage or deterioration |
| B | Accessible to maintenance and operations staff without a ladder | Fair | Minor, repairable damage, cracking or deterioration. |
| C | Accessible to maintenance and operations staff with a ladder. Also rarely entered, locked areas. | Poor | Irreparable damage or deterioration with exposed and missing material. |
| D | Not normally accessible or without demolition | | |

APPENDIX VIII
TEM Air Sample Lab Analysis Report



Air Monitoring for Asbestos by Transmission Electron Microscopy

CCGS Limnos
Vessel Number 328088
370 Dalhousie Street,
Amherstburg, Ontario

Prepared for:

Canadian Coast Guard

520 Exmouth Street
Sarnia, Ontario, N7T 8B1
Attention: Leslie Anne Veldman

Project Officer, Marine Engineering, Central and Arctic

June 4, 2019

Pinchin File: 241027



Issued to: Canadian Coast Guard
Contact: Leslie Anne Veldman
Project Officer, Marine
Engineering, Central and Artic
Issued on: June 4, 2019
Pinchin File: 241027
Issuing Office: Tilbury, ON
Primary Pinchin
Contact: Graham Rogers
519.682.4492 ext. 3302
grogers@pinchin.com

Author:

Dylan Melo, B.Sc.
Project Technologist
519.682.4492 ext. 3307
dmelo@pinchin.com

Reviewer:

Tina Manning, CRSP, PMP, LEED AP
Operations Manager
519.682.4492 ext. 3301
tmanning@pinchin.com



TABLE OF CONTENTS

| | | |
|-----|---|---|
| 1.0 | INTRODUCTION AND SCOPE | 1 |
| 2.0 | BACKGROUND: TYPICAL AIRBORNE ASBESTOS CONCENTRATIONS IN BUILDINGS AND OUTDOOR AIR | 1 |
| 3.0 | SAMPLING AND ANALYTICAL PROCEDURE..... | 3 |
| 4.0 | RESULTS AND DISCUSSION | 4 |
| 5.0 | TERMS AND LIMITATIONS | 5 |

APPENDICES

| | |
|------------|--------------------|
| APPENDIX I | Analytical Results |
|------------|--------------------|



1.0 INTRODUCTION AND SCOPE

Canadian Coast Guard (Client) retained Pinchin Ltd. (Pinchin) to measure airborne asbestos concentrations in the CCGS Limnos vessel docked at 370 Dalhousie Street, Amherstburg, Ontario.. The samples were analyzed using Transmission Electron Microscopy (TEM).

The following sections of this report describe the collection and analysis of three (3) air samples collected at locations selected by the Client and included the Focle Deck, MCR, and the Lower Deck Hallway (between the Mess and Old Incinerator Room). The results are discussed in relation to asbestos levels detected in ambient air.

2.0 BACKGROUND: TYPICAL AIRBORNE ASBESTOS CONCENTRATIONS IN BUILDINGS AND OUTDOOR AIR

In order to interpret the results of the air monitoring, it is necessary to discuss the general meaning and use of air sampling. No standards or guidelines for the assessment of asbestos exposures in occupied buildings by TEM have been published by any federal or provincial authority.

For control of airborne asbestos fibre concentrations in workplaces where asbestos is used in industrial operations, the Ontario Ministry of Labour (MOL) Regulation 278/05 applies a 40 hour per week exposure limit of 0.1 fibres/mL of air longer than 5 micrometres (fibres/mL >5 µm). This exposure limit applies to all types of asbestos fibres. The specified measurement technique is phase contrast optical microscopy (PCM). In this technique, the sample is examined under phase contrast illumination at a magnification of 450x and all particles that meet the following criteria are counted as fibres:

- Longer than 5 µm;
- Diameter of less than 3 µm;
- Length to width (aspect) ratio equal to or greater than 3:1.

The PCM method cannot distinguish asbestos fibres from other common fibrous particles such as cellulose, fibreglass, synthetic fibres or mineral wool. The resolution of the PCM microscope under these conditions is about 0.25 µm. Fibres thinner than this diameter will not be included in the count, regardless of their length. The detection limit varies with the sampling volume. However, the practical lower limit of quantitation in general use buildings is 0.01-0.03 fibres/mL, due to the common presence of other fibrous and dusts at these levels, and overloading of the filter by general building dust if a higher sampling volume was used. Given these limitations, this measurement technique is generally applied only where most airborne fibres are likely to be asbestos, such as in the asbestos industry or inside or immediately adjacent to or following asbestos abatement operations.



Existing legislation and environmental guidelines concerning permissible airborne asbestos fibre concentrations are expressed in terms of those fibres having lengths exceeding 5 micrometers (μm). There is a general, although not universal, agreement that shorter fibres pose a much lower hazard to health than long fibres. As stated by the Ontario Royal Commission on Asbestos¹ (Page 8 Chapter 1, Section B; Health Effects of Asbestos).

"The asbestos fibres which are most likely to cause adverse health effects when inhaled are long and thin. "Length" and "diameter" are, of course, relative phenomena: fibres are measured in microns, one micron being one-millionth of a metre. The hazardous asbestos fibres are those which would be longer than 5, perhaps longer than 8 microns, and thinner than 1.5 or perhaps 0.25 microns."

When airborne asbestos fibres are present in the outdoor environment, they are generally too thin to be detected by phase contrast microscopy. In addition, in areas where asbestos is not the principal source of airborne dust, the concentration of airborne asbestos fibres is not necessarily correlated with the total fibre concentration. Particles or aggregates of particles can appear to be fibres when viewed under the conditions of the PCM examination. Conversely, particles, which appear in PCM to be non-fibrous particles, may actually be closely associated groups of fibres. In these circumstances it is not possible to predict the airborne asbestos level from the result of a measurement made by PCM.

Guidelines have not been established specifically for asbestos air quality in non-industrial, general occupancy buildings. The most thorough literature review of TEM air monitoring of buildings containing Asbestos Containing Material (ACM) was published in 1991 by the Health Effects Institute.² Based on the results of monitoring of 198 buildings containing ACM, their report stated that the concentration of airborne asbestos fibres (longer than 5 μm) ranged from 0.00004 to 0.00243 fibres/mL with a mean concentration of 0.00027 fibres/mL and a 95% percentile of 0.0014 fibres/mL. Based on this, it is clear that the existence of airborne fibres longer than 5 μm , even in a building with ACM, is relatively uncommon. It should be noted however that low levels of short (<5 μm) chrysotile fibres are commonly found in both outdoor air and in buildings with and without ACM. Although no study has provided an average for short fibres (as was provided by the HEI for fibres longer than 5 μm) it is quite common in Pinchin's experience to detect up to 3 fibres of short chrysotile asbestos in the TEM counting area of a typical air sample (with a volume collected in the order of 2000-2400 litres), equivalent to a concentration of about 0.01 fibres/mL. Amosite or crocidolite types of asbestos are very rarely detected in outdoor or building air.

1 Report of the Royal Commission on Matters of Health and Safety Arising from the Use of Asbestos in Ontario, Queens Printer for Ontario, Toronto 1984.

2 Asbestos in Public and Commercial Buildings: A Literature Review and Synthesis of Current Knowledge, Health Effects Institute-Asbestos Research, Cambridge, MA, 1991.



Based on all of the above studies and experience, Pinchin believes that it is reasonable to consider the asbestos concentration in a building atypical in any of the following circumstances:

- The average concentration of fibres $>5\mu\text{m}$ exceeds 0.0014 fibres/mL (the 95th percentile of the HEI reported result); or
- The concentration of short chrysotile asbestos fibres exceeds 0.01 fibres/mL; or
- Asbestos fibres other than chrysotile are detected in the sample.

These criteria will be used to evaluate the air samples collected. It should be noted that even if concentrations exceed these criteria they do not automatically imply an actual health risk to occupants – merely an elevated level of airborne asbestos at the time of sampling.

3.0 SAMPLING AND ANALYTICAL PROCEDURE

The air sampling was conducted on May 13, 2019 at 9:00 am. The vessel occupants were present during the sampling period and the air handling systems remained operational.

The sampling locations were chosen by Canadian Coast Guard. The following presents the sampling details.

| Sample Number | Location | Run Time (minutes) | Volume (L) |
|----------------------|-------------------------|---------------------------|-------------------|
| 303848 | N/A-Blank | N/A | N/A |
| 303829 | Aft Entrance Lower Deck | 70 | 1056.3 |
| 303849 | Focle Deck | 70 | 1055.04 |
| 303841 | MCR | 70 | 1052.31 |

The samples were collected by drawing predetermined volumes of air through a mixed cellulose ester (MCE) filter having a pore size of $0.45\mu\text{m}$ complete with backup pad, and an effective collection area of 380 mm^2 . The filter is held in a 25 mm three-piece conductive cassette with a 50 mm extension cowl. Diaphragm vacuum pumps were used in sample collection. The pumps were calibrated using a primary standard before use. Sampling volumes were adjusted for the anticipated airborne fibre level, to give appropriate concentrations of fibres on the filter surface. Known flow rates were provided either by battery operated constant-flow personal air sampling pumps, or by AC-powered vacuum pumps and critical orifice controllers. The sampling equipment was flow calibrated with a DryCal Lite calibrator prior to sampling. Calibration was confirmed after sampling with either a DryCal or flowmeter. The pumps were generally collected open-faced at heights representative of occupant breathing zones (approximately 4.5 feet to 6 feet).



The samples were analyzed by Transmission Electron Microscopy (TEM) at Scientific Analytical Institute Inc. in Greensboro North Carolina according to the NIOSH 7402 method. This method is used to allow comparison with occupational exposure limits based on the PCM method, which has limited resolving power compared to the TEM methods and also counts all fibres as asbestos. First the sample is analysed by PCM to produce a fibre/cc count. Then another section of the sample is analysed by TEM, using methods similar to the Yamate method, except that only fibres that meet the NIOSH 7400 counting criteria (diameter $>0.25\ \mu\text{m}$; aspect ratio 3:1 or higher; longer than $5\ \mu\text{m}$) are counted. The % of asbestos fibres in the optically visible range is determined in the TEM. This percentage is then multiplied by the result obtained by the Phase Contrast Microscope (PCM) result to obtain a final result for asbestos in f/cc. This eliminates the overestimate caused by counting of non-asbestos fibres in the PCM method and eliminates asbestos fibres that would have been too thin to count by PCM.

The analytical results are provided in Appendix II of this report. The number of fibres detected (both Asbestos and Non-Asbestos Fibers) and the concentration in fibres/cc are reported in the analytical results. The results are reported in f/cc and are interpreted in exactly the same way as a normal PCM count. The only differences is that non-asbestos fibres in the optically visible range by PCM (diameter greater than $0.25\ \mu\text{m}$, aspect ratio $\geq 3:1$, longer than $5.0\ \mu\text{m}$) have been eliminated from the reported result. The calculated concentration of asbestos present is dependent upon the number of structures counted, the area of the filter analyzed, the effective collection area of the filter and the volume of air drawn through the filter. If no asbestos structures are identified in the sample, the result is reported as being less than the Limit of Detection.

4.0 RESULTS AND DISCUSSION

The analytical results are attached and summarized below for clarity. The attached results are presented by # or asbestos fibres present and the concentration in fibres/cc.

The calculated concentration of asbestos present is dependent upon the number of grid openings analyzed, the number of structures counted, the area of the filter analyzed, the effective collection area of the filter and the volume of air drawn through the filter. If no asbestos structures are identified in the sample, the result is reported as being less than the Limit of Detection. Analytical results are attached and summarized below.



| Date | Sample ID | Volume Sampled | Description of Sample | PCM Concentration (f/cc) | # of Asbestos Fibres | Concentration Asbestos Fibers/cc (fibres/mL), |
|--------------|-----------|----------------|----------------------------------|--------------------------|----------------------|---|
| May 13, 2019 | 303848 | N/A | Blank | <0.02 | None Detected | <0.00096 |
| May 13, 2019 | 303829 | 1056.3 | Occupied Aft Entrance Lower Deck | <0.02 | None Detected | <0.00096 |
| May 13, 2019 | 303849 | 1055.04 | Occupied Focle Deck | <0.02 | None Detected | <0.00096 |
| May 13, 2019 | 303841 | 1052.31 | Occupied MCR | <0.02 | None Detected | <0.00096 |

The three (3) samples were collected in typical areas of the vessel during normal use and occupation.

The analytical results presented in Appendix I show that all the samples contained no asbestos fibres.

The calculated concentration is less than the analytical sensitivity of 0.00096 fibres/cc (or fibres/mL).

Based on the results of this monitoring, the airborne concentration of asbestos in the locations tested was not considered elevated and well below the Occupational Exposure Limit (OEL) of 0.1 fibres/mL.

5.0 TERMS AND LIMITATIONS

This work was performed subject to the Terms and Limitations presented or referenced in the proposal for this project.

Information provided by Pinchin is intended for Client use only. Pinchin will not provide results or information to any party unless disclosure by Pinchin is required by law. Any use by a third party of reports or documents authored by Pinchin or any reliance by a third party on or decisions made by a third party based on the findings described in said documents, is the sole responsibility of such third parties. Pinchin accepts no responsibility for damages suffered by any third party as a result of decisions made or actions conducted. No other warranties are implied or expressed.

J:\241000s\0241027.000 CanadianCoastGuard,CCGSLimnos,HAZ,REASST\Deliverables\241027 CGS Limno Vessel TEM Airborne Asbestos Report.docx

Template: Master TEM Airborne Asbestos Report, Haz, April 23, 2019

APPENDIX I
Analytical Results



Airborne Asbestos Analysis

By Transmission Electron Microscopy

NIOSH 7402
SAI Method T-SOP-006



Client: Pinchin Ltd.
2470 Milltower Court
Mississauga, ON L5N 7W5
Project: Canadian Coast Guard,
Hazardous Materials
Reassessment, 370

Attn: Graham Rogers
D Melo
T Deweerd

Lab Order ID: 71913439
Date Received: 05/17/2019
Date Reported: 05/22/2019

Page: 1 of 1

| Sample ID | Description | Volume (L) | PCM Concentration (f/cc)* | # Non-Asbestos Fibers | # Asbestos Fibers | Concentration |
|---------------|-------------------------|----------------------------------|---------------------------|-----------------------|-------------------|--------------------|
| Lab Sample ID | Lab Notes | Area Analyzed (mm ²) | | | | Asbestos Fibers/cc |
| 303848 | Field Blank | 0 | N/A | 0 | None Detected | N/A |
| 71913439TNI_1 | | 0.380 | | | | |
| 303829 | Aft Entrance Lower Deck | 1056 | <0.02 | 0 | None Detected | <0.00096 |
| 71913439TNI_2 | | 0.380 | | | | |
| 303849 | Focle Deck | 1055 | <0.02 | 0 | None Detected | <0.00096 |
| 71913439TNI_3 | | 0.380 | | | | |
| 303841 | MCR | 1052 | <0.02 | 0 | None Detected | <0.00096 |
| 71913439TNI_4 | | 0.380 | | | | |

*PCM data provided by client

Daniel Schwartz

Analyst

Lab Director


This report relates only to the samples test and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by AIHA or any other agency of the U.S. government. Scientific Analytical Institute participates in the AIHA IHPAT program. IHPAT Laboratory ID: 173190 Unless otherwise noted blank sample correction was not performed on analytical results.

Scientific Analytical Institute, Inc. 4604 Dundas Dr. Greensboro, NC 27407 (336) 292-3888

T-F-007 EXP: 3/1/2020


71913439

Version 1-15-2012

| | | | |
|------------------------|--|---|--|
| Client: | Pinchin Ltd. | *Instructions: Use Column "B" for your contact info To See an Example Click the bottom Example Tab. Enter samples between "<<" and ">>" Begin Samples with a "<<" above the first sample and end with a ">>" below the last sample. Only Enter your data on the first sheet "Sheet1" Note: Data 1 and Data 2 are optional fields that do not show up on the official report, however they will be included in the electronic data returned to you to facilitate your reintegration of the report data. | Invoice to: |
| Contact: | Graham Rogers | | Graham Rogers |
| Address: | 2470 Milltower court | | ap@pinchin.com |
| Phone: | 905-363-0678 | | |
| Fax: | 905-363-0681 | | |
| Email: | grogers@pinchin.com;dmelo@pinchin.com;tdeweerd@pinchin.com | | |
| Project: | Canadian Coast Guard, Hazardous | | Scientific Analytical Institute  4604 Dundas Dr. Greensboro, NC 27407 Phone: 336.292.3888 Fax: 336.292.3313 Email: lab@sailab.com |
| Client Notes: | Canadian Coast Guard | | |
| P.O. #. | 241027 | | |
| Date Submitted: | May 15/2019 | | |
| Analysis: | TEM Niosh 7402 Method | | |
| TurnAroundTime: | Regular B6 | | |

| Sample Number | Data 1 (Lab use only) | Sample Description | Data 2 (Lab use only) |
|---------------|-----------------------|-------------------------|-----------------------|
| << | | | |
| | 303848 | Field Blank | |
| | 303829 | Aft Entrance Lower Deck | |
| | 303849 | Focle Deck | |
| | 303841 | MCR | |
| >> | | | |

Accepted ☒Rejected ☐

 5.17
 10:30A