

APPENDIX 5
WATER ACCESS



Photo 1: Looking north – Light Tower building is to the right outside of photo frame.



Photo 2: Looking north – showing possible landing slip. Same location as shown in Photo 1 above.



Photo 3: Looking north-east towards the Light Tower building. Remains of former concrete dock.



Photo 4: Closer view of remains of former concrete dock.



Photo 5: Looking north-west at possible landing slip.



Photo 6: Looking south towards the site. Shore conditions on the north side of the island.