

APPENDIX 5
SITE PHOTOGRAPHS



Photograph No.1 – View of light tower facing northwest.



Photograph No.2 – View of former light keepers dwelling facing northwest.



Photograph No.3 – View of flat area south of light tower.



Photograph No.4 – View of light tower and former light keeper dwelling facing west from base of slope.



Photograph No.5 – View of shale and vegetation half-way down slope facing west.



Photograph No.6 – View of slope facing north.



Photograph No.7 – View of slope facing north-northwest



Photograph No.8 – View of slope facing north-northwest



Photograph No.9 – View of cobble shoreline facing south-southwest.



Photograph No.10 – View facing south



Photograph No. 11 – View of site facing southwest.



Photograph No.12 – View of spend shell casings along footpath towards shoreline.