

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

<b>Building Number :</b> 520092	<b>Survey date:</b>	<b>Building name or address</b> Gulf Fisheries
---------------------------------	---------------------	--

**Level :** 0 - Basement

**Asbestos present :** potential

**Room :** 001 - Mechanical Room

Ceiling	concrete	N/A
Duct	not insulated	N/A
Floor	concrete	N/A
Mechanical	Fiberglass	N/A
Pipe	fiberglass	N/A
Structure	steel	N/A
Wall	concrete	N/A

## Comments:

**Level :** 0 - Basement

**Asbestos present :** potential

**Room :** 002/008 - Mechanical Room

Ceiling	concrete	N/A
Duct	not insulated	N/A
Floor	concrete	N/A
Mechanical	Fiberglass	N/A
Pipe	fiberglass	N/A
Structure	steel	N/A
Wall	concrete	N/A

## Comments:

**Level :** 0 - Basement

**Asbestos present :** potential

**Room :** 003 - Mechanical Room

Ceiling	concrete	N/A
Duct	not insulated	N/A
Floor	concrete	N/A
Mechanical	Fiberglass	N/A
Pipe	fiberglass	N/A

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond. Sample	Asbestos type	Access.	Action
Structure	steel		N/A			
Wall	concrete		N/A			

## Comments:

**Level : 0 - Basement**

**Asbestos present :** potential

**Room : 004 - Mechanical Room**

Ceiling	concrete		N/A			
Duct	not insulated		N/A			
Floor	concrete		N/A			
Mechanical	Fiberglass		N/A			
Pipe	fiberglass		N/A			
Pipe	not insulated		N/A			
Structure	steel		N/A			
Wall	concrete		N/A			

## Comments:

**Level : 0 - Basement**

**Asbestos present :** potential

**Room : 004A - Storage Room**

Ceiling	concrete		N/A			
Duct	not insulated		N/A			
Floor	concrete		N/A			
Mechanical	Fiberglass		N/A			
Pipe	fiberglass		N/A			
Pipe	not insulated		N/A			
Structure	steel		N/A			
Wall	concrete		N/A			

## Comments:

**Level : 0 - Basement**

**Asbestos present :** potential

**Room : 004B - Storage Room**

Ceiling	concrete		N/A			
---------	----------	--	-----	--	--	--

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond. Sample	Asbestos type	Access.	Action
Duct	not insulated		N/A			
Floor	concrete		N/A			
Mechanical	Fiberglass		N/A			
Pipe	fiberglass		N/A			
Pipe	not insulated		N/A			
Structure	steel		N/A			
Wall	concrete		N/A			

## Comments:

Level : 0 - Basement

Asbestos present : potential

Room : 004C - Storage Room

Ceiling	concrete		N/A			
Duct	not insulated		N/A			
Floor	concrete		N/A			
Mechanical	Fiberglass		N/A			
Pipe	fiberglass		N/A			
Pipe	not insulated		N/A			
Structure	steel		N/A			
Wall	concrete		N/A			

## Comments:

Level : 0 - Basement

Asbestos present : potential

Room : 004D - Oil Tank Room

Ceiling	concrete		N/A			
Duct	not insulated		N/A			
Floor	concrete		N/A			
Mechanical	Fiberglass		N/A			
Pipe	fiberglass		N/A			
Pipe	not insulated		N/A			
Structure	steel		N/A			
Wall	concrete		N/A			

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond. Sample	Asbestos type	Access.	Action
--------	-------------	----------	--------------	---------------	---------	--------

## Comments:

**Level : 0 - Basement**

**Asbestos present :** potential

**Room : 005 - Mechanical Room**

Ceiling	concrete	N/A
Duct	not insulated	N/A
Floor	concrete	N/A
Mechanical	Fiberglass	N/A
Pipe	fiberglass	N/A
Structure	steel	N/A
Wall	concrete	N/A

## Comments:

**Level : 0 - Basement**

**Asbestos present :** potential

**Room : 009 - Mechanical Room**

Ceiling	concrete	N/A
Duct	not insulated	N/A
Floor	concrete	N/A
Mechanical	Fiberglass	N/A
Pipe	fiberglass	N/A
Structure	steel	N/A
Wall	concrete	N/A

## Comments:

**Level : 0-1 - Ground Level**

**Asbestos present :** potential

**Room : 006 - storage**

Ceiling	drywall	N/A	V-024
Floor	concrete	N/A	
Pipe	fiberglass	N/A	
Pipe	parging	N/A	V-015
Wall	concrete	N/A	

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

Wall	drywall		N/A	V-024			
------	---------	--	-----	-------	--	--	--

**Comments:**

**Level :** 0-1 - Ground Level  
**Room :** 006A - Lunch Room

**Asbestos present :** potential

Ceiling	plaster		N/A				
Floor	concrete		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-024			

**Comments:**

**Level :** 0-1 - Ground Level  
**Room :** 007 - Storage Room

**Asbestos present :** potential

Ceiling	drywall		N/A				
Floor	plywood		N/A				
Pipe	not insulated		N/A				
Wall	brick		N/A				
Wall	cinder block		N/A				

**Comments:** no access into walls or ceiling cavities  
Located above Rooms 004 area.

**Level :** 0-1 - Ground Level  
**Room :** 039 - Chemical Storage

**Asbestos present :** potential

Ceiling	drywall		N/A	V-024			
Duct	not insulated		N/A				
Floor	Concrete		N/A				
Pipe	not insulated		N/A				
Wall	cinder block		N/A				

**Comments:** No access into walls or ceilings

**Level :** 0-1 - Ground Level  
**Room :** 049 - Chemical Storage

**Asbestos present :** potential

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Ceiling	drywall						
Duct	not insulated						
Floor	Concrete						
Pipe	not insulated						
Wall	cinder block						

**Comments:** No access into walls or ceilings

**Level :** 0-1 - Ground Level

**Asbestos present :** potential

**Room :** 049A - Chemical Storage

Ceiling	drywall						
Duct	not insulated						
Floor	Concrete						
Pipe	not insulated						
Wall	cinder block						

**Comments:** No access into walls or ceilings

**Level :** 0-1 - Ground Level

**Asbestos present :** potential

**Room :** 049B - Chemical Storage

Ceiling	drywall						
Duct	not insulated						
Floor	Concrete						
Pipe	not insulated						
Wall	cinder block						

**Comments:** No access into walls or ceilings

**Level :** 0-1 - Ground Level

**Asbestos present :** potential

**Room :** 049EXT - Exterior

Wall	Concrete						
Wall	fiberglass						
Wall	Stucco					NEW	
Wall	Styrofoam						

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

**Comments:** No access into walls

**Level :** 1 - 1st Floor

**Asbestos present :** potential

**Room :** 100 - Hallway

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-030			
Duct	not insulated		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	fiberglass		N/A				
Pipe	parging		N/A	V-015			
Wall	drywall		N/A	V-024			

**Comments:**

**Level :** 1 - 1st Floor

**Asbestos present :** potential

**Room :** 101 - Electrical Room

Ceiling	concrete		N/A				
Duct	not insulated		N/A				
Electrical	not insulated		N/A				
Floor	concrete		N/A				
Pipe	not insulated		N/A				
Structure	concrete		N/A				
Wall	concrete		N/A				

**Comments:**

**Level :** 1 - 1st Floor

**Asbestos present :** potential

**Room :** 101A - Electrical Room

Ceiling	concrete		N/A				
Duct	not insulated		N/A				
Electrical	not insulated		N/A				
Floor	concrete		N/A				
Pipe	not insulated		N/A				

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Structure	concrete		N/A				
Wall	concrete		N/A				

## Comments:

**Level : 1 - 1st Floor**

**Asbestos present : potential**

**Room : 101B - Electrical Room**

Ceiling	concrete		N/A				
Duct	not insulated		N/A				
Electrical	not insulated		N/A				
Floor	concrete		N/A				
Pipe	not insulated		N/A				
Structure	concrete		N/A				
Wall	concrete		N/A				

## Comments:

**Level : 1 - 1st Floor**

**Asbestos present : potential**

**Room : 102 - Stairwell**

Ceiling	plaster		N/A	V-030			
Floor	vinyl sheet flooring		N/A	V-012			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-024			
Wall	plaster		N/A	V-029			

## Comments:

**Level : 1 - 1st Floor**

**Asbestos present : potential**

**Room : 106 - storage**

Ceiling	plaster		N/A	V-030			
Floor	vinyl sheet flooring		N/A	V-012			
Pipe	fiberglass		N/A				
Pipe	not insulated		N/A				
Pipe	paring		N/A	V-015			



# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Pipe	parging		N/A	V2010-01			
Wall	drywall		N/A	V-024			
Wall	plaster		N/A	V-029			

## Comments:

**Level : 1 - 1st Floor**

**Asbestos present : potential**

**Room : 106A - Freezer**

Ceiling	metal		N/A				
Floor	concrete		N/A				
Pipe	insulation		N/A				
Pipe	not insulated		N/A				
Wall	metal		N/A				

## Comments:

**Level : 1 - 1st Floor**

**Asbestos present : potential**

**Room : 107 - Lab**

Ceiling	plaster		N/A	V-030			
Floor	vinyl sheet flooring		N/A	V-012			
Pipe	fiberglass		N/A				
Pipe	not insulated		N/A				
Pipe	parging		N/A	V2010-01			
Wall	ceramic tile		N/A				

**Comments:** no access into walls or ceiling cavities

**Level : 1 - 1st Floor**

**Asbestos present : potential**

**Room : 108 - Lab**

Ceiling	2' x 4' fiberglass		N/A				
Floor	vinyl sheet flooring		N/A	V-012			
Other	Fume Hood - Metal		N/A				
Pipe	fiberglass		N/A				

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user: All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Pipe	not insulated		N/A				
Pipe	parging		N/A	2010-01A			
Wall	ceramic tile		N/A				

**Comments:** no access into walls or ceiling cavities  
Pipe elbows new (1990's) according to Chris from SNC.

<b>Level :</b> 1 - 1st Floor	<b>Asbestos present :</b> potential
<b>Room :</b> 109 - Lab	

Ceiling	2' x 4' fibreglass	N/A	
Duct	not insulated	N/A	
Floor	vinyl sheet flooring	N/A	V-012
Other	Fume Hood - Metal	N/A	
Pipe	fiberglass	N/A	
Pipe	not insulated	N/A	
Wall	ceramic tile	N/A	

**Comments:** no access into walls or ceiling cavities

<b>Level :</b> 1 - 1st Floor	<b>Asbestos present :</b> potential
<b>Room :</b> 110 - Lab	

Ceiling	2' x 4' fibreglass	N/A	
Duct	not insulated	N/A	
Floor	vinyl sheet flooring	N/A	V-012
Other	Fume Hood - Metal	N/A	
Pipe	fiberglass	N/A	
Pipe	not insulated	N/A	
Wall	ceramic tile	N/A	

**Comments:** no access into walls or ceiling cavities

<b>Level :</b> 1 - 1st Floor	<b>Asbestos present :</b> potential
<b>Room :</b> 110A - Lab	

Ceiling	2' x 4' fibreglass	N/A	
---------	--------------------	-----	--

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Duct	not insulated		N/A				
Floor	vinyl sheet flooring		N/A	V-012			
Other	Fume Hood - Metal		N/A				
Pipe	fiberglass		N/A				
Pipe	not insulated		N/A				
Wall	ceramic tile		N/A				

**Comments:** no access into walls or ceiling cavities

**Level :** 1 - 1st Floor

**Asbestos present :** potential

**Room :** 111 - Lab

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-030			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A	025			
Pipe	fiberglass		N/A				
Pipe	not insulated		N/A				
Pipe	parging		N/A	V2010-01			
Wall	drywall		N/A	V-024			
Wall	plaster		N/A	V-029			

**Comments:**

**Level :** 1 - 1st Floor

**Asbestos present :** potential

**Room :** 112 - Elevator

No Access	unsurveyed		N/A				
-----------	------------	--	-----	--	--	--	--

**Comments:** no access

**Level :** 1 - 1st Floor

**Asbestos present :** potential

**Room :** 113 - Hallway

Ceiling	2' x 4' fibreglass		N/A				
Duct	not insulated		N/A				

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Floor	vinyl sheet flooring		N/A	V-035			
Pipe	fiberglass		N/A				
Wall	drywall		N/A	024			

## Comments:

<b>Level :</b> 1 - 1st Floor	<b>Asbestos present :</b> potential
<b>Room :</b> 114 - Lab	

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-030			
Floor	vinyl sheet flooring		N/A	V-035			
Fumehood	Panel		N/A	V-020			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-024			
Wall	plaster		N/A	V-039			

## Comments:

<b>Level :</b> 1 - 1st Floor	<b>Asbestos present :</b> potential
<b>Room :</b> 114A - Lab	

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-030			
Floor	vinyl sheet flooring		N/A	V-035			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-024			

## Comments:

<b>Level :</b> 1 - 1st Floor	<b>Asbestos present :</b> yes
<b>Room :</b> 115 - Stairwell	

Ceiling	plaster		N/A	V-041			
Ceiling	plaster		N/A	V-030			
Floor	vinyl sheet flooring		N/A	V-012			
Pipe	Elbows - Parging	7.0	units	good	V-022	Chrysotile 80.00%	C 7

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user: All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Pipe	fiberglass		N/A				
Pipe	parging		N/A	V-015			
Pipe	tees	1.0	Unknown good	V-022	Chrysotile 80.00%	C	7
Wall	plaster		N/A	V-039			

## Comments:

**Level : 1 - 1st Floor**

**Asbestos present : yes**

**Room : 116 - Gym**

Ceiling	plaster		N/A	V-030			
Duct	not insulated		N/A				
Floor	vinyl sheet flooring		N/A				
Pipe	Elbows - Parging	6.0	units	good	V-022	Chrysotile 80.00%	C 7
Pipe	insulation	30.0	ft	fair	V-023	Chrysotile 60.00%	C 6
Wall	plaster		N/A	V-039			

## Comments:

Gaps in pipe insulation - exposed ends.

**Level : 1 - 1st Floor**

**Asbestos present : yes**

**Room : 116A - Aquarium**

Ceiling	plaster		N/A	V-030			
Floor	ceramic tile		N/A				
Mechanical	not insulated		N/A				
Pipe	Elbows - Parging	19.0	units	good	V-022	Chrysotile 80.00%	C 7
Pipe	insulation	75.0	ft	fair	V-023	Chrysotile 60.00%	C 5
Wall	plaster		N/A	V-039			

## Comments:

Gaps in pipe insulation - exposed ends.

**Level : 1 - 1st Floor**

**Asbestos present : potential**

**Room : 118 - Lab**

Ceiling	drywall		N/A	V-024			
Floor	vinyl sheet flooring		N/A	V-035			

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Fumehood	Panel		N/A	V-020			
Wall	drywall		N/A	V-024			
Wall	plaster		N/A	GF-2009-09			
Wall	plaster		N/A	GF-2009-10			

## Comments:

**Level : 1 - 1st Floor**

**Asbestos present : potential**

**Room : 118A - Lab**

Ceiling	drywall		N/A	V-024			
Floor	vinyl sheet flooring		N/A	V-035			
Wall	drywall		N/A	V-024			

## Comments:

**Level : 1 - 1st Floor**

**Asbestos present : potential**

**Room : 119 - Lab**

Ceiling	plaster		N/A	V-030			
Floor	vinyl sheet flooring		N/A	V-012			
Pipe	fiberglass		N/A				
Pipe	parging		N/A	V-015			
Wall	plaster		N/A	V-039			

## Comments:

**Level : 1 - 1st Floor**

**Asbestos present : potential**

**Room : 119A - Lab**

Ceiling	plaster		N/A	V-030			
Floor	vinyl sheet flooring		N/A	V-012			
Pipe	fiberglass		N/A				
Pipe	parging		N/A	V-015			
Wall	plaster		N/A	V-039			

## Comments:

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

**Level : 1 - 1st Floor**  
**Room : 119B - Lab**

**Asbestos present : potential**

Ceiling	plaster		N/A	V-030			
Floor	vinyl sheet flooring		N/A	V-012			
Pipe	fiberglass		N/A				
Pipe	parging		N/A	V-015			
Wall	plaster		N/A	V-039			

## Comments:

**Level : 1 - 1st Floor**  
**Room : 119C - Lab**

**Asbestos present : potential**

Ceiling	plaster		N/A	V-030			
Floor	vinyl sheet flooring		N/A	V-012			
Pipe	fiberglass		N/A				
Pipe	parging		N/A	V-015			
Wall	plaster		N/A	V-039			

## Comments:

**Level : 1 - 1st Floor**  
**Room : 120 - Office**

**Asbestos present : potential**

Ceiling	drywall		N/A	V-024			
Floor	vinyl sheet flooring		N/A	V-012			
Pipe	fiberglass		N/A				
Pipe	parging		N/A	V-015			
Wall	drywall		N/A	V-024			

## Comments:

**Level : 1 - 1st Floor**  
**Room : 121 - Lab**

**Asbestos present : potential**

Ceiling	drywall		N/A	V-024			
Floor	vinyl sheet flooring		N/A	V-035			

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Fumehood	Panel		N/A	V-020			
Wall	drywall		N/A	V-024			

## Comments:

**Level : 1 - 1st Floor**

**Asbestos present : potential**

**Room : 122 - Hall**

Ceiling	2' x 4' fibreglass		N/A				
Floor	vinyl sheet flooring		N/A	NEW			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-024			

**Comments:** no access into walls or ceiling cavities

**Level : 1 - 1st Floor**

**Asbestos present : potential**

**Room : 123 - Freezer**

Ceiling	metal		N/A				
Floor	concrete		N/A				
Pipe	insulation		N/A				
Wall	metal		N/A				

## Comments:

**Level : 1 - 1st Floor**

**Asbestos present : potential**

**Room : 124 - Lab**

Ceiling	drywall		N/A	V-024			
Floor	vinyl sheet flooring		N/A	V-035			
Fumehood	Panel		N/A	V-020			
Wall	drywall		N/A	V-024			

## Comments:

**Level : 1 - 1st Floor**

**Asbestos present : potential**

**Room : 125 - Lab**

Ceiling	drywall		N/A	V-024			
---------	---------	--	-----	-------	--	--	--



# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Floor	vinyl sheet flooring		N/A	V-035			
Fumehood	Panel		N/A	V-020			
Wall	drywall		N/A	V-024			

## Comments:

**Level : 1 - 1st Floor**  
**Room : 126 - Hallway**

**Asbestos present : potential**

Ceiling	plaster		N/A	V-030			
Floor	concrete		N/A				
Pipe	fiberglass		N/A				
Pipe	parging		N/A	V-015			
Wall	drywall		N/A	V-024			

## Comments:

**Level : 1 - 1st Floor**  
**Room : 127 - Hallway**

**Asbestos present : potential**

Ceiling	plaster		N/A	V-028			
Floor	vinyl sheet flooring		N/A	V-012			
Pipe	fiberglass		N/A				
Pipe	parging		N/A	V-015			
Wall	drywall		N/A	V-024			

## Comments:

**Level : 1 - 1st Floor**  
**Room : 128 - Mechanical Room**

**Asbestos present : potential**

Ceiling	plaster		N/A	V-030			
Duct	not insulated		N/A				
Floor	concrete		N/A				
Mechanical	not insulated		N/A				
Pipe	fiberglass		N/A				
Pipe	parging		N/A	V-015			

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Wall	drywall		N/A	V-024			
Wall	plaster		N/A	V-031			

## Comments:

**Level : 1 - 1st Floor**

**Asbestos present : potential**

**Room : 129 - storage**

Ceiling	plaster		N/A	V-030			
Floor	concrete		N/A				
Pipe	fiberglass		N/A				
Pipe	parging		N/A	V-015			
Wall	concrete		N/A				

## Comments:

**Level : 1 - 1st Floor**

**Asbestos present : potential**

**Room : 130 - Lab**

Ceiling	plaster		N/A	V-030			
Floor	non-slip flooring		N/A	NEW			
Mechanical	not insulated		N/A				
Pipe	Elbow		N/A	NEW			
Pipe	fiberglass		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-030			

**Comments:** no access into walls or ceiling cavities

**Level : 1 - 1st Floor**

**Asbestos present : potential**

**Room : 131 - storage**

Ceiling	drywall		N/A	V-024			
Floor	vinyl sheet flooring		N/A	V-035			
Pipe	fiberglass		N/A				
Wall	drywall		N/A	V-024			
Wall	plaster		N/A	V-033			

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

## Comments:

**Level : 1 - 1st Floor**

**Asbestos present : potential**

**Room : 132 - Lab**

Ceiling	drywall		N/A	V-024
Duct	not insulated		N/A	
Floor	vinyl sheet flooring		N/A	NEW
Other	Fume Hood - Metal		N/A	
Wall	drywall		N/A	V-024
Wall	plaster		N/A	V-030

**Comments:** No access into walls or ceilings

**Level : 1 - 1st Floor**

**Asbestos present : potential**

**Room : 133 - Lab**

Ceiling	drywall		N/A	V-024
Floor	vinyl sheet flooring		N/A	V-035
Fumehood	transite panel		N/A	V-020
Pipe	not insulated		N/A	
Wall	drywall		N/A	V-024

## Comments:

**Level : 1 - 1st Floor**

**Asbestos present : potential**

**Room : 134 - Hallway**

Ceiling	plaster		N/A	V-032
Duct	not insulated		N/A	
Floor	vinyl sheet flooring		N/A	V-035
Pipe	fiberglass		N/A	
Pipe	parging		N/A	V-015
Structure	steel		N/A	
Wall	drywall		N/A	V-024

## Comments:

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

**Level : 1 - 1st Floor**

**Asbestos present : potential**

**Room : 135 - storage**

Ceiling	plaster		N/A	V-032			
Floor	concrete		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-024			

**Comments:**

**Level : 1 - 1st Floor**

**Asbestos present : potential**

**Room : 135A - Storage**

Ceiling	plaster		N/A	V-032			
Duct	not insulated		N/A				
Floor	Concrete		N/A				
Pipe	fiberglass		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-032			

**Comments:** No access into walls or ceilings

**Level : 1 - 1st Floor**

**Asbestos present : potential**

**Room : 135B - Storage**

Ceiling	plaster		N/A	V-032			
Duct	not insulated		N/A				
Floor	Concrete		N/A				
Pipe	fiberglass		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-032			

**Comments:** No access into walls or ceilings

**Level : 1 - 1st Floor**

**Asbestos present : potential**

**Room : 135C - Storage**

Ceiling	Speed Tile		N/A				
---------	------------	--	-----	--	--	--	--

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Floor	Concrete		N/A				
Wall	Concrete		N/A				

## Comments:

**Level : 1 - 1st Floor**

**Asbestos present : potential**

**Room : 136 - Stairwell**

Ceiling	concrete		N/A				
Floor	vinyl sheet flooring		N/A	V-012			
Pipe	fiberglass		N/A				
Pipe	parging		N/A	V-015			
Wall	concrete		N/A				
Wall	drywall		N/A	V-024			

## Comments:

**Level : 1 - 1st Floor**

**Asbestos present : potential**

**Room : 137 - Lab**

Ceiling	drywall		N/A	V-024			
Wall	drywall		N/A	V-024			
Wall	Vinyl over Drywall		N/A				

## Comments:

**Level : 1 - 1st Floor**

**Asbestos present : potential**

**Room : 138 - Lab**

Ceiling	drywall		N/A	V-024			
Wall	drywall		N/A	V-024			
Wall	Vinyl over Drywall		N/A				

## Comments:

**Level : 1 - 1st Floor**

**Asbestos present : potential**

**Room : 140 - storage**

Ceiling	concrete		N/A				
Floor	concrete		N/A				

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Pipe	fiberglass		N/A				
Pipe	parging		N/A	V-015			
Structure	concrete		N/A				
Wall	concrete		N/A				

## Comments:

**Level : 1 - 1st Floor**

**Asbestos present : potential**

**Room : 140A - Sprinkler Room**

Ceiling	concrete		N/A				
Floor	concrete		N/A				
Mechanical	not insulated		N/A				
Pipe	fiberglass		N/A				
Pipe	parging		N/A	V-015			
Wall	concrete		N/A				

## Comments:

**Level : 1 - 1st Floor**

**Asbestos present : potential**

**Room : 141 - Washroom**

Ceiling	2' x 4' fibreglass		N/A				
Floor	vinyl sheet flooring		N/A	V-012			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-024			

## Comments:

**Level : 1 - 1st Floor**

**Asbestos present : potential**

**Room : 142 - Washroom**

Ceiling	2' x 4' fibreglass		N/A				
Floor	vinyl sheet flooring		N/A	V-012			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-024			

## Comments:

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
<b>Level : 1 - 1st Floor</b>		<b>Asbestos present : potential</b>					
<b>Room : 143 - Washroom</b>							
Ceiling	drywall		N/A	V-024			
Floor	ceramic tile		N/A				
Wall	plaster		N/A	V-029			
<b>Comments:</b>							
<b>Level : 1 - 1st Floor</b>		<b>Asbestos present : potential</b>					
<b>Room : 144 - Washroom</b>							
Ceiling	drywall		N/A	V-024			
Floor	ceramic tile		N/A				
Wall	plaster		N/A	V-031			
<b>Comments:</b>							
<b>Level : 1 - 1st Floor</b>		<b>Asbestos present : potential</b>					
<b>Room : 145 - Communications</b>							
Ceiling	none observed		N/A				
Floor	vinyl sheet flooring		N/A	V-035			
Pipe	fiberglass		N/A				
Wall	drywall		N/A	V-024			
<b>Comments:</b> No access into walls or ceilings							
<b>Level : 1 - 1st Floor</b>		<b>Asbestos present : potential</b>					
<b>Room : 146 - Generator Room</b>							
Ceiling	plaster		N/A	V-028			
Duct	not insulated		N/A				
Floor	concrete		N/A				
Mechanical	not insulated		N/A				
Pipe	fiberglass		N/A				
Pipe	paring		N/A	V-015			
Wall	plaster		N/A	V-027			

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

## Comments:

**Level : 1 - 1st Floor**

**Asbestos present : potential**

**Room : 147 - Pipe Chase**

Ceiling	concrete		N/A		
Floor	concrete		N/A		
Pipe	fiberglass		N/A		
Pipe	parging		N/A	V-015	
Wall	concrete		N/A		
Wall	drywall		N/A	V-024	

## Comments:

**Level : 1 - 1st Floor**

**Asbestos present : potential**

**Room : 148 - Stairwell**

Ceiling	plaster		N/A	V-032	
Floor	vinyl sheet flooring		N/A	V-012	
Pipe	fiberglass		N/A		
Pipe	parging		N/A	V-015	
Wall	plaster		N/A	V-033	

## Comments:

**Level : 1 - 1st Floor**

**Asbestos present : potential**

**Room : 148A - Storage**

Floor	Concrete		N/A		
Wall	Concrete		N/A		

**Comments:** no access

Only accessed through window.

**Level : 2 - 2nd Floor**

**Asbestos present : potential**

**Room : 200 - Entrance**

Ceiling	concrete		N/A		
Ceiling	metal		N/A		



# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Floor	ceramic tile		N/A				
Wall	drywall		N/A	V-019			
Wall	plaster		N/A	V-042			

**Comments:** no access into walls or ceiling cavities

**Level :** 2 - 2nd Floor

**Asbestos present :** potential

**Room :** 201 - Lobby

Ceiling	metal		N/A				
Floor	clay tile		N/A				
Wall	drywall		N/A	V-019			

**Comments:**

**Level :** 2 - 2nd Floor

**Asbestos present :** potential

**Room :** 202 - Stairwell

Ceiling	plaster		N/A	V-042			
Duct	not insulated		N/A				
Floor	vinyl sheet flooring		N/A	NEW			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-042			

**Comments:** no access into walls or ceiling cavities

**Level :** 2 - 2nd Floor

**Asbestos present :** potential

**Room :** 203 - Foyer

Ceiling	adhesive		N/A	V-14			
Ceiling	metal		N/A				
Floor	ceramic tile		N/A				
Pipe	fiberglass		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-019			

**Comments:** no access into walls or ceiling cavities

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
<b>Level : 2 - 2nd Floor</b>		<b>Asbestos present : potential</b>					
<b>Room : 204 - Hallway</b>							
Ceiling	2' x 4' fibreglass		N/A				
Ceiling	adhesive		N/A	V-014			
Ceiling	plaster		N/A	V-043			
Duct	not insulated		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	fiberglass		N/A				
Pipe	parging		N/A	V-015			
Wall	plaster		N/A	V-042			

## Comments:

<b>Level : 2 - 2nd Floor</b>		<b>Asbestos present : potential</b>					
<b>Room : 205 - Mail Room</b>							
Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-043			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A	V-045			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-019			
Wall	plaster		N/A	V-042			

## Comments:

<b>Level : 2 - 2nd Floor</b>		<b>Asbestos present : potential</b>					
<b>Room : 205A - Mail Room</b>							
Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-043			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A	V-045			
Pipe	not insulated		N/A				

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Wall	drywall		N/A	V-019			
Wall	plaster		N/A	V-042			

## Comments:

**Level : 2 - 2nd Floor**

**Asbestos present : potential**

**Room : 205B - Mail Room**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-043			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A	V-045			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-019			
Wall	plaster		N/A	V-042			

## Comments:

**Level : 2 - 2nd Floor**

**Asbestos present : potential**

**Room : 206 - Mail Room**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-043			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A	V-045			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-019			
Wall	plaster		N/A	V-042			

## Comments:

**Level : 2 - 2nd Floor**

**Asbestos present : potential**

**Room : 207 - Mail Room**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-043			
Duct	fiberglass		N/A				

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Floor	vinyl sheet flooring		N/A	V-045			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-019			
Wall	plaster		N/A	V-042			

## Comments:

**Level :** 2 - 2nd Floor

**Asbestos present :** potential

**Room :** 208 - Elevator

No Access                      unsurveyed                      N/A

## Comments: no access

**Level :** 2 - 2nd Floor

**Asbestos present :** potential

**Room :** 210 - Computer Room

Ceiling	2' x 4' ceiling tile		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-019			

## Comments:

**Level :** 2 - 2nd Floor

**Asbestos present :** potential

**Room :** 211 - Lab

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-043			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A	V-045			
Fumehood	Panel		N/A	020			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-019			
Wall	plaster		N/A	V-042			

## Comments:

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
<b>Level : 2 - 2nd Floor</b>		<b>Asbestos present : potential</b>					
<b>Room : 212 - Lab</b>							
Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-043			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A	V-012			
Floor	VSF (new)		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-019			
Wall	plaster		N/A	V-042			

## Comments:

<b>Level : 2 - 2nd Floor</b>		<b>Asbestos present : yes</b>					
<b>Room : 213 - Office</b>							
Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-041			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A	V-045			
Pipe	Elbows - Parging	2.0	units	good	V-022	Chrysotile 80.00%	C 7
Pipe	Elbows - Parging	1.0	unit(s)	poor	V-022	Chrysotile 80.00%	C 1
Pipe	Elbows - Parging	1.0	unit(s)	Unknown	V-022	Chrysotile 80.00%	C 7
Pipe	insulation	3.0	ft	fair	V-023	Chrysotile 60.00%	C 6
Pipe	not insulated			N/A			
Wall	drywall			N/A	V-019		
Wall	plaster			N/A	V-040		

## Comments: limited access in ceiling space

1 poor elbow crumbling, 2 good visible, at least 1 other likely in room but view blocked by ductwork.

<b>Level : 2 - 2nd Floor</b>		<b>Asbestos present : yes</b>					
<b>Room : 214 - Office</b>							
Ceiling	2' x 4' fibreglass		N/A				

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity		Cond.	Sample	Asbestos type	Access.	Action
Ceiling	plaster			N/A	V-041			
Duct	fiberglass			N/A				
Floor	vinyl sheet flooring			N/A	V-045			
Pipe	Elbows - Parging	4.0	units	good	V-022	Chrysotile 80.00%	C	7
Pipe	insulation	12.0	ft	fair	V-023	Chrysotile 60.00%	C	6
Pipe	not insulated			N/A				
Wall	drywall			N/A	V-019			
Wall	plaster			N/A	V-040			

**Comments:** limited access in ceiling space

<b>Level : 2 - 2nd Floor</b>	<b>Asbestos present : potential</b>
<b>Room : 215 - Office</b>	

Ceiling	2' x 4' fibreglass			N/A				
Ceiling	plaster			N/A	V-041			
Duct	fiberglass			N/A				
Floor	vinyl sheet flooring			N/A	V-045			
Pipe	not insulated			N/A				
Wall	drywall			N/A	V-019			
Wall	plaster			N/A	V-040			

**Comments:**

<b>Level : 2 - 2nd Floor</b>	<b>Asbestos present : potential</b>
<b>Room : 216 - Office</b>	

Ceiling	2' x 4' fibreglass			N/A				
Ceiling	plaster			N/A	V-041			
Duct	fiberglass			N/A				
Floor	vinyl sheet flooring			N/A	V-045			
Pipe	not insulated			N/A				
Wall	drywall			N/A	V-019			
Wall	plaster			N/A	V-040			

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

**Comments:**

<b>Level : 2 - 2nd Floor</b>	<b>Asbestos present :</b> potential
<b>Room : 217 - Hallway</b>	

Ceiling	plaster		N/A	V-041		
Floor	vinyl sheet flooring		N/A	V-012		
Pipe	not insulated		N/A			
Wall	plaster		N/A	V-040		

**Comments:**

<b>Level : 2 - 2nd Floor</b>	<b>Asbestos present :</b> yes
<b>Room : 218 - Stairwell</b>	

Ceiling	plaster		N/A	V-041				
Floor	Mastic under floor tile		N/A	GF-2009-11				
Floor	vinyl sheet flooring		N/A	021				
Floor	vinyl sheet flooring		N/A	GF-2009-11				
Floor	vinyl sheet flooring		N/A	GF-2009-12				
Pipe	Elbows - Parging	3.0	units	good	022	Chrysotile 80.00%	A	7
Pipe	fiberglass			N/A				
Pipe	insulation	15.0	ft	good	023	Chrysotile 60.00%	A	7
Wall	plaster			N/A	V-040			

**Comments:**

GF-2009-11 is green/grey VSF and mastic, GF-2009-12 is multicolour VSF border.  
 Pipe insulation from floor to 5 feet up is fibreglass, rest is ACM. Located on exterior side (side farthest from Room 217).

<b>Level : 2 - 2nd Floor</b>	<b>Asbestos present :</b> potential
<b>Room : 219 - Office</b>	

Ceiling	2' x 4' fiberglass		N/A			
Ceiling	plaster		N/A	V-041		
Duct	fiberglass		N/A			

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Floor	vinyl sheet flooring		N/A	V-045			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-019			
Wall	plaster		N/A	V-040			

## Comments:

Level : 2 - 2nd Floor

Asbestos present : potential

Room : 220 - Office

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-041			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A	V-045			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-019			
Wall	plaster		N/A	V-040			

## Comments:

Level : 2 - 2nd Floor

Asbestos present : potential

Room : 221 - Office

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-041			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A	V-045			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-019			
Wall	plaster		N/A	V-040			

## Comments:

Level : 2 - 2nd Floor

Asbestos present : potential

Room : 222 - Hallway

Ceiling	plaster		N/A	V-041			
---------	---------	--	-----	-------	--	--	--



# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Floor	vinyl sheet flooring		N/A	V-045			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-019			
Wall	plaster		N/A	V-040			

## Comments:

**Level : 2 - 2nd Floor**

**Asbestos present : potential**

**Room : 223 - Hallway**

Ceiling	plaster		N/A	V-041			
Floor	vinyl sheet flooring		N/A	V-045			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-019			
Wall	plaster		N/A	V-040			

## Comments:

**Level : 2 - 2nd Floor**

**Asbestos present : potential**

**Room : 224 - Stairwell**

Ceiling	plaster		N/A	V-041			
Floor	12" x 12" floor tile		N/A				
Floor	9" x 9" floor tile		N/A	GF-2009-13			
Floor	9" x 9" floor tile		N/A	V-009			
Floor	Mastic under floor tile		N/A	GF-2009-13			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-040			

## Comments:

GF-2009-13 is red 9X9 floor tile and mastic.

**Level : 2 - 2nd Floor**

**Asbestos present : potential**

**Room : 225 - Office**

Ceiling	plaster		N/A	V-041			
Floor	vinyl sheet flooring		N/A	V-045			

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-040			

## Comments:

**Level : 2 - 2nd Floor**

**Asbestos present : potential**

**Room : 226 - Office**

Ceiling	plaster		N/A	V-041			
Floor	vinyl sheet flooring		N/A	V-045			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-040			

## Comments:

**Level : 2 - 2nd Floor**

**Asbestos present : potential**

**Room : 227 - Office**

Ceiling	plaster		N/A	V-041			
Floor	vinyl sheet flooring		N/A	V-045			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-040			

## Comments:

**Level : 2 - 2nd Floor**

**Asbestos present : potential**

**Room : 228 - Office**

Ceiling	plaster		N/A	V-041			
Floor	vinyl sheet flooring		N/A	V-045			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-040			

## Comments:

**Level : 2 - 2nd Floor**

**Asbestos present : potential**

**Room : 229 - Office**

Ceiling	plaster		N/A	V-041			
Floor	vinyl sheet flooring		N/A	V-045			

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

Pipe	not insulated		N/A				
Wall	plaster		N/A	V-040			

## Comments:

<b>Level : 2 - 2nd Floor</b>	<b>Asbestos present :</b> potential
<b>Room : 230 - Office</b>	

Ceiling	plaster		N/A	V-041			
Floor	vinyl sheet flooring		N/A	V-045			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-040			

## Comments:

<b>Level : 2 - 2nd Floor</b>	<b>Asbestos present :</b> potential
<b>Room : 231 - Office</b>	

Ceiling	plaster		N/A	V-041			
Floor	vinyl sheet flooring		N/A	V-045			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-040			

## Comments:

<b>Level : 2 - 2nd Floor</b>	<b>Asbestos present :</b> potential
<b>Room : 232 - Hallway</b>	

Ceiling	plaster		N/A	V-041			
Floor	vinyl sheet flooring		N/A	V-012			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-040			

## Comments:

<b>Level : 2 - 2nd Floor</b>	<b>Asbestos present :</b> potential
<b>Room : 233 - Lab</b>	

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-043			

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A	V-045			
Fumehood	Panel		N/A	020			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-019			
Wall	plaster		N/A	042			

## Comments:

Level : 2 - 2nd Floor

Asbestos present : potential

Room : 234 - Lab

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-043			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A	V-045			
Fumehood	Panel		N/A	020			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-019			
Wall	plaster		N/A	V-042			

## Comments:

Level : 2 - 2nd Floor

Asbestos present : potential

Room : 235 - Office

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-043			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A	V-045			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-019			
Wall	plaster		N/A	V-042			

## Comments:

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
<b>Level : 2 - 2nd Floor</b>		<b>Asbestos present : potential</b>					
<b>Room : 235A - Office</b>							
Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-043			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A	V-045			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-019			
Wall	plaster		N/A	V-042			

## Comments:

<b>Level : 2 - 2nd Floor</b>		<b>Asbestos present : potential</b>					
<b>Room : 236 - Lab</b>							
Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-043			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A	V-045			
Fumehood	Panel		N/A	020			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-019			
Wall	plaster		N/A	V-042			

## Comments:

<b>Level : 2 - 2nd Floor</b>		<b>Asbestos present : potential</b>					
<b>Room : 237 - Lab</b>							
Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-043			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A	V-012			
Pipe	not insulated		N/A				

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Wall	drywall		N/A	V-019			
Wall	plaster		N/A	V-042			

## Comments:

**Level : 2 - 2nd Floor**

**Asbestos present : potential**

**Room : 238 - Lab**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-043			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A	V-045			
Fumehood	Panel		N/A	020			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-019			
Wall	plaster		N/A	V-042			

## Comments:

**Level : 2 - 2nd Floor**

**Asbestos present : potential**

**Room : 239 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-047			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A	GF-2009-02			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-019			
Wall	plaster		N/A	V-044	Chrysotile < 1%		

## Comments:

**Level : 2 - 2nd Floor**

**Asbestos present : potential**

**Room : 239A - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-047			

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A	V-045			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-019			
Wall	plaster		N/A	V-044	Chrysotile < 1%		

## Comments:

Level : 2 - 2nd Floor

Asbestos present : potential

Room : 240 - Office

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-047			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A	V-045			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-019			
Wall	plaster		N/A	V-044	Chrysotile < 1%		

## Comments:

Level : 2 - 2nd Floor

Asbestos present : potential

Room : 241 - Office

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-047			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A	V-045			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-019			
Wall	plaster		N/A	V-044	Chrysotile < 1%		

## Comments:

Level : 2 - 2nd Floor

Asbestos present : potential

Room : 242 - Office

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-047			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A	V-045			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-019			
Wall	plaster		N/A	V-044	Chrysotile < 1%		

## Comments:

Level : 2 - 2nd Floor

Asbestos present : potential

Room : 242A - Office

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-047			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A	V-045			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-019			
Wall	plaster		N/A	V-044	Chrysotile < 1%		

## Comments:

Level : 2 - 2nd Floor

Asbestos present : potential

Room : 243 - Office

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-047			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A	045			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-019			
Wall	plaster		N/A	V-044	Chrysotile < 1%		

## Comments:



# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user: All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
<b>Level : 2 - 2nd Floor</b> <b>Room : 244 - Hallway</b>		<b>Asbestos present : potential</b>					
Ceiling	2' x 4' fibreglass		N/A				
Ceiling	adhesive		N/A	V-014			
Ceiling	plaster		N/A	V-047			
Duct	not insulated		N/A				
Floor	12" x 12" floor tile		N/A	GF-2009-01			
Pipe	fiberglass		N/A				
Pipe	parging		N/A	V-015			
Wall	plaster		N/A	V-044	Chrysotile < 1%		

**Comments:**

<b>Level : 2 - 2nd Floor</b> <b>Room : 245 - Lab</b>		<b>Asbestos present : yes</b>					
Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-047			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A	V-045			
Fumehood	transite panel	10.0 ft <sup>2</sup>	Good		Chrysotile 45.00%	A	7
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-019			
Wall	plaster		N/A	V-044	Chrysotile < 1%		

**Comments:**

The paneling in the fumehood was not sampled, but was visually identified as asbestos.

<b>Level : 2 - 2nd Floor</b> <b>Room : 246 - Office</b>		<b>Asbestos present : potential</b>					
Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-047			
Duct	fiberglass		N/A				

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Floor	vinyl sheet flooring		N/A	V-045			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-019			
Wall	plaster		N/A	V-046			

## Comments:

Level : 2 - 2nd Floor

Asbestos present : potential

Room : 247 - Office

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-047			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A	V-045			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-019			
Wall	plaster		N/A	V-046			

## Comments:

Level : 2 - 2nd Floor

Asbestos present : potential

Room : 248 - Stairwell

Ceiling	plaster		N/A	V-047			
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-046			

## Comments:

Level : 2 - 2nd Floor

Asbestos present : potential

Room : 249 - Exit

Ceiling	plaster		N/A	V-047			
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-046			

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

## Comments:

**Level : 2 - 2nd Floor**

**Asbestos present : potential**

**Room : 250 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-049			
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	019			

## Comments:

**Level : 2 - 2nd Floor**

**Asbestos present : potential**

**Room : 251 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-049			
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	019			

## Comments:

**Level : 2 - 2nd Floor**

**Asbestos present : potential**

**Room : 252 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-049			
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	019			

## Comments:

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

**Level : 2 - 2nd Floor**

**Asbestos present : potential**

**Room : 253 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-049			
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	019			

**Comments:**

**Level : 2 - 2nd Floor**

**Asbestos present : potential**

**Room : 254 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-049			
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	019			

**Comments:**

**Level : 2 - 2nd Floor**

**Asbestos present : potential**

**Room : 255 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-049			
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	019			

**Comments:**

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

**Level : 2 - 2nd Floor**

**Asbestos present : potential**

**Room : 256 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-049			
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	019			

**Comments:**

**Level : 2 - 2nd Floor**

**Asbestos present : potential**

**Room : 257 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-049			
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	019			

**Comments:**

**Level : 2 - 2nd Floor**

**Asbestos present : potential**

**Room : 258 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-049			
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	019			

**Comments:**

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

**Level : 2 - 2nd Floor**

**Asbestos present : potential**

**Room : 259 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-049			
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	019			

**Comments:**

**Level : 2 - 2nd Floor**

**Asbestos present : potential**

**Room : 260 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-049			
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	019			

**Comments:**

**Level : 2 - 2nd Floor**

**Asbestos present : potential**

**Room : 261 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-049			
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	019			

**Comments:**

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
<b>Level : 2 - 2nd Floor</b>		<b>Asbestos present : potential</b>					
<b>Room : 262 - Office</b>							
Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-049			
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	019			

## Comments:

<b>Level : 2 - 2nd Floor</b>		<b>Asbestos present : potential</b>					
<b>Room : 263 - Office</b>							
Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-049			
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	019			

## Comments:

<b>Level : 2 - 2nd Floor</b>		<b>Asbestos present : potential</b>					
<b>Room : 264 - Stairwell</b>							
Ceiling	drywall		N/A	V-019			
Floor	vinyl sheet flooring		N/A	NEW			
Wall	plaster		N/A	V-049			

**Comments:** no access into walls or ceiling cavities

<b>Level : 2 - 2nd Floor</b>		<b>Asbestos present : potential</b>					
<b>Room : 265 - Office</b>							
Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-049			

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	019			

## Comments:

Level : 2 - 2nd Floor

Asbestos present : potential

Room : 266 - Office

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-049			
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	019			

## Comments:

Level : 2 - 2nd Floor

Asbestos present : potential

Room : 266A - Office

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-049			
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	019			

## Comments:

Level : 2 - 2nd Floor

Asbestos present : potential

Room : 267 - Office

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-049			
Duct	fiberglass		N/A				



# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	019			

## Comments:

**Level : 2 - 2nd Floor**

**Asbestos present : potential**

**Room : 268 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-049			
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	019			

## Comments:

**Level : 2 - 2nd Floor**

**Asbestos present : potential**

**Room : 269 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-049			
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	019			

## Comments:

**Level : 2 - 2nd Floor**

**Asbestos present : potential**

**Room : 269A - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-049			
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Pipe	not insulated		N/A				
Wall	drywall		N/A	019			

## Comments:

**Level : 2 - 2nd Floor**

**Asbestos present : potential**

**Room : 270 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-049			
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	019			

## Comments:

**Level : 2 - 2nd Floor**

**Asbestos present : potential**

**Room : 270A - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-049			
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	019			

## Comments:

**Level : 2 - 2nd Floor**

**Asbestos present : potential**

**Room : 270B - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-049			
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

Wall	drywall		N/A	019			
------	---------	--	-----	-----	--	--	--

## Comments:

**Level : 2 - 2nd Floor**

**Asbestos present : potential**

**Room : 271 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-047			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A	V-051			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-019			
Wall	plaster		N/A	V-046			

## Comments:

**Level : 2 - 2nd Floor**

**Asbestos present : potential**

**Room : 272 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-047			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A	V-051			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-019			
Wall	plaster		N/A	V-046			

## Comments:

**Level : 2 - 2nd Floor**

**Asbestos present : potential**

**Room : 273 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-047			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A	V-051			

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-019			
Wall	plaster		N/A	V-046			

## Comments:

**Level : 2 - 2nd Floor**

**Asbestos present : potential**

**Room : 274 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-047			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A	V-051			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-019			
Wall	plaster		N/A	V-046			

## Comments:

**Level : 2 - 2nd Floor**

**Asbestos present : potential**

**Room : 275 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-047			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A	V-051			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-019			
Wall	plaster		N/A	V-046			

## Comments:

**Level : 2 - 2nd Floor**

**Asbestos present : potential**

**Room : 276 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-047			

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A	V-051			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-019			
Wall	plaster		N/A	V-046			

## Comments:

Level : 2 - 2nd Floor

Asbestos present : potential

Room : 277 - Office

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-047			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A	V-051			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-019			
Wall	plaster		N/A	V-046			

## Comments:

Level : 2 - 2nd Floor

Asbestos present : potential

Room : 278 - Office

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-047			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A	V-051			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-019			
Wall	plaster		N/A	V-046			

## Comments:

Level : 2 - 2nd Floor

Asbestos present : potential

Room : 279 - Office

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-047			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A	V-051			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-019			
Wall	plaster		N/A	V-046			

## Comments:

Level : 2 - 2nd Floor

Asbestos present : potential

Room : 280 - Lab

Ceiling	2' x 4' fibreglass		N/A				
Floor	vinyl sheet flooring		N/A	V-051			
Wall	drywall		N/A	V-019			

Comments: no access into walls or ceiling cavities

Level : 2 - 2nd Floor

Asbestos present : potential

Room : 281 - Washroom

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-047			
Floor	vinyl sheet flooring		N/A	V-012			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-019			
Wall	plaster		N/A	V-044	Chrysotile < 1%		

## Comments:

Level : 2 - 2nd Floor

Asbestos present : potential

Room : 282 - Washroom

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-047			
Floor	vinyl sheet flooring		N/A	V-012			

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-019			
Wall	plaster		N/A	V-044	Chrysotile < 1%		

## Comments:

**Level : 2 - 2nd Floor**

**Asbestos present : potential**

**Room : 282A - Pipe Chase**

Ceiling	plaster		N/A	V-047			
Floor	9" x 9" floor tile		N/A	V-002			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-019			
Wall	plaster		N/A	V-044	Chrysotile < 1%		

## Comments:

**Level : 2 - 2nd Floor**

**Asbestos present : potential**

**Room : 283**

Ceiling	plaster		N/A	V-042			
Floor	Concrete		N/A				
Wall	Concrete		N/A				
Wall	drywall		N/A	V-019			

## Comments:

**Level : 2 - 2nd Floor**

**Asbestos present : potential**

**Room : 284 - Office**

Ceiling	2' x 4' fiberglass		N/A				
Ceiling	plaster		N/A	V-047			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A	V-051			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-019			
Wall	plaster		N/A	V-046			

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

## Comments:

**Level : 2 - 2nd Floor**

**Asbestos present : potential**

**Room : 285 - Lab**

Ceiling	2' x 4' fibreglass		N/A				
Floor	vinyl sheet flooring		N/A	V-051			
Wall	drywall		N/A	V-019			

**Comments:** no access into walls or ceiling cavities

**Level : 3 - 3rd Floor**

**Asbestos present : potential**

**Room : 301 - Hallway**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	adhesive		N/A	V-014			
Ceiling	plaster		N/A	V-059			
Duct	not insulated		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-056			

## Comments:

**Level : 3 - 3rd Floor**

**Asbestos present : potential**

**Room : 302 - Stairwell**

Ceiling	plaster		N/A	V-059			
Floor	vinyl sheet flooring		N/A	V-012			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-056			

## Comments:

**Level : 3 - 3rd Floor**

**Asbestos present : potential**

**Room : 303 - Hallway**

Ceiling	2' x 4' fibreglass		N/A				
---------	--------------------	--	-----	--	--	--	--



# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Ceiling	adhesive		N/A	V-014			
Ceiling	plaster		N/A	V-059			
Duct	not insulated		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-055			

## Comments:

**Level : 3 - 3rd Floor**

**Asbestos present : potential**

**Room : 307 - Hallway**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-059			
Floor	vinyl sheet flooring		N/A	V-012			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-018			

## Comments:

**Level : 3 - 3rd Floor**

**Asbestos present : potential**

**Room : 308 - Stage**

Ceiling	plaster		N/A	V-059			
Floor	wood		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-018			

## Comments:

**Level : 3 - 3rd Floor**

**Asbestos present : potential**

**Room : 309 - Theatre**

Ceiling	texture coat		N/A				
Floor	wood		N/A				
Pipe	not insulated		N/A				

## Comments:

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

**Level : 3 - 3rd Floor**  
**Room : 310 - Hallway**

**Asbestos present : potential**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	adhesive		N/A	V-014			
Duct	not insulated		N/A				
Floor	vinyl sheet flooring		N/A	V-012			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-058			

## Comments:

**Level : 3 - 3rd Floor**  
**Room : 311 - storage**

**Asbestos present : potential**

Ceiling	plaster		N/A	V-059			
Floor	vinyl sheet flooring		N/A	V-012			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-058			

## Comments:

**Level : 3 - 3rd Floor**  
**Room : 312 - Hallway**

**Asbestos present : potential**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	adhesive		N/A	V-014			
Duct	not insulated		N/A				
Floor	vinyl sheet flooring		N/A	V-012			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-058			

## Comments:

**Level : 3 - 3rd Floor**  
**Room : 313 - storage**

**Asbestos present : potential**

Ceiling	plaster		N/A	V-059			
---------	---------	--	-----	-------	--	--	--

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Floor	vinyl sheet flooring		N/A	V-012			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-058			

## Comments:

**Level :** 3 - 3rd Floor  
**Room :** 314 - Stairwell

**Asbestos present :** potential

Ceiling	plaster		N/A	V-059			
Floor	vinyl sheet flooring		N/A	V-012			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-058			

## Comments:

**Level :** 3 - 3rd Floor  
**Room :** 315 - Server Room

**Asbestos present :** potential

Ceiling	plaster		N/A	V-058			
Floor	12" x 12" floor tile		N/A	NEW			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-058			

**Comments:** no access into walls or ceiling cavities

**Level :** 3 - 3rd Floor  
**Room :** 316 - Server Room

**Asbestos present :** potential

Ceiling	plaster		N/A	V-058			
Floor	12" x 12" floor tile		N/A	NEW			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-058			

**Comments:** no access into walls or ceiling cavities

**Level :** 3 - 3rd Floor  
**Room :** 317 - Elevator

**Asbestos present :** potential

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

No Access	unsurveyed		N/A				
-----------	------------	--	-----	--	--	--	--

**Comments:** no access

**Level :** 3 - 3rd Floor

**Asbestos present :** potential

**Room :** 318 - Office

Ceiling	2' x 4' ceiling tile		N/A				
Ceiling	plaster		N/A	V-059			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-018			
Wall	plaster		N/A	V-056			

**Comments:**

**Level :** 3 - 3rd Floor

**Asbestos present :** potential

**Room :** 318A - Office

Ceiling	2' x 4' ceiling tile		N/A				
Ceiling	plaster		N/A	V-059			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-018			
Wall	plaster		N/A	V-056			

**Comments:**

**Level :** 3 - 3rd Floor

**Asbestos present :** potential

**Room :** 318B - Office

Ceiling	2' x 4' ceiling tile		N/A				
Ceiling	plaster		N/A	V-059			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A				

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-018			
Wall	plaster		N/A	V-056			

## Comments:

**Level :** 3 - 3rd Floor  
**Room :** 318C - Office

**Asbestos present :** potential

Ceiling	2' x 4' ceiling tile		N/A				
Ceiling	plaster		N/A	V-059			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-018			
Wall	plaster		N/A	V-056			

## Comments:

**Level :** 3 - 3rd Floor  
**Room :** 319 - Hallway

**Asbestos present :** potential

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	adhesive		N/A	V-014			
Ceiling	plaster		N/A	V-059			
Duct	not insulated		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-055			

## Comments:

**Level :** 3 - 3rd Floor  
**Room :** 320 - Office

**Asbestos present :** potential

Ceiling	2' x 4' ceiling tile		N/A	V-016			
Ceiling	plaster		N/A	V-059			

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-018			
Wall	plaster		N/A	V-056			

## Comments:

**Level :** 3 - 3rd Floor  
**Room :** 320A - Office

**Asbestos present :** potential

Ceiling	2' x 4' ceiling tile		N/A	V-016			
Ceiling	plaster		N/A	V-059			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-018			
Wall	plaster		N/A	V-056			

## Comments:

**Level :** 3 - 3rd Floor  
**Room :** 320B - Office

**Asbestos present :** potential

Ceiling	2' x 4' ceiling tile		N/A	V-016			
Ceiling	plaster		N/A	V-059			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-018			
Wall	plaster		N/A	V-056			

## Comments:

**Level :** 3 - 3rd Floor  
**Room :** 320C - Office

**Asbestos present :** potential

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Ceiling	2' x 4' ceiling tile		N/A	V-016			
Ceiling	plaster		N/A	V-059			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-018			
Wall	plaster		N/A	V-056			

## Comments:

**Level : 3 - 3rd Floor**

**Asbestos present : potential**

**Room : 320D - Office**

Ceiling	2' x 4' ceiling tile		N/A	V-016			
Ceiling	plaster		N/A	V-059			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-018			
Wall	plaster		N/A	V-056			

## Comments:

**Level : 3 - 3rd Floor**

**Asbestos present : potential**

**Room : 320E - Office**

Ceiling	2' x 4' ceiling tile		N/A	V-016			
Ceiling	plaster		N/A	V-059			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-018			
Wall	plaster		N/A	V-056			

## Comments:

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
<b>Level : 3 - 3rd Floor</b>		<b>Asbestos present : potential</b>					
<b>Room : 320F - Office</b>							
Ceiling	2' x 4' ceiling tile		N/A	V-016			
Ceiling	plaster		N/A	V-059			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-018			
Wall	plaster		N/A	V-056			

## Comments:

<b>Level : 3 - 3rd Floor</b>		<b>Asbestos present : potential</b>					
<b>Room : 320G - Office</b>							
Ceiling	2' x 4' ceiling tile		N/A	V-016			
Ceiling	plaster		N/A	V-059			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-018			
Wall	plaster		N/A	V-056			

## Comments:

<b>Level : 3 - 3rd Floor</b>		<b>Asbestos present : potential</b>					
<b>Room : 321 - Office</b>							
Ceiling	2' x 4' ceiling tile		N/A				
Ceiling	plaster		N/A	V-059			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-018			



# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

Wall	plaster		N/A	V-055			
------	---------	--	-----	-------	--	--	--

## Comments:

**Level : 3 - 3rd Floor**

**Asbestos present : potential**

**Room : 322 - Office**

Ceiling	2' x 4' ceiling tile		N/A				
Ceiling	plaster		N/A	V-059			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-018			
Wall	plaster		N/A	V-055			

## Comments:

**Level : 3 - 3rd Floor**

**Asbestos present : potential**

**Room : 322A - Office**

Ceiling	2' x 4' ceiling tile		N/A				
Ceiling	plaster		N/A	V-059			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-018			
Wall	plaster		N/A	V-055			

## Comments:

**Level : 3 - 3rd Floor**

**Asbestos present : potential**

**Room : 322B - Office**

Ceiling	2' x 4' ceiling tile		N/A				
Ceiling	plaster		N/A	V-059			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A				

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-018			
Wall	plaster		N/A	V-055			

## Comments:

**Level : 3 - 3rd Floor**  
**Room : 322C - Office**

**Asbestos present : potential**

Ceiling	2' x 4' ceiling tile		N/A				
Ceiling	plaster		N/A	V-059			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-018			
Wall	plaster		N/A	V-055			

## Comments:

**Level : 3 - 3rd Floor**  
**Room : 322D - Office**

**Asbestos present : potential**

Ceiling	2' x 4' ceiling tile		N/A				
Ceiling	plaster		N/A	V-059			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-018			
Wall	plaster		N/A	V-055			

## Comments:

**Level : 3 - 3rd Floor**  
**Room : 322E - Office**

**Asbestos present : potential**

Ceiling	2' x 4' ceiling tile		N/A				
Ceiling	plaster		N/A	V-059			

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-018			
Wall	plaster		N/A	V-055			

## Comments:

**Level :** 3 - 3rd Floor

**Asbestos present :** potential

**Room :** 322F - Office

Ceiling	2' x 4' ceiling tile		N/A				
Ceiling	plaster		N/A	V-059			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-018			
Wall	plaster		N/A	V-055			

## Comments:

**Level :** 3 - 3rd Floor

**Asbestos present :** potential

**Room :** 322G - Office

Ceiling	2' x 4' ceiling tile		N/A				
Ceiling	plaster		N/A	V-059			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-018			
Wall	plaster		N/A	V-055			

## Comments:

**Level :** 3 - 3rd Floor

**Asbestos present :** potential

**Room :** 323 - Office

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Ceiling	2' x 4' ceiling tile		N/A				
Ceiling	plaster		N/A	V-059			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-018			
Wall	plaster		N/A	V-055			

## Comments:

**Level :** 3 - 3rd Floor

**Asbestos present :** potential

**Room :** 326 - Office

Ceiling	2' x 4' ceiling tile		N/A				
Duct	not insulated		N/A				
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-018			
Wall	plaster		N/A	V-055			

## Comments:

**Level :** 3 - 3rd Floor

**Asbestos present :** potential

**Room :** 328 - storage

Ceiling	plaster		N/A	V-059			
Floor	9" x 9" floor tile		N/A	V-007			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-054	Chrysotile < 1%		

## Comments:

**Level :** 3 - 3rd Floor

**Asbestos present :** potential

**Room :** 329 - Electrical Room

Ceiling	plaster		N/A	V-059			
Electrical	not insulated		N/A				

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Floor	concrete		N/A				
Wall	plaster		N/A	V-054	Chrysotile < 1%		
Wall	wood		N/A				

## Comments:

**Level : 3 - 3rd Floor**

**Asbestos present : potential**

**Room : 330 - Office**

Ceiling	2' x 4' ceiling tile		N/A				
Duct	not insulated		N/A				
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-018			
Wall	plaster		N/A	V-055			

## Comments:

**Level : 3 - 3rd Floor**

**Asbestos present : potential**

**Room : 331 - Hallway**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	adhesive		N/A	V-057			
Ceiling	plaster		N/A	V-059			
Floor	carpet		N/A				
Floor	concrete		N/A				
Wall	plaster		N/A	054	Chrysotile < 1%		

## Comments:

**Level : 3 - 3rd Floor**

**Asbestos present : potential**

**Room : 332 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-059			
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Wall	plaster		N/A	V-054	Chrysotile < 1%		

## Comments:

**Level : 3 - 3rd Floor**

**Asbestos present : potential**

**Room : 333 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-059			
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-054	Chrysotile < 1%		

## Comments:

**Level : 3 - 3rd Floor**

**Asbestos present : potential**

**Room : 334 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-059			
Debris	on ceiling tile		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-018			
Wall	plaster		N/A	V-054			

## Comments:

**Level : 3 - 3rd Floor**

**Asbestos present : potential**

**Room : 335 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-059			
Debris	on ceiling tile		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-018			

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Wall	plaster		N/A	V-054	Chrysotile < 1%		

## Comments:

**Level : 3 - 3rd Floor**

**Asbestos present : potential**

**Room : 336 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-059			
Debris	on ceiling tile		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-018			
Wall	plaster		N/A	V-053			

## Comments:

**Level : 3 - 3rd Floor**

**Asbestos present : potential**

**Room : 337 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-059			
Debris	on ceiling tile		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	018			
Wall	plaster		N/A	V-053			

## Comments:

**Level : 3 - 3rd Floor**

**Asbestos present : potential**

**Room : 338 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-059			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A				

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Pipe	not insulated		N/A				
Wall	drywall		N/A	018			

## Comments:

**Level : 3 - 3rd Floor**

**Asbestos present : potential**

**Room : 339 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-059			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	018			

## Comments:

**Level : 3 - 3rd Floor**

**Asbestos present : potential**

**Room : 340 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-059			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	018			

## Comments:

**Level : 3 - 3rd Floor**

**Asbestos present : potential**

**Room : 341 - Stairwell**

Ceiling	drywall		N/A	V-018			
Floor	vinyl sheet flooring		N/A	NEW			
Wall	plaster		N/A	V-059			

**Comments:** no access into walls or ceiling cavities



# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

**Level : 3 - 3rd Floor**  
**Room : 342 - Office**

**Asbestos present : potential**

Ceiling	2' x 4' fibreglass		N/A				
Floor	carpet		N/A				
Floor	concrete		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A		V-053		

## Comments:

**Level : 3 - 3rd Floor**  
**Room : 343 - Office**

**Asbestos present : potential**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A		V-059		
Floor	concrete		N/A				
Floor	concrete		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A		V-018		
Wall	plaster		N/A		V-053		

## Comments:

**Level : 3 - 3rd Floor**  
**Room : 343A - Office**

**Asbestos present : potential**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A		V-059		
Floor	concrete		N/A				
Floor	concrete		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A		V-018		
Wall	plaster		N/A		V-053		

## Comments:

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
<b>Level : 3 - 3rd Floor</b>		<b>Asbestos present : potential</b>					
<b>Room : 344 - Office</b>							
Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-059			
Floor	concrete		N/A				
Floor	concrete		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-018			
Wall	plaster		N/A	V-053			

## Comments:

<b>Level : 3 - 3rd Floor</b>		<b>Asbestos present : potential</b>					
<b>Room : 344A - Office</b>							
Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-059			
Floor	concrete		N/A				
Floor	concrete		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-018			
Wall	plaster		N/A	V-053			

## Comments:

<b>Level : 3 - 3rd Floor</b>		<b>Asbestos present : potential</b>					
<b>Room : 345 - Office</b>							
Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-059			
Floor	concrete		N/A				
Floor	concrete		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-018			

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Wall	plaster		N/A	V-054	Chrysotile < 1%		

## Comments:

**Level :** 3 - 3rd Floor

**Asbestos present :** potential

**Room :** 348 - Board Room

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-059			
Duct	fiberglass		N/A				
Floor	carpet		N/A				
Floor	concrete		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-054	Chrysotile < 1%		

## Comments:

**Level :** 3 - 3rd Floor

**Asbestos present :** potential

**Room :** 349 - Stairwell

Ceiling	plaster		N/A	V-059			
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-054	Chrysotile < 1%		

## Comments:

**Level :** 3 - 3rd Floor

**Asbestos present :** potential

**Room :** 350 - Office

Ceiling	2' x 4' fibreglass		N/A				
Duct	not insulated		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-018			
Wall	plaster		N/A	V-054	Chrysotile < 1%		

## Comments:

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

**Level : 3 - 3rd Floor**

**Asbestos present : potential**

**Room : 351 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Duct	not insulated		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-018			
Wall	plaster		N/A	V-054	Chrysotile < 1%		

## Comments:

**Level : 3 - 3rd Floor**

**Asbestos present : potential**

**Room : 352 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Duct	not insulated		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-018			
Wall	plaster		N/A	V-054	Chrysotile < 1%		

## Comments:

**Level : 3 - 3rd Floor**

**Asbestos present : potential**

**Room : 353 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Duct	not insulated		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-018			
Wall	plaster		N/A	V-055			

## Comments:

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

**Level : 3 - 3rd Floor**  
**Room : 354 - Office**

**Asbestos present : potential**

Ceiling	2' x 4' fibreglass		N/A				
Duct	not insulated		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A		V-018		
Wall	plaster		N/A		V-055		

## Comments:

**Level : 3 - 3rd Floor**  
**Room : 355 - Office**

**Asbestos present : potential**

Ceiling	2' x 4' fibreglass		N/A				
Duct	not insulated		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A		V-018		
Wall	plaster		N/A		V-055		

## Comments:

**Level : 3 - 3rd Floor**  
**Room : 355A - Office**

**Asbestos present : potential**

Ceiling	2' x 4' fibreglass		N/A				
Duct	not insulated		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A		V-018		
Wall	plaster		N/A		V-055		

## Comments:

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

**Level : 3 - 3rd Floor**

**Asbestos present : potential**

**Room : 356 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Duct	not insulated		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A		V-018		
Wall	plaster		N/A		V-055		

**Comments:**

**Level : 3 - 3rd Floor**

**Asbestos present : potential**

**Room : 357 - Washroom**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A		V-059		
Floor	vinyl sheet flooring		N/A		V-012		
Pipe	not insulated		N/A				
Wall	drywall		N/A		V-018		
Wall	plaster		N/A		V-055		

**Comments:**

**Level : 3 - 3rd Floor**

**Asbestos present : potential**

**Room : 358 - Washroom**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A		V-059		
Floor	vinyl sheet flooring		N/A		V-012		
Pipe	not insulated		N/A				
Wall	drywall		N/A		V-018		
Wall	plaster		N/A		V-055		

**Comments:**

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

**Level : 3 - 3rd Floor**

**Asbestos present : potential**

**Room : 358A - Pipe Chase**

Ceiling	plaster		N/A	V-059			
Floor	vinyl sheet flooring		N/A	V-001			
Pipe	fiberglass		N/A				
Wall	drywall		N/A	V-018			

**Comments:**

**Level : 4 - 4th Floor**

**Asbestos present : potential**

**Room : 400 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-017			

**Comments:**

**Level : 4 - 4th Floor**

**Asbestos present : potential**

**Room : 401 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-017			

**Comments:**

**Level : 4 - 4th Floor**

**Asbestos present : potential**

**Room : 402 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-017			

**Comments:**

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
<b>Level : 4 - 4th Floor</b>		<b>Asbestos present : potential</b>					
<b>Room : 403 - Hallway</b>							
Ceiling	2' x 4' fibreglass		N/A				
Ceiling	adhesive		N/A	V-014			
Ceiling	plaster		N/A	V-063			
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-066	Chrysotile < 1%		

## Comments:

<b>Level : 4 - 4th Floor</b>		<b>Asbestos present : potential</b>					
<b>Room : 405 - Office</b>							
Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-069			
Duct	not insulated		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-017			

## Comments:

<b>Level : 4 - 4th Floor</b>		<b>Asbestos present : potential</b>					
<b>Room : 406 - Stairwell</b>							
Ceiling	plaster		N/A	V-069			
Floor	vinyl sheet flooring		N/A	V-012			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-067	Chrysotile < 1%		

## Comments:

<b>Level : 4 - 4th Floor</b>		<b>Asbestos present : potential</b>					
<b>Room : 407 - Office</b>							



# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-069			
Duct	not insulated		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-017			

## Comments:

Level : 4 - 4th Floor

Asbestos present : potential

Room : 408 - Office

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-069			
Duct	not insulated		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-017			

## Comments:

Level : 4 - 4th Floor

Asbestos present : potential

Room : 409 - Office

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-069			
Duct	not insulated		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-017			

## Comments:

Level : 4 - 4th Floor

Asbestos present : potential

Room : 410 - Office

Ceiling	2' x 4' fibreglass		N/A				
---------	--------------------	--	-----	--	--	--	--

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Ceiling	plaster		N/A	V-069			
Duct	not insulated		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-017			

## Comments:

**Level : 4 - 4th Floor**

**Asbestos present : potential**

**Room : 411 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-069			
Duct	not insulated		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-017			

## Comments:

**Level : 4 - 4th Floor**

**Asbestos present : potential**

**Room : 412 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-069			
Duct	not insulated		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-017			

## Comments:

**Level : 4 - 4th Floor**

**Asbestos present : potential**

**Room : 413 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-069			

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Duct	not insulated		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-017			

## Comments:

Level : 4 - 4th Floor

Asbestos present : potential

Room : 414 - Office

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-069			
Duct	not insulated		N/A				
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-017			
Wall	plaster		N/A	V-068	Chrysotile < 1%		

## Comments:

Level : 4 - 4th Floor

Asbestos present : potential

Room : 415 - Office

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-069			
Duct	not insulated		N/A				
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-017			
Wall	plaster		N/A	V-068	Chrysotile < 1%		

## Comments:

Level : 4 - 4th Floor

Asbestos present : potential

Room : 416 - Hallway

Ceiling	2' x 4' fibreglass		N/A				
---------	--------------------	--	-----	--	--	--	--

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Ceiling	plaster		N/A	V-069			
Duct	not insulated		N/A				
Floor	vinyl sheet flooring		N/A	V-012			
Pipe	not insulated		N/A				

## Comments:

Level : 4 - 4th Floor

Asbestos present : potential

Room : 417 - Hallway

Ceiling	plaster		N/A	069			
Floor	vinyl sheet flooring		N/A	V-012			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-068	Chrysotile < 1%		

## Comments:

Level : 4 - 4th Floor

Asbestos present : potential

Room : 418 - Stairwell

Ceiling	plaster		N/A	V-069			
Floor	9" x 9" floor tile		N/A	GF-2009-14			
Floor	Mastic under floor tile		N/A	GF-2009-15			
Floor	Mastic under floor tile		N/A	GF-2009-16			
Floor	Stair tread/nosing		N/A	GF-2009-15			
Floor	vinyl sheet flooring		N/A	V-012			
Floor	vinyl sheet flooring		N/A	GF-2009-16			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-017			

## Comments:

GF-2009-14 is beige with swirl pattern 9X9 floor tile, GF-2009-15 is stair nosing and mastic, GF-2009-16 is checker VSF.

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

**Level : 4 - 4th Floor**

**Asbestos present : potential**

**Room : 419 - Theatre**

Ceiling	plaster		N/A	V-069			
Floor	wood		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-068	Chrysotile < 1%		

## Comments:

**Level : 4 - 4th Floor**

**Asbestos present : potential**

**Room : 419A - Camera Room**

Ceiling	plaster		N/A	V-069			
Floor	9" x 9" floor tile		N/A	V-009			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-068	Chrysotile < 1%		

## Comments:

**Level : 4 - 4th Floor**

**Asbestos present : potential**

**Room : 420 - Office**

Ceiling	2' x 4' ceiling tile		N/A	V-016			
Ceiling	plaster		N/A	V-069			
Duct	not insulated		N/A				
Floor	carpet		N/A				
Floor	concrete		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-017			
Wall	plaster		N/A	V-068	Chrysotile < 1%		

## Comments:

**Level : 4 - 4th Floor**

**Asbestos present : potential**

**Room : 422 - Lunch Room**

Ceiling	2' x 4' ceiling tile		N/A				
---------	----------------------	--	-----	--	--	--	--

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Ceiling	plaster		N/A	V-069			
Duct	not insulated		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-017			
Wall	plaster		N/A	V-068	Chrysotile < 1%		

## Comments:

**Level :** 4 - 4th Floor

**Asbestos present :** potential

**Room :** 423 - Computer Room

Ceiling	plaster		N/A	V-069			
Electrical	not insulated		N/A				
Floor	concrete		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-017			

## Comments:

**Level :** 4 - 4th Floor

**Asbestos present :** potential

**Room :** 424 - Office

Ceiling	2' x 4' ceiling tile		N/A	V-016			
Ceiling	plaster		N/A	V-069			
Duct	not insulated		N/A				
Floor	carpet		N/A				
Floor	concrete		N/A				
Pipe	not insulated		N/A				

## Comments:

**Level :** 4 - 4th Floor

**Asbestos present :** potential

**Room :** 425 - Office

Ceiling	2' x 4' ceiling tile		N/A	V-016			
Ceiling	plaster		N/A	V-069			

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Duct	not insulated		N/A				
Floor	carpet		N/A				
Floor	concrete		N/A				
Pipe	not insulated		N/A				

## Comments:

Level : 4 - 4th Floor

Asbestos present : potential

Room : 426 - Office

Ceiling	2' x 4' ceiling tile		N/A	V-016			
Ceiling	plaster		N/A	V-069			
Duct	not insulated		N/A				
Floor	carpet		N/A				
Floor	concrete		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-017			
Wall	plaster		N/A	V-067	Chrysotile < 1%		

## Comments:

Level : 4 - 4th Floor

Asbestos present : potential

Room : 427 - Office

Ceiling	2' x 4' ceiling tile		N/A	V-016			
Ceiling	plaster		N/A	V-069			
Duct	not insulated		N/A				
Floor	carpet		N/A				
Floor	concrete		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-017			
Wall	plaster		N/A	V-067	Chrysotile < 1%		

## Comments:

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
<b>Level : 4 - 4th Floor</b>		<b>Asbestos present : potential</b>					
<b>Room : 428 - Office</b>							
Ceiling	2' x 4' ceiling tile		N/A	V-016			
Ceiling	plaster		N/A	V-069			
Duct	not insulated		N/A				
Floor	carpet		N/A				
Floor	concrete		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-017			
Wall	plaster		N/A	V-067	Chrysotile < 1%		

## Comments:

<b>Level : 4 - 4th Floor</b>		<b>Asbestos present : potential</b>					
<b>Room : 429 - Office</b>							
Ceiling	2' x 4' ceiling tile		N/A	V-016			
Ceiling	plaster		N/A	V-063			
Duct	fiberglass		N/A				
Floor	carpet		N/A				
Floor	concrete		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-017			

## Comments:

<b>Level : 4 - 4th Floor</b>		<b>Asbestos present : potential</b>					
<b>Room : 431 - Office</b>							
Ceiling	2' x 4' ceiling tile		N/A	V-016			
Ceiling	plaster		N/A	V-063			
Duct	fiberglass		N/A				
Floor	carpet		N/A				
Floor	concrete		N/A				



# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-017			

## Comments:

**Level : 4 - 4th Floor**

**Asbestos present : potential**

**Room : 432 - Office**

Ceiling	2' x 4' ceiling tile		N/A	V-016			
Ceiling	plaster		N/A	V-063			
Duct	fiberglass		N/A				
Floor	carpet		N/A				
Floor	concrete		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-017			

## Comments:

**Level : 4 - 4th Floor**

**Asbestos present : potential**

**Room : 433 - Office**

Ceiling	2' x 4' ceiling tile		N/A	V-016			
Ceiling	plaster		N/A	V-063			
Duct	fiberglass		N/A				
Floor	carpet		N/A				
Floor	concrete		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-017			

## Comments:

**Level : 4 - 4th Floor**

**Asbestos present : potential**

**Room : 434 - Office**

Ceiling	2' x 4' ceiling tile		N/A	V-016			
Ceiling	plaster		N/A	V-063			
Duct	fiberglass		N/A				

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Floor	carpet		N/A				
Floor	concrete		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-017			

## Comments:

**Level : 4 - 4th Floor**

**Asbestos present : potential**

**Room : 435 - Office**

Ceiling	2' x 4' ceiling tile		N/A	V-016			
Duct	not insulated		N/A				
Floor	carpet		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	017			

## Comments:

**Level : 4 - 4th Floor**

**Asbestos present : potential**

**Room : 436 - Office**

Ceiling	2' x 4' ceiling tile		N/A	V-016			
Duct	not insulated		N/A				
Floor	carpet		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	017			

## Comments:

**Level : 4 - 4th Floor**

**Asbestos present : potential**

**Room : 437 - Office**

Ceiling	2' x 4' ceiling tile		N/A	V-016			
Duct	not insulated		N/A				
Floor	carpet		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	017			

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

## Comments:

**Level : 4 - 4th Floor**

**Asbestos present : potential**

**Room : 438 - Office**

Ceiling	2' x 4' ceiling tile		N/A	V-016
Duct	not insulated		N/A	
Floor	carpet		N/A	
Pipe	not insulated		N/A	
Wall	drywall		N/A	017

## Comments:

**Level : 4 - 4th Floor**

**Asbestos present : potential**

**Room : 439 - Office**

Ceiling	2' x 4' ceiling tile		N/A	V-016
Duct	not insulated		N/A	
Floor	carpet		N/A	
Pipe	not insulated		N/A	
Wall	drywall		N/A	017

## Comments:

**Level : 4 - 4th Floor**

**Asbestos present : potential**

**Room : 440 - Office**

Ceiling	2' x 4' ceiling tile		N/A	V-016
Duct	not insulated		N/A	
Floor	carpet		N/A	
Pipe	not insulated		N/A	
Wall	drywall		N/A	017

## Comments:

**Level : 4 - 4th Floor**

**Asbestos present : potential**

**Room : 441 - Office**

Ceiling	2' x 4' ceiling tile		N/A	V-016
---------	----------------------	--	-----	-------

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Duct	not insulated		N/A				
Floor	carpet		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	017			

## Comments:

**Level :** 4 - 4th Floor

**Asbestos present :** potential

**Room :** 442 - Office

Ceiling	2' x 4' ceiling tile		N/A	V-016			
Duct	not insulated		N/A				
Floor	carpet		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	017			

## Comments:

**Level :** 4 - 4th Floor

**Asbestos present :** potential

**Room :** 443 - Office

Ceiling	2' x 4' ceiling tile		N/A	V-016			
Duct	not insulated		N/A				
Floor	carpet		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	017			

## Comments:

**Level :** 4 - 4th Floor

**Asbestos present :** potential

**Room :** 444 - Office

Ceiling	2' x 4' ceiling tile		N/A	V-016			
Duct	not insulated		N/A				
Floor	carpet		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	017			

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

## Comments:

**Level :** 4 - 4th Floor

**Asbestos present :** potential

**Room :** 445 - Office

Ceiling	2' x 4' ceiling tile		N/A	V-016
Duct	not insulated		N/A	
Floor	carpet		N/A	
Pipe	not insulated		N/A	
Wall	drywall		N/A	017

## Comments:

**Level :** 4 - 4th Floor

**Asbestos present :** potential

**Room :** 446 - Office

Ceiling	2' x 4' ceiling tile		N/A	016
Ceiling	plaster		N/A	V-063
Duct	not insulated		N/A	
Floor	12" x 12" floor tile		N/A	
Pipe	not insulated		N/A	
Wall	plaster		N/A	V-060

## Comments:

**Level :** 4 - 4th Floor

**Asbestos present :** potential

**Room :** 447 - Stairwell

Ceiling	plaster		N/A	V-063
Floor	vinyl sheet flooring		N/A	V-012
Pipe	not insulated		N/A	
Wall	plaster		N/A	060

## Comments:

**Level :** 4 - 4th Floor

**Asbestos present :** potential

**Room :** 448 - Communications

Ceiling	plaster		N/A	V-060
---------	---------	--	-----	-------

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Floor	vinyl sheet flooring		N/A	NEW			
Wall	plaster		N/A	V-060			

**Comments:** no access into walls or ceiling cavities

**Level :** 4 - 4th Floor

**Asbestos present :** potential

**Room :** 460 - Stairwell

Ceiling	plaster		N/A	V-063			
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-062			

**Comments:**

**Level :** 4 - 4th Floor

**Asbestos present :** potential

**Room :** 461 - Office

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-063			
Duct	not insulated		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-017			
Wall	plaster		N/A	V-062			

**Comments:**

**Level :** 4 - 4th Floor

**Asbestos present :** potential

**Room :** 462 - Office

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-063			
Duct	not insulated		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-017			

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

Wall	plaster		N/A	V-062			
------	---------	--	-----	-------	--	--	--

## Comments:

**Level : 4 - 4th Floor**

**Asbestos present : potential**

**Room : 463 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-063			
Duct	not insulated		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-017			
Wall	plaster		N/A	V-062			

## Comments:

**Level : 4 - 4th Floor**

**Asbestos present : potential**

**Room : 464 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-063			
Duct	not insulated		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-017			
Wall	plaster		N/A	V-062			

## Comments:

**Level : 4 - 4th Floor**

**Asbestos present : potential**

**Room : 465 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-063			
Duct	not insulated		N/A				
Floor	12" x 12" floor tile		N/A				

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-017			
Wall	plaster		N/A	V-062			

## Comments:

**Level : 4 - 4th Floor**

**Asbestos present : potential**

**Room : 466 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-063			
Duct	not insulated		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-017			
Wall	plaster		N/A	V-062			

## Comments:

**Level : 4 - 4th Floor**

**Asbestos present : potential**

**Room : 467 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-063			
Duct	not insulated		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-017			
Wall	plaster		N/A	V-062			

## Comments:

**Level : 4 - 4th Floor**

**Asbestos present : potential**

**Room : 468 - Washroom**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-063			



# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-017			
Wall	plaster		N/A	V-066	Chrysotile < 1%		

## Comments:

**Level :** 4 - 4th Floor

**Asbestos present :** potential

**Room :** 469 - Washroom

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-063			
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-017			
Wall	plaster		N/A	V-066	Chrysotile < 1%		

## Comments:

**Level :** 4 - 4th Floor

**Asbestos present :** potential

**Room :** 469A - Pipe Chase

Ceiling	plaster		N/A	V-063			
Floor	vinyl sheet flooring		N/A	V-001			
Pipe	fiberglass		N/A				
Pipe	parging		N/A	V-015			
Wall	drywall		N/A	V-017			

## Comments:

**Level :** 5 - 5th Floor

**Asbestos present :** potential

**Room :** 500 - Hallway

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-077			
Ceiling	tile panels		N/A	014			
Floor	12" x 12" floor tile		N/A				

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Pipe	fiberglass		N/A				
Pipe	parging		N/A	015			
Wall	plaster		N/A	V-070			

## Comments:

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 501 - Pipe Chase**

Ceiling	plaster		N/A	V-076			
Floor	9" x 9" floor tile		N/A	V-002			
Pipe	fiberglass		N/A				
Pipe	parging		N/A	V-015			
Wall	drywall		N/A				

## Comments:

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 502 - Stairwell**

Ceiling	plaster		N/A	V-077			
Floor	vinyl sheet flooring		N/A	V-012			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-075	Chrysotile < 1%		

## Comments:

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 522 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-076			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-013			
Wall	plaster		N/A	V-072			

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

## Comments:

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 523 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-076			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-013			
Wall	plaster		N/A	V-072			

## Comments:

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 524 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-076			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-013			
Wall	plaster		N/A	V-072			

## Comments:

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 524A - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-076			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Wall	drywall		N/A	V-013			
Wall	plaster		N/A	V-072			

## Comments:

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 525 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-076			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-013			
Wall	plaster		N/A	V-072			

## Comments:

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 526 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-076			
Duct	fiberglass		N/A				
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-013			
Wall	plaster		N/A	V-072			

## Comments:

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 527 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-074			
Floor	vinyl sheet flooring		N/A				

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-073			

## Comments:

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 528 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-074			
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-073			

## Comments:

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 529 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-074			
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-073			

## Comments:

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 530 - Library**

Ceiling	plaster		N/A				
Floor	carpet		N/A	V-074			
Floor	concrete		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-073			

## Comments:

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 532 - Stairwell**

Ceiling	plaster		N/A	V-073
Floor	12" x 12" floor tile		N/A	NEW
Pipe	not insulated		N/A	
Wall	plaster		N/A	V-073

**Comments:** no access into walls or ceiling cavities

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 533 - Office**

Ceiling	2' x 4' fibreglass		N/A	
Ceiling	plaster		N/A	V-074
Floor	carpet		N/A	
Pipe	not insulated		N/A	
Wall	plaster		N/A	V-073

**Comments:**

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 534 - Office**

Ceiling	2' x 4' fibreglass		N/A	
Ceiling	plaster		N/A	V-074
Floor	carpet		N/A	
Pipe	not insulated		N/A	
Wall	plaster		N/A	V-073

**Comments:**

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 535 - storage**

Ceiling	plaster		N/A	V-074
Floor	vinyl sheet flooring		N/A	V-012
Pipe	not insulated		N/A	

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

Wall	plaster		N/A	V-073			
------	---------	--	-----	-------	--	--	--

**Comments:**

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 536 - storage**

Ceiling	plaster		N/A	V-074			
---------	---------	--	-----	-------	--	--	--

Floor	vinyl sheet flooring		N/A	V-012			
-------	----------------------	--	-----	-------	--	--	--

Pipe	not insulated		N/A				
------	---------------	--	-----	--	--	--	--

Wall	plaster		N/A	V-073			
------	---------	--	-----	-------	--	--	--

**Comments:**

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 537 - storage**

Ceiling	plaster		N/A	V-074			
---------	---------	--	-----	-------	--	--	--

Floor	vinyl sheet flooring		N/A	012			
-------	----------------------	--	-----	-----	--	--	--

Pipe	not insulated		N/A				
------	---------------	--	-----	--	--	--	--

Wall	plaster		N/A	V-073			
------	---------	--	-----	-------	--	--	--

**Comments:**

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 538 - Washroom**

Ceiling	fiberglass		N/A				
---------	------------	--	-----	--	--	--	--

Ceiling	plaster		N/A	V-076			
---------	---------	--	-----	-------	--	--	--

Floor	12" x 12" floor tile		N/A				
-------	----------------------	--	-----	--	--	--	--

Pipe	not insulated		N/A				
------	---------------	--	-----	--	--	--	--

Wall	plaster		N/A	071	Chrysotile < 1%		
------	---------	--	-----	-----	-----------------	--	--

**Comments:**

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 539 - Washroom**

Ceiling	fiberglass		N/A				
---------	------------	--	-----	--	--	--	--

Ceiling	plaster		N/A	V-076			
---------	---------	--	-----	-------	--	--	--

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-071	Chrysotile < 1%		

## Comments:

Level : 5 - 5th Floor

Asbestos present : potential

Room : 540 - Office

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-076			
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-013			

## Comments:

Level : 5 - 5th Floor

Asbestos present : potential

Room : 540A - Office

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-076			
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-013			

## Comments:

Level : 5 - 5th Floor

Asbestos present : potential

Room : 542 - Office

Ceiling	plaster		N/A	V-076			
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	013			

## Comments:



# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

**Level : 5 - 5th Floor**  
**Room : 543 - Office**

**Asbestos present : potential**

Ceiling	plaster		N/A	V-076			
Floor	carpet		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-013			

**Comments:**

**Level : 5 - 5th Floor**  
**Room : 544/544A - Office**

**Asbestos present : yes**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-076			
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-013			
Wall	plaster	2,500.0	ft <sup>2</sup>	good	GF-2009-08	Chrysotile 1.20%	A 7
Wall	plaster	25.0	ft <sup>2</sup>	poor	GF-2009-08	Chrysotile 1.20%	A 6
Wall	plaster			N/A	GF-2009-07		

**Comments:**

GF-2009-07 is white coat (top coat) plaster, GF-2009-08 is brown coat (bottom coat) plaster.  
Damaged section is on left side of room next to pillar.

**Level : 5 - 5th Floor**  
**Room : 546 - Office**

**Asbestos present : potential**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-076			
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-013			

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

## Comments:

**Level : 5 - 5th Floor**  
**Room : 546A - Office**

**Asbestos present : potential**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-076			
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-013			

## Comments:

**Level : 5 - 5th Floor**  
**Room : 546B - Office**

**Asbestos present : potential**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-076			
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-013			

## Comments:

**Level : 5 - 5th Floor**  
**Room : 547 - Office**

**Asbestos present : potential**

Ceiling	2' x 4' fibreglass		N/A				
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-013			

## Comments:

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 548 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A		V-013		

## Comments:

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 549 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A		V-013		

## Comments:

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 550 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A		V-013		

## Comments:

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 551 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Duct	fiberglass		N/A				

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-013			

## Comments:

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 552 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-076			
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-013			

## Comments:

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 553 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-076			
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-013			

## Comments:

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 554 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	drywall		N/A	V-013			
Ceiling	plaster		N/A	V-076			
Floor	12" x 12" floor tile		N/A				
Pipe	fiberglass		N/A				
Wall	drywall		N/A	V-013			

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

## Comments:

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 555 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A		V-013		

## Comments:

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 556 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A		V-013		

## Comments:

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 557 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A		V-013		

## Comments:

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 558 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A		V-013		

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

## Comments:

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 559 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A		V-013		

## Comments:

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 560 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A		V-013		

## Comments:

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 561A - Office**

Ceiling	2' x 4' fibreglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A		V-013		

## Comments:

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 561B - Office**

Ceiling	2' x 4' fibreglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A		V-013		

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

## Comments:

Level : 5 - 5th Floor

Asbestos present : potential

Room : 562 - Office

Ceiling	2' x 4' fibreglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A		V-013		

## Comments:

Level : 5 - 5th Floor

Asbestos present : potential

Room : 563 - Office

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A		V-077		
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A		V-013		
Wall	plaster		N/A		V-078		

## Comments:

Level : 5 - 5th Floor

Asbestos present : potential

Room : 564 - Office

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A		V-077		
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A		V-013		
Wall	plaster		N/A		V-078		

## Comments:

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
<b>Level : 5 - 5th Floor</b>		<b>Asbestos present : potential</b>					
<b>Room : 565 - Office</b>							
Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-077			
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-013			
Wall	plaster		N/A	V-078			

## Comments:

<b>Level : 5 - 5th Floor</b>		<b>Asbestos present : potential</b>					
<b>Room : 566 - Office</b>							
Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-077			
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-013			
Wall	plaster		N/A	V-078			

## Comments:

<b>Level : 5 - 5th Floor</b>		<b>Asbestos present : potential</b>					
<b>Room : 567 - Office</b>							
Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-077			
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-013			



# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Wall	plaster		N/A	V-078			

## Comments:

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 568 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-077			
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-013			
Wall	plaster		N/A	V-078			

## Comments:

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 569 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-077			
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-013			
Wall	plaster		N/A	V-078			

## Comments:

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 570 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-077			
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-013			
Wall	plaster		N/A	V-078			

## Comments:

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 571 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-077			
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-013			
Wall	plaster		N/A	V-078			

## Comments:

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 572 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-077			
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-013			
Wall	plaster		N/A	V-078			

## Comments:

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 573 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-077			

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-013			
Wall	plaster		N/A	V-078			

## Comments:

**Level : 5 - 5th Floor**  
**Room : 574 - Office**

**Asbestos present : potential**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-077			
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-013			
Wall	plaster		N/A	V-078			

## Comments:

**Level : 5 - 5th Floor**  
**Room : 575 - Office**

**Asbestos present : potential**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-077			
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-013			
Wall	plaster		N/A	V-078			

## Comments:

**Level : 5 - 5th Floor**  
**Room : 576 - Office**

**Asbestos present : potential**

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-077			
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-013			
Wall	plaster		N/A	V-078			

## Comments:

Level : 5 - 5th Floor

Asbestos present : potential

Room : 576A - Office

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-077			
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-013			
Wall	plaster		N/A	V-078			

## Comments:

Level : 5 - 5th Floor

Asbestos present : potential

Room : 576B - Office

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-077			
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-013			
Wall	plaster		N/A	V-078			

## Comments:

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
<b>Level : 5 - 5th Floor</b>			<b>Asbestos present : potential</b>				
<b>Room : 577 - storage</b>							
Ceiling	plaster		N/A	V-077			
Floor	vinyl sheet flooring		N/A	V-006			
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-013			
Wall	plaster		N/A	V-075	Chrysotile < 1%		

## Comments:

<b>Level : 5 - 5th Floor</b>			<b>Asbestos present : potential</b>				
<b>Room : 578 - Office</b>							
Ceiling	2' x 4' fibreglass		N/A				
Floor	12" x 12" floor tile		N/A				
Floor	carpet		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-013			

## Comments:

<b>Level : 5 - 5th Floor</b>			<b>Asbestos present : potential</b>				
<b>Room : 578A - Office</b>							
Ceiling	2' x 4' fibreglass		N/A				
Floor	12" x 12" floor tile		N/A				
Floor	carpet		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-013			

## Comments:

<b>Level : 5 - 5th Floor</b>			<b>Asbestos present : potential</b>				
<b>Room : 579 - Stairwell</b>							
Ceiling	plaster		N/A	V-077			
Floor	vinyl sheet flooring		N/A	V-012			

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

Wall	plaster		N/A	V-078			
------	---------	--	-----	-------	--	--	--

**Comments:**

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 580 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-077			
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-013			
Wall	plaster		N/A	V-078			

**Comments:**

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 581 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-077			
Duct	fiberglass		N/A				
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-013			
Wall	plaster		N/A	V-078			

**Comments:**

**Level : 5 - 5th Floor**

**Asbestos present : potential**

**Room : 582 - Elevator**

No Access	unsurveyed		N/A				
-----------	------------	--	-----	--	--	--	--

**Comments:** no access

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
<b>Level : 6 - 6th Floor</b>		<b>Asbestos present : potential</b>					
<b>Room : 601 - Hallway</b>							
Ceiling	plaster		N/A	V-079	Chrysotile < 1%		
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

## Comments:

<b>Level : 6 - 6th Floor</b>		<b>Asbestos present : potential</b>					
<b>Room : 602 - Stairwell</b>							
Ceiling	plaster		N/A	V-080			
Floor	vinyl sheet flooring		N/A	NEW			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

**Comments:** no access into walls or ceiling cavities

<b>Level : 6 - 6th Floor</b>		<b>Asbestos present : potential</b>					
<b>Room : 605 - Hallway</b>							
Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-079	Chrysotile < 1%		
Floor	vinyl sheet flooring		N/A	GF-2009-03			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

## Comments:

<b>Level : 6 - 6th Floor</b>		<b>Asbestos present : potential</b>					
<b>Room : 606 - Vending Machine</b>							
Ceiling	2' x 4' fibreglass		N/A				
Floor	vinyl sheet flooring		N/A	NEW			
Wall	plaster		N/A	V-080			

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

**Comments:** no access into walls or ceiling cavities

**Level :** 6 - 6th Floor

**Asbestos present :** potential

**Room :** 608 - Cafeteria

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-090			
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

**Comments:**

**Level :** 6 - 6th Floor

**Asbestos present :** potential

**Room :** 609 - Anterroom

Ceiling	plaster		N/A	V-080			
Floor	vinyl sheet flooring		N/A	NEW			
Wall	plaster		N/A	V-080			

**Comments:** no access into walls or ceiling cavities

**Level :** 6 - 6th Floor

**Asbestos present :** potential

**Room :** 609A - Washroom

Ceiling	plaster		N/A	V-080			
Floor	vinyl sheet flooring		N/A	NEW			
Wall	plaster		N/A	V-080			

**Comments:** no access into walls or ceiling cavities

**Level :** 6 - 6th Floor

**Asbestos present :** potential

**Room :** 610 - Board Room

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-090			
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				



# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

Wall	plaster		N/A	V-080			
------	---------	--	-----	-------	--	--	--

**Comments:**

**Level : 6 - 6th Floor**

**Asbestos present : potential**

**Room : 611 - Board Room**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-090			
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

**Comments:**

**Level : 6 - 6th Floor**

**Asbestos present : potential**

**Room : 612 - Board Room**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-090			
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

**Comments:**

**Level : 6 - 6th Floor**

**Asbestos present : potential**

**Room : 613 - Board Room**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-090			
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

**Comments:**

**Level : 6 - 6th Floor**

**Asbestos present : potential**

**Room : 614 - Board Room**

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Ceiling	plaster		N/A	V-090			
Floor	wood		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

## Comments:

**Level :** 6 - 6th Floor

**Asbestos present :** potential

**Room :** 615 - Hallway

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-090			
Duct	not insulated		N/A				
Floor	vinyl sheet flooring		N/A				
Wall	plaster		N/A	V-080			

## Comments:

**Level :** 6 - 6th Floor

**Asbestos present :** potential

**Room :** 616 - Stairwell

Ceiling	plaster		N/A	V-080			
Floor	12" x 12" floor tile		N/A	NEW			
Wall	plaster		N/A	V-080			

**Comments:** no access into walls or ceiling cavities

**Level :** 6 - 6th Floor

**Asbestos present :** potential

**Room :** 618 - storage

Ceiling	plaster		N/A	V-090			
Floor	9" x 9" floor tile		N/A	V-009			
Wall	plaster		N/A	V-080			

## Comments:

**Level :** 6 - 6th Floor

**Asbestos present :** potential

**Room :** 620 - storage

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Ceiling	plaster		N/A	V-090			
Floor	9" x 9" floor tile		N/A	V-009			
Wall	plaster		N/A	V-080			

## Comments:

**Level :** 6 - 6th Floor

**Asbestos present :** potential

**Room :** 622 - storage

Ceiling	plaster		N/A	V-090			
Floor	9" x 9" floor tile		N/A	009			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

## Comments:

**Level :** 6 - 6th Floor

**Asbestos present :** potential

**Room :** 624 - storage

Ceiling	plaster		N/A	V-090			
Floor	9" x 9" floor tile		N/A	009			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

## Comments:

**Level :** 6 - 6th Floor

**Asbestos present :** potential

**Room :** 626 - Office

Ceiling	plaster		N/A	V-090			
Floor	12" x 12" floor tile		N/A				
Pipe	fiberglass		N/A				
Wall	drywall		N/A	008			
Wall	plaster		N/A	V-080			

## Comments:

**Level :** 6 - 6th Floor

**Asbestos present :** potential

**Room :** 628 - storage

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Ceiling	plaster		N/A	V-090			
Floor	9" x 9" floor tile		N/A	V-009			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

## Comments:

**Level :** 6 - 6th Floor

**Asbestos present :** potential

**Room :** 630 - Office

Ceiling	plaster		N/A	V-090			
Floor	carpet		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	V-008			

## Comments:

**Level :** 6 - 6th Floor

**Asbestos present :** potential

**Room :** 634 - Washroom

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-090			
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

## Comments:

**Level :** 6 - 6th Floor

**Asbestos present :** potential

**Room :** 634A - Pipe Chase

Ceiling	plaster		N/A	V-090			
Floor	9" x 9" floor tile		N/A	V-002			
Pipe	fiberglass		N/A				
Wall	drywall		N/A				

## Comments:

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

**Level : 6 - 6th Floor**

**Asbestos present : potential**

**Room : 635 - Washroom**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-090			
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

## Comments:

**Level : 6 - 6th Floor**

**Asbestos present : potential**

**Room : 636 - Hallway**

Ceiling	2' x 4' fibreglass		N/A				
Floor	9" x 9" floor tile		N/A	V-007			
Wall	plaster		N/A	V-080			

## Comments:

**Level : 6 - 6th Floor**

**Asbestos present : potential**

**Room : 638 - Office**

Ceiling	plaster		N/A	V-090			
Floor	carpet		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

## Comments:

**Level : 6 - 6th Floor**

**Asbestos present : potential**

**Room : 639 - Computer Room**

Ceiling	plaster		N/A	V-090			
Duct	not insulated		N/A				
Electrical	non insulated		N/A				
Floor	vinyl sheet flooring		N/A	010			
Pipe	fiberglass		N/A				

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

Wall	plaster		N/A	V-080			
------	---------	--	-----	-------	--	--	--

## Comments:

**Level : 6 - 6th Floor**

**Asbestos present : potential**

**Room : 640 - Mechanical Room**

Ceiling	plaster		N/A	V-083			
Duct	not insulated		N/A				
Floor	vinyl sheet flooring		N/A	011			
Mechanical	not insulated		N/A				
Pipe	fiberglass		N/A				
Wall	plaster		N/A	080			

## Comments:

**Level : 6 - 6th Floor**

**Asbestos present : potential**

**Room : 641 - Board Room**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-083			
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

## Comments:

**Level : 6 - 6th Floor**

**Asbestos present : potential**

**Room : 642 - storage**

Ceiling	plaster		N/A	V-083			
Floor	12" x 12" floor tile		N/A	GF-2009-04			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

## Comments:

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

**Level : 6 - 6th Floor**  
**Room : 643 - Hallway**

**Asbestos present : potential**

Ceiling	plaster		N/A	V-083			
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

## Comments:

**Level : 6 - 6th Floor**  
**Room : 644 - storage**

**Asbestos present : potential**

Ceiling	plaster		N/A	V-083			
Floor	concrete		N/A				
Pipe	not insulated		N/A				
Wall	drywall		N/A	008			
Wall	plaster		N/A	026			

## Comments:

**Level : 6 - 6th Floor**  
**Room : 645 - Stairwell**

**Asbestos present : potential**

Ceiling	plaster		N/A	V-080			
Wall	plaster		N/A	V-080			

**Comments:** no access into walls or ceiling cavities

**Level : 6 - 6th Floor**  
**Room : 646 - Hallway**

**Asbestos present : potential**

Ceiling	plaster		N/A	V-083			
Floor	9" x 9" floor tile		N/A	V-006			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

## Comments:

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

**Level : 6 - 6th Floor**  
**Room : 647 - Stairwell**

**Asbestos present :** potential

Ceiling	plaster		N/A	V-083			
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

**Comments:**

**Level : 6 - 6th Floor**  
**Room : 648 - Elevator**

**Asbestos present :** potential

No Access	unsurveyed		N/A				
-----------	------------	--	-----	--	--	--	--

**Comments:** no access into walls or ceiling cavities

**Level : 6 - 6th Floor**  
**Room : 649 - Copier Room**

**Asbestos present :** potential

Ceiling	2' x 4' fibreglass		N/A				
Floor	vinyl sheet flooring		N/A	NEW			
Wall	plaster		N/A	V-080			

**Comments:** no access into walls or ceiling cavities

**Level : 6 - 6th Floor**  
**Room : 650 - Office**

**Asbestos present :** potential

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-083			
Floor	12" x 12" floor tile		N/A				
Floor	vinyl sheet flooring		N/A	V-011			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

**Comments:**



# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

**Level : 6 - 6th Floor**  
**Room : 650A - Office**

**Asbestos present : potential**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-083			
Floor	12" x 12" floor tile		N/A				
Floor	vinyl sheet flooring		N/A	V-011			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

**Comments:**

**Level : 6 - 6th Floor**  
**Room : 651 - Office**

**Asbestos present : potential**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-083			
Floor	12" x 12" floor tile		N/A				
Floor	vinyl sheet flooring		N/A	V-011			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

**Comments:**

**Level : 6 - 6th Floor**  
**Room : 652 - Office**

**Asbestos present : potential**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-083			
Floor	12" x 12" floor tile		N/A				
Floor	vinyl sheet flooring		N/A	V-011			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

**Comments:**

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

**Level : 6 - 6th Floor**

**Asbestos present : potential**

**Room : 653 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-083			
Floor	12" x 12" floor tile		N/A				
Floor	vinyl sheet flooring		N/A	V-011			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

## Comments:

**Level : 6 - 6th Floor**

**Asbestos present : potential**

**Room : 654 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-083			
Floor	12" x 12" floor tile		N/A				
Floor	vinyl sheet flooring		N/A	V-011			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

## Comments:

**Level : 6 - 6th Floor**

**Asbestos present : potential**

**Room : 655 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-083			
Floor	12" x 12" floor tile		N/A				
Floor	vinyl sheet flooring		N/A	V-011			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

## Comments:

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

**Level : 6 - 6th Floor**

**Asbestos present : potential**

**Room : 656 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-083			
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

## Comments:

**Level : 6 - 6th Floor**

**Asbestos present : potential**

**Room : 657 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-083			
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

## Comments:

**Level : 6 - 6th Floor**

**Asbestos present : potential**

**Room : 658 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-083			
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

## Comments:

**Level : 6 - 6th Floor**

**Asbestos present : potential**

**Room : 659 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-083			

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

## Comments:

**Level :** 6 - 6th Floor

**Asbestos present :** potential

**Room :** 660 - Office

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-083			
Floor	12" x 12" floor tile		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

## Comments:

**Level :** 6 - 6th Floor

**Asbestos present :** potential

**Room :** 661 - Hallway

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-083			
Floor	12" x 12" floor tile		N/A				
Pipe	fiberglass		N/A				
Wall	plaster		N/A	V-080			

## Comments:

**Level :** 6 - 6th Floor

**Asbestos present :** potential

**Room :** 662 - Board Room

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-083			
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

## Comments:

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

**Level : 6 - 6th Floor**

**Asbestos present : potential**

**Room : 664 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-090			
Floor	carpet		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

## Comments:

**Level : 6 - 6th Floor**

**Asbestos present : potential**

**Room : 665 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-090			
Floor	carpet		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

## Comments:

**Level : 6 - 6th Floor**

**Asbestos present : potential**

**Room : 666 - Hallway**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-090			
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

## Comments:

**Level : 6 - 6th Floor**

**Asbestos present : potential**

**Room : 667 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-090			

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Floor	carpet		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

## Comments:

**Level : 6 - 6th Floor**

**Asbestos present : potential**

**Room : 668 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-090			
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

## Comments:

**Level : 6 - 6th Floor**

**Asbestos present : potential**

**Room : 669 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-090			
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

## Comments:

**Level : 6 - 6th Floor**

**Asbestos present : potential**

**Room : 670 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-090			
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

## Comments:

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

**Level : 6 - 6th Floor**

**Asbestos present : potential**

**Room : 671 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-090			
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

**Comments:**

**Level : 6 - 6th Floor**

**Asbestos present : potential**

**Room : 672 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-090			
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

**Comments:**

**Level : 6 - 6th Floor**

**Asbestos present : potential**

**Room : 673 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-090			
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

**Comments:**

**Level : 6 - 6th Floor**

**Asbestos present : potential**

**Room : 674 - Office**

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-090			

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

## Comments:

**Level :** 6 - 6th Floor  
**Room :** 674A - Office

**Asbestos present :** potential

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-090			
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

## Comments:

**Level :** 6 - 6th Floor  
**Room :** 675 - Hallway

**Asbestos present :** potential

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-090			
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-080			

## Comments:

**Level :** 6 - 6th Floor  
**Room :** 676 - Office

**Asbestos present :** potential

Ceiling	plaster		N/A	V-090			
Floor	concrete		N/A				
Wall	plaster		N/A	V-080			

## Comments:

**Level :** 6 - 6th Floor  
**Room :** 677 - Office

**Asbestos present :** potential



# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Ceiling	plaster		N/A	V-090			
Floor	concrete		N/A				
Wall	plaster		N/A	V-080			

**Comments:**

**Level :** 7 - 7th Floor  
**Room :** 700 - Hallway

**Asbestos present :** potential

Ceiling	plaster		N/A	V-098			
Floor	9" x 9" floor tile		N/A	002			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-097	Chrysotile < 1%		

**Comments:**

No access to structure, walls or ceiling

**Level :** 7 - 7th Floor  
**Room :** 701 - Stairwell

**Asbestos present :** potential

Ceiling	2' x 4' fibreglass		N/A				
Floor	12" x 12" floor tile		N/A	NEW			
Floor	vinyl sheet flooring		N/A	NEW			
Wall	plaster		N/A	V-104	Chrysotile < 1%		

**Comments:** no access into walls or ceiling cavities

**Level :** 7 - 7th Floor  
**Room :** 702 - Stairwell

**Asbestos present :** potential

Ceiling	plaster		N/A	V-098			
Floor	vinyl sheet flooring		N/A	NEW			
Wall	plaster		N/A	V-104	Chrysotile < 1%		

**Comments:** no access into walls or ceiling cavities

**Level :** 7 - 7th Floor  
**Room :** 703 - Hallway

**Asbestos present :** potential

Ceiling	plaster		N/A	V-098			
---------	---------	--	-----	-------	--	--	--

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Floor	9" x 9" floor tile		N/A	002			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-097	Chrysotile < 1%		

## Comments:

No access to structure, walls or ceiling

**Level :** 7 - 7th Floor

**Asbestos present :** potential

**Room :** 704 - storage

Ceiling	plaster		N/A	V-098			
Floor	black mastic		N/A	V-003			
Floor	vinyl sheet flooring		N/A	V-001			
Mechanical	not insulated		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-104	Chrysotile < 1%		

## Comments:

No access to structure, walls or ceiling

**Level :** 7 - 7th Floor

**Asbestos present :** potential

**Room :** 705 - Glycol heating & ventilat

Ceiling	plaster		N/A	V-098			
Floor	Concrete		N/A				
Wall	plaster		N/A	V-104	Chrysotile < 1%		

**Comments:** no access into walls or ceiling cavities

**Level :** 7 - 7th Floor

**Asbestos present :** potential

**Room :** 706 - Hallway

Ceiling	plaster		N/A	V-098			
Floor	black mastic		N/A	003			
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-097	Chrysotile < 1%		

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

## Comments:

No access to structure, walls or ceiling

**Level :** 7 - 7th Floor

**Asbestos present :** potential

**Room :** 707 - Elevator

No Access

unsurveyed

N/A

## Comments: no access

**Level :** 7 - 7th Floor

**Asbestos present :** potential

**Room :** 708 - Hallway

Ceiling

plaster

N/A

V-098

Floor

black mastic

N/A

V-003

Floor

vinyl sheet flooring

N/A

Pipe

not insulated

N/A

Wall

plaster

N/A

V-097

Chrysotile < 1%

## Comments:

No access to structure, walls or ceiling

**Level :** 7 - 7th Floor

**Asbestos present :** potential

**Room :** 709 - Mechanical Room

Ceiling

plaster

N/A

V-098

Floor

concrete

N/A

Mechanical

not insulated

N/A

Pipe

not insulated

N/A

Wall

plaster

N/A

V-104

Chrysotile < 1%

## Comments:

No access to structure, walls or ceiling

**Level :** 7 - 7th Floor

**Asbestos present :** potential

**Room :** 710 - storage

Ceiling

plaster

N/A

V-098

Floor

black mastic

N/A

V-003

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Floor	vinyl sheet flooring		N/A	001			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-104			

## Comments:

No access to structure, walls or ceiling

**Level :** 7 - 7th Floor

**Asbestos present :** potential

**Room :** 711 - storage

Ceiling	plaster		N/A	V-098			
Floor	vinyl sheet flooring		N/A	V-001			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-104	Chrysotile < 1%		

## Comments:

No access to structure, walls or ceiling

**Level :** 7 - 7th Floor

**Asbestos present :** potential

**Room :** 712 - storage

Ceiling	plaster		N/A	V-098			
Floor	vinyl sheet flooring		N/A	V-001			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-104	Chrysotile < 1%		

## Comments:

**Level :** 7 - 7th Floor

**Asbestos present :** potential

**Room :** 713 - storage

Ceiling	plaster		N/A	V-098			
Floor	vinyl sheet flooring		N/A	V-001			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-104	Chrysotile < 1%		

## Comments:

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

**Level : 7 - 7th Floor**

**Asbestos present : potential**

**Room : 714 - storage**

Ceiling	plaster		N/A	V-098			
Floor	vinyl sheet flooring		N/A	V-001			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-104	Chrysotile < 1%		

## Comments:

**Level : 7 - 7th Floor**

**Asbestos present : potential**

**Room : 715 - storage**

Ceiling	plaster		N/A	V-098			
Floor	vinyl sheet flooring		N/A	V-001			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-104	Chrysotile < 1%		

## Comments:

No access to structure, walls or ceiling

**Level : 7 - 7th Floor**

**Asbestos present : potential**

**Room : 716 - storage**

Ceiling	plaster		N/A	V-098			
Floor	vinyl sheet flooring		N/A	V-001			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-104	Chrysotile < 1%		

## Comments:

No access to structure, walls or ceiling

**Level : 7 - 7th Floor**

**Asbestos present : potential**

**Room : 717 - Stairwell**

Ceiling	plaster		N/A	V-098			
Floor	12" x 12" floor tile		N/A	NEW			
Floor	vinyl sheet flooring		N/A	NEW			
Pipe	not insulated		N/A				

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

Wall	plaster		N/A	V-104	Chrysotile < 1%		
------	---------	--	-----	-------	-----------------	--	--

**Comments:** no access into walls or ceiling cavities

**Level :** 7 - 7th Floor

**Asbestos present :** potential

**Room :** 718 - storage

Ceiling	plaster		N/A	V-107			
Floor	vinyl sheet flooring		N/A	V-001			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-104	Chrysotile < 1%		

**Comments:**

No access to structure, walls or ceiling

**Level :** 7 - 7th Floor

**Asbestos present :** potential

**Room :** 719 - storage

Ceiling	plaster		N/A	V-107			
Floor	vinyl sheet flooring		N/A	V-001			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-104	Chrysotile < 1%		

**Comments:**

No access to structure, walls or ceiling

**Level :** 7 - 7th Floor

**Asbestos present :** potential

**Room :** 720 - storage

Ceiling	plaster		N/A	V-107			
Floor	vinyl sheet flooring		N/A	V-001			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-104	Chrysotile < 1%		

**Comments:**

No access to structure, walls or ceiling

**Level :** 7 - 7th Floor

**Asbestos present :** potential

**Room :** 723 - storage

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Ceiling	plaster		N/A	V-107			
Floor	vinyl sheet flooring		N/A	V-001			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-104	Chrysotile < 1%		

## Comments:

**Level : 7 - 7th Floor**

**Asbestos present : potential**

**Room : 724 - storage**

Ceiling	plaster		N/A	V-107			
Floor	vinyl sheet flooring		N/A	V-001			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-104	Chrysotile < 1%		

## Comments:

**Level : 7 - 7th Floor**

**Asbestos present : potential**

**Room : 725 - storage**

Ceiling	plaster		N/A	V-107			
Floor	vinyl sheet flooring		N/A	V-001			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-104	Chrysotile < 1%		

## Comments:

**Level : 7 - 7th Floor**

**Asbestos present : potential**

**Room : 726 - storage**

Ceiling	plaster		N/A	V-107			
Floor	vinyl sheet flooring		N/A	V-001			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-104	Chrysotile < 1%		

## Comments:

**Level : 7 - 7th Floor**

**Asbestos present : potential**

**Room : 727 - storage**

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Ceiling	plaster		N/A	V-107			
Floor	vinyl sheet flooring		N/A	V-001			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-104	Chrysotile < 1%		

## Comments:

**Level :** 7 - 7th Floor

**Asbestos present :** potential

**Room :** 728 - storage

Ceiling	plaster		N/A	V-107			
Floor	vinyl sheet flooring		N/A	V-001			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-104	Chrysotile < 1%		

## Comments:

**Level :** 7 - 7th Floor

**Asbestos present :** potential

**Room :** 729 - storage

Ceiling	plaster		N/A	V-107			
Floor	vinyl sheet flooring		N/A	V-001			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-104	Chrysotile < 1%		

## Comments:

**Level :** 7 - 7th Floor

**Asbestos present :** potential

**Room :** 730 - Stairwell

Ceiling	plaster		N/A	V-107			
Floor	9" x 9" floor tile		N/A	007			
Pipe	not insulated		N/A				
Wall	plaster		N/A	GF-2009-05	Chrysotile < 1%		
Wall	plaster		N/A	GF-2009-06	Chrysotile 0.50%		
Wall	plaster		N/A	V-104	Chrysotile < 1%		



# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

**Comments:**

**Level :** 7 - 7th Floor

**Asbestos present :** potential

**Room :** 731 - Washroom

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-107			
Floor	vinyl sheet flooring		N/A	006			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-100	Chrysotile < 1%		

**Comments:**

**Level :** 7 - 7th Floor

**Asbestos present :** potential

**Room :** 732 - Washroom

Ceiling	2' x 4' fibreglass		N/A				
Ceiling	plaster		N/A	V-107			
Floor	vinyl sheet flooring		N/A	006			
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-100	Chrysotile < 1%		

**Comments:**

**Level :** 7 - 7th Floor

**Asbestos present :** potential

**Room :** 734 - Roof Access

Ceiling	plaster		N/A	V-107			
Floor	vinyl sheet flooring		N/A				
Pipe	not insulated		N/A				
Wall	plaster		N/A	V-104	Chrysotile < 1%		
Wall	plaster		N/A	005			

**Comments:**

**Level :** EXT - Exterior

**Asbestos present :** potential

**Room :** EXT - Exterior

Wall	concrete		N/A				
------	----------	--	-----	--	--	--	--

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user:All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
--------	-------------	----------	-------	--------	---------------	---------	--------

Wall	Stone			N/A			
------	-------	--	--	-----	--	--	--

## Comments:

**Level :** ROOF - Roof

**Asbestos present :** potential

**Room :** PH1 - Penthouse

Ceiling	wood			N/A			
Electrical	not insulated			N/A			
Floor	concrete			N/A			
Floor	wood			N/A			
Mechanical	not insulated			N/A			
Pipe	not insulated			N/A			
Structure	steel			N/A			
Structure	wood			N/A			
Wall	wood			N/A			

## Comments:

**Level :** ROOF - Roof

**Asbestos present :** potential

**Room :** PH2 - Penthouse

Ceiling	metal			N/A			
Duct	not insulated			N/A			
Electrical	not insulated			N/A			
Floor	concrete			N/A			
Mechanical	not insulated			N/A			
Pipe	fiberglass			N/A			
Pipe	fittings-(new) DHW/DCW			N/A			
Structure	steel			N/A			
Wall	metal			N/A			

## Comments:

**Level :** ROOF - Roof

**Asbestos present :** potential

**Room :** ROOF - Roof Access

# Assessment Report

(sorted by asset ID)

520092 - Gulf Fisheries

Registered user: All-TECH Environmental services

Design	Description	Quantity	Cond.	Sample	Asbestos type	Access.	Action
Duct	not insulated		N/A				
Floor	adhesive		N/A	004			
Mechanical	not insulated		N/A				
Pipe	not insulated		N/A				
Wall	metal		N/A				

**Comments:**