




**Photo 1** – Existing damaged concrete encased steel beams at expansion joint (south side of expansion joint)



**Photo 2** – Existing damaged concrete encased steel beams at expansion joint (south side of expansion joint)



**Photo 3** – Existing damaged concrete encased steel beams at expansion joint (north side of expansion joint)



**Photo 4** – Existing damaged concrete encased steel beams at expansion joint (north side of expansion joint)



**Photo 5** – Existing damaged concrete encased steel beam at expansion joint (south side of expansion joint)



**Photo 6** – Existing damaged concrete encased steel beam at expansion joint (south side of expansion joint)