


CHIPP LAKE



FINAL



- LEGEND:
- WASTE ROCK SAMPLE LOCATION
 - TRENCH
 - WASTE ROCK
 - CONTROL POINT
 - APEC BOUNDARY



 Public Works and Government Services Canada / Travaux publics et Services gouvernementaux Canada	REMEDATION ACTION PLAN FOR 7 ABANDONED MINE SITES, NT				
	CHIPP LAKE MINE: ESTIMATED VOLUMES FOR WASTE ROCK AND PHYSICAL HAZARDS				
	PROJECT No. 122510933	OFFICE OTT	DES DW	CKD FL	REV 0
DATE: Mar 2015	SHEET No. - of -	DWN APP	LC	STATUS -	DRAWING FIGURE CL 2

C:\Users\jgibson\OneDrive\Documents\Projects\2015\122510933\122510933_02.dwg - 27/03/2015 10:59:39 AM - 601 - CADP - LMS

CHIPP HAZARDOUS AND NON-HAZARDOUS MATERIALS INVENTORY TABLE						
APEC #	APEC Description	Material Classification	Material Type	Volume (m³ and drums)¹	Material Description	Condition
1A	Trenches and loose waste rock	None Identified	None Identified	None Identified	None Identified	None Identified
1B	Trenches and loose waste rock	None Identified	None Identified	None Identified	None Identified	None Identified
1C	Trenches and loose waste rock	None Identified	None Identified	None Identified	None Identified	None Identified
1D	Trenches and loose waste rock	None Identified	None Identified	None Identified	None Identified	None Identified
1E	Trenches and loose waste rock	None Identified	None Identified	None Identified	None Identified	None Identified
1F	Trenches and loose waste rock	None Identified	None Identified	None Identified	None Identified	None Identified
2	Shaft with trenches and waste rock	Non-Hazardous	Wood Debris	2	Wood logs around shaft at unknown depth, logs scattered	Unpainted
			Metal Debris	0.5	Metal stake: 2 m long, 2 cm thick, 6 core racks	Unpainted
			Core	0.5	Coresh	Broken
3	Cabin	Non-Hazardous	Wood Debris	4	Cabin: wood logs within. Made of wood logs, 2x4 frames, 21 logs high	Unpainted, no roof
			Metal Debris	0.5	Metal pipe, tin cans, empty drum (75 L), pot, pan	Rusted
			Plastic	0.5	1 inch black pvc pipe	Intact
			Roofing Material	0.5	Black shingles and felt scattered sampled and is not an ACM	Torn, scattered
4	Dock	Non-Hazardous	Wood Debris	2	Dock: wood and tent Frame: plywood, logs and 2x4s	Unpainted
			Metal Debris	0.5	Stove and vents, piles of cans and food containers	Rusted
			Plastic	1	1 inch black pvc pipe	Intact
		Hazardous (leachable lead paint)	Drum (75L)	1 drum	1 (75L) drum red and blue, empty	Intact
Totals (Uncrushed and m³)	Non-Hazardous	Wood Debris	8		Notes: 1. All volumes: uncrushed	
		Metal Debris	1.5			
		Core	0.5			
		Plastic	1.5			
		Roofing Material	0.5			
	Hazardous (Leachable lead paint)	Drums (75 L)	1 drum			



- LEGEND:
- ⊗ - HAZMAT SAMPLE LOCATION
 - TRENCH
 - WASTE ROCK
 - CP - CONTROL POINT
 - APEC BOUNDARY
 - D - DRUMS
 - M - METAL DEBRIS
 - W - WOOD DEBRIS
 - V - VEHICLE



CLIENT: Public Works and Government Services Canada / Travaux publics et Services gouvernementaux Canada

REMEDIACTION ACTION PLAN FOR 7 ABANDONED MINE SITES, NT

CHIPP LAKE MINE: HAZARDOUS AND NON-HAZARDOUS MATERIALS

PROJECT No.	OFFICE	DES	CKD	REV	DRAWING
122510933	OTT	DW	FL	0	FIGURE CL 3
DATE:	SHEET No.	DWN	APP	STATUS	
Mar 2015	- of -	LC	-	-	

Stantec