




2009 – Upstream riverbed during low water conditions



2009 – Pool No. 1 with attraction flow grating



2009 – Repair work at Pool No. 6



2009 – Inlet at Pool No. 6



2009 – Wall repairs in Pool No. 1




2009 – Wooden fish counting trap without above enclosure (Pools No. 4 and 5)



2009 – Wooden fish counting trap without above enclosure (Pools No. 4 & 5)



2009 – Wooden fish counting trap without above enclosure (Pool’s No. 4 & 5)



2009 – Stop logs and screen (on left) in Pool No. 6



2009 – Retaining wall and inlet to Pool No. 1



2009 – Overall fishway with timber enclosure over fish trap area



2009 – Steel pipe railing around Pool No. 5 & 6



2015 – Rock outcrop in area of new staircase



2015 – Concrete deterioration/cracks in far wall




2015 – Embedded steel grating supports



2015 – Debris on screen in Pool No. 6



2015 – Uplands wooden fence/railing



2015 – Fish trap enclosure indicating raised portion of Pool No. 5 and Pool No. 6



2015 – Pool No. 1



2015 – Pool No. 2 & 3



2015 – Raised portion of Pool No. 5




2015 – Stop logs at inlet to Pool No. 5



2015 – Retaining wall adjoining Pool No. 6 and No. 7



2015 – Staircase, rock outcrop, trap enclosure, wooden hoist and uplands wooden fence



2015 – Embedded steel grating support with concrete damage



2015 – Inlet at Pool No. 1



2015 – Pool No. 1 with partial section of grating removed exposing steel supports



2015 – Site cabin during winter



2015 – Fishway during winter



2015 – Fishway during winter



2015 – Fishway during winter, Pool No. 5 & 6



2015 – Staircase during winter



2015 – Fishway during winter, looking towards Pool No. 6



2015 – Fishway during winter