



LES TRAVAUX DÉCRITS SUR CE PLAN SONT :


- LES TRAVAUX AU-NIVEAU DE LA DALLE DE BÉTON EXISTANTE, UNE FOIS LES TRAVAUX DE DÉMOLITION DE LA STRUCTURE DE BOIS TERMINÉS.

WORKS DETAILED ON THIS PLAN ARE :


- WORK AT THE EXISTING CONCRETE SLAB LEVEL, ONCE THE DEMOLITION WORK OF THE RAISED ROOF STRUCTURE ARE COMPLETED

THE ISSUES NOW SURROUNDING THE PROBLEM.

| BLOC B                  |                        |                               |
|-------------------------|------------------------|-------------------------------|
| BLOC B                  |                        |                               |
| BASSIN<br><i>BASSIN</i> | SURFACE<br><i>AREA</i> | STRUCTURE<br><i>STRUCTURE</i> |
| B-1                     | ± 112 m <sup>2</sup>   | BETON<br><i>CONCRETE</i>      |
| B-2                     | ± 676 m <sup>2</sup>   | BETON<br><i>CONCRETE</i>      |
| B-3                     | ± 754 m <sup>2</sup>   | BETON<br><i>CONCRETE</i>      |
| B-4                     | ± 87 m <sup>2</sup>    | BETON<br><i>CONCRETE</i>      |
| B-5                     | ± 120 m <sup>2</sup>   | BETON<br><i>CONCRETE</i>      |



CONSTRUCTION - TOITURE  
CONSTRUCTION - ROOF

GENERAL NOTES  
CONSTRUCTION[illegible]NOTES GÉNÉRALES  
CONSTRUCTION[illegible]

## CONSTRUCTION NOTES

### STATISTIQUE ET DIAGNOSTIC

## CONSTRUCTION NOTES

[illegible]

| LEGEND - ROOF CONSTRUCTION |  |
|----------------------------|--|
|                            | SYMBOLS<br>CONCRETE SLAB ON STEEL DECK (ROOF DECK) |

ROOF LEVEL MEASURED FROM EXISTING ROOF DECK

DIRECTION AND INCLINE OF ROOF PITCH

HATCHES

NOT IN CONTRACT ZONE

• • • • •

NEW FARMER LEASING

ARCHITECTURE

NEW ROOF SLOPES AND DRAINS, SEE CONSTRUCTION NOTES

11/10/23

REINSTALLED MECHANICAL EQUIPMENT AND/OR ACCESSORIES, SEE CONSTRUCTION NOTES

MEMB.280 : MODIFIED BITUMEN PROTECTION AND TRAFFIC

PADS, CONTRASTING COLOUR, SEE DETAIL 9/A452

---

---