


FEEDER WIRING DIAGRAM – POWER CENTRE #1

NOTES:


1. SPLICES IN JUNCTION BOXES TO BE MADE WITH HEAT SHRINK BOOTS.



FEEDER WIRING DIAGRAM – POWER CENTRE #3

NOTES:


1. SPLICES IN JUNCTION BOXES TO BE MADE WITH HEAT SHRINK BOOTS.




FEEDER WIRING DIAGRAM – POWER CENTRE #5

NOTES:

1. SPLICES IN JUNCTION BOXES TO BE MADE WITH HEAT SHRINK BOOTS



FEEDER WIRING DIAGRAM – POWER CENTRE #2



FEEDER WIRING DIAGRAM – POWER CENTRE #4

NOTES:

1. SPLICES IN JUNCTION BOXES TO BE MADE WITH HEAT SHRINK BOOTS.