




**FENDER PILE DETAIL** 13A  
7/13





**FENDER PILE SADDLE DETAIL** 13B  
13/13




**AR2 (GALV) FENDER AND SHEATHING ANCHOR ROD DETAIL**




**PILE SHOE DETAIL** 13C  
13/13




**LADDER EXTENSION DETAIL at EXISTING WHARF** 13K  
8/13 (3-LOCS AT DREDGE EL 5.50 2-LOCS AT DREDGE EL 6.00)




**TYPICAL LADDER & SHEATHING DETAIL** 13E  
7/13




**TYPICAL LADDER DETAIL** 13F  
13/13



**DETAIL** 13H  
13/13



**DETAIL** 13G  
13/13



**PLAN DETAIL** 13J  
13/13