

July 11, 2016

ADDENDUM TO REQUEST FOR PROPOSAL DOCUMENT  
FOR  
Duncairn Dam  
Service Contract No. 18  
Engineering Services for Rehabilitation of the Downstream Low Level Gate System  
REQUEST FOR PROPOSAL # 4547:928-7D10-0-S1-18

Addendum No. 1

Q1 - Do you have any photos showing the damage to the gate frame and downstream area?

A1 - The pdf of photos is attached. The first shows the damage to the top of the gate frame (approximately 300 mm chunk broken out of the top of the gate frame and pointed out by an arrow) the second (fully labelled) shows the cavitation damage to the frame itself.

Q2 - Also can you tell us what the air vent pipe diameter is?

A2 - PDFs of two plans are provided. 26714\_C is an old plan but indicates the vent is 2 inch galvanized. 206888 does not state the diameter but does show the approximate location of the vent pipe relative to the gate.

Colby Collinge  
Materiel Manager, AAFC  
Regina, Saskatchewan