

03	RE-ISSUED FOR TENDER	05.07.16
02	ISSUED FOR TENDER	03.05.16
01	ISSUED FOR 99%	06.04.16
revisions		date

project project

**MACHIAS SEAL ISLAND
LIGHTHOUSE
RESTORATION**

drawing dessin

DETAIL PHOTOS

designed TAYLOR HAZELL ARCHITECTS conçu

date 2016-02

drawn N. ADDISON dessiné

date

approved C. HAZELL approuvé

date

Tender Soumission

PWGSC Project Manager Administrateur de projets TPSCG

project number no. du projet

R.080316.001

drawing no. no. du dessin

A301



PHOTO 15 - INTERIOR OF SECOND FLOOR PLATFORM ACCESS DOOR. REMOVE DOOR, ROUGHEN EDGES AND FILL WITH CONCRETE. REFER TO STRUCTURAL.



PHOTO 12 - DETAIL VIEW OF INTERIOR LANTERN TIE BAR TO BE REPLACED TO MATCH ORIGINAL. REFER TO STRUCTURAL.



PHOTO 13 - DETAIL OF EXISTING LANTERN VENT WITH FAILED RUBBER SEAL, INTERIOR. REMOVE SEAL, PAINT AND CORROSION. PROVIDE REPLACEMENT CAP WITH GASKET AND INSTALL IN "CLOSED" POSITION. MAKE-GOOD ANY DAMAGE TO CONCRETE SUSTAINED DURING REMOVAL.




PHOTO 11 - EXISTING PLATFORMS TO BE REMOVED. EXISTING PLATFORM ACCESS DOORS TO BE REMOVED. REINSTATE CONCRETE TO MATCH EXISTING BOARD FORM FINISH. REFER TO STRUCTURAL.



PHOTO 17 - EXAMPLE OF BOARD-FORMED CONCRETE FINISH TECHNIQUE BEING APPLIED AT POINT ABINO LIGHTHOUSE, ONTARIO. ALL CONCRETE REPAIRS TO HAVE BOARD FORMED FINISH.



PHOTO 14 - DETAIL OF EXISTING LANTERN VENT, INTERIOR. REMOVE CAP AND REMOVE PAINT AND CORROSION. PROVIDE GASKET FOR SEAL AND REINSTATE CAP IN "CLOSED" POSITION. MAKE-GOOD ANY DAMAGE TO CONCRETE SUSTAINED DURING REMOVAL OF CAP.




PHOTO 10 - TYPICAL CONCRETE PEDIMENTS AT WINDOWS W13, W14, W15 & W16 TO BE REPAIRED IN PLACE. NEW CONCRETE PEDIMENTS AT WINDOWS W17 & W18. REFER TO STRUCTURAL.



PHOTO 16 - INTERIOR OF GALLERY HATCH. SILL AND HEAD CASING ARE ORIGINAL AND ARE TO BE RETAINED. JAMBS AND DOOR TO BE REPLACED. REFER TO DETAIL 3/A500



PHOTO 13 - EXTERIOR GALLERY LADDER. PROVIDE NEW METAL BOLTED CONNECTIONS. REFER TO DETAIL 2/A501.



PHOTO 04 -INTERIOR VIEW SHOWING FOG DETECTOR TO BE REMOVED BY OTHERS. FOG DETECTOR WINDOW TO BE REMOVED WITH INSIDE FACE OF OPENING ROUGHENED AND FILLED WITH CONCRETE. REFER TO STRUCTURAL.