

Overview of rock slope




Photo Taken: June 22, 2016

CONSULTING ENGINEERS & SCIENTISTS • www.eba.ca





Photo Taken: June 22, 2016

CONSULTING ENGINEERS & SCIENTISTS • www.eba.ca













Location of 20 m Rundle Stone wall to be constructed to match existing walls along trail. Wall to be constructed after scaling activities are finished.










Photo Taken: June 22, 2016

CONSULTING ENGINEERS & SCIENTISTS • www.eba.ca












Photo Taken: June 22, 2016

CONSULTING ENGINEERS & SCIENTISTS • www.eba.ca





Photo Taken: June 22, 2016

CONSULTING ENGINEERS & SCIENTISTS • www.eba.ca











Erosion control matting installation
area combination of normal and
Greenax about 250 m²







Photo Taken: June 22, 2016


CONSULTING ENGINEERS & SCIENTISTS • www.eba.ca

















Example of area requiring cold patching repair



Example of areas requiring cold patch repair

Summary of Cold Patch Locations	
Location	Estimated Cold Patch Area (m ²)
0+512 to 0+545	45
0+789 to 0+815	9
0+815 to 0+867	60
0+953 to 0+983	5
1+020	10
1+020 to 1+060	15
~2+100 to 2+650	50
Junction to Ink Pots Trail (~2+610 m) to Upper Lookout	15
Total	209