

Appendix B

Photos



2009 – Upstream riverbed during low water conditions




2009 – Pool No. 1 with attraction flow grating



2009 – Repair work at Pool No. 6



2009 – Inlet at Pool No. 6



2009 – Stop logs and screen (on left) in Pool No. 6



2009 – Retaining wall and inlet to Pool No. 1



2015 – Debris on screen in Pool No. 6




2015 – Inlet at Pool No. 1



2015 – Fishway during winter, Pool No. 5 & 6



Water level dropped at entrance (Pool #5 & #6)



Steel sill wall, interior steel frame and rock & debris at entrance to Pool #6



Steel frame assembly inside Pool #6



Attraction flow floor grating in Pool #1



Screen replacement in Pool #6



Existing screens for Pool #6



June 2016 – Overall Site



June 2016 – Overall Site