

APPENDIX A

Site Photographs



Photograph 1: Northeast view of AEC 6 and overhead power line



Photograph 2: South view of AEC 6 and septic field (right).



Photograph 3: AEC 6 Sample core of 6-BH15-29, showing coarse gravel and sand layers.



Photograph 4: Southwest view of AEC 6, looking towards MW05-6-9 and 6-BH15-30.



Photograph 5: AEC 6 drilling of location 6-BH15-35, adjacent to the Hangar building.



Photograph 6: Northeast view of AEC 6, looking towards 01TP06-1 and the Hangar building.



Photograph 7: Northwest view of AEC 7, showing current fence location and bollards.



Photograph 8: North view of AEC 7, showing access road, current fence location and bollards.



Photograph 9: Northwest overview of AEC 7.



Photograph 10: Northeast view of AEC 7.



Photograph 11: Curtain liner roll supplied by PWGSC/TC.



Photograph 12: Small to medium size liner perforations along LTF berm.



Photograph 13: Detailed view of LTF cell liner perforation.



Photograph 14: Northeast view of Land Treatment Facility #4



Photograph 15: Southwest view of Land Treatment Facility #4, showing central sump.



Photograph 16: View of Backfill Owner Supplied stockpile.