

Cape Spear Lightstation
Remediation/Risk Management
Cape Spear, NL

2016-08-20

<u>Section</u>	<u>Title</u>	<u>Pages</u>
01 10 10	GENERAL INSTRUCTIONS	12
01 33 00	SUBMITTAL PROCEDURES	5
01 35 24	SPECIAL PROCEDURES ON FIRE SAFETY REQUIREMENTS	5
01 35 29	HEALTH AND SAFETY REQUIREMENTS	12
01 35 43	ENVIRONMENTAL PROCEDURES	4
01 50 00	TEMPORARY FACILITIES	1
01 56 00	TEMPORARY BARRIERS AND ENCLOSURES	1
01 74 11	CLEANING	1
01 78 00	CLOSEOUT SUBMITTALS	1
02 41 16	SITWORK, DEMOLITION AND REMOVAL	2
02 83 12	LEAD PAINT MAXIMUM PRECAUTIONS	7
03 30 00	CONCRETE REPAIRS	3
06 10 00	ROUGH CARPENTRY	3
06 05 73	WOOD TREATMENT	2
07 46 23	WOOD SIDING	3
09 91 13	PAINTING	12
15 49 10	ENVIRONMENTAL REMEDIATION	2
31 23 25	ROCK FILL	1
32 11 23	GRANULAR BASE COURSES	5

Appendix A: Remediation/Risk Management Options, Dillon, March, 2016
Appendix B: Paint Sample Analysis
Appendix C: AMEC Leachate Report - July 2016