



[Back to home page](#)

## Report

### Tank System Information

#### Tank System Description

EC #:  
00019939  
Internal Number

Description:  
Fort Chipewyan RCMP Gasoline Tank

#### Contact Information

##### Owner

Royal Canadian Mounted Police  
73 Leikin Dr  
M1-4 Mailstop #18  
Ottawa  
Ontario  
K1A 0R2  
Tel: (613) 843-5516  
Fax: (613) 825-7518

##### Tank Operator

Royal Canadian Mounted Police  
73 Leikin Dr  
M1-4 Mailstop #18  
Ottawa  
Ontario  
K1A 0R2  
Tel: (613) 843-5516  
Fax: (613) 825-7518

##### Contact

Rod Savard  
11140-109 Street  
Edmonton  
Alberta  
Tel: (780) 670-8580

##### Contact

Rod Savard  
11140-109 Street  
Edmonton  
Alberta  
Tel: (780) 670-8580

##### Land Owner

Federal entity under Financial Administration Act

#### Months of service

January  
February  
March  
April

May  
June  
July  
August  
September  
October  
November  
December

### **System Location**

#### **Tank System Location**

117 Mellor Avenue  
Fort Chipewyan  
Alberta  
TOP 1B0

#### **System Record Location**

117 Mellor Avenue  
Fort Chipewyan  
Alberta  
TOP 1B0

#### **Emergency Plan Location**

117 Mellor Avenue  
Fort Chipewyan  
Alberta  
TOP 1B0  
Details:

### **Miscellaneous Information**

Tank Use:

Name of Tank Manufacturer:

Year of Manufacture:

Certification # of System Installer:

Certification # of System Remover:

## **Tank 1 of 1**

### **Tank Information**

Tank Description:  
15,000L Gasoline tank  
Tank Internal Number:

Type of Tank:  
Aboveground  
ULC or API Standard Number:  
ULC-S601  
Year of installation:  
2011  
Material of construction:  
Steel

Overfill Protection:

- None

Type of pump:

No pump

Spill Containment:

Spill box at fill point (aboveground tank)

Product Stored:

Gasoline

Tank Capacity:

15000 L

Transfer area:

Concrete dyke

Tank Leak Detection:

- Visual inspection

Corrosion Protection:

- Painted

Secondary Containment:

- Double Walled

### **Piping for tank 1**

Type of Piping:

Aboveground

Piping diameter:

1 inch

Piping Leak Detection:

- Visual inspection

Leak detection for sumps:

- No sump for storage tank system

Material of construction:

- Steel

Corrosion Protection:

- Painted

Secondary Containment:

- None