

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Site Name : PWGSC		Structure No : 600514			Structure name : GOCB-SASKATOON			
Asbestos Present : Yes		Vermiculite Present : No			Survey Date : 01/29/2003		Last Inspected : 01/06/2015	
Level : 1		Level Description : Floor - Ground Level				Asbestos Present : Potential		
Room : 01		Room Description : Front Lobby						
Ceiling	Acoustical Tile - 24" by 24"	0.00		T-N-A	A032			
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Concrete/Terrazo	0.00		C-N-A				
Floor	Tile - Quarry/Ceramic	0.00		C-N-A				
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Arborite	0.00		C-N-A				
Wall	Block	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Stone	0.00		C-N-A				
Level : 1		Level Description : Floor - Ground Level				Asbestos Present : Potential		
Room : 02		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 1		Level Description : Floor - Ground Level				Asbestos Present : Potential		
Room : 03		Room Description : Elevator Room						
Ceiling	Acoustical Tile - 24" by 24"	0.00		n/a	A033			
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Floor	Sheet flooring	0.00		n/a	V034			
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Level : 1		Level Description : Floor - Ground Level				Asbestos Present : Potential		
Room : 05		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 1		Level Description : Floor - Ground Level				Asbestos Present : Potential		
Room : 06		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 1		Level Description : Floor - Ground Level				Asbestos Present : Potential		
Room : 07		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 1	Level Description : Floor - Ground Level	Asbestos Present : Potential
Room : 08	Room Description : General Office	

Ceiling	Acoustical Tile - 24" by 48"	0.00	C-N-A
Ceiling	Cast in Place Concrete	0.00	C-N-A
Ceiling	Plaster - Base coat	0.00	C-N-A
Ceiling	Plaster - Top coat	0.00	C-N-A
Ductwork	Insulated	0.00	C-N-A
Ductwork	Metal - Bare	0.00	C-N-A
Floor	Carpet	0.00	C-N-A
Floor	Concrete	0.00	C-N-A
Pipe	Fittings Insulated - Fibreglass	0.00	C-N-A
Pipe	Straight Run-Fiberglass	0.00	C-N-A
Wall	Drywall	0.00	C-N-A
Wall	Plaster - Base coat	0.00	C-N-A
Wall	Plaster - Top coat	0.00	C-N-A
Wall	Vinyl covered drywall	0.00	C-N-A
Wall	Windows - Aluminum Frame	0.00	C-N-A
Wall	Windows - Wood	0.00	C-N-A

Level : 1	Level Description : Floor - Ground Level	Asbestos Present : Potential
Room : 09	Room Description : General Office	

Ceiling	Acoustical Tile - 24" by 48"	0.00	C-N-A
Ceiling	Cast in Place Concrete	0.00	C-N-A
Ceiling	Plaster - Base coat	0.00	C-N-A

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				

Level : 1	Level Description : Floor - Ground Level	Asbestos Present : Potential
Room : 10	Room Description : General Office	

Ceiling	Acoustical Tile - 24" by 48"	0.00	C-N-A
Ceiling	Cast in Place Concrete	0.00	C-N-A
Ceiling	Plaster - Base coat	0.00	C-N-A
Ceiling	Plaster - Top coat	0.00	C-N-A
Ductwork	Insulated	0.00	C-N-A
Ductwork	Metal - Bare	0.00	C-N-A
Floor	Carpet	0.00	C-N-A
Floor	Concrete	0.00	C-N-A
Pipe	Fittings Insulated - Fibreglass	0.00	C-N-A
Pipe	Straight Run-Fiberglass	0.00	C-N-A
Wall	Drywall	0.00	C-N-A
Wall	Plaster - Base coat	0.00	C-N-A
Wall	Plaster - Top coat	0.00	C-N-A
Wall	Vinyl covered drywall	0.00	C-N-A

Level : 1	Level Description : Floor - Ground Level	Asbestos Present : No
Room : 11	Room Description : Loading Dock	

Ceiling	Cast in Place Concrete	0.00	C-N-A
Ceiling	Plaster - Base coat	0.00	C-N-A

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ceiling	Plaster - Top coat	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Wall	Wood Finish	0.00		C-N-A				

Level : 1	Level Description : Floor - Ground Level	Asbestos Present : Potential
Room : 12	Room Description : General Office	

Ceiling	Acoustical Tile - 24" by 48"	0.00	C-N-A
Ceiling	Cast in Place Concrete	0.00	C-N-A
Ceiling	Plaster - Base coat	0.00	C-N-A
Ceiling	Plaster - Top coat	0.00	C-N-A
Ductwork	Insulated	0.00	C-N-A
Ductwork	Metal - Bare	0.00	C-N-A
Floor	Carpet	0.00	C-N-A
Floor	Concrete	0.00	C-N-A
Pipe	Fittings Insulated - Fibreglass	0.00	C-N-A
Pipe	Straight Run-Fiberglass	0.00	C-N-A
Wall	Drywall	0.00	C-N-A
Wall	Plaster - Base coat	0.00	C-N-A
Wall	Plaster - Top coat	0.00	C-N-A
Wall	Vinyl covered drywall	0.00	C-N-A
Wall	Windows - Aluminum Frame	0.00	C-N-A
Wall	Windows - Wood	0.00	C-N-A

Level : 1	Level Description : Floor - Ground Level	Asbestos Present : Potential
Room : 13	Room Description : General Office	

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 1		Level Description : Floor - Ground Level				Asbestos Present : Potential		
Room : 14		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Floor	Sheet flooring	0.00		T-N-A	A035			
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fiberglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 1		Level Description : Floor - Ground Level				Asbestos Present : Potential		
Room : 15		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 1		Level Description : Floor - Ground Level				Asbestos Present : Potential		
Room : 16		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Floor	Concrete	0.00		C-N-A				
Floor	Sheet flooring	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				

Level : 1		Level Description : Floor - Ground Level				Asbestos Present : Potential		
Room : 17		Room Description : Washroom						

Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Floor	Leveling Compound	0.00		T-N-A	A036			
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 1		Level Description : Floor - Ground Level				Asbestos Present : Potential		
Room : 18		Room Description : Washroom						

Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Floor	Leveling Compound	0.00		n/a	V036			
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 1		Level Description : Floor - Ground Level				Asbestos Present : Potential		
Room : 19		Room Description : Telephone/Data						

Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Floor	Concrete/Terrazo	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Wood Finish	0.00		C-N-A				

Level : 1		Level Description : Floor - Ground Level				Asbestos Present : Yes		
Room : 20		Room Description : Janitor Room						

Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Fittings Insulated	7.00	Units	REMOVED	V023	Chrysotile: 70%	A	7
Wall	Concrete	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				

Level : 1		Level Description : Floor - Ground Level				Asbestos Present : Potential		
Room : 21		Room Description : Stairwell						

Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ceiling	Plaster - Top coat	0.00		C-N-A				
Floor	Concrete/Terrazo	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		T-N-A	A005			
Wall	Stone	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 1		Level Description : Floor - Ground Level				Asbestos Present : Potential		
Room : 22		Room Description : Stairwell						
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Floor	Tile - Vinyl/Asbestos	0.00		C-N-A				
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		n/a	V005			

Level : 1		Level Description : Floor - Main				Asbestos Present : Potential		
Room : 04		Room Description : Elevator Room						
Ceiling	Acoustical Tile - 24" by 24"	0.00		n/a	V033			
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Floor	Sheet flooring	0.00		n/a	V034			
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				

Level : 2		Level Description : Floor - General				Asbestos Present : Potential		
Room : 01		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 2		Level Description : Floor - General				Asbestos Present : Potential		
Room : 02		Room Description : Telephone/Data						
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				
Wall	Wood Finish	0.00		C-N-A				

Level : 2		Level Description : Floor - General				Asbestos Present : Potential		
Room : 03		Room Description : Washroom						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ceiling	Plaster - Top coat	0.00		C-N-A				
Floor	Sheet flooring	0.00		P-A				
Pipe	Fittings Insulated	0.00		T-N-A	A011			
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Ceramic tile	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				

Level : 2		Level Description : Floor - General				Asbestos Present : Potential		
Room : 04		Room Description : General Office						

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 2		Level Description : Floor - General				Asbestos Present : Potential		
Room : 05		Room Description : Washroom						

Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Floor	Terazzo	0.00		C-N-A				
Wall	Ceramic tile	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				

Level : 2		Level Description : Floor - General				Asbestos Present : Potential		
Room : 06		Room Description : General Office						

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 2		Level Description : Floor - General				Asbestos Present : Potential		
Room : 07		Room Description : General Office						

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 2		Level Description : Floor - General				Asbestos Present : Potential		
Room : 08		Room Description : General Office						

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 2		Level Description : Floor - General				Asbestos Present : Potential		
Room : 09		Room Description : General Office						

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 2		Level Description : Floor - General				Asbestos Present : Potential		
Room : 10		Room Description : General Office						

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ductwork	Insulated	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 2	Level Description : Floor - General	Asbestos Present : Yes
Room : 11	Room Description : Service Shaft	
Comments : 3 fittings removed 2004.		

Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Fittings Insulated	1.00	Units	Good	A012	Chrysotile: 70%	D	7
Pipe	Insulated - Fibreglass	0.00		T-N-A	A13			
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				

Level : 2		Level Description : Floor - General				Asbestos Present : Potential		
Room : 12		Room Description : General Office						

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				

Level : 2		Level Description : Floor - General				Asbestos Present : Potential		
Room : 13		Room Description : General Office						

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 2		Level Description : Floor - General				Asbestos Present : Potential		
Room : 14		Room Description : General Office						

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 2		Level Description : Floor - General				Asbestos Present : Potential		
Room : 15		Room Description : General Office						

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
---------	------------------------------	------	--	-------	--	--	--	--

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 2		Level Description : Floor - General				Asbestos Present : Potential		
Room : 16		Room Description : Front Lobby						
Ceiling	Acoustical Tile - 24" by 24"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Floor	Terazzo	0.00		C-N-A				
Wall	Block	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				

Level : 2		Level Description : Floor - General				Asbestos Present : Potential		
Room : 17		Room Description : Elevator Room						
Ceiling	Acoustical Tile - 24" by 24"	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Floor	Leveling Compound	0.00		T-N-A	A014C			
Floor	Sheet flooring	0.00		T-N-A	A014A			
Floor	Tile - Vinyl/Asbestos	0.00		T-N-A	A014B			
Wall	Block	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Level : 2		Level Description : Floor - General				Asbestos Present : Potential		
Room : 18		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 2		Level Description : Floor - General				Asbestos Present : Potential		
Room : 19		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Wall	Windows - Wood	0.00		C-N-A				
Level : 2		Level Description : Floor - General				Asbestos Present : Potential		
Room : 20		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 2		Level Description : Floor - General				Asbestos Present : Potential		
Room : 21		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Level : 2		Level Description : Floor - General				Asbestos Present : Potential		
Room : 22		Room Description : Washroom						
Ceiling	Plaster - Top coat	0.00		C-N-A				
Floor	Terazzo	0.00		C-N-A				
Wall	Ceramic tile	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Level : 2		Level Description : Floor - General				Asbestos Present : Potential		
Room : 23		Room Description : Washroom						
Ceiling	Plaster - Top coat	0.00		C-N-A				
Floor	Terazzo	0.00		C-N-A				
Wall	Ceramic tile	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Level : 2		Level Description : Floor - General				Asbestos Present : Potential		
Room : 24		Room Description : Washroom						
Ceiling	Plaster - Top coat	0.00		C-N-A				
Floor	Terazzo	0.00		C-N-A				
Wall	Ceramic tile	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Level : 2		Level Description : Floor - General				Asbestos Present : Potential		
Room : 25		Room Description : Stairwell						
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Floor	Concrete/Terrazo	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		T-N-A	A005			
Wall	Stone	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Wall	Windows - Wood	0.00		C-N-A				
Level : 2		Level Description : Floor - General				Asbestos Present : Potential		
Room : 26		Room Description : Stairwell						
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Floor	Tile - Vinyl/Asbestos	0.00		C-N-A				
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		n/a	V005			
Level : 3		Level Description : Floor - General				Asbestos Present : Potential		
Room : 01		Room Description : Storage Room						
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Floor	Adhesive Compound	0.00		T-N-A	A015B			
Floor	Sheet flooring	0.00		T-N-A	A015A			
Wall	Brick	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Level : 3		Level Description : Floor - General				Asbestos Present : Potential		
Room : 02		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Tile - Quarry/Ceramic	0.00		C-N-A				
Floor	Tile - Vinyl/Asbestos	0.00		n/a	V016			
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 3		Level Description : Floor - General				Asbestos Present : Potential		
Room : 03		Room Description : General Office						

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Tile - Vinyl/Asbestos	0.00		n/a	V016			
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 3		Level Description : Floor - General				Asbestos Present : Potential		
Room : 04		Room Description : General Office						

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Tile - Vinyl/Asbestos	0.00		n/a	V016			
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 3		Level Description : Floor - General				Asbestos Present : Potential		
Room : 05		Room Description : General Office						

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Tile - Vinyl/Asbestos	0.00		n/a	V016			
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Level : 3		Level Description : Floor - General				Asbestos Present : Potential		
Room : 06		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Tile - Quarry/Ceramic	0.00		C-N-A				
Floor	Tile - Vinyl/Asbestos	0.00		n/a	V016			
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 3		Level Description : Floor - General				Asbestos Present : Potential		
Room : 07		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Tile - Vinyl/Asbestos	0.00		n/a	V016			
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Wall	Windows - Wood	0.00		C-N-A				
Level : 3		Level Description : Floor - General				Asbestos Present : Potential		
Room : 08		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Tile - Vinyl/Asbestos	0.00		T-N-A	A016			
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 3		Level Description : Floor - General				Asbestos Present : Potential		
Room : 09		Room Description : Front Lobby						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Acoustical Tile - Decorative	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Floor	Sheet flooring	0.00		n/a	V018			
Floor	Terazzo	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Wall	Windows - Wood	0.00		C-N-A				
Level : 3		Level Description : Floor - General				Asbestos Present : Potential		
Room : 10		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Tile - Vinyl/Asbestos	0.00		n/a	V016			
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 3		Level Description : Floor - General				Asbestos Present : Potential		
Room : 11		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Tile - Quarry/Ceramic	0.00		C-N-A				
Floor	Tile - Vinyl/Asbestos	0.00		n/a	V016			
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 3		Level Description : Floor - General				Asbestos Present : Potential		
Room : 12		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Tile - Vinyl/Asbestos	0.00		n/a	V016			
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 3		Level Description : Floor - General				Asbestos Present : Potential		
Room : 13		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Tile - Vinyl/Asbestos	0.00		n/a	V016			
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 3		Level Description : Floor - General				Asbestos Present : Potential		
Room : 14		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Level : 3		Level Description : Floor - General				Asbestos Present : Potential		
Room : 15		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Wall	Windows - Wood	0.00		C-N-A				
Level : 3		Level Description : Floor - General				Asbestos Present : Potential		
Room : 16		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 3		Level Description : Floor - General				Asbestos Present : Potential		
Room : 17		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 3		Level Description : Floor - General				Asbestos Present : Potential		
Room : 18		Room Description : Kitchen						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Level : 3		Level Description : Floor - General				Asbestos Present : Potential		
Room : 19		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 3		Level Description : Floor - General				Asbestos Present : Potential		
Room : 20		Room Description : Washroom						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Sheet flooring	0.00		P-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Ceramic tile	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				

Level : 3	Level Description : Floor - General	Asbestos Present : REMOVED
Room : 21	Room Description : Janitor Room	

Ceiling	Cast in Place Concrete	0.00		C-N-A		
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A		
Ductwork	Metal - Bare	0.00		C-N-A		
Floor	Concrete	0.00		C-N-A		
Pipe	Fittings Insulated	0.00		REMOVED	V023	
Wall	Block	0.00		C-N-A		
Wall	Brick	0.00		C-N-A		
Wall	Plaster - Base coat	0.00		C-N-A		
Wall	Plaster - Top coat	0.00		C-N-A		
Wall	Windows - Aluminum Frame	0.00		C-N-A		
Wall	Windows - Wood	0.00		C-N-A		

Level : 3	Level Description : Floor - General	Asbestos Present : Potential
Room : 22	Room Description : Electrical Room	

Ceiling	Adhesive	0.00		C-N-A		
Ceiling	Cast in Place Concrete	0.00		C-N-A		
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A		
Floor	Concrete	0.00		C-N-A		
Wall	Plaster - Base coat	0.00		C-N-A		

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Wood Finish	0.00		C-N-A				
Level : 3		Level Description : Floor - General				Asbestos Present : Potential		
Room : 23		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Floor	Tile - Quarry/Ceramic	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 3		Level Description : Floor - General				Asbestos Present : Potential		
Room : 24		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 3		Level Description : Floor - General				Asbestos Present : Potential		
Room : 25		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 3		Level Description : Floor - General				Asbestos Present : Potential		
Room : 26		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Wall	Windows - Wood	0.00		C-N-A				
Level : 3		Level Description : Floor - General				Asbestos Present : Potential		
Room : 27		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 3		Level Description : Floor - General				Asbestos Present : Potential		
Room : 28		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Level : 3		Level Description : Floor - General					Asbestos Present : Potential	
Room : 29		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 3		Level Description : Floor - General					Asbestos Present : Potential	
Room : 30		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 3		Level Description : Floor - General					Asbestos Present : Potential	
Room : 31		Room Description : General Office						

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 3	Level Description : Floor - General	Asbestos Present : Potential
Room : 32	Room Description : General Office	

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 3	Level Description : Floor - General	Asbestos Present : Potential
Room : 33	Room Description : General Office	

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
---------	------------------------------	------	--	-------	--	--	--	--

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 3		Level Description : Floor - General		Asbestos Present : Potential	
Room : 34		Room Description : General Office			
Ceiling	Acoustical Tile - 24" by 48"	0.00	C-N-A		
Ceiling	Fiberglass wrapped pipes	0.00	C-N-A		
Ceiling	Firestop sealant	0.00	C-N-A		
Ceiling	Plaster - Base coat	0.00	C-N-A		
Ceiling	Plaster - Top coat	0.00	C-N-A		
Ductwork	Metal - Bare	0.00	C-N-A		
Floor	Carpet	0.00	C-N-A		
Floor	Concrete	0.00	C-N-A		
Wall	Plaster - Base coat	0.00	C-N-A		
Wall	Plaster - Top coat	0.00	C-N-A		
Wall	Vinyl covered drywall	0.00	C-N-A		
Wall	Windows - Aluminum Frame	0.00	C-N-A		
Wall	Windows - Wood	0.00	C-N-A		

Level : 3		Level Description : Floor - General		Asbestos Present : Potential
Room : 35		Room Description : General Office		
Ceiling	Acoustical Tile - 24" by 48"	0.00	C-N-A	
Ceiling	Fiberglass wrapped pipes	0.00	C-N-A	

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 3		Level Description : Floor - General				Asbestos Present : Potential		
Room : 36		Room Description : Kitchen						

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Tile - Vinyl/Asbestos	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				

Level : 3		Level Description : Floor - General				Asbestos Present : REMOVED		
Room : 37		Room Description : Mechanical Room						

Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Duct Sealant	0.00		REMOVED	V019			
Floor	Terazzo	0.00		C-N-A				
Pipe	Fittings Insulated	0.00		n/a	V020			
Wall	Block	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Wall	Plaster - Top coat	0.00		C-N-A				
Level : 3		Level Description : Floor - General				Asbestos Present : Potential		
Room : 38		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Floor	Terazzo	0.00		C-N-A				
Floor	Tile - Quarry/Ceramic	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 3		Level Description : Floor - General				Asbestos Present : Potential		
Room : 39		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Floor	Terazzo	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 3		Level Description : Floor - General				Asbestos Present : Potential		
Room : 40		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Floor	Terazzo	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 3		Level Description : Floor - General				Asbestos Present : Potential		
Room : 41		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Floor	Sheet flooring	0.00		P-A				
Floor	Terazzo	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 3		Level Description : Floor - General				Asbestos Present : Potential		
Room : 42		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Floor	Terazzo	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 3		Level Description : Floor - General				Asbestos Present : Potential		
Room : 43		Room Description : Washroom						
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Terazzo	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Ceramic tile	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 3		Level Description : Floor - General				Asbestos Present : Potential		
Room : 44		Room Description : Stairwell						
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Floor	Concrete/Terrazo	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		T-N-A	A005			
Wall	Stone	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 3		Level Description : Floor - General				Asbestos Present : Potential		
Room : 45		Room Description : Stairwell						
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Floor	Tile - Vinyl/Asbestos	0.00		C-N-A				
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Wall	Plaster - Top coat	0.00		n/a	V005			
Level : 4		Level Description : Floor - General				Asbestos Present : Potential		
Room : 01		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Floor	Tile - Quarry/Ceramic	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 4		Level Description : Floor - General				Asbestos Present : Potential		
Room : 02		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 4		Level Description : Floor - General				Asbestos Present : Potential		
Room : 03		Room Description : General Office						

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 4		Level Description : Floor - General				Asbestos Present : Potential		
Room : 04		Room Description : General Office						

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 4		Level Description : Floor - General				Asbestos Present : Potential		
Room : 05		Room Description : General Office						

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 4		Level Description : Floor - General				Asbestos Present : Potential		
Room : 06		Room Description : General Office						

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ductwork	Insulated	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Floor	Tile - Quarry/Ceramic	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 4	Level Description : Floor - General	Asbestos Present : Potential
Room : 07	Room Description : General Office	

Ceiling	Acoustical Tile - 24" by 48"	0.00	C-N-A
Ceiling	Fiberglass wrapped pipes	0.00	C-N-A
Ceiling	Plaster - Base coat	0.00	C-N-A
Ceiling	Plaster - Top coat	0.00	C-N-A
Ductwork	Insulated	0.00	C-N-A
Ductwork	Metal - Bare	0.00	C-N-A
Floor	Carpet	0.00	C-N-A
Floor	Concrete	0.00	C-N-A
Pipe	Straight Run-Fiberglass	0.00	C-N-A
Wall	Plaster - Base coat	0.00	C-N-A
Wall	Plaster - Top coat	0.00	C-N-A
Wall	Vinyl covered drywall	0.00	C-N-A
Wall	Windows - Aluminum Frame	0.00	C-N-A
Wall	Windows - Wood	0.00	C-N-A

Level : 4	Level Description : Floor - General	Asbestos Present : Potential
Room : 08	Room Description : General Office	

Ceiling	Acoustical Tile - 24" by 48"	0.00	C-N-A
Ceiling	Fiberglass wrapped pipes	0.00	C-N-A

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 4		Level Description : Floor - General				Asbestos Present : Potential		
Room : 09		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 4		Level Description : Floor - General				Asbestos Present : Potential		
Room : 10		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 4		Level Description : Floor - General				Asbestos Present : Potential		
Room : 11		Room Description : General Office						

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 4		Level Description : Floor - General				Asbestos Present : Potential		
Room : 12		Room Description : General Office						

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 4		Level Description : Floor - General				Asbestos Present : Potential		
Room : 13		Room Description : General Office						

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Level : 4		Level Description : Floor - General					Asbestos Present : Potential	
Room : 14		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 4		Level Description : Floor - General					Asbestos Present : Potential	
Room : 15		Room Description : Kitchen						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Floor	Sheet flooring	0.00		n/a	V008			
Floor	Tile - Vinyl/Asbestos	0.00		T-N-A	A017			
Wall	Drywall	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Level : 4		Level Description : Floor - General					Asbestos Present : Potential	
Room : 16		Room Description : Kitchen						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Floor	Sheet flooring	0.00		n/a	V008			
Floor	Tile - Vinyl/Asbestos	0.00		n/a	V017			
Wall	Drywall	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Level : 4		Level Description : Floor - General					Asbestos Present : Potential	
Room : 17		Room Description : Kitchen						

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Floor	Sheet flooring	0.00		P-A	V008			
Floor	Tile - Vinyl/Asbestos	0.00		n/a	V017			
Wall	Drywall	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				

Level : 4		Level Description : Floor - General				Asbestos Present : Potential		
Room : 18		Room Description : Front Lobby						

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Acoustical Tile - Decorative	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Sheet flooring	0.00		T-N-A	A018			
Floor	Terazzo	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 4		Level Description : Floor - General				Asbestos Present : Potential		
Room : 19		Room Description : General Office						

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 4		Level Description : Floor - General				Asbestos Present : Potential		
Room : 20		Room Description : Washroom						
Ceiling	Accoustical Spray-on	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Terazzo	0.00		C-N-A				
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Ceramic tile	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Level : 4		Level Description : Floor - General				Asbestos Present : REMOVED		
Room : 21		Room Description : Mechanical Room						
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		REMOVED	A019			
Floor	Terazzo	0.00		C-N-A				
Pipe	Fittings Insulated	0.00		T-N-A	A020			
Wall	Block	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Level : 4		Level Description : Floor - General				Asbestos Present : Potential		
Room : 22		Room Description : General Office						
Std. Comments : No access into room								

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Room	Not accessible	0.00						
Level : 4		Level Description : Floor - General				Asbestos Present : Potential		
Room : 23		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Floor	Leveling Compound	0.00		T-N-A	A021			
Floor	Tile - Vinyl/Asbestos	0.00		n/a	V016			
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 4		Level Description : Floor - General				Asbestos Present : Potential		
Room : 24		Room Description : General Office						
Std. Comments : No access into room								
Room	Not accessible	0.00						
Level : 4		Level Description : Floor - General				Asbestos Present : Potential		
Room : 25		Room Description : Telephone/Data						
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ceiling	Plaster - Top coat	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Wood Finish	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Level : 4		Level Description : Floor - General					Asbestos Present : REMOVED	
Room : 26		Room Description : Janitor Room						
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Fittings Insulated	0.00		REMOVED	V023			
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Level : 4		Level Description : Floor - General					Asbestos Present : Potential	
Room : 27		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Acoustical Tile - Decorative	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 4		Level Description : Floor - General					Asbestos Present : Potential	
Room : 28		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Acoustical Tile - Decorative	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ductwork	Insulated	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 4		Level Description : Floor - General				Asbestos Present : Potential		
Room : 29		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Acoustical Tile - Decorative	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 4		Level Description : Floor - General				Asbestos Present : Potential		
Room : 30		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Acoustical Tile - Decorative	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 4	Level Description : Floor - General	Asbestos Present : Potential
Room : 31	Room Description : General Office	

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Acoustical Tile - Decorative	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 4	Level Description : Floor - General	Asbestos Present : Potential
Room : 32	Room Description : General Office	

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Acoustical Tile - Decorative	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 4	Level Description : Floor - General	Asbestos Present : Potential
Room : 33	Room Description : General Office	

Ceiling	Acoustical Tile - 24" by 48"	0.00	C-N-A
Ceiling	Acoustical Tile - Decorative	0.00	C-N-A
Ceiling	Fiberglass wrapped pipes	0.00	C-N-A
Ceiling	Plaster - Base coat	0.00	C-N-A
Ceiling	Plaster - Top coat	0.00	C-N-A
Ductwork	Insulated	0.00	C-N-A
Ductwork	Metal - Bare	0.00	C-N-A
Floor	Carpet	0.00	C-N-A
Floor	Concrete	0.00	C-N-A
Pipe	Fittings Insulated - Fibreglass	0.00	C-N-A
Pipe	Insulated - Fibreglass	0.00	C-N-A
Pipe	Straight Run-Fiberglass	0.00	C-N-A
Wall	Block	0.00	C-N-A
Wall	Drywall	0.00	C-N-A
Wall	Plaster - Base coat	0.00	C-N-A
Wall	Plaster - Top coat	0.00	C-N-A

Level : 4	Level Description : Floor - General	Asbestos Present : Potential
Room : 34	Room Description : General Office	

Ceiling	Acoustical Tile - 24" by 48"	0.00	C-N-A
Ceiling	Acoustical Tile - Decorative	0.00	C-N-A
Ceiling	Fiberglass wrapped pipes	0.00	C-N-A

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Block	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				

Level : 4		Level Description : Floor - General				Asbestos Present : Potential		
Room : 35		Room Description : Washroom						

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Floor	Sheet flooring	0.00		n/a	V035			
Floor	Terazzo	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Ceramic tile	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				

Level : 4		Level Description : Floor - General				Asbestos Present : Potential		
Room : 36		Room Description : Stairwell						

Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Floor	Concrete/Terrazo	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Wall	Plaster - Top coat	0.00		T-N-A	A005			
Wall	Stone	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 4		Level Description : Floor - General				Asbestos Present : Potential		
Room : 37		Room Description : Stairwell						
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Floor	Tile - Vinyl/Asbestos	0.00		C-N-A				
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		n/a	V005			
Level : 5		Level Description : Floor - General				Asbestos Present : Potential		
Room : 01		Room Description : Mechanical Room						
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Terazzo	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Level : 5		Level Description : Floor - General				Asbestos Present : Potential		
Room : 02		Room Description : Front Lobby						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Acoustical Tile - Decorative	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Tile - Quarry/Ceramic	0.00		C-N-A				
Pipe	Fittings Insulated	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Level : 5		Level Description : Floor - General				Asbestos Present : Potential		
Room : 03		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		P-A	V1			
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 5		Level Description : Floor - General				Asbestos Present : Potential		
Room : 04		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		P-A	V1			
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 5	Level Description : Floor - General	Asbestos Present : Potential
Room : 05	Room Description : General Office	

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		P-A	V1			
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 5	Level Description : Floor - General	Asbestos Present : Potential
Room : 06	Room Description : General Office	

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 5		Level Description : Floor - General				Asbestos Present : Potential		
Room : 07		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Level : 5		Level Description : Floor - General				Asbestos Present : Potential		
Room : 08		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 5		Level Description : Floor - General				Asbestos Present : Potential		
Room : 09		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Level : 5		Level Description : Floor - General				Asbestos Present : Potential		
Room : 10		Room Description : General Office						

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				

Level : 5		Level Description : Floor - General		Asbestos Present : Potential	
Room : 11		Room Description : General Office			
Ceiling	Acoustical Tile - 24" by 48"	0.00	C-N-A		
Ceiling	Cast in Place Concrete	0.00	C-N-A		
Ceiling	Firestop sealant	0.00	n/a	V001	
Ceiling	Plaster - Base coat	0.00	C-N-A		
Ceiling	Plaster - Top coat	0.00	C-N-A		
Ductwork	Metal - Bare	0.00	C-N-A		
Floor	Carpet	0.00	C-N-A		
Floor	Concrete	0.00	C-N-A		
Wall	Brick	0.00	C-N-A		
Wall	Plaster - Base coat	0.00	C-N-A		
Wall	Plaster - Top coat	0.00	C-N-A		
Wall	Vinyl covered drywall	0.00	C-N-A		
Wall	Windows - Aluminum Frame	0.00	C-N-A		
Wall	Windows - Wood	0.00	C-N-A		

Level : 5		Level Description : Floor - General		Asbestos Present : Potential	
Room : 12		Room Description : General Office			
Ceiling	Acoustical Tile - 24" by 48"	0.00	C-N-A		

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 5		Level Description : Floor - General				Asbestos Present : Potential		
Room : 13		Room Description : General Office						

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Acoustical Tile - Decorative	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				

Level : 5		Level Description : Floor - General				Asbestos Present : Potential		
Room : 14		Room Description : General Office						

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 5	Level Description : Floor - General	Asbestos Present : Potential
Room : 15	Room Description : General Office	

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				

Level : 5	Level Description : Floor - General	Asbestos Present : Potential
Room : 16	Room Description : General Office	

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
---------	------------------------------	------	--	-------	--	--	--	--

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				

Level : 5	Level Description : Floor - General	Asbestos Present : Potential
Room : 17	Room Description : General Office	

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 5	Level Description : Floor - General	Asbestos Present : Potential
Room : 18	Room Description : General Office	

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ceiling	Firestop sealant	0.00		n/a	V001			
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 5		Level Description : Floor - General		Asbestos Present : Potential	
Room : 19		Room Description : General Office			
Ceiling	Acoustical Tile - 24" by 48"	0.00	C-N-A	V001	
Ceiling	Cast in Place Concrete	0.00	C-N-A		
Ceiling	Firestop sealant	0.00	n/a		
Ceiling	Plaster - Base coat	0.00	C-N-A		
Ceiling	Plaster - Top coat	0.00	C-N-A		
Ductwork	Metal - Bare	0.00	C-N-A		
Floor	Carpet	0.00	C-N-A		
Floor	Concrete	0.00	C-N-A		
Wall	Brick	0.00	C-N-A		
Wall	Plaster - Base coat	0.00	C-N-A		
Wall	Plaster - Top coat	0.00	C-N-A		
Wall	Vinyl covered drywall	0.00	C-N-A		
Wall	Windows - Aluminum Frame	0.00	C-N-A		
Wall	Windows - Wood	0.00	C-N-A		

Level : 5		Level Description : Floor - General		Asbestos Present : Potential	
Room : 20		Room Description : General Office			
Ceiling	Acoustical Tile - 24" by 48"	0.00	C-N-A		

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 5	Level Description : Floor - General	Asbestos Present : Potential
Room : 21	Room Description : General Office	

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 5	Level Description : Floor - General	Asbestos Present : Potential
Room : 22	Room Description : Kitchen	

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Floor	Sheet flooring	0.00		n/a	V008			
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 5	Level Description : Floor - General	Asbestos Present : Potential
Room : 23	Room Description : Washroom	

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Floor	Sheet flooring	0.00		n/a	V008			
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Wall	Plaster - Top coat	0.00		C-N-A				
Level : 5		Level Description : Floor - General				Asbestos Present : Yes		
Room : 24		Room Description : Janitor Room						
Comments : A023 resampled by Ryan Hales, Environmental Coordinator February 2010. Results indicate that there are still ACM containing materials in this room. ACM piping is still present.								
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Fittings Insulated	7.00		Good	A023	Chrysotile: 50%	B	7
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Level : 5		Level Description : Floor - General				Asbestos Present : Potential		
Room : 25		Room Description : Telephone/Data						
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Wood Finish	0.00		C-N-A				
Level : 5		Level Description : Floor - General				Asbestos Present : Potential		
Room : 26		Room Description : Electrical Room						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Floor	Sheet flooring	0.00		n/a	V008			

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Wall	Brick	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				

Level : 5		Level Description : Floor - General				Asbestos Present : Potential		
Room : 27		Room Description : General Office						

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 5		Level Description : Floor - General				Asbestos Present : Potential		
Room : 28		Room Description : General Office						

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Floor	Concrete	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				

Level : 5		Level Description : Floor - General				Asbestos Present : Potential		
Room : 29		Room Description : General Office						

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 5		Level Description : Floor - General				Asbestos Present : Potential		
Room : 30		Room Description : General Office						

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Wall	Brick	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 5		Level Description : Floor - General				Asbestos Present : Potential		
Room : 31		Room Description : General Office						

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 5		Level Description : Floor - General				Asbestos Present : Potential		
Room : 32		Room Description : General Office						

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Floor	Concrete	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 5		Level Description : Floor - General				Asbestos Present : Potential		
Room : 33		Room Description : Elevator Room						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Floor	Sheet flooring	0.00		n/a	V008			
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Level : 5		Level Description : Floor - General				Asbestos Present : Potential		
Room : 34		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		P-A	V1			
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 5		Level Description : Floor - General				Asbestos Present : Potential		
Room : 35		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 5		Level Description : Floor - General				Asbestos Present : Potential		
Room : 36		Room Description : Stairwell						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Floor	Sheet flooring	0.00		n/a	V008			
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Level : 5		Level Description : Floor - General				Asbestos Present : Potential		
Room : 37		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A	V001			
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 5		Level Description : Floor - General				Asbestos Present : Potential		
Room : 38		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A	V001			
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action	
Level : 5		Level Description : Floor - General				Asbestos Present : Potential			
Room : 39		Room Description : Washroom							
Ceiling	Cast in Place Concrete	0.00		C-N-A	V001				
Ceiling	Firestop sealant	0.00		n/a					
Floor	Terazzo	0.00		C-N-A					
Pipe	Insulated - Fibreglass	0.00		C-N-A					
Wall	Brick	0.00		C-N-A					
Wall	Ceramic tile	0.00		C-N-A					
Wall	Drywall	0.00		C-N-A					
Wall	Plaster - Base coat	0.00		C-N-A					
Wall	Plaster - Top coat	0.00		C-N-A					
Wall	Windows - Aluminum Frame	0.00		C-N-A					
Wall	Windows - Wood	0.00		C-N-A					
Level : 5		Level Description : Floor - General				Asbestos Present : Potential			
Room : 40		Room Description : Stairwell							
Ceiling	Cast in Place Concrete	0.00		C-N-A	A005				
Ceiling	Plaster - Base coat	0.00		C-N-A					
Ceiling	Plaster - Top coat	0.00		C-N-A					
Floor	Concrete/Terrazo	0.00		C-N-A					
Wall	Drywall	0.00		C-N-A					
Wall	Plaster - Base coat	0.00		C-N-A					
Wall	Plaster - Top coat	0.00		T-N-A					
Wall	Stone	0.00		C-N-A					
Wall	Windows - Aluminum Frame	0.00		C-N-A					
Wall	Windows - Wood	0.00		C-N-A					
Level : 5		Level Description : Floor - General				Asbestos Present : Potential			
Room : 41		Room Description : Stairwell							
Ceiling	Cast in Place Concrete	0.00		C-N-A					
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A					
Ceiling	Firestop sealant	0.00		C-N-A					
Ceiling	Plaster - Base coat	0.00		C-N-A					
Ceiling	Plaster - Top coat	0.00		C-N-A					

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Floor	Tile - Vinyl/Asbestos	0.00		C-N-A				
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fibreglass	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		n/a	V005			

Level : 6		Level Description : Floor - General				Asbestos Present : Potential		
Room : 01		Room Description : General Office						

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 6		Level Description : Floor - General				Asbestos Present : Potential		
Room : 02		Room Description : General Office						

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Floor	Terazzo	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Ceramic tile	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Drywall	0.00		T-N-A	A006			
Wall	Plaster - Top coat	0.00		C-N-A				

Level : 6		Level Description : Floor - General				Asbestos Present : Potential		
Room : 03		Room Description : General Office						

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 6		Level Description : Floor - General				Asbestos Present : Potential		
Room : 04		Room Description : General Office						

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 6		Level Description : Floor - General				Asbestos Present : Potential		
Room : 05		Room Description : General Office						

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 6		Level Description : Floor - General				Asbestos Present : Potential		
Room : 06		Room Description : General Office						

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 6		Level Description : Floor - General				Asbestos Present : Potential		
Room : 07		Room Description : General Office						

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Drywall Filler Compound	0.00		T-N-A	A007			
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 6		Level Description : Floor - General				Asbestos Present : Potential		
Room : 08		Room Description : General Office						

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 6		Level Description : Floor - General				Asbestos Present : Potential		
Room : 09		Room Description : General Office						

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 6		Level Description : Floor - General				Asbestos Present : Potential		
Room : 10		Room Description : General Office						

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ceiling	Firestop sealant	0.00		n/a	V001			
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 6		Level Description : Floor - General				Asbestos Present : Potential		
Room : 11		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 6		Level Description : Floor - General				Asbestos Present : Potential		
Room : 12		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 6	Level Description : Floor - General	Asbestos Present : Potential
Room : 13	Room Description : General Office	

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 6	Level Description : Floor - General	Asbestos Present : Potential
Room : 14	Room Description : General Office	

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : 6		Level Description : Floor - General				Asbestos Present : Potential		
Room : 15		Room Description : General Office						

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Level : 6		Level Description : Floor - General				Asbestos Present : Potential		
Room : 16		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 6		Level Description : Floor - General				Asbestos Present : Potential		
Room : 17		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action	
Level : 6		Level Description : Floor - General				Asbestos Present : Potential			
Room : 18		Room Description : General Office							
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A	V001				
Ceiling	Cast in Place Concrete	0.00		C-N-A					
Ceiling	Firestop sealant	0.00		n/a					
Ductwork	Metal - Bare	0.00		C-N-A					
Floor	Carpet	0.00		C-N-A					
Floor	Concrete	0.00		C-N-A					
Pipe	Insulated - Fibreglass	0.00		C-N-A					
Wall	Brick	0.00		C-N-A					
Wall	Drywall	0.00		C-N-A					
Wall	Plaster - Base coat	0.00		C-N-A					
Wall	Plaster - Top coat	0.00		C-N-A					
Wall	Vinyl covered drywall	0.00		C-N-A					
Wall	Windows - Aluminum Frame	0.00		C-N-A					
Wall	Windows - Wood	0.00		C-N-A					
Level : 6		Level Description : Floor - General				Asbestos Present : Potential			
Room : 19		Room Description : General Office							
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A	V001				
Ceiling	Cast in Place Concrete	0.00		C-N-A					
Ceiling	Firestop sealant	0.00		n/a					
Ductwork	Metal - Bare	0.00		C-N-A					
Floor	Carpet	0.00		C-N-A					
Floor	Concrete	0.00		C-N-A					
Pipe	Insulated - Fibreglass	0.00		C-N-A					
Wall	Brick	0.00		C-N-A					
Wall	Drywall	0.00		C-N-A					
Wall	Plaster - Base coat	0.00		C-N-A					
Wall	Plaster - Top coat	0.00		C-N-A					
Wall	Vinyl covered drywall	0.00		C-N-A					
Level : 6		Level Description : Floor - General				Asbestos Present : Potential			
Room : 20		Room Description : General Office							

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 6		Level Description : Floor - General				Asbestos Present : Potential		
Room : 21		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Drywall Filler Compound	0.00		T-N-A	A007			
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Level : 6		Level Description : Floor - General				Asbestos Present : Potential		
Room : 22		Room Description : General Office						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 6		Level Description : Floor - General				Asbestos Present : Potential		
Room : 23		Room Description : Elevator Room						
Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Floor	Sheet flooring	0.00		T-N-A	A008			
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 6		Level Description : Floor - General				Asbestos Present : No		
Room : 24		Room Description : Service Shaft						
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				
Level : 6		Level Description : Floor - General				Asbestos Present : Potential		
Room : 25		Room Description : Telephone/Data						

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ceiling	Firestop sealant	0.00		n/a	V001			
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Fittings Insulated	0.00		T-N-A	A009			
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Wood Finish	0.00		C-N-A				

Level : 6		Level Description : Floor - General				Asbestos Present : Potential		
Room : 26		Room Description : Janitor Room						

Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Fittings Insulated	0.00		n/a	V009			
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				

Level : 6		Level Description : Floor - General				Asbestos Present : Potential		
Room : 27		Room Description : Washroom						

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		n/a	V001			
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Sheet flooring	0.00		P-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Ceramic tile	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				

Level : 6		Level Description : Floor - General				Asbestos Present : Potential		
Room : 28		Room Description : Front Lobby						

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Floor	Terazzo	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Pipe	Fittings Insulated	0.00		n/a	V009			
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Level : 6		Level Description : Floor - General				Asbestos Present : REMOVED		
Room : 29		Room Description : Mechanical Room						
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		REMOVED	A010			
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Terazzo	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Level : 6		Level Description : Floor - General				Asbestos Present : Potential		
Room : 30		Room Description : Stairwell						
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Floor	Concrete/Terrazo	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		T-N-A	A005			
Wall	Stone	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 6		Level Description : Floor - General				Asbestos Present : Potential		
Room : 31		Room Description : Stairwell						
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Floor	Tile - Vinyl/Asbestos	0.00		C-N-A				
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		n/a	V005			
Level : 7		Level Description : Roof - Main				Asbestos Present : No		
Room : 01		Room Description : Boiler Room						
Ceiling	Metal - Decorative	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Siding - Metal	0.00		C-N-A				
Level : 7		Level Description : Roof - Main				Asbestos Present : Potential		
Room : 02		Room Description : Front Lobby						
Ceiling	Firestop sealant	0.00		T-N-A	A001			
Floor	Sheet flooring	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Level : 7		Level Description : Roof - Main				Asbestos Present : REMOVED		
Room : 03		Room Description : Elevator Shaft						
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Floor	Sheet flooring	0.00		C-N-A				
Mechanical	Elevator Brake Shoes	0.00		REMOVED	V002			
Wall	Concrete	0.00		C-N-A				
Level : 7		Level Description : Roof - Main				Asbestos Present : REMOVED		
Room : 04		Room Description : Mechanical Room						
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		REMOVED	A004			
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Level : 7		Level Description : Roof - Main				Asbestos Present : Potential		
Room : 05		Room Description : Stairwell						
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Floor	Concrete/Terrazo	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		T-N-A	A005			
Wall	Stone	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 7		Level Description : Roof - Main				Asbestos Present : Potential		
Room : 06		Room Description : Stairwell						
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Floor	Tile - Vinyl/Asbestos	0.00		C-N-A				
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		n/a	V005			

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Level : 7		Level Description : Roof - Penthouse					Asbestos Present : Potential	
Room :		Room Description :						
Roof	Built Up Roof Membrane	0.00		C-N-A				
Level : 8		Level Description : Roof - Upper					Asbestos Present : REMOVED	
Room : 01		Room Description : Mechanical Room						
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Floor	Leveling Compound	0.00		P-A				
Mechanical	Elevator Brake Shoes	0.00		REMOVED	A002			
Mechanical	Elevator Brake Shoes	0.00		T-N-A	A003			
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Level : 8		Level Description : Roof - Upper					Asbestos Present : Potential	
Room : 02		Room Description : Telephone/Data						
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Floor	Leveling Compound	0.00		P-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		P-A				
Level : 8		Level Description : Roof - Upper					Asbestos Present : Potential	
Room : 03		Room Description : Stairwell						
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Floor	Concrete/Terrazo	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		T-N-A	A005			
Wall	Stone	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : B		Level Description : Basement				Asbestos Present : REMOVED		
Room : 01		Room Description : General Office						

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Floor	Sheet flooring	0.00		P-A				
Pipe	Fittings Insulated	0.00		P-A				
Pipe	Straight Run Insulated	0.00		REMOVED	A025			
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				

Level : B		Level Description : Basement				Asbestos Present : REMOVED		
Room : 02		Room Description : Kitchen						

Ceiling	Acoustical Tile - 24" by 48"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Floor	Sheet flooring	0.00		P-A				
Pipe	Fittings Insulated	0.00		C-N-A				
Pipe	Straight Run Insulated	0.00		REMOVED	A024			
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Level : B		Level Description : Basement				Asbestos Present : Potential		
Room : 03		Room Description : Washroom						
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Floor	Tile - Quarry/Ceramic	0.00		C-N-A				
Pipe	Fittings Insulated	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Ceramic tile	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Level : B		Level Description : Basement				Asbestos Present : Potential		
Room : 04		Room Description : Locker Room						
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Level : B		Level Description : Basement				Asbestos Present : Potential		
Room : 05		Room Description : Storage Room						
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Floor	Terazzo	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Block	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Level : B		Level Description : Basement				Asbestos Present : REMOVED		
Room : 06		Room Description : Hallway						
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Floor	Sheet flooring	0.00		P-A				
Floor	Sheet flooring	0.00		T-N-A	A029			
Pipe	Fittings Insulated	0.00		REMOVED	A026			
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run Insulated	0.00		T-N-A	A027			
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Level : B		Level Description : Basement				Asbestos Present : REMOVED		
Room : 07		Room Description : Service Shaft						
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Floor	Tile - Vinyl/Asbestos	0.00		REMOVED	A028			
Pipe	Fittings Insulated	0.00		REMOVED	V026			
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run Insulated	0.00		n/a	V027			
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Level : B		Level Description : Basement				Asbestos Present : Potential		
Room : 08		Room Description : Maintenance Shop						
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Floor	Concrete	0.00		C-N-A				
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				

Level : B		Level Description : Basement				Asbestos Present : Potential		
Room : 09		Room Description : Maintenance Shop						

Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				

Level : B		Level Description : Basement				Asbestos Present : Potential		
Room : 10		Room Description : Maintenance Shop						

Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				

Level : B		Level Description : Basement				Asbestos Present : Potential		
Room : 11		Room Description : General Office						

Ceiling	Acoustical Tile - 24" by 24"	0.00		C-N-A				
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Carpet	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Floor	Concrete	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Level : B		Level Description : Basement				Asbestos Present : Potential		
Room : 12		Room Description : Boiler Room						
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Siding - Wood	0.00		C-N-A				
Level : B		Level Description : Basement				Asbestos Present : Potential		
Room : 13		Room Description : Storage Room						
Ceiling	Metal - Decorative	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				
Level : B		Level Description : Basement				Asbestos Present : Potential		
Room : 14		Room Description : Storage Room						
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Wood Finish	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Level : B		Level Description : Basement				Asbestos Present : Potential		
Room : 15		Room Description : Electrical Room						
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Insulated	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				
Wall	Drywall	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Level : B		Level Description : Basement				Asbestos Present : REMOVED		
Room : 16		Room Description : Mechanical Room						
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Mechanical	Boiler Gasket	0.00		P-A				
Pipe	Fittings Insulated	0.00		REMOVED	A031			
Pipe	Straight Run Insulated	0.00		REMOVED	A030			
Wall	Brick	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Level : B		Level Description : Basement				Asbestos Present : Potential		
Room : 17A		Room Description : Storage Room						
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Floor	Concrete	0.00		C-N-A				
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Wall	Wood Finish	0.00		C-N-A				

Level : B		Level Description : Basement				Asbestos Present : Potential		
Room : 17B		Room Description : Storage Room						

Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Wall	Wood Finish	0.00		C-N-A				

Level : B		Level Description : Basement				Asbestos Present : Potential		
Room : 17C		Room Description : Storage Room						

Ceiling	Cast in Place Concrete	0.00		C-N-A				
---------	------------------------	------	--	-------	--	--	--	--

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Wall	Wood Finish	0.00		C-N-A				
Level : B		Level Description : Basement				Asbestos Present : Potential		
Room : 17D		Room Description : Storage Room						
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Wall	Wood Finish	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Level : B		Level Description : Basement				Asbestos Present : Potential		
Room : 17E		Room Description : Storage Room						
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Vinyl covered drywall	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Wall	Windows - Wood	0.00		C-N-A				
Wall	Wood Finish	0.00		C-N-A				
Level : B		Level Description : Basement				Asbestos Present : Potential		
Room : 18A		Room Description : Storage Room						
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Block	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				
Level : B		Level Description : Basement				Asbestos Present : Potential		
Room : 18B		Room Description : Storage Room						

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Block	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				

Level : B		Level Description : Basement				Asbestos Present : Potential		
Room : 18C		Room Description : Storage Room						

Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Block	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				

Level : B		Level Description : Basement				Asbestos Present : Potential		
Room : 19		Room Description : Storage Room						

Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Concrete/Terrazo	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Block	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				

Level : B	Level Description : Basement	Asbestos Present : Potential
Room : 20	Room Description : Elevator Room	

Ceiling	Cast in Place Concrete	0.00	C-N-A
Ceiling	Plaster - Base coat	0.00	C-N-A
Ceiling	Plaster - Top coat	0.00	C-N-A
Ductwork	Metal - Bare	0.00	C-N-A
Floor	Concrete	0.00	C-N-A
Pipe	Fittings Insulated - Fibreglass	0.00	C-N-A
Pipe	Insulated - Fibreglass	0.00	C-N-A
Pipe	Straight Run-Fiberglass	0.00	C-N-A
Wall	Block	0.00	C-N-A
Wall	Concrete	0.00	C-N-A
Wall	Drywall	0.00	C-N-A
Wall	Plaster - Base coat	0.00	C-N-A
Wall	Plaster - Top coat	0.00	C-N-A

Level : B	Level Description : Basement	Asbestos Present : Potential
Room : 21	Room Description : Elevator Shaft	
Comments : Dust on elevator chain sampled. Sample No. A037		

Ceiling	Cast in Place Concrete	0.00	C-N-A	
Floor	Concrete	0.00	C-N-A	
Mechanical	Elevator Brake Shoes	0.00	T-N-A	A037
Wall	Concrete	0.00	C-N-A	
Wall	Plaster - Base coat	0.00	C-N-A	
Wall	Plaster - Top coat	0.00	C-N-A	

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Level : B		Level Description : Basement				Asbestos Present : Potential		
Room : 21A		Room Description : Elevator Room						
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Concrete/Terrazo	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Level : B		Level Description : Basement				Asbestos Present : Potential		
Room : 22A		Room Description : Storage Room						
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Block	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Wall	Windows - Aluminum Frame	0.00		C-N-A				
Level : B		Level Description : Basement				Asbestos Present : Potential		
Room : 22B		Room Description : Storage Room						
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Block	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				

Level : B		Level Description : Basement				Asbestos Present : Potential		
Room : 22C		Room Description : Storage Room						

Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Block	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				

Level : B		Level Description : Basement				Asbestos Present : Potential		
Room : 22D		Room Description : Storage Room						

Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ceiling	Plaster - Top coat	0.00		C-N-A				
Ductwork	Metal - Bare	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Block	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				

Level : B		Level Description : Basement				Asbestos Present : Potential		
Room : 23A		Room Description : Storage Room						

Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Block	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				

Level : B		Level Description : Basement				Asbestos Present : Potential		
Room : 23B		Room Description : Storage Room						

Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Block	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				

Level : B		Level Description : Basement				Asbestos Present : Potential		
Room : 23C		Room Description : Storage Room						

Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Block	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				

Level : B		Level Description : Basement				Asbestos Present : Potential		
Room : 23D		Room Description : Storage Room						

Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fibreglass	0.00		C-N-A				
Wall	Block	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				

Level : B		Level Description : Basement				Asbestos Present : Potential		
Room : 23E		Room Description : Storage Room						
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fibreglass	0.00		C-N-A				
Wall	Block	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				

Level : B		Level Description : Basement				Asbestos Present : Potential		
Room : 23F		Room Description : Storage Room						
Ceiling	Cast in Place Concrete	0.00		C-N-A				

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Block	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				

Level : B		Level Description : Basement				Asbestos Present : Potential		
Room : 23G		Room Description : Storage Room						

Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Block	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				

Level : B		Level Description : Basement				Asbestos Present : Potential		
Room : 24		Room Description : Storage Room						

Asbestos Assessment Report

(sorted by structure no.)

Material/Design	Description	Quantity	Units	Condition	Sample	Asbestos Type	Access	Action
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Floor	Concrete/Terrazo	0.00		C-N-A				
Pipe	Fittings Insulated - Fibreglass	0.00		C-N-A				
Pipe	Insulated - Fibreglass	0.00		C-N-A				
Pipe	Straight Run-Fiberglass	0.00		C-N-A				
Wall	Block	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				
Level : B		Level Description : Basement				Asbestos Present : Potential		
Room : 25		Room Description : Storage Room						
Ceiling	Cast in Place Concrete	0.00		C-N-A				
Ceiling	Fiberglass wrapped pipes	0.00		C-N-A				
Ceiling	Firestop sealant	0.00		C-N-A				
Ceiling	Plaster - Base coat	0.00		C-N-A				
Ceiling	Plaster - Top coat	0.00		C-N-A				
Floor	Concrete	0.00		C-N-A				
Wall	Block	0.00		C-N-A				
Wall	Brick	0.00		C-N-A				
Wall	Concrete	0.00		C-N-A				
Wall	Plaster - Base coat	0.00		C-N-A				
Wall	Plaster - Top coat	0.00		C-N-A				