

QUESTION AND ANSWER

Question 3

Would you happen to know how much the road/bridge closure is per daily?

Answer 3

No, the contractor has to contact MTO for this information.

Question 4

Section 01 35 29, Part 1.7 states 'Contractor to refer to DSS report titled Environmental Compliance Audit – Burlington Lift Bridge, 2018 prepared by Environmental Services - Ontario Region'.

Answer 4

For this project the contractor must review and comply with "Asbestos and Lead Reassessment Survey – Burlington Lift Bridge", 2018 section 02 44 99 part 1.5 "site conditions". This document forms part of Amendment 005.

Question 5

Is the existing tower window frame galvanized steel? (Section A-09/A, A-09/1.

Answer 5

Existing window frames are aluminum, not galvanized steel.