

1) Refer to the attached 13 pages of site photos (26 photos) as requested during the site visit

The following changes to the tender documents are effective immediately and will form part of the contract documents:

2) Where new holes need to be cored through the existing concrete floor slab, take Xrays of the slab before coring.

Refer to Drawing 2/A1.1 Bow Unit Reflected Ceiling Plan:

3) Where the exit sign is being relocated and where the light fixtures are being rotated 90 degrees in the New Observation Gallery BD104 and on the other side of the new wall, patch and paint the ceiling.

END OF ADDENDUM NO. 2