

Pacific Biological Station – Taylor Building Window Replacement






Photo 1 – Southeast Elevation



**Photo 2 – Typical Interior Condition
Showing Existing Windows, Stairs, and Stair
Curb**



**Photo 3 – Typical Interior Condition
Showing Existing Windows, Stairs, and Stair
Curb**



Photo 4 – Sample of Base of Wall Conditions



Photo 5 – Sample of Jamb Conditions



Photo 6 –Northwest Elevation