





Site Location



Legend

 Site Boundary




Notes

1. This map is not intended to be a "stand-alone" document, but a visual aid of the information contained within the referenced Report. It is intended to be used in conjunction with the scope of services and limitations described therein.

Sources

- Aerial Imagery: District of North Vancouver, 2013
- Inset Basemap: ESRI World Topographic Map



Path: S:\Geomatics\Projects\102655-57\2020 PEC Soil Disposal Program\Fig1_102655_57_SiteLocation_200122.mxd

**PEC Site Road Routing and
Health & Safety Features**

Legend

- Fence
- [Dashed Box] Site Location
- [Yellow Grid] Proposed Contractor Support Zone
- [Green Grid] Site Support Zone
- [White Box] New Pavement Area
- [Blue Box] Wheel Wash
- [Grey Box] Access Roads

Site Support Zone
- Muster Station
- Site Office
- Fire Extinguisher
- First Aid

Wheel Wash

Site Vehicle Gate

METRO VANCOUVER RIGHT-OF-WAY

DNV:ROW




Notes

1. Aerial image used for general reference only - may not be representative of pre remediation phase.
2. This map is not intended to be a "stand-alone" document, but a visual aid of the information contained within the referenced Report. It is intended to be used in conjunction with the scope of services and limitations described therein.

Sources

- Site Imagery: Trevia Survey orthophoto, March 2015
- Off-Site Imagery: District of North Vancouver, 2013




Path: S:\Operations\Projects\102655\2020 PEC Soil Disposal Program\Fig2_100655_52_healthSafety_200114.mxd

Site Control Zones

Legend

- ×— Fence
- ⬜ Site Boundary
- ⬜ Work Exclusion Zone
- ⬜ Work Zone
- ⊠ Contractor Support Zone
- ⊠ Site Support Zone
- Wheel Wash
- Access Road




Notes

1. Aerial image used for general reference only - may not be representative of pre remediation phase.
2. This map is not intended to be a "stand-alone" document, but a visual aid of the information contained within the referenced Report. It is intended to be used in conjunction with the scope of services and limitations described therein.
3. All measurements displayed on the figure are approximate and are to be verified in the field.

Sources


- Site Imagery: Trevita Survey orthophoto, March 2015
- Off-Site Imagery: District of North Vancouver, 2013



Site Plan

Legend

- x—x Fence
- Site Boundary
- Approximate Top of 2019 Remedial Excavation
- Approximate Top of 2019 Remedial Excavation
- Final Excavation Areas for the North and South Excavations from the 2018 Remedial Excavation Program
- Future Soil Storage Area
- Transfer Facility
- Final excavation area for the former Heede Crane Area Remediation Base Work
- Final excavation area for the former Heede Crane Area Remediation Optional Work
- Site Support Zone
- Wheel Wash
- Water Holding Cell
- Existing Owner Supplied Backfill
- Imported Backfill Stockpile Area
- Gravel and Cobble Stockpile
- Metals Contaminated Soil Stockpile
- Access Road
- Paved Area




Notes

1. Aerial image used for general reference only - may not be representative of post remediation phase.
2. This map is not intended to be a "stand-alone" document, but a visual aid of the information contained within the referenced Report. It is intended to be used in conjunction with the scope of services and limitations described therein.
3. All measurements displayed on the figure are approximate and are to be verified in the field.

Sources

- Site Imagery: Trevia Survey orthophoto, March 2015
- Off-Site Imagery: District of North Vancouver, 2013



Path: S:\C:\emalia\Projects\102655-57\2020 PEC Soil Disposal Program\Fig_102655-57_RE_SitePlan_202116.mxd

Example Storage Cells Results

NOTES:
Example cell only- Not an actual cell.





- Legend**
- Cell #6
 - Subcell
 - Base of Lift 2 and 3
 - Exceeds CSR CL Standards
 - Exceeds BC Hazardous Waste Regulation for Lead - Leachate Quality Standards
 - Exceeds BC Hazardous Waste Regulation for Copper - Leachate Quality Standards
 - Exceeds BC Hazardous Waste Regulation for Copper and Lead - Leachate Quality Standards



- Notes**
1. Aerial image used for general reference only - may not be representative of post remediation phase.
 2. This map is not intended to be a "stand-alone" document, but a visual aid of the information contained within the referenced Report. It is intended to be used in conjunction with the scope of services and limitations described

Sources

- Trevisa Survey orthophoto - March 2015



Path: C:\Users\matt\Documents\102655-57\2020 PEC Soil Disposal Program\Fig_102655-57_ExampleStorageCellsResults_202113.mxd