


1 SITE PLAN
A0 NOT TO SCALE



2 FLOOR PLAN
A0 1:50

GENERAL NOTES:

- PRIOR TO COMMENCING WORK, THE CONTRACTOR OR SUBCONTRACTOR IS RESPONSIBLE FOR VERIFYING THE DIMENSIONS ON THE DRAWINGS AGAINST THE EXISTING BUILDING CONDITIONS. SCALED MEASUREMENTS ARE NOT TO BE TAKEN FROM THE DRAWINGS.
- ACCESS AND USE OF THE INTERIOR OF THE BUILDING MUST BE LIMITED AND APPROVED PRIOR.
- USE CAUTION WHEN PERFORMING ANY AND ALL WORK (INCLUDING DEMOLITION AND CONSTRUCTION) IN AREAS ADJACENT TO OR ABUTTING AGAINST HERITAGE ELEMENTS IN ORDER TO AVOID DAMAGE TO THE ORIGINAL HERITAGE FABRIC.
- ENSURE THAT OPENINGS INTO WORK AREAS CREATED BY THE REMOVAL OF DOORS OR WINDOWS ARE SECURED IN ORDER TO RESTRICT ACCESS BY THE GENERAL PUBLIC AND IN A MANNER THAT WILL NOT DAMAGE THE ADJACENT HERITAGE FABRIC.
- ALL HERITAGE MATERIAL THAT HAS BEEN REMOVED FOR RESTORATION AND REPAIR MUST BE REINSTALLED IN ITS ORIGINAL LOCATION UNLESS OTHERWISE INDICATED.
- PCA MUST BE CONTACTED WITHOUT DELAY UPON DISCOVERY OF UNDOCUMENTED EXISTING DAMAGE, DEFECTIVE OR UNSOUND MATERIALS OR CONSTRUCTION. ALL WORK IN THE IMMEDIATE AREA IS TO CEASE PENDING FURTHER INSTRUCTIONS.
- PCA MUST BE INFORMED UPON DISCOVERY OF ANY UNDOCUMENTED HERITAGE MATERIALS. ALL WORK IN THE IMMEDIATE AREA IS TO CEASE PENDING FURTHER INSTRUCTIONS.
- IT IS THE CONTRACTOR'S RESPONSIBILITY TO ENSURE THAT ALL REGULATORY PROCEDURES WITH REGARD TO DESIGNATED SUBSTANCES ARE ADHERED TO ON SITE AND IN ALL WORK AREAS. ALL PAINT CONTAINS LEAD, MORTARS CONTAIN SILICA, AND IT IS ASSUMED THAT THE CAULKING CONTAINS ASBESTOS.
- PRIOR TO DISMANTLING OR REMOVING AN ELEMENT OR ASSEMBLY, PHOTOGRAPH, MEASURE AND FULLY DOCUMENT IT INCLUDING EACH OF ITS COMPONENTS, THEIR MATERIALS AND CONSTRUCTION. NUMBER AND IDENTIFY EACH ELEMENT AS PER SPECIFICATIONS.
- ALL REQUIRED DOCUMENTATION MUST BE SUBMITTED AND REVIEWED PRIOR TO STARTING ANY DEMOLITION OR DISMANTLING WORK.
- ALL STONE THAT IS TO BE REMOVED AND STORED MUST FIRST BE INVENTORIED, CATALOGUED, PHOTOGRAPHED AND CLEARLY IDENTIFIED IN ACCORDANCE TO THE RECOMMENDATIONS DESCRIBED IN THE SPECIFICATIONS.
- ALL DOORS, FRAMES, CASINGS, WINDOWS, SHUTTERS, AND HARDWARE TO BE REMOVED AND STORED MUST FIRST BE INVENTORIED, CATALOGUED, PHOTOGRAPHED AND CLEARLY IDENTIFIED WITH THE NUMBER INDICATED ON THESE DRAWINGS AND IN ACCORDANCE TO THE RECOMMENDATIONS DESCRIBED IN THE SPECIFICATIONS.
- ROOFING INSTALLATION WORK PROCEEDING CONCURRENTLY WITH DISMANTLING WORK SHALL BE SEQUENCED IN SUCH A WAY TO MINIMIZE THE AREA EXPOSED TO WEATHER. PROVIDE NECESSARY RAIN AND WIND RESISTANT INSTALLATIONS TO PROTECT EXPOSED PORTIONS OF THE BUILDING FROM WATER INFILTRATION.

GENERAL SCOPE NOTES

- MASONRY REPAIR SCOPE OF WORK TO BE PRICED ACCORDING TO UNIT PRICE TABLE.
- STONES MARKED FOR REPLACEMENT THAT ARE DEEMED BY THE CONSULTANT TO BE PARTIALLY OR WHOLLY IN SOUND CONDITION UPON REMOVAL ARE TO BE SALVAGED AND STORED FOR LATER REUSE.
- PROVIDE GRAVEL UNDER ENDS OF GUTTER LOCATIONS.
- CLEAN 100% OF ALL MASONRY INCLUDING LOCALIZED AREAS OF SPECIALIZED CLEANING TO REMOVE COPPER STAINING AND BIOLOGICAL GROWTH.

NOTES

- REMOVE AND DISPOSE OF EXISTING WOOD QUARTER ROUND TO ALLOW FOR MASONRY REPOINTING.
- REMOVE AND DISPOSE OF EXISTING COPPER ROOF, FLASHING, & UNDERLAYMENT.
- REMOVE AND DISPOSE OF EXISTING COPPER FLASHING AT JUNCTION OF VESTIBLE AND MAIN STRUCTURE TO ALLOW FOR MASONRY REPOINTING.
- REMOVE AND SALVAGE EXISTING WINDOW SHUTTERS AND DOOR TO ALLOW FOR MASONRY REPOINTING & REINSTATE AFTER COMPLETION.
- REMOVE AND DISPOSE OF EXISTING COPPER GUTTER.
- INSTALL NEW UNDERLAYMENT, COPPER ROOF, & FLASHING.
- INSTALL NEW 150mm X 100mm COPPER GUTTER. SLOPE GUTTER 2% IN EITHER DIRECTION FROM MID-POINT OF ROOF.
- INSTALL NEW STEP COPPER FLASHING IN REGLET AFTER REPOINTING IS COMPLETED.
- INSTALL NEW WOOD QUARTER ROUND IMPREGNATED WITH LINSEED OIL. SIZE TO MATCH EXISTING.
- REINSTALL WINDOW SHUTTERS AND DOORS.
- CLEAN COPPER AND BRONZE PANELS, HINGES, AND HARDWARE. REFER TO SPECIFICATION SECTION 07.61.00.
- REMOVE AND DISCARD INCOMPATIBLE COPPER OR BRONZE HARDWARE AND INSTALL NEW COPPER OR BRONZE HARDWARE.

LEGEND:

- EXISTING BUILDING ENTRANCE ACCESS
- PROPOSED LOCKABLE GATE
- PROPOSED TEMPORARY FENCE FOR CONSTRUCTION SITE
- PROPOSED LAYDOWN/STAGING AREAS
- WATER ACCESS



ARCHITECTS:

EVOO

366 ADELAIDE ST. EAST, SUITE 225
TORONTO (ONTARIO) M5A 3X9
T. 647-729-2030

ENGINEERS:

ojdrovic engineering

4195 DUNDAS ST. W., SUITE 233
TORONTO, ON M8X 1Y4
T. 416-925-0333

SEALS:



NO.	DATE	DESCRIPTION	Drawn by	Approved
2	12/19/19	TENDER SUBMISSION	RM	DC
1	10/01/19	99% SUBMISSION	RM	DC

REVISIONS

	A Detail number	A Numero de detail
	B Sheet number	B Sur feuille numero

Linear dimensions in millimeters Dimensions lineaires en millimetres

Parcs Canada Parks Canada

Canada

PARKS CANADA
SOUTHWESTERN ONTARIO FIELD UNIT

Type of Record /
Type d'enregistrement

Project title / Titre du projet

**FORT GEORGE NATIONAL HISTORIC
SITE POWDER MAGAZINE**

Drawing title / Titre du dessin

SITE PLAN

Plot Scale / Echelle

NOT TO SCALE

Drawn by/ Dessine par Date
RM/JM 12/19/19

Field Recording by /
Relevé-Terminé par Date
DC/JM/RM 12/19/19






Approved by / Approuvé par Date
DC 12/19/19

Checked by/ Verifié par Date
DC 12/19/19

Project No./ No. du projet Asset No. Sheet No./
001504-010 1202269 Feuille No.

Drawing Re No./No. du Dessin

A0



STONE REPAIRS	
ALLOW FOR THE FOLLOWING NUMBER OF STONE REPAIRS/REPLACEMENTS. SEE SPECIFICATION SECTIONS 04.03.42, 04.03.43, & 04.03.45.	
FILLING OF STONE CRACKS IN SITU	15
MECHANICAL CONSOLIDATION OF CRACKS IN SITU	15
REPAIR OF REMOVED FRACTURED STONE	50
REPLACEMENT OF IRREGULAR SIZED STONES RANGING FROM 100 TO 300mm IN HEIGHT, 125 TO 375mm IN LENGTH & 50 TO 250mm IN DEPTH.	50

GENERAL NOTES:

- PRIOR TO COMMENCING WORK, THE CONTRACTOR OR SUBCONTRACTOR IS RESPONSIBLE FOR VERIFYING THE DIMENSIONS ON THE DRAWINGS AGAINST THE EXISTING BUILDING CONDITIONS. SCALED MEASUREMENTS ARE NOT TO BE TAKEN FROM THE DRAWINGS.
- ACCESS AND USE OF THE INTERIOR OF THE BUILDING MUST BE LIMITED AND APPROVED PRIOR.
- USE CAUTION WHEN PERFORMING ANY AND ALL WORK (INCLUDING DEMOLITION AND CONSTRUCTION) IN AREAS ADJACENT TO OR ABUTTING AGAINST HERITAGE ELEMENTS IN ORDER TO AVOID DAMAGE TO THE ORIGINAL HERITAGE FABRIC.
- ENSURE THAT OPENINGS INTO WORK AREAS CREATED BY THE REMOVAL OF DOORS OR WINDOWS ARE SECURED IN ORDER TO RESTRICT ACCESS BY THE GENERAL PUBLIC AND IN A MANNER THAT WILL NOT DAMAGE THE ADJACENT HERITAGE FABRIC.
- ALL HERITAGE MATERIAL THAT HAS BEEN REMOVED FOR RESTORATION AND REPAIR MUST BE REINSTALLED IN ITS ORIGINAL LOCATION UNLESS OTHERWISE INDICATED.
- PCA MUST BE CONTACTED WITHOUT DELAY UPON DISCOVERY OF UNDOCUMENTED EXISTING DAMAGE, DEFECTIVE OR UNSOUND MATERIALS OR CONSTRUCTION. ALL WORK IN THE IMMEDIATE AREA IS TO CEASE PENDING FURTHER INSTRUCTIONS.
- PCA MUST BE INFORMED UPON DISCOVERY OF ANY UNDOCUMENTED HERITAGE MATERIALS. ALL WORK IN THE IMMEDIATE AREA IS TO CEASE PENDING FURTHER INSTRUCTIONS.
- IT IS THE CONTRACTOR'S RESPONSIBILITY TO ENSURE THAT ALL REGULATORY PROCEDURES WITH REGARD TO DESIGNATED SUBSTANCES ARE ADHERED TO ON SITE AND IN ALL WORK AREAS. ALL PAINT CONTAINS LEAD, MORTARS CONTAIN SILICA, AND IT IS ASSUMED THAT THE CAULKING CONTAINS ASBESTOS.
- PRIOR TO DISMANTLING OR REMOVING AN ELEMENT OR ASSEMBLY, PHOTOGRAPH, MEASURE AND FULLY DOCUMENT IT INCLUDING EACH OF ITS COMPONENTS, THEIR MATERIALS AND CONSTRUCTION. NUMBER AND IDENTIFY EACH ELEMENT AS PER SPECIFICATIONS.
- ALL REQUIRED DOCUMENTATION MUST BE SUBMITTED AND REVIEWED PRIOR TO STARTING ANY DEMOLITION OR DISMANTLING WORK.
- ALL STONE THAT IS TO BE REMOVED AND STORED MUST FIRST BE INVENTORIED, CATALOGUED, PHOTOGRAPHED AND CLEARLY IDENTIFIED IN ACCORDANCE TO THE RECOMMENDATIONS DESCRIBED IN THE SPECIFICATIONS.
- ALL DOORS, FRAMES, CASINGS, WINDOWS, SHUTTERS, AND HARDWARE TO BE REMOVED AND STORED MUST FIRST BE INVENTORIED, CATALOGUED, PHOTOGRAPHED AND CLEARLY IDENTIFIED WITH THE NUMBER INDICATED ON THESE DRAWINGS AND IN ACCORDANCE TO THE RECOMMENDATIONS DESCRIBED IN THE SPECIFICATIONS.
- ROOFING INSTALLATION WORK PROCEEDING CONCURRENTLY WITH DISMANTLING WORK SHALL BE SEQUENCED IN SUCH A WAY TO MINIMIZE THE AREA EXPOSED TO WEATHER. PROVIDE NECESSARY RAIN AND WIND RESISTANT INSTALLATIONS TO PROTECT EXPOSED PORTIONS OF THE BUILDING FROM WATER INFILTRATION.

GENERAL SCOPE NOTES

- MASONRY REPAIR SCOPE OF WORK TO BE PRICED ACCORDING TO UNIT PRICE TABLE.
- STONES MARKED FOR REPLACEMENT THAT ARE DEEMED BY THE CONSULTANT TO BE PARTIALLY OR WHOLLY IN SOUND CONDITION UPON REMOVAL ARE TO BE SALVAGED AND STORED FOR LATER REUSE.
- PROVIDE GRAVEL UNDER ENDS OF GUTTER LOCATIONS.
- CLEAN 100% OF ALL MASONRY INCLUDING LOCALIZED AREAS OF SPECIALIZED CLEANING TO REMOVE COPPER STAINING AND BIOLOGICAL GROWTH.

- NOTES**
- REMOVE AND DISPOSE OF EXISTING WOOD QUARTER ROUND TO ALLOW FOR MASONRY REPOINTING.
 - REMOVE AND DISPOSE OF EXISTING COPPER ROOF, FLASHING, & UNDERLAYMENT.
 - REMOVE AND DISPOSE OF EXISTING COPPER FLASHING AT JUNCTION OF VESTIBLE AND MAIN STRUCTURE TO ALLOW FOR MASONRY REPOINTING.
 - REMOVE AND SALVAGE EXISTING WINDOW SHUTTERS AND DOOR TO ALLOW FOR MASONRY REPOINTING & REINSTATE AFTER COMPLETION.
 - REMOVE AND DISPOSE OF EXISTING COPPER GUTTER.
 - INSTALL NEW UNDERLAYMENT, COPPER ROOF, & FLASHING.
 - INSTALL NEW 150mm X 100mm COPPER GUTTER. SLOPE GUTTER 2% IN EITHER DIRECTION FROM MID-POINT OF ROOF.
 - INSTALL NEW STEP COPPER FLASHING IN REGLET AFTER REPOINTING IS COMPLETED.
 - INSTALL NEW WOOD QUARTER ROUND IMPREGNATED WITH LINSEED OIL. SIZE TO MATCH EXISTING.
 - REINSTALL WINDOW SHUTTERS AND DOORS.
 - CLEAN COPPER AND BRONZE PANELS, HINGES, AND HARDWARE. REFER TO SPECIFICATION SECTION 07.61.00.
 - REMOVE AND DISCARD INCOMPATIBLE COPPER OR BRONZE HARDWARE AND INSTALL NEW COPPER OR BRONZE HARDWARE.

LEGEND:

- RAKE OUT JOINTS FROM EXTERIOR FACE OF WALL REMOVING ALL HARD CEMENTITIOUS MORTAR TO A MINIMUM DEPTH OF 40MM. ADD GALLETS INTO MORTAR WHERE GAPS BETWEEN STONES ARE LARGER THAN 40MM. CONFIRM WALL CORE CONDITION. REMOVE ANY LOOSE STONES AND/OR CORE MATERIAL. CONSOLIDATE RUBBLE CORE AND REINSTALL REMOVED STONE.
- RAKE OUT JOINTS FROM EXTERIOR FACE OF WALL REMOVING ALL HARD CEMENTITIOUS MORTAR TO A MINIMUM DEPTH OF 150MM. ADD GALLETS INTO MORTAR WHERE GAPS BETWEEN STONES ARE LARGER THAN 40MM. CONFIRM WALL CORE CONDITION. REMOVE ANY LOOSE STONES AND/OR CORE MATERIAL. CONSOLIDATE RUBBLE CORE AND REINSTALL REMOVED STONE.
- BUTTRESS SCOPE IS INCREMENTAL. CONTRACTOR TO PRICE FULL DISMANTLE.
 - CUT OUT ALL JOINTS AND REMOVE OVERPOINTING
 - ALLOW FOR CONSULTANT ASSESSMENT OF STONES AND IDENTIFICATION OF EXTENT OF DISMANTLING & STONE REPLACEMENT
 - DISMANTLE FACE STONES FROM TOP HALF OF BUTTRESS
 - DETERMINE WHETHER ADDITIONAL DISMANTLING IS REQUIRED.
 - COMPLETE ADDITIONAL DISMANTLING IF REQUIRED
 - CONSOLIDATE CORE
 - REBUILD FACE STONE
 - REPOINT

ARCHITECTS:

EVOO

366 ADELAIDE ST. EAST, SUITE 225
TORONTO (ONTARIO) M5A 3X9
T. 647-723-2030

ENGINEERS:

ojdrovic engineering

4195 DUNDAS ST. W., SUITE 233
TORONTO, ON M8X 1Y4
T. 416-925-0333

SEALS:

ONTARIO ASSOCIATION OF ARCHITECTS
GEORGES DROLET
LICENCE 8196

NO.	DATE	DESCRIPTION	Drawn by	Approved
3	12/19/19	TENDER SUBMISSION	RM	DC
2	10/01/19	99% SUBMISSION	RM	DC
1	08/16/19	FHBR REVIEW	RM	DC

REVISIONS

A Detail number / A Numéro de détail
B Sheet number / B Sur feuille numero

Linear dimensions in millimeters / Dimensions lineaires en millimetres

Parcs Canada / Parks Canada

Canadä

PARKS CANADA
SOUTHWESTERN ONTARIO FIELD UNIT

Type of Record / Type d'enregistrement

Project title / Titre du projet
FORT GEORGE NATIONAL HISTORIC SITE POWDER MAGAZINE

Drawing title / Titre du dessin
REPOINTING, STONE REPAIR & ROOF DEMOLITION DRAWINGS

Plot Scale / Echelle
1:50

Drawn by/ Dessine par
RM/JM Date
12/19/19

Field Recording by / Releve-Temoin par
DC/JM/RM Date
12/19/19

Approved by / Approuve par
DC Date
12/19/19





Checked by/ Verifie par
DC Date
12/19/19

Project No./ No. du projet
001504-010

Asset No.
1202269

Sheet No./ Feuille No.
A1

Drawing Re No./No. du Dessin



- GENERAL NOTES:**
- PRIOR TO COMMENCING WORK, THE CONTRACTOR OR SUBCONTRACTOR IS RESPONSIBLE FOR VERIFYING THE DIMENSIONS ON THE DRAWINGS AGAINST THE EXISTING BUILDING CONDITIONS. SCALED MEASUREMENTS ARE NOT TO BE TAKEN FROM THE DRAWINGS.
 - ACCESS AND USE OF THE INTERIOR OF THE BUILDING MUST BE LIMITED AND APPROVED PRIOR.
 - USE CAUTION WHEN PERFORMING ANY AND ALL WORK (INCLUDING DEMOLITION AND CONSTRUCTION) IN AREAS ADJACENT TO OR ABUTTING AGAINST HERITAGE ELEMENTS IN ORDER TO AVOID DAMAGE TO THE ORIGINAL HERITAGE FABRIC.
 - ENSURE THAT OPENINGS INTO WORK AREAS CREATED BY THE REMOVAL OF DOORS OR WINDOWS ARE SECURED IN ORDER TO RESTRICT ACCESS BY THE GENERAL PUBLIC AND IN A MANNER THAT WILL NOT DAMAGE THE ADJACENT HERITAGE FABRIC.
 - ALL HERITAGE MATERIAL THAT HAS BEEN REMOVED FOR RESTORATION AND REPAIR MUST BE REINSTALLED IN ITS ORIGINAL LOCATION UNLESS OTHERWISE INDICATED.
 - PCA MUST BE CONTACTED WITHOUT DELAY UPON DISCOVERY OF UNDOCUMENTED EXISTING DAMAGE, DEFECTIVE OR UNSOUND MATERIALS OR CONSTRUCTION. ALL WORK IN THE IMMEDIATE AREA IS TO CEASE PENDING FURTHER INSTRUCTIONS.
 - PCA MUST BE INFORMED UPON DISCOVERY OF ANY UNDOCUMENTED HERITAGE MATERIALS. ALL WORK IN THE IMMEDIATE AREA IS TO CEASE PENDING FURTHER INSTRUCTIONS.
 - IT IS THE CONTRACTOR'S RESPONSIBILITY TO ENSURE THAT ALL REGULATORY PROCEDURES WITH REGARDS TO DESIGNATED SUBSTANCES ARE ADHERED TO ON SITE AND IN ALL WORK AREAS. ALL PAINT CONTAINS LEAD, MORTARS CONTAIN SILICA, AND IT IS ASSUMED THAT THE CAULKING CONTAINS ASBESTOS.
 - PRIOR TO DISMANTLING OR REMOVING AN ELEMENT OR ASSEMBLY, PHOTOGRAPH, MEASURE AND FULLY DOCUMENT IT INCLUDING EACH OF ITS COMPONENTS, THEIR MATERIALS AND CONSTRUCTION. NUMBER AND IDENTIFY EACH ELEMENT AS PER SPECIFICATIONS.
 - ALL REQUIRED DOCUMENTATION MUST BE SUBMITTED AND REVIEWED PRIOR TO STARTING ANY DEMOLITION OR DISMANTLING WORK.
 - ALL STONE THAT IS TO BE REMOVED AND STORED MUST FIRST BE INVENTORIED, CATALOGUED, PHOTOGRAPHED AND CLEARLY IDENTIFIED IN ACCORDANCE TO THE RECOMMENDATIONS DESCRIBED IN THE SPECIFICATIONS.
 - ALL DOORS, FRAMES, CASINGS, WINDOWS, SHUTTERS, AND HARDWARE TO BE REMOVED AND STORED MUST FIRST BE INVENTORIED, CATALOGUED, PHOTOGRAPHED AND CLEARLY IDENTIFIED WITH THE NUMBER INDICATED ON THESE DRAWINGS AND IN ACCORDANCE TO THE RECOMMENDATIONS DESCRIBED IN THE SPECIFICATIONS.
 - ROOFING INSTALLATION WORK PROCEEDING CONCURRENTLY WITH DISMANTLING WORK SHALL BE SEQUENCED IN SUCH A WAY TO MINIMIZE THE AREA EXPOSED TO WEATHER. PROVIDE NECESSARY RAIN AND WIND RESISTANT INSTALLATIONS TO PROTECT EXPOSED PORTIONS OF THE BUILDING FROM WATER INFILTRATION.

- GENERAL SCOPE NOTES**
- MASONRY REPAIR SCOPE OF WORK TO BE PRICED ACCORDING TO UNIT PRICE TABLE.
 - STONES MARKED FOR REPLACEMENT THAT ARE DEEMED BY THE CONSULTANT TO BE PARTIALLY OR WHOLLY IN SOUND CONDITION UPON REMOVAL ARE TO BE SALVAGED AND STORED FOR LATER REUSE.
 - PROVIDE GRAVEL UNDER ENDS OF GUTTER LOCATIONS.
 - CLEAN 100% OF ALL MASONRY INCLUDING LOCALIZED AREAS OF SPECIALIZED CLEANING TO REMOVE COPPER STAINING AND BIOLOGICAL GROWTH.

- NOTES**
- REMOVE AND DISPOSE OF EXISTING WOOD QUARTER ROUND TO ALLOW FOR MASONRY REPOINTING.
 - REMOVE AND DISPOSE OF EXISTING COPPER ROOF, FLASHING, & UNDERLAYMENT.
 - REMOVE AND DISPOSE OF EXISTING COPPER FLASHING AT JUNCTION OF VESTIBLE AND MAIN STRUCTURE TO ALLOW FOR MASONRY REPOINTING.
 - REMOVE AND SALVAGE EXISTING WINDOW SHUTTERS AND DOOR TO ALLOW FOR MASONRY REPOINTING & REINSTATE AFTER COMPLETION.
 - REMOVE AND DISPOSE OF EXISTING COPPER GUTTER.
 - INSTALL NEW UNDERLAYMENT, COPPER ROOF, & FLASHING.
 - INSTALL NEW 150mm X 100mm COPPER GUTTER. SLOPE GUTTER 2% IN EITHER DIRECTION FROM MID-POINT OF ROOF.
 - INSTALL NEW STEP COPPER FLASHING IN REGLET AFTER REPOINTING IS COMPLETED.
 - INSTALL NEW WOOD QUARTER ROUND IMPREGNATED WITH LINSEED OIL. SIZE TO MATCH EXISTING.
 - REINSTALL WINDOW SHUTTERS AND DOORS.
 - CLEAN COPPER AND BRONZE PANELS, HINGES, AND HARDWARE. REFER TO SPECIFICATION SECTION 07.61.00.
 - REMOVE AND DISCARD INCOMPATIBLE COPPER OR BRONZE HARDWARE AND INSTALL NEW COPPER OR BRONZE HARDWARE.

- LEGEND:**
- AREAS OF LOCALIZED COPPER STAINING TO BE CLEANED.
 - AREAS OF LOCALIZED BIOLOGICAL GROWTH TO BE CLEANED.

ARCHITECTS:

EVOO

366 ADELAIDE ST. EAST, SUITE 225
TORONTO (ONTARIO) M5A 3X9
T. 647-729-2030

ENGINEERS:

ojdrovic engineering

4195 DUNDAS ST. W., SUITE 233
TORONTO, ON M8X 1Y4
T. 416-925-0333

SEALS:

NO.	DATE	DESCRIPTION	Drawn by	Approved
3	12/19/19	TENDER SUBMISSION	RM	DC
2	10/01/19	99% SUBMISSION	RM	DC
1	08/16/19	FHBRO REVIEW	RM	DC

NO. DATE DESCRIPTION Drawn by Approved
Dessine par Approuve

REVISIONS

NO.	DATE	DESCRIPTION	Drawn by	Approved
3	12/19/19	TENDER SUBMISSION	RM	DC
2	10/01/19	99% SUBMISSION	RM	DC
1	08/16/19	FHBRO REVIEW	RM	DC

Linear dimensions in millimeters / Dimensions lineaires en millimetres

Parcs Canada / Parks Canada

Canada

PARKS CANADA
SOUTHWESTERN ONTARIO FIELD UNIT

Type of Record /
Type d'enregistrement

Project title / Titre du projet

FORT GEORGE NATIONAL HISTORIC SITE POWDER MAGAZINE

Drawing title / Titre du dessin








MASONRY CLEANING DRAWINGS

Plot Scale / Echelle
1:50

Drawn by / Dessine par RM/JM	Date 12/19/19
Field Recording by / Releve-Temoin par DC/JM/RM	Date 12/19/19
Approved by / Approuve par DC	Date 12/19/19
Checked by / Verifie par DC	Date 12/19/19

Project No./ No. du projet 001504-010	Asset No. 1202269	Sheet No./ Feuille No. A2
--	----------------------	--

Drawing Re No./No. du Dessin



- GENERAL NOTES:**
- PRIOR TO COMMENCING WORK, THE CONTRACTOR OR SUBCONTRACTOR IS RESPONSIBLE FOR VERIFYING THE DIMENSIONS ON THE DRAWINGS AGAINST THE EXISTING BUILDING CONDITIONS. SCALED MEASUREMENTS ARE NOT TO BE TAKEN FROM THE DRAWINGS.
 - ACCESS AND USE OF THE INTERIOR OF THE BUILDING MUST BE LIMITED AND APPROVED PRIOR.
 - USE CAUTION WHEN PERFORMING ANY AND ALL WORK (INCLUDING DEMOLITION AND CONSTRUCTION) IN AREAS ADJACENT TO OR ABUTTING AGAINST HERITAGE ELEMENTS IN ORDER TO AVOID DAMAGE TO THE ORIGINAL HERITAGE FABRIC.
 - ENSURE THAT OPENINGS INTO WORK AREAS CREATED BY THE REMOVAL OF DOORS OR WINDOWS ARE SECURED IN ORDER TO RESTRICT ACCESS BY THE GENERAL PUBLIC AND IN A MANNER THAT WILL NOT DAMAGE THE ADJACENT HERITAGE FABRIC.
 - ALL HERITAGE MATERIAL THAT HAS BEEN REMOVED FOR RESTORATION AND REPAIR MUST BE REINSTALLED IN ITS ORIGINAL LOCATION UNLESS OTHERWISE INDICATED.
 - PCA MUST BE CONTACTED WITHOUT DELAY UPON DISCOVERY OF UNDOCUMENTED EXISTING DAMAGE, DEFECTIVE OR UNSOUND MATERIALS OR CONSTRUCTION. ALL WORK IN THE IMMEDIATE AREA IS TO CEASE PENDING FURTHER INSTRUCTIONS.
 - PCA MUST BE INFORMED UPON DISCOVERY OF ANY UNDOCUMENTED HERITAGE MATERIALS. ALL WORK IN THE IMMEDIATE AREA IS TO CEASE PENDING FURTHER INSTRUCTIONS.
 - IT IS THE CONTRACTOR'S RESPONSIBILITY TO ENSURE THAT ALL REGULATORY PROCEDURES WITH REGARD TO DESIGNATED SUBSTANCES ARE ADHERED TO ON SITE AND IN ALL WORK AREAS. ALL PAINT CONTAINING LEAD, MORTARS CONTAIN SILICA, AND IT IS ASSUMED THAT THE CAULKING CONTAINS ASBESTOS.
 - PRIOR TO DISMANTLING OR REMOVING AN ELEMENT OR ASSEMBLY, PHOTOGRAPH, MEASURE AND FULLY DOCUMENT IT INCLUDING EACH OF ITS COMPONENTS, THEIR MATERIALS AND CONSTRUCTION. NUMBER AND IDENTIFY EACH ELEMENT AS PER SPECIFICATIONS.
 - ALL REQUIRED DOCUMENTATION MUST BE SUBMITTED AND REVIEWED PRIOR TO STARTING ANY DEMOLITION OR DISMANTLING WORK.
 - ALL STONE THAT IS TO BE REMOVED AND STORED MUST FIRST BE INVENTORIED, CATALOGUED, PHOTOGRAPHED AND CLEARLY IDENTIFIED IN ACCORDANCE TO THE RECOMMENDATIONS DESCRIBED IN THE SPECIFICATIONS.
 - ALL DOORS, FRAMES, CASINGS, WINDOWS, SHUTTERS, AND HARDWARE TO BE REMOVED AND STORED MUST FIRST BE INVENTORIED, CATALOGUED, PHOTOGRAPHED AND CLEARLY IDENTIFIED WITH THE NUMBER INDICATED ON THESE DRAWINGS AND IN ACCORDANCE TO THE RECOMMENDATIONS DESCRIBED IN THE SPECIFICATIONS.
 - ROOFING INSTALLATION WORK PROCEEDING CONCURRENTLY WITH DISMANTLING WORK SHALL BE SEQUENCED IN SUCH A WAY TO MINIMIZE THE AREA EXPOSED TO WEATHER. PROVIDE NECESSARY RAIN AND WIND RESISTANT INSTALLATIONS TO PROTECT EXPOSED PORTIONS OF THE BUILDING FROM WATER INFILTRATION.

- GENERAL SCOPE NOTES**
- MASONRY REPAIR SCOPE OF WORK TO BE PRICED ACCORDING TO UNIT PRICE TABLE.
 - STONES MARKED FOR REPLACEMENT THAT ARE DEEMED BY THE CONSULTANT TO BE PARTIALLY OR WHOLLY IN SOUND CONDITION UPON REMOVAL ARE TO BE SALVAGED AND STORED FOR LATER REUSE.
 - PROVIDE GRAVEL UNDER ENDS OF GUTTER LOCATIONS.
 - CLEAN 100% OF ALL MASONRY INCLUDING LOCALIZED AREAS OF SPECIALIZED CLEANING TO REMOVE COPPER STAINING AND BIOLOGICAL GROWTH.

- NOTES**
- REMOVE AND DISPOSE OF EXISTING WOOD QUARTER ROUND TO ALLOW FOR MASONRY REPOINTING.
 - REMOVE AND DISPOSE OF EXISTING COPPER ROOF, FLASHING, & UNDERLAYMENT.
 - REMOVE AND DISPOSE OF EXISTING COPPER FLASHING AT JUNCTION OF VESTIBLE AND MAIN STRUCTURE TO ALLOW FOR MASONRY REPOINTING.
 - REMOVE AND SALVAGE EXISTING WINDOW SHUTTERS AND DOOR TO ALLOW FOR MASONRY REPOINTING & REINSTATE AFTER COMPLETION.
 - REMOVE AND DISPOSE OF EXISTING COPPER GUTTER.
 - INSTALL NEW UNDERLAYMENT, COPPER ROOF, & FLASHING.
 - INSTALL NEW 150mm X 100mm COPPER GUTTER. SLOPE GUTTER 2% IN EITHER DIRECTION FROM MID-POINT OF ROOF.
 - INSTALL NEW STEP COPPER FLASHING IN REGLET AFTER REPOINTING IS COMPLETED.
 - INSTALL NEW WOOD QUARTER ROUND IMPREGNATED WITH LINSEED OIL. SIZE TO MATCH EXISTING.
 - REINSTALL WINDOW SHUTTERS AND DOORS.
 - CLEAN COPPER AND BRONZE PANELS, HINGES, AND HARDWARE. REFER TO SPECIFICATION SECTION 07.61.00.
 - REMOVE AND DISCARD INCOMPATIBLE COPPER OR BRONZE HARDWARE AND INSTALL NEW COPPER OR BRONZE HARDWARE.

ARCHITECTS:
EVOO
366 ADELAIDE ST. EAST, SUITE 225
TORONTO (ONTARIO) M5A 3X9
T. 416-723-2030

ENGINEERS:
ojdrovic engineering
4195 DUNDAS ST. W., SUITE 233
TORONTO, ON M8X 1Y4
T. 416-925-0333

SEALS:
ONTARIO ASSOCIATION OF ARCHITECTS
GEORGES DROLET
LICENCE 6196

NO.	DATE	DESCRIPTION	Drawn by	Approved
3	12/19/19	TENDER SUBMISSION	RM	DC
2	10/01/19	99% SUBMISSION	RM	DC
1	08/16/19	FHBR REVIEW	RM	DC

REVISIONS

NO.	DATE	DESCRIPTION	Drawn by	Approved
			Dessine par	Approuve

Linear dimensions in millimeters / Dimensions lineaires en millimetres

Parcs Canada / Parks Canada

Canadä

PARKS CANADA
SOUTHWESTERN ONTARIO FIELD UNIT

Type of Record / Type d'enregistrement

Project title / Titre du projet
FORT GEORGE NATIONAL HISTORIC SITE POWDER MAGAZINE

Drawing title / Titre du dessin
ROOF CONSTRUCTION

Plot Scale / Echelle
AS NOTED

Drawn by / Dessine par: RM/JM Date: 12/19/19







Field Recording by / Releve-Temoin par: DC/JM/RM Date: 12/19/19

Approved by / Approuve par: DC Date: 12/19/19

Checked by / Verifie par: DC Date: 12/19/19

Project No./ No. du projet: 001504-010 Asset No.: 1202269 Sheet No./ Feuille No.: A3

Drawing Re No./No. du Dessin



- GENERAL NOTES:**
- PRIOR TO COMMENCING WORK, THE CONTRACTOR OR SUBCONTRACTOR IS RESPONSIBLE FOR VERIFYING THE DIMENSIONS ON THE DRAWINGS AGAINST THE EXISTING BUILDING CONDITIONS. SCALED MEASUREMENTS ARE NOT TO BE TAKEN FROM THE DRAWINGS.
 - ACCESS AND USE OF THE INTERIOR OF THE BUILDING MUST BE LIMITED AND APPROVED PRIOR.
 - USE CAUTION WHEN PERFORMING ANY AND ALL WORK (INCLUDING DEMOLITION AND CONSTRUCTION) IN AREAS ADJACENT TO OR ABUTTING AGAINST HERITAGE ELEMENTS IN ORDER TO AVOID DAMAGE TO THE ORIGINAL HERITAGE FABRIC.
 - ENSURE THAT OPENINGS INTO WORK AREAS CREATED BY THE REMOVAL OF DOORS OR WINDOWS ARE SECURED IN ORDER TO RESTRICT ACCESS BY THE GENERAL PUBLIC AND IN A MANNER THAT WILL NOT DAMAGE THE ADJACENT HERITAGE FABRIC.
 - ALL HERITAGE MATERIAL THAT HAS BEEN REMOVED FOR RESTORATION AND REPAIR MUST BE REINSTALLED IN ITS ORIGINAL LOCATION UNLESS OTHERWISE INDICATED.
 - PCA MUST BE CONTACTED WITHOUT DELAY UPON DISCOVERY OF UNDOCUMENTED EXISTING DAMAGE, DEFECTIVE OR UNSOUND MATERIALS OR CONSTRUCTION. ALL WORK IN THE IMMEDIATE AREA IS TO CEASE PENDING FURTHER INSTRUCTIONS.
 - PCA MUST BE INFORMED UPON DISCOVERY OF ANY UNDOCUMENTED HERITAGE MATERIALS. ALL WORK IN THE IMMEDIATE AREA IS TO CEASE PENDING FURTHER INSTRUCTIONS.
 - IT IS THE CONTRACTOR'S RESPONSIBILITY TO ENSURE THAT ALL REGULATORY PROCEDURES WITH REGARDS TO DESIGNATED SUBSTANCES ARE ADHERED TO ON SITE AND IN ALL WORK AREAS. ALL PAINT CONTAINS LEAD, MORTARS CONTAIN SILICA, AND IT IS ASSUMED THAT THE CAULKING CONTAINS ASBESTOS.
 - PRIOR TO DISMANTLING OR REMOVING AN ELEMENT OR ASSEMBLY, PHOTOGRAPH, MEASURE AND FILELY DOCUMENT IT INCLUDING EACH OF ITS COMPONENTS, THEIR MATERIALS AND CONSTRUCTION. NUMBER AND IDENTIFY EACH ELEMENT AS PER SPECIFICATIONS.
 - ALL REQUIRED DOCUMENTATION MUST BE SUBMITTED AND REVIEWED PRIOR TO STARTING ANY DEMOLITION OR DISMANTLING WORK.
 - ALL STONE THAT IS TO BE REMOVED AND STORED MUST FIRST BE INVENTORIED, CATALOGUED, PHOTOGRAPHED AND CLEARLY IDENTIFIED IN ACCORDANCE TO THE RECOMMENDATIONS DESCRIBED IN THE SPECIFICATIONS.
 - ALL DOORS, FRAMES, CASINGS, WINDOWS, SHUTTERS, AND HARDWARE TO BE REMOVED AND STORED MUST FIRST BE INVENTORIED, CATALOGUED, PHOTOGRAPHED AND CLEARLY IDENTIFIED WITH THE NUMBER INDICATED ON THESE DRAWINGS AND IN ACCORDANCE TO THE RECOMMENDATIONS DESCRIBED IN THE SPECIFICATIONS.
 - ROOFING INSTALLATION WORK PROCEEDING CONCURRENTLY WITH DISMANTLING WORK SHALL BE SEQUENCED IN SUCH A WAY TO MINIMIZE THE AREA EXPOSED TO WEATHER. PROVIDE NECESSARY RAIN AND WIND RESISTANT INSTALLATIONS TO PROTECT EXPOSED PORTIONS OF THE BUILDING FROM WATER INFILTRATION.

- GENERAL SCOPE NOTES**
- MASONRY REPAIR SCOPE OF WORK TO BE PRICED ACCORDING TO UNIT PRICE TABLE.
 - STONES MARKED FOR REPLACEMENT THAT ARE DEEMED BY THE CONSULTANT TO BE PARTIALLY OR WHOLLY IN SOUND CONDITION UPON REMOVAL ARE TO BE SALVAGED AND STORED FOR LATER REUSE.
 - PROVIDE GRAVEL UNDER ENDS OF GUTTER LOCATIONS.
 - CLEAN 100% OF ALL MASONRY INCLUDING LOCALIZED AREAS OF SPECIALIZED CLEANING TO REMOVE COPPER STAINING AND BIOLOGICAL GROWTH.

- NOTES**
- REMOVE AND DISPOSE OF EXISTING WOOD QUARTER ROUND TO ALLOW FOR MASONRY REPOINTING.
 - REMOVE AND DISPOSE OF EXISTING COPPER ROOF FLASHING, & UNDERLAYMENT.
 - REMOVE AND DISPOSE OF EXISTING COPPER FLASHING AT JUNCTION OF VESTIBULE AND MAIN STRUCTURE TO ALLOW FOR MASONRY REPOINTING.
 - REMOVE AND SALVAGE EXISTING WINDOW SHUTTERS AND DOOR TO ALLOW FOR MASONRY REPOINTING & REINSTATE AFTER COMPLETION.
 - REMOVE AND DISPOSE OF EXISTING COPPER GUTTER.
 - INSTALL NEW UNDERLAYMENT, COPPER ROOF, & FLASHING.
 - INSTALL NEW 150mm X 100mm COPPER GUTTER. SLOPE GUTTER 2% IN EITHER DIRECTION FROM MID-POINT OF ROOF.
 - INSTALL NEW STEP COPPER FLASHING IN REGLET AFTER REPOINTING IS COMPLETED.
 - INSTALL NEW WOOD QUARTER ROUND IMPREGNATED WITH LINSEED OIL. SIZE TO MATCH EXISTING.
 - REINSTATE WINDOW SHUTTERS AND DOORS.
 - CLEAN COPPER AND BRONZE PANELS, HINGES, AND HARDWARE. REFER TO SPECIFICATION SECTION 07.61.00.
 - REMOVE AND DISCARD INCOMPATIBLE COPPER OR BRONZE HARDWARE AND INSTALL NEW COPPER OR BRONZE HARDWARE.

ARCHITECTS:

EVOO

366 ADELAIDE ST. EAST, SUITE 225
TORONTO (ONTARIO) M5A 3X9
T. 647-723-2030

ENGINEERS:

ojdrovic engineering

4195 DUNDAS ST. W., SUITE 233
TORONTO, ON M8X 1Y4
T. 416-925-0333

SEALS:

NO.	DATE	DESCRIPTION	Drawn by	Approved
3	12/19/19	TENDER SUBMISSION	RM	DC
2	10/01/19	99% SUBMISSION	RM	DC
1	08/16/19	FHBR REVIEW	RM	DC

REVISIONS

NO.	DATE	DESCRIPTION	Drawn by	Approved
3	12/19/19	TENDER SUBMISSION	RM	DC
2	10/01/19	99% SUBMISSION	RM	DC
1	08/16/19	FHBR REVIEW	RM	DC

Linear dimensions in millimeters / Dimensions lineaires en millimetres

Parcs Canada / Parks Canada

Canada

PARKS CANADA
SOUTHWESTERN ONTARIO FIELD UNIT

Type of Record / Type d'enregistrement

Project title / Titre du projet
FORT GEORGE NATIONAL HISTORIC SITE POWDER MAGAZINE


Drawing title / Titre du dessin
WINDOW EXISTING CONDITION & CONSTRUCTION

Plot Scale / Echelle
1:10


Drawn by / Dessine par RM/JM	Date 12/19/19
Field Recording by / Releve-Termin par DC/JM/RM	Date 12/19/19
Approved by / Approuve par DC	Date 12/19/19
Checked by / Verifie par DC	Date 12/19/19

Project No./ No. du projet 001504-010	Asset No. 1202269	Sheet No./ Feuille No. A4
--	----------------------	------------------------------


Drawing Re No./No. du Dessin




1 D01 EXT. ELEVATION
A5 1:10




2 D01 INT. ELEVATION
A5 1:10




3 D01 SECTION
A5 1:10



4 D02 EXT. ELEVATION
A5 1:10



5 D02 INT. ELEVATION
A5 1:10



6 D02 TYP. HEADER AND JAMB DETAIL
A5 1:10

GENERAL NOTES:

- PRIOR TO COMMENCING WORK, THE CONTRACTOR OR SUBCONTRACTOR IS RESPONSIBLE FOR VERIFYING THE DIMENSIONS ON THE DRAWINGS AGAINST THE EXISTING BUILDING CONDITIONS. SCALED MEASUREMENTS ARE NOT TO BE TAKEN FROM THE DRAWINGS.
- ACCESS AND USE OF THE INTERIOR OF THE BUILDING MUST BE LIMITED AND APPROVED PRIOR.
- USE CAUTION WHEN PERFORMING ANY AND ALL WORK (INCLUDING DEMOLITION AND CONSTRUCTION) IN AREAS ADJACENT TO OR ABUTTING AGAINST HERITAGE ELEMENTS IN ORDER TO AVOID DAMAGE TO THE ORIGINAL HERITAGE FABRIC.
- ENSURE THAT OPENINGS INTO WORK AREAS CREATED BY THE REMOVAL OF DOORS OR WINDOWS ARE SECURED IN ORDER TO RESTRICT ACCESS BY THE GENERAL PUBLIC AND IN A MANNER THAT WILL NOT DAMAGE THE ADJACENT HERITAGE FABRIC.
- ALL HERITAGE MATERIAL THAT HAS BEEN REMOVED FOR RESTORATION AND REPAIR MUST BE REINSTALLED IN ITS ORIGINAL LOCATION UNLESS OTHERWISE INDICATED.
- PCA MUST BE CONTACTED WITHOUT DELAY UPON DISCOVERY OF UNDOCUMENTED EXISTING DAMAGE, DEFECTIVE OR UNSOUND MATERIALS OR CONSTRUCTION. ALL WORK IN THE IMMEDIATE AREA IS TO CEASE PENDING FURTHER INSTRUCTIONS.
- PCA MUST BE INFORMED UPON DISCOVERY OF ANY UNDOCUMENTED HERITAGE MATERIALS. ALL WORK IN THE IMMEDIATE AREA IS TO CEASE PENDING FURTHER INSTRUCTIONS.
- IT IS THE CONTRACTOR'S RESPONSIBILITY TO ENSURE THAT ALL REGULATORY PROCEDURES WITH REGARDS TO DESIGNATED SUBSTANCES ARE ADHERED TO ON SITE AND IN ALL WORK AREAS. ALL PAINT CONTAINING LEAD, MORTARS CONTAIN SILICA, AND IT IS ASSUMED THAT THE CAULKING CONTAINS ASBESTOS.
- PRIOR TO DISMANTLING OR REMOVING AN ELEMENT OR ASSEMBLY, PHOTOGRAPH, MEASURE AND FULLY DOCUMENT IT INCLUDING EACH OF ITS COMPONENTS, THEIR MATERIALS AND CONSTRUCTION. NUMBER AND IDENTIFY EACH ELEMENT AS PER SPECIFICATIONS.
- ALL REQUIRED DOCUMENTATION MUST BE SUBMITTED AND REVIEWED PRIOR TO STARTING ANY DEMOLITION OR DISMANTLING WORK.
- ALL STONE THAT IS TO BE REMOVED AND STORED MUST FIRST BE INVENTORIED, CATALOGUED, PHOTOGRAPHED AND CLEARLY IDENTIFIED IN ACCORDANCE TO THE RECOMMENDATIONS DESCRIBED IN THE SPECIFICATIONS.
- ALL DOORS, FRAMES, CASINGS, WINDOWS, SHUTTERS, AND HARDWARE TO BE REMOVED AND STORED MUST FIRST BE INVENTORIED, CATALOGUED, PHOTOGRAPHED AND CLEARLY IDENTIFIED WITH THE NUMBER INDICATED ON THESE DRAWINGS AND IN ACCORDANCE TO THE RECOMMENDATIONS DESCRIBED IN THE SPECIFICATIONS.
- ROOFING INSTALLATION WORK PROCEEDING CONCURRENTLY WITH DISMANTLING WORK SHALL BE SEQUENCED IN SUCH A WAY TO MINIMIZE THE AREA EXPOSED TO WEATHER. PROVIDE NECESSARY RAIN AND WIND RESISTANT INSTALLATIONS TO PROTECT EXPOSED PORTIONS OF THE BUILDING FROM WATER INFILTRATION.

GENERAL SCOPE NOTES

- MASONRY REPAIR SCOPE OF WORK TO BE PRICED ACCORDING TO UNIT PRICE TABLE.
- STONES MARKED FOR REPLACEMENT THAT ARE DEEMED BY THE CONSULTANT TO BE PARTIALLY OR WHOLLY IN SOUND CONDITION UPON REMOVAL ARE TO BE SALVAGED AND STORED FOR LATER REUSE.
- PROVIDE GRAVEL UNDER ENDS OF GUTTER LOCATIONS.
- CLEAN 100% OF ALL MASONRY INCLUDING LOCALIZED AREAS OF SPECIALIZED CLEANING TO REMOVE COPPER STAINING AND BIOLOGICAL GROWTH.

NOTES

- REMOVE AND DISPOSE OF EXISTING WOOD QUARTER ROUND TO ALLOW FOR MASONRY REPOINTING.
- REMOVE AND DISPOSE OF EXISTING COPPER ROOF FLASHING, & UNDERLAYMENT.
- REMOVE AND DISPOSE OF EXISTING COPPER FLASHING AT JUNCTION OF VESTIBLE AND MAIN STRUCTURE TO ALLOW FOR MASONRY REPOINTING.
- REMOVE AND SALVAGE EXISTING WINDOW SHUTTERS AND DOOR TO ALLOW FOR MASONRY REPOINTING & REINSTATE AFTER COMPLETION.
- REMOVE AND DISPOSE OF EXISTING COPPER GUTTER.
- INSTALL NEW UNDERLAYMENT, COPPER ROOF, & FLASHING.
- INSTALL NEW 150mm X 100mm COPPER GUTTER. SLOPE GUTTER 2% IN EITHER DIRECTION FROM MID-POINT OF ROOF.
- INSTALL NEW STEP COPPER FLASHING IN REGLET AFTER REPOINTING IS COMPLETED.
- INSTALL NEW WOOD QUARTER ROUND IMPREGNATED WITH LINSEED OIL. SIZE TO MATCH EXISTING.
- REINSTALL WINDOW SHUTTERS AND DOORS.
- CLEAN COPPER AND BRONZE PANELS, HINGES, AND HARDWARE. REFER TO SPECIFICATION SECTION 07.61.00.
- REMOVE AND DISCARD INCOMPATIBLE COPPER OR BRONZE HARDWARE AND INSTALL NEW COPPER OR BRONZE HARDWARE.

ARCHITECTS:

EVOO

366 ADELAIDE ST. EAST, SUITE 225
TORONTO (ONTARIO) M5A 3X9
T. 647-723-2030

ENGINEERS:

ojdrovic engineering

4195 DUNDAS ST. W., SUITE 233
TORONTO, ON M8X 1Y4
T. 416-925-0333

SEALS:



NO.	DATE	DESCRIPTION	Drawn by	Approved
3	12/19/19	TENDER SUBMISSION	RM	DC
2	10/01/19	99% SUBMISSION	RM	DC
1	08/16/19	FHBR REVIEW	RM	DC

REVISIONS

A	B	Detail number	Sheet number	A Numero de detail	B Sur feuille numero
---	---	---------------	--------------	--------------------	----------------------

Linear dimensions in millimeters / Dimensions lineaires en millimetres



Canada

PARKS CANADA
SOUTHWESTERN ONTARIO FIELD UNIT

Type of Record / Type d'enregistrement

Project title / Titre du projet

FORT GEORGE NATIONAL HISTORIC
SITE POWDER MAGAZINE

Drawing title / Titre du dessin

DOOR EXISTING
CONDITION &
CONSTRUCTION

Plot Scale / Echelle

AS NOTED

Drawn by/ Dessine par: RM Date: 12/19/19

Field Recording by / Releve-Temoin par: DC/JM/RM Date: 12/19/19

Approved by / Approuve par: DC Date: 12/19/19

Checked by/ Verifie par: DC Date: 12/19/19

Project No./ No. du projet: 001504-010 Asset No.: 1202269

Sheet No./ Feuille No.: A5

Drawing Re No./No. du Dessin