



- 1 CONCEALED 19mm PLYWOOD BLOCKING WITHIN PARTITION TO SUPPORT MONITORS (BY OTHERS). AT BRICK WALL LOCATIONS, PLYWOOD IS NOT REQUIRED, BRICK NEEDS TO BE DRILLED TO ALLOW FOR MOUNTING HARDWARE. REFER TO DEPARTMENTAL REPRESENTATIVES DRAWINGS FOR LOCATIONS AND MOUNTING HEIGHTS AND PROPORTIONS.
- 2 FLOOR DRAIN UNDER BANQUETTE TO HAVE A NEW GRATE IN BLACK FINISH. REFER TO MECHANICAL DRAWINGS.
- 3 CLEAN, PATCH, AND REPAIR ALL EXPOSED SIDES AND EDGES OF EXISTING BASE BUILDING BRICK ELEMENTS TO BE LEFT EXPOSED IN NEW DESIGN
- 4 CONCRETE COLUMNS TO BE CLEANED ON ALL EXPOSED SIDES AND EDGES. PATCHED REPAIR FOLLOWING PARTITION OR FURRING REMOVAL. FILL IN UNUSED PENETRATIONS MATCHING CONCRETE MIXTURE.
- 5 CLEAN, PATCH AND REPAIR ALL EXPOSED SIDES AND EDGES OF EXISTING BASE BUILDING CONCRETE ELEMENTS TO BE LEFT EXPOSED IN NEW DESIGN.
- 6 ELECTRICAL CABLEING TO BE BROUGHT THROUGH EXISTING SERVER ROOM INTO MEN'S WASHROOM. REMOVAL & PATCHING TO BE DONE TO EXISTING BRICK IN SERVER ROOM AND DRYWALL ABOVE CEILING ON 8TH FLOOR. REFER TO ENGINEER'S DRAWINGS FOR SCOPE OF WORK.
- 7 FHC CABINET- REFER TO MECHANICAL DRAWINGS.
- 8 EXISTING WOOD COMPONENTS OF RAILINGS ALONG ENTIRE PERIMETER TO BE REMOVED, SANDED & RE-STAINED TO MATCH PL.1. DEPARTMENTAL REPRESENTATIVE TO APPROVE SAMPLE.
- 9 PARTIALLY FILLED WALL TO BE COMPLETELY PATCHED, MADE GOOD & PAINTED.
- 10 NEW WINDOW SHADES TO BE INSTALLED ON ENTIRE PERIMETER. TYPICAL WINDOW OPENING BETWEEN MULLIONS IS 1423MM WIDE BY 2032MM HIGH- TO BE VERIFIED ON SITE.