



Parks Canada (PCA) – Wood Buffalo NP  
Hay Camp Rd – Culvert Washout Inspection



Aug, 2020 condition: photo taken looking east toward Slave river.



Aug, 2020 condition: photo looking west toward unnamed tributary.



Aug, 2020 condition: both ~600mm dia. existing culverts to be removed.



Aug, 2020 condition: in-situ material is damp silty/ clayey gravel.



Aug, 2020 condition: west side slope on upstream (unnamed tributary) side.



Aug, 2020 condition: east side slope on downstream (Slave river) side.