LaSalle Causeway

Deck Grating Inspection and Repair Report

PWGSC Project No. R.082857.001

Prepared for: Public Works Government Services Canada

Prepared by:



1223 Michael Street Suite 100 Ottawa, ON K1J 7T2

March 2017

476073-012010

TABLE OF CONTENTS

1. 2.		RODUCTION
	2.1 2.2	STRUCTURE DESCRIPTION
3. 4.		PECTION METHODOLOGY2 MARY OF SIGNIFICANT FINDINGS2
	4.1 4.2 4.3 4.4	SERRATED WEARING SURFACE
		4.4.1 East Abutment
	4.5	GRATING FAILURE
5.	REC	OMMENDED SHORT-TERM REPAIRS4
	5.1 5.2 5.3	IMPACT DAMAGE
6. 7. 8. 9.	COS [.] CON	STRUCTION DURATION, STAGING AND TRAFFIC MANAGEMENT4 T ESTIMATE OF SHORT-TERM REPAIRS5 CLUSIONS5 SURE

LIST OF TABLES

Table 1: Cost Estimate for Short-term Re	pairs to Deck Grating5

LIST OF FIGURES

Figure	1: Key Pl	lan1	l
--------	-----------	------	---

APPENDICES

APPENDIX ASITE INSPECTION PHOTOGRAPHSAPPENDIX BDECK GRATING DETERIORATION DRAWINGS & SUGGUESTED SHORT-
TERM REPAIR DETAILS

1. INTRODUCTION

The LaSalle Causeway, owned and operated by PWGSC, carries County Road No. 2 across the Cataraqui River within the City of Kingston, providing a critical transportation link between the downtown area on the west side of the river with the Barriefield/CFB Kingston area on the east side of the river. Approximately 23,000 vehicles cross the Causeway daily. The bascule bridge provides marine access to the inner harbour of Kingston, lifting an average of 900 times per year, and access to the southern entrance of the Rideau Canal. Construction was completed on April 15, 1917. The Bascule Bridge is a single leaf Strauss heel trunnion bascule bridge with a roadway width of 7.32m which carries one eastbound and one westbound traffic lane on an open steel deck grating.

In March 2017, Parsons was retained by Public Works and Government Services Canada (PWGSC) to complete an emergency inspection of the steel deck grating on the Bascule Bridge, following an observed hole in the deck grating on February 27, 2017. The hole in the grating was repaired by George A Wright, a sub-contractor to Louis W. Bray who was on site to complete the replacement of span locks contract. The repair consisted of welding a temporary plate over the hole, which was completed on the same day.

This report documents the location and quantity of defects detected during the inspection as well as outlines short term repairs of the steel deck grating and a permanent repair of the hole in the grating.






Figure 1: Key Plan

2. EXISTING CONDITIONS

2.1 Structure Description

The Bascule Bridge is a single leaf Strauss heel trunnion bascule bridge, designed by The Strauss Bascule Bridge Co. of Chicago, and constructed in 1916. The main span of the bridge consists of a Modified Warren through truss with a span length of 48.77 m (160'). The center-to-center truss width is 8.23 m (27') and the center of bottom chord to center of top chord height varies from the east end to the west end from 6.10 m (20') to 7.92 m (26'). The concrete counterweight weighs approximately 500 tonnes (1,100,000 lbs).

The roadway width on the bridge of 7.32 m (24') carries one eastbound and one westbound vehicular traffic lane on an open steel deck grating (Photo 1). A 1.2 m (4') wide timber plank sidewalk is cantilevered on exterior of the south truss. The posted vertical clearance on the bridge is 4.2 m.

The steel grating was replaced was designed in 1973 and built in 1976 based on the as-built contract drawings "LaSalle Causeway – Repairs to Bridges" by C.C. Parker. The steel grating consists of 25mm x 6mm (1" x 1⁄4") transverse cross bars supported on 64mm x 6mm (2 1⁄2" x 1⁄4") longitudinal bearing bars that are supported on small transverse rolled I-beam sills. The longitudinal bearing bars are welded to every second steel sill and the cross-bars are fillet welded to the bearing bars in one alternating corner at each intersection. The opening size of the grating is approximately 57mm (2 1⁄4") x 54mm (2 1/8"). There are 63 grating panels on the bascule bridge, 7 panels transversely (A-G) and 9 panels longitudinally (0-16, based on the nodes of the truss starting from the east). The longitudinal panel joints are centered on the steel sills and the cross-bars and the bearing bars are separated by an angle at approximately 318mm (1' – 1/2") spacing. Both the cross-bars and the bearing bars were originally serrated to provide traction for vehicular traffic.

2.2 Data Collection and Review

The following reference material was reviewed and used in the inspection of the bridge and preparation of this report:

- 1. "LaSalle Causeway Repairs to Bridges" As-Built Drawings, PWGSC Project Number 81254, prepared by C.C. Parker and Associates Limited, March 1973.
- 2. "LaSalle Causeway 2016 Annual Comprehensive Detailed (Bascule) & General Inspection Report", PWGSC Project No. R.055058.002, prepared by Parsons, March 2017.

3. INSPECTION METHODOLOGY

On March 8, 2017, Maurice Mansfield, CEng, P.Eng., Amir Tehranian E.I.T., and Cara Waddell, E.I.T. from Parsons conducted the steel deck grating inspection during a night time closure of the bridge. The bridge was closed between 9:00pm and 6:00am and the traffic was detoured to conduct the inspection. The inspection included hammer sounding of the deck grating system to determine if there are any loose bars or broken welds, mapping of all defects and removal of the temporary steel plate to further investigate the cause of the steel failure which created the hole in the deck grating. Two samples of the bearing bars were removed from the piece of grating that failed for further investigation.

4. SUMMARY OF SIGNIFICANT FINDINGS

The steel deck grating of the Bascule Bridge at the LaSalle Causeway is in fair condition with localized areas in poor condition. Appendix A includes various photographs showing the condition of the steel deck grating. Refer to steel deck grating deterioration drawings in Appendix B for the location and type of deterioration.

4.1 Serrated Wearing Surface

The steel deck grating has serrated edges to provide traction to vehicular traffic. The serrated edge on the grating has been completely worn away on both the cross bars and the bearing bars within the wheel tracks in each vehicular lane (Photo 2). In addition, the bearing bars are worn up to an additional 3mm in between cross-bars. This deterioration is typical as the steel grating is over 41 years old and has 23000 vehicles crossings a day. The steel grating no longer provides the same slip resistance as designed due to the wearing of the serrated surface. This could increase vehicle braking distances in poor weather conditions.

4.2 Coating

The as-built drawings do not indicate what protective coating was originally applied to the grating. However presumably there was some form of coating. The coating of the grating has typically worn away and the steel grating has light corrosion on the vertical faces of the cross bars and bearing bars and medium corrosion along the north and south curb face (Photo 3). Portions of the steel grating were over sprayed when they were coating the steel sills during the coating contract in 2010.

4.3 Debris

It was noted that there is concrete and debris in the grating in several locations over the transverse sills at the east abutment (Photo 4). This may have been placed to protect the corroded transverse sills and prevent salt-laden water from collecting on the transverse sills. When in fact, the salt-laden water infiltrates the concrete which increases the rate of deterioration of the steel below.

4.4 Impact Damage

Most of the deterioration on the bridge has been caused by impact damage and has caused numerous transverse cross bars to either bend and deform or completely break off at the bearing bar interface (Photos 5 to 7). The deformed/ broken bars can be contributed to impact damage from vehicular traffic as the bars are generally deformed in the direction of traffic. There is one localized area in the middle of the deck grating that has multiple broken and bent transverse cross-bars and bent longitudinal bearing bars (Photo 8). This could have been caused due to impact with a defective vehicle component or impact from a snow plow.

4.4.1 East Abutment

The condition of the grating at the east abutment is worse than the rest of the bridge with significant damage. This is due to the elevation difference between the abutment and the steel grating. The steel grating is 16mm higher than the abutment on the south side and 11mm higher on the north side. On the south side at the curb face, there is a 450mm long steel angle, that is welded to the steel grating to prevent further impact damage (Photo 9). The end cross-bar which protects the end of the of the bearing bars only extends 2250mm from the south curb (Photo 10). There is one location on the south side that multiple cross-bars have been deformed and there is an enlarged opening where a couple of transverse cross-bars and longitudinal bearing bars have broken (Photo 11). In the west bound lane (north side), there is four broken transverse cross-bars which expose the edges of the bearing bars which may cause vehicular damage (Photo 12). During the inspection, Parsons directed Eastern Fluid Power (EFP) to weld a temporary steel plate over the grating at this location to protect vehicles from any damage (Photo 13).

4.5 Grating Failure

As observed on February 27, 2017, a large piece of grating failed and broke off from the remaining grating and the transverse sill beneath (Photo 14). The piece of grating was approximately six openings wide by seven openings long (370mm wide by 420mm long) centered about the interface between panels C and D in bay 10-12 (Photo 15). The piece of grating was centered over one of the transverse sills (Photo 16).

Multiple cracks were observed in the piece that broke free and the bearing bars surrounding the opening. Most of the cracks propagated from the notch for the cross-bars and extended to the base of the metal (Photo 17 to 20). It appears from the wearing of the base of the longitudinal bearing bars at the sill that the welds had failed between the sills and the bearing bars first which caused the portion of the grating to vibrate which placed additional stress on the bearing bars which caused them to crack and fail (Photo 21). There are multiple cross-bars and bearing bars missing which may have completely broken off from the piece and fallen into the river (Photo 22). There are multiple bent transverse cross-bars adjacent to the grating failure but did not appear to be the cause of the grating failure (Photo 23). It should be noted that the longitudinal splice angle that is welded between the bearing bars of the two adjacent panels remained intact and kept the two panels together (Photo 15).

5. RECOMMENDED SHORT-TERM REPAIRS

The following are recommended short term repairs that should be completed within the next year to prevent further deterioration of the steel deck grating. Appendix B includes the drawings for the short-term repairs.

5.1 Impact Damage

At every location where there are broken transverse cross bars or three or more consecutive bent transverse cross bars, an angle should be welded between the two bearing bars similar to the angle provided as a longitudinal splice between adjacent panels. An additional angle will be required every three openings for bent transverse bars. It is anticipated that the 75 additional angles will be required as seen in Drawing 01 in Appendix B.

5.2 East Abutment

The first eight openings from the east end including the existing armouring angle at the south end and the temporary steel plate repair in the west bound lane should be replaced with new grating with an armouring angle. The armouring angle is to prevent any further damage from impact due to the elevation difference. The splice of the new and existing grating panels is to be centered over the first transverse sill from the east and welded to a new trim bar.

The concrete / debris at the east end of the bridge over the transverse sills should be removed to decelerate the corrosion of the steel sills.

The elevation difference between the approach and deck should be rectified under ongoing steel repairs for the span locks.

5.3 Grating Failure

The repair area for the existing opening in the grating would extend beyond the limits of the broken grating to the next transverse sill to the east and west making the repair approximately 915mm long (3') and extend the repair area transversely by 5 additional openings on each side making it approximately 955mm wide. The longitudinal splices will require four new angles welded on each side to the adjoining panels and the transverse splices will require a new trim bar for the existing and new panels to be welded to.

6. CONSTRUCTION DURATION, STAGING AND TRAFFIC MANAGEMENT

A full bridge closure would be required to complete the deck grating repairs. The work is estimated to take five nights between the hours of 9:30pm and 6:00am as specified by the City of Kingston. A detour would be created directing traffic to cross the Cataraqui River by the Highway 401 bridge via Montreal Street and Highway 15.

7. COST ESTIMATE OF SHORT-TERM REPAIRS

The Class 'C' Cost Estimate for the repairs to the steel deck grating on the LaSalle Causeway is \$48,000. The cost estimate includes a 15% contingency allowance and is based on 2017 construction prices, but excludes the detailed repair drawings, engineering oversight and HST. The detailed breakdown of the work items and cost estimate is provided in Table 1. The cost estimate is based on recent construction costs available and Parsons' own databases.

LaSalle Cau	seway - Bascule Bridge - Steel Deck Grating Repairs					
ltem No.	Item Description	Unit	Quantity	Unit Rate	Total Cost	% of Total
1	Traffic Control (Bridge Shutdowns)	LS	5	\$2,000	\$10,000	24.24%
2	Removal of Existing Steel Grating	m2	4	\$500	\$2,000	4.85%
3	Installation of New Steel Grating	m2	4	\$3,500	\$14,000	33.94%
4	Installation of New Steel Angle at East Abutment	m	7	\$500	\$3,500	8.48%
5	Installation of Angles for Bent and Broken Cross-Bars	Each	75	\$150	\$11,250	27.27%
5	Remove Concrete/ Debris from Grating	LS	1	\$500	\$500	1.21%
				Sub-total	\$41,250	100.00%
			Conting	ency (15%)	\$6,188	
			Total Estir	nated Cost	\$48,000	

8. CONCLUSIONS

Based on the inspection completed on March 8, 2017 by Parsons, the steel deck grating on the Bascule Bridge is in fair condition with localized areas in poor condition. The following short term repairs are recommended to be completed within the next year:

- Replace the steel grating from 450mm from the east abutment;
- Install a steel angle along the east end of the deck to prevent further impact damage due to the elevation difference;
- Correct elevation difference at east abutment;
- Replace a portion of the grating at the location of the grating failure;
- Install steel angles at locations of bent or broken transverse cross-bars; and
- Remove the debris / concrete in the grating over the transverse sills at the east abutment.

This repair work is anticipated to be completed during five night closures between 9 pm and 6 am and cost approximately \$48,000.

In the medium term, it is expected that the steel grating will reach the end of its service life. As is, it no longer has any serrated edges along the wheel path, and is starting to exhibit medium corrosion in localized areas. Local repairs due to fractures and broken welds can be expected as it nears the end of its service life.

It is recommended that capital allowances are made to replace the entire steel deck grating in the 6 to 10year timeframe.

9. CLOSURE

We trust that this report contains sufficient information for your present purposes. If you have any questions regarding this report, please contact us.

Yours truly,

PARSONS INC.

Prepared by: Cara Waddell, M.Eng., E.I.T. Structural Designer Reviewed by: Maurice Mansfield, M.Phil, CEng, P.Eng. Senior Structural Engineer – Project Manager APPENDIX A

SITE INSPECTION PHOTOGRAPHS



Photo 1: General view of the steel grating on the Bascule bridge looking from the east approach.




Photo 2: Loss of serrated edge on both cross-bars and bearing bars and profile of bearing bars



Photo 3: Light to medium corrosion of cross bars and bearing bars at the north curb by the west abutment.



Photo 4: Debris in the grating at the east abutment (Photo on left taken in September 2015)



Photo 5: Multiple bent transverse cross-bars (C8-10 at 64-6) - typical at multiple locations



Photo 6: Bent Transverse Cross-Bar (Typical throughout)



Photo 7: Broken Bars at (D14-15 at row 4)



Photo 8: Broken and Bent Transverse Cross-Bars (12-14 at 1-13)



Photo 9: Armouring at south side at east abutment.



Photo 10: End cross-bar terminates 2.2 metres from the south curb.



Photo 11: Broken and bent cross-bars and bearing bars at east abutment



Photo 12: Condition of grating at east abutment prior to temporary repair.



Photo 13: Temporary steel plate repair at east abutment.




Photo 14: Broken piece of grating at the center of the bridge in the eastbound lane.




Photo 15: Piece of grating that broke loss.



Photo 16: Size of opening in grating over transverse sill.



Photo 17: Crack in bearing bar propagating from notch for cross bar at sill. Adjacent to piece that was broken off.



Photo 18: Crack in Bearing bar propagating from cross bar notch.



Photo 19: Crack in bearing bar propagating from notch in sample taken from piece that failed.



Photo 20: Crack in bearing bar propagating from cross bar notch.



Photo 21: Wearing of base of bearing bars at sill location.




Photo 22: Piece of grating that broke off in opening.



Photo 23: Bent Transverse Bars at location of grating hole

APPENDIX B

DECK GRATING DETERIORATION DRAWINGS & SUGGUESTED SHORT-TERM REPAIR DETAILS



RECOMMENDED REPAIRS:


- (1)REMOVE AND REPLACE STEEL GRATING AT GRATING FAILURE.
- (2)REMOVE AND REPLACE STEEL GRATING AT EAST END.
- $(\overline{\mathcal{S}})$ REMOVE DEBRIS/CONCRETE FROM GRATING AT EAST END.
- (4)INSTALL ANGLES FOR BENT AND BROKEN CROSS-BARS.

LEGEND:


- NEW STEEL DECK GRATING
- \bigotimes NEW STEEL ANGLE BETWEEN BEARING BARS
- CONCRETE/DEBRIS IN GRATING


RANGEMENT	JS drawn by	dessine par	17-03-2 project date	
ED REPAIRS	CW designed by	conc par		357.001
	MM approved by	approuve par	project no.	no. du projet
ONS	tender p	roject manager nistrateur de projets	01 OF drawing no.	65 dessine no.
	sournission dunn	matratear de projeta		

DATE PLOTTED: Monday, March 27, 2017 1:58:55 PM




CAD FILE: H:\ISO\476073\12010 Grating System Inspection And Repair Phase 1\Dwgs\Bascule Bridge Deck Inspection.dwg







DEFECT No.	DESCRIPTION
1	ABRASION
2	BROKEN LONGITUDINAL BAR
3	BROKEN LONGITUDINAL BAR
4	DEBRIS
5	DEBRIS
6	BENT LONGITUDINAL BAR
7	BENT TRANSVERSE BAR
8	DEBRIS
8	DEBRIS BROKEN LONGITUDINAL BAR
9	BROKEN LONGITUDINAL BAR



CAD FILE: H:\ISO\476073\12010 Grating System Inspection And Repair Phase 1\Dwgs\Bascule Bridge Deck Inspection GRATING 0-2.dwg








DEFECT No.	DESCRIPTION
1	ABRASION
2	BENT TRANSVERSE BAR
3	BENT TRANSVERSE BAR
4	BENT TRANSVERSE BAR
5	BENT TRANSVERSE BAR
6	BENT TRANSVERSE BAR
7	BENT TRANSVERSE BAR
8	BENT TRANSVERSE BAR
9	DEBRIS
10	DEBRIS
11	BENT TRANSVERSE BAR
12	DEBRIS
13	BENT TRANSVERSE BAR
14	BENT TRANSVERSE BAR
15	SEVERELY BENT AND BROKEN TRANSVERSE BARS
16	BENT STEEL END PLATE
17	BROKEN TRANSVERSE BAR

1615 14 12 10 8 6 4 2 0 G G G G G G G G G G G G G G G G G G G	Public Works and Government Services Canada Architectural and Engineering Services Ontario Region Travaux publics et Services gouvernementaux Canada Services d'architecture et de génie Région de l'Ontario	project title titre du projet LASALLE CAUSEWAY BASCULE BRIDGE KINGSTON ONTARIO DECK GRATING REPAIRS	drawing title titre du dessin BRIDGE GRATING DETERIORATIONS PARSONS	JS drawn by dessine par CW designed by conc par MM approved by approuve par tender project manager sournission administrateur de projets	04 OF 65
0\476073\12010 Grating System Inspection And Repair Phase 1\Dwas\Bascule Bridge Deck Inspection GRATING	0-2 dwg			DATE PLOTTED: Monday	March 27 2017 1:49:54 PM




DEFECT No.	DESCRIPTION	DEFECT No.	DESCRIPTION
1	ABRASION	17	BENT TRANSVERSE BAR
2	BENT TRANSVERSE BAR	18	BENT TRANSVERSE BAR
3	BENT TRANSVERSE BAR	19	BENT TRANSVERSE BAR
4	BENT TRANSVERSE BAR	20	BENT TRANSVERSE BAR
5	BENT TRANSVERSE BAR	21	BENT TRANSVERSE BAR
6	BENT TRANSVERSE BAR	22	BROKEN LONGITUDINAL BAR
7	BROKEN TRANSVERSE BAR	23	BROKEN LONGITUDINAL BAR
8	BENT TRANSVERSE BAR	24	BROKEN TRANSVERSE BAR
9	BENT TRANSVERSE BAR	25	BROKEN TRANSVERSE BAR
10	BENT TRANSVERSE BAR	26	BENT TRANSVERSE BAR
11	BENT TRANSVERSE BAR	27	BROKEN TRANSVERSE BAR
12	BROKEN TRANSVERSE BAR	28	BENT TRANSVERSE BAR
13	BENT TRANSVERSE BAR	29	BROKEN TRANSVERSE BAR
14	BENT TRANSVERSE BAR	30	BENT TRANSVERSE BAR
15	BENT TRANSVERSE BAR	31	AREA OF BROKEN TRANSVERSE BARS
16	BROKEN TRANSVERSE BAR		

6

4

2

 \cap



1:20

95-09
C-A3A

D D			

1615 14 12 10 8

∎┿∎

Public Works and Government Services Canada Architectural and Engineering Services Ontario Region

Travaux publics et Services gouvernementaux Canada Services d'architecture et de génie Région de l'Ontario


project title titre du projet LASALLE CAUSEWAY BASCULE BRIDGE KINGSTON ONTARIO DECK GRATING REPAIRS

drawing title titre du dessin BRIDGE GRATING

DETERIORATIONS

CAD FILE: H:\ISO\476073\12010 Grating System Inspection And Repair Phase 1\Dwgs\Bascule Bridge Deck Inspection GRATING 0-2.dwg






 $\frac{O-2 - D}{1:20}$


DEFECT No.	DESCRIPTION	DEFECT No.	DESCRIPTION
1	BROKEN TRANSVERSE BAR	12	BROKEN LONGITUDINAL BAR
2	BENT TRANSVERSE BAR	13	BROKEN LONGITUDINAL BAR
3	BROKEN TRANSVERSE BAR	14	BROKEN LONGITUDINAL BAR
4	BROKEN LONGITUDINAL BAR	15	BROKEN LONGITUDINAL BAR
5	BENT TRANSVERSE BAR	16	BROKEN LONGITUDINAL BAR
6	BROKEN TRANSVERSE BAR	17	BROKEN LONGITUDINAL BAR
7	BROKEN TRANSVERSE BAR	18	BROKEN LONGITUDINAL BAR
8	BROKEN LONGITUDINAL BAR	19	BROKEN LONGITUDINAL BAR
9	BROKEN TRANSVERSE BAR	20	BROKEN LONGITUDINAL BAR
10	BROKEN TRANSVERSE BAR	21	BROKEN LONGITUDINAL BAR
11	BROKEN TRANSVERSE BAR		



CAD FILE: H:\ISO\476073\12010 Grating System Inspection And Repair Phase 1\Dwgs\Bascule Bridge Deck Inspection GRATING 0-2.dwg








CAD FILE: H:\ISO\476073\12010 Grating System Inspection And Repair Phase 1\Dwgs\Bascule Bridge Deck Inspection GRATING 0-2.dwg

DATE PLOTTED: Monday, March 27, 2017 1:50:39 PM



1:20


					1.20		
DEFECT No.	DESCRIPTION	DEFECT No.		DESCRIPTION	DEFECT No	DESCRIPT	ION
1	ABRASION	22	BENT TRANSVER	RSE BAR	43	BROKEN TRANSVERSE BA	R
2	AREA OF BROKEN TRANSVERSE BARS	23	BROKEN TRANSVERSE BAR		44	BROKEN TRANSVERSE BA	R
3	BROKEN TRANSVERSE BAR	24	BROKEN TRANS	ROKEN TRANSVERSE BAR 45		BROKEN TRANSVERSE BA	R
4	BROKEN TRANSVERSE BAR	25	BROKEN TRANS	verse bar	46	BROKEN TRANSVERSE BA	R
5	BROKEN TRANSVERSE BAR	26	BROKEN TRANS	verse bar	47	BROKEN TRANSVERSE BA	R
6	BROKEN TRANSVERSE BAR	27	BROKEN TRANS	verse bar	48	BROKEN TRANSVERSE BA	R
7	BROKEN TRANSVERSE BAR	28	BROKEN TRANS	verse bar	49	BROKEN TRANSVERSE BA	R
8	BROKEN TRANSVERSE BAR	29	BENT TRANSVER	RSE BAR	50	BROKEN TRANSVERSE BA	R
9	BENT TRANSVERSE BAR	30	BENT TRANSVER	RSE BAR	51	BENT TRANSVERSE BAR	
10	BROKEN TRANSVERSE BAR	31	BENT TRANSVER	RSE BAR	52	BENT TRANSVERSE BAR	
11	BROKEN TRANSVERSE BAR	32	BENT TRANSVER	RSE BAR	53	BENT TRANSVERSE BAR	
12	BENT TRANSVERSE BAR	33	BENT TRANSVER	RSE BAR	54	BENT TRANSVERSE BAR	
13	BENT TRANSVERSE BAR	34	BENT TRANSVER	BENT TRANSVERSE BAR		BENT TRANSVERSE BAR	
14	BROKEN TRANSVERSE BAR	35	BENT TRANSVER	BENT TRANSVERSE BAR		BENT TRANSVERSE BAR	
15	BROKEN TRANSVERSE BAR	36	BENT TRANSVER	RSE BAR	57	BENT TRANSVERSE BAR	
16	BROKEN TRANSVERSE BAR	37	BENT TRANSVER	RSE BAR	58	BENT TRANSVERSE BAR	
17	BROKEN TRANSVERSE BAR	38	BROKEN TRANS	verse bar	59	BENT TRANSVERSE BAR	
18	BROKEN TRANSVERSE BAR	39	BROKEN TRANS	verse bar	60	BROKEN TRANSVERSE BA	R
19	BENT TRANSVERSE BAR	40	BROKEN TRANS	verse bar	61	BROKEN TRANSVERSE BA	R
20	BENT TRANSVERSE BAR	41	BROKEN TRANS	verse bar	62	BROKEN TRANSVERSE BA	R
21	BENT TRANSVERSE BAR	42	BROKEN TRANS	verse bar	63	BROKEN TRANSVERSE BA	R
					64	MISSING STEEL PLATE	
1615 G D C A	14 12 10 8 6	4 2		Public Works and Government Services Can Architectural and Engineering S Ontario Region Travaux publics et Services gouvernementaux Services d'architecture et de g	ervices x Canada	project title titre du projet LASALLE CAUSEWAY BASCULE BRIDGE KINGSTON ONTARIO DECK GRATING REPAIRS	drawing title titre du dessin BRIDGE GRATI DETERIORATION
				Région de l'Ontario			PARSO

CAD FILE: H:\ISO\476073\12010 Grating System Inspection And Repair Phase 1\Dwgs\Bascule Bridge Deck Inspection GRATING 0-2.dwg

- **-**



DATE PLOTTED: Monday, March 27, 2017 1:50:53 PM






DEFECT No.	DESCRIPTION	DEFECT No.	DESCRIPTION
1	ABRASION	13	BROKEN TRANSVERSE BAR
2	MISSING STEEL PLATE	14	BROKEN TRANSVERSE BAR
3	AREA OF BENT TRANSVERSE BARS	15	BROKEN TRANSVERSE BAR
4	BENT TRANSVERSE BAR	16	BROKEN TRANSVERSE BAR
5	BENT TRANSVERSE BAR	17	BROKEN TRANSVERSE BAR
6	BENT TRANSVERSE BAR	18	BROKEN TRANSVERSE BAR
7	BENT TRANSVERSE BAR	19	BROKEN TRANSVERSE BAR
8	BENT TRANSVERSE BAR	20	BROKEN TRANSVERSE BAR
9	BENT TRANSVERSE BAR	21	BROKEN TRANSVERSE BAR
10	BROKEN TRANSVERSE BAR	22	BROKEN TRANSVERSE BAR
11	BROKEN TRANSVERSE BAR	23	BROKEN TRANSVERSE BAR
12	BROKEN TRANSVERSE BAR	24	DEBRIS



CAD FILE: H:\ISO\476073\12010 Grating System Inspection And Repair Phase 1\Dwgs\Bascule Bridge Deck Inspection GRATING 0-2.dwg

	JS drawn by	dessine par	17-03-2 project date	27 date du projet
TING DNS	CW designed by	conc par	R.0828	357.001
	MAM		project no.	no. du projet
	MM approved by	approuve par		
ONG			09 OF	65
	tender pro soumission adminis	ject manager strateur de projets	drawing no.	dessine no.

DATE PLOTTED: Monday, March 27, 2017 1:51:08 PM




1615 14 12 10 8 6 4 2 0 G D C	Public Works and Government Services Canada Architectural and Engineering Services Ontario Region Travaux publics et Services gouvernementaux Canada	project title titre du projet LASALLE CAUSEWAY BASCULE BRIDGE KINGSTON ONTARIO	drawing title titre du dessin BRIDGE GRATING DETERIORATIONS	JS drawn by dessine par CW designed by conc par	17-03-27 project date du projet R.082857.001 project no. no. du projet
	Services gouvernementaux contradu Services d'architecture et de génie Région de l'Ontario	DECK GRATING REPAIRS	PARSONS	MM approved by approuve par tender project manager soumission administrateur de projets	10 OF 65 drawing no. dessine no.

CAD FILE: H:\ISO\476073\12010 Grating System Inspection And Repair Phase 1\Dwgs\Bascule Bridge Deck Inspection GRATING 2-4.dwg

SC-A3A 95-09

DATE PLOTTED: Monday, March 27, 2017 12:18:29 PM





CAD FILE: H:\ISO\476073\12010 Grating System Inspection And Repair Phase 1\Dwgs\Bascule Bridge Deck Inspection GRATING 2-4.dwg

.

	JS drawn by	dessine par	17-03-2 project date	
TING ONS	CW designed by	conc par	R.0828	857.001
	MM approved by	approuve par	project no.	no. du projet
ONS			11 OF	65
	tender soumission adm	project manager inistrateur de projets	drawing no.	dessine no.

DATE PLOTTED: Monday, March 27, 2017 12:18:32 PM






DEFECT No.	DESCRIPTION
1	ABRASION
	ABRASION
2	BENT TRANSVERSE BAR
3	BENT TRANSVERSE BAR
4	BENT TRANSVERSE BAR
5	BENT TRANSVERSE BAR
6	BENT TRANSVERSE BAR
7	BENT TRANSVERSE BAR
8	BENT TRANSVERSE BAR

GSC-A3A

1615 14 12 10 8 6 4 2 0 G D C A	Public Works and Government Services Canada Architectural and Engineering Services Ontario Region Travaux publics et Services gouvernementaux Canada Services d'architecture et de génie	project title titre du projet LASALLE CAUSEWAY BASCULE BRIDGE KINGSTON ONTARIO DECK GRATING REPAIRS	drawing title titre du dessin BRIDGE GRATING DETERIORATIONS	JS drawn by dessine par CW designed by conc par MM approved by approuve par	17-03-27 project date du projet R.082857.001 project no. no. du projet
	Région de l'Ontario	DECK GRATING REPAIRS	PARSONS	tender project manager soumission administrateur de projets	12 OF 65 drawing no. dessine no.

CAD FILE: H:\ISO\476073\12010 Grating System Inspection And Repair Phase 1\Dwgs\Bascule Bridge Deck Inspection GRATING 2-4.dwg

DATE PLOTTED: Monday, March 27, 2017 12:18:34 PM




1615 14 12 10 8 6 4 2 0 G G G G G G G G G G G G G G G G G G G	Public Works and Government Services Canada Architectural and Engineering Services Ontario Region Travaux publics et Services gouvernementaux Canada Services d'architecture et de génie Région de l'Ontario	project title titre du projet LASALLE CAUSEWAY BASCULE BRIDGE KINGSTON ONTARIO DECK GRATING REPAIRS	drawing title titre du dessin BRIDGE GRATII DETERIORATION
--	---	---	--


CAD FILE: H:\ISO\476073\12010 Grating System Inspection And Repair Phase 1\Dwgs\Bascule Bridge Deck Inspection GRATING 2-4.dwg


43A

SSC



DATE PLOTTED: Monday, March 27, 2017 12:18:35 PM





DEFECT No.	DESCRIPTION
1	ABRASION
2	BENT TRANSVERSE BAR
3	BENT TRANSVERSE BAR
4	BENT TRANSVERSE BAR
5	BENT TRANSVERSE BAR
6	BENT TRANSVERSE BAR
7	BENT TRANSVERSE BAR
8	BENT TRANSVERSE BAR


95-09

GSC-A3A

1615 14 12 10 8 6 4 2 0 G	Public Works and Government Services Canada Architectural and Engineering Services Ontario Region	project title titre du projet LASALLE CAUSEWAY BASCULE BRIDGE KINGSTON	drawing title titre du dessin BRIDGE GRATING DETERIORATIONS	JS drawn by dessine par CW designed by conc par	17-03-27 project date du projet R.082857.001
	Travaux publics et Services gouvernementaux Canada Services d'architecture et de génie Région de l'Ontario	ONTARIO DECK GRATING REPAIRS	PARSONS	MM approved by approuve par tender project manager soumission administrateur de projets	project no. no. du projet 14 OF 65 drawing no. dessine no.


CAD FILE: H:\ISO\476073\12010 Grating System Inspection And Repair Phase 1\Dwgs\Bascule Bridge Deck Inspection GRATING 2-4.dwg

DATE PLOTTED: Monday, March 27, 2017 12:18:36 PM






DEFECT No.	DESCRIPTION		
1	ABRASION		
2	BENT TRANSVERSE BAR		
3	BENT TRANSVERSE BAR		
4	BENT TRANSVERSE BAR		
5	BENT TRANSVERSE BAR		



	JS drawn by	dessine par	17-03-2 project date	
TING ONS	CW designed by	conc par	R.0828	357.001
	ММ		project no.	no. du projet
	approved by	approuve par	15 OF	65
	tender pr soumission admin	oject manager istrateur de projets	drawing no.	dessine no.

DATE PLOTTED: Monday, March 27, 2017 12:18:39 PM




V 2 V U U U U

CAD FILE: H:\ISO\476073\12010 Grating System Inspection And Repair Phase 1\Dwgs\Bascule Bridge Deck Inspection GRATING 2-4.dwg

TING ONS	JS drawn by	dessine par	17-03-2 project date	
	CW designed by	conc par	R.0828	357.001
	ММ		project no.	no. du projet
ONS	approved by	approuve par	16 OF	65
	tender p soumission admi	roject manager nistrateur de projets	drawing no.	dessine no.

DATE PLOTTED: Monday, March 27, 2017 12:18:40 PM




Public Works and Government Services Canada Architectural and Engineering Services	project title titre du projet LASALLE CAUSEWAY BASCULE BRIDGE	drawing title titre du dessin BRIDGE GRATING DETERIORATIONS	JS drawn by dessine par CW	17-03-27 project date du projet
Ontario Region Travaux publics et Services gouvernementaux Canada	KINGSTON ONTARIO	DETENIONATIONS	designed by conc par	R.082857.001 project no. no. du projet
Services d'architecture et de génie Région de l'Ontario	DECK GRATING REPAIRS	PARSONS	approved by approuve par	18 OF 65 drawing no. dessine no.

95-09


GSC-A3A


DATE PLOTTED: Monday, March 27, 2017 12:18:41 PM




1615 14 12 10 8 6 4 2 0	Public Works and Government Services Canada	project title titre du projet LASALLE CAUSEWAY	drawing title titre du dessin BRIDGE GRATING	JS drawn by dessine par	17-03-27 project date date du projet
G D C	Architectural and Engineering Services Ontario Region Travaux publics et Services gouvernementaux Canada	BASCULE BRIDGE KINGSTON ONTARIO	DETERIORATIONS	CW designed by conc par MM	R.082857.001 project no. no. du projet
	Services gouvernementaux oundau Services d'architecture et de génie Région de l'Ontario	DECK GRATING REPAIRS	PARSONS	approved by approuve par	18 OF 65 drawing no. dessine no.

DATE PLOTTED: Monday, March 27, 2017 12:18:43 PM






DEFECT No.	DESCRIPTION		
1	ABRASION		
2	BENT TRANSVERSE BAR		
3	BENT TRANSVERSE BAR		
4	BENT TRANSVERSE BAR		
5	BENT TRANSVERSE BAR		
6	BENT TRANSVERSE BAR		



	JS drawn by	dessine par	17-03-2 project date	
TING ONS	CW designed by	conc par	R.0828	857.001
	MM		project no.	no. du projet
ONS	approved by	approuve par	19 OF	65
	tender p soumission admi	project manager nistrateur de projets	drawing no.	dessine no.


DATE PLOTTED: Monday, March 27, 2017 12:18:45 PM






CAD FILE: H:\ISO\476073\12010 Grating System Inspection And Repair Phase 1\Dwgs\Bascule Bridge Deck Inspection GRATING 4-6.dwg


DATE PLOTTED: Monday, March 27, 2017 12:18:47 PM



<u>4-6 - E</u>

1:20






CAD FILE: H:\ISO\476073\12010 Grating System Inspection And Repair Phase 1\Dwgs\Bascule Bridge Deck Inspection GRATING 4-6.dwg


	JS drawn by	dessine par	17-03-2 project date	7 date du projet
TING ONS	CW designed by	conc par	R.0828	57.001
	MM approved by	approuve par	project no.	no. du projet
ONS	approved by	approuve par	21 OF 6	65
	tender pro soumission admini	oject manager strateur de projets	drawing no.	dessine no.


DATE PLOTTED: Monday, March 27, 2017 12:18:49 PM



4 - 6 - F

1:20







CAD FILE: H:\ISO\476073\12010 Grating System Inspection And Repair Phase 1\Dwgs\Bascule Bridge Deck Inspection GRATING 4-6.dwg

TING ONS	JS drawn by	dessine par	17–03–2 project date	
	CW designed by	conc par	R.0828	357.001
	MM		project no.	no. du projet
ONS	approved by	approuve par	22 OF	65
	tender p soumission admir	roject manager histrateur de projets	drawing no.	dessine no.

DATE PLOTTED: Monday, March 27, 2017 12:18:51 PM







1615 14 12 10 8 6 4 2 0	Public Works and Government Services Canada	project title titre du projet LASALLE CAUSEWAY	drawing title titre du dessin BRIDGE GRATING	JS drawn by dessine par	17-03-27 project date date du projet
	Architectural and Engineering Services Ontario Region Travaux publics et Services gouvernementaux Canada	BASCULE BRIDGE KINGSTON ONTARIO	DETERIORATIONS	CW designed by conc par	R.082857.001 project no. no. du projet
Ă L	Services gouvernementaux canada Services d'architecture et de génie Région de l'Ontario	DECK GRATING REPAIRS	PARSONS	MM approved by approuve par tender project manager soumission administrateur de projets	23 OF 65 drawing no. dessine no.

GSC


DATE PLOTTED: Monday, March 27, 2017 12:18:53 PM






TING ONS	JS drawn by	dessine par	17-03-2 project date	7 date du projet
	CW designed by	conc par	R.0828	57.001
	ММ		project no.	no. du projet
ONS	approved by	approuve par	24 OF 6	65
	tender pr soumission admin	oject manager istrateur de projets	drawing no.	dessine no.

DATE PLOTTED: Monday, March 27, 2017 12:18:54 PM




DEFECT No.	DESCRIPTION		
1	ABRASION		
4	BENT TRANSVERSE BAR		
5	BENT TRANSVERSE BAR		




CAD FILE: H:\ISO\476073\12010 Grating System Inspection And Repair Phase 1\Dwgs\Bascule Bridge Deck Inspection GRATING 6-8.dwg

	JS drawn by	dessine par	17-03-2 project date	7 date du projet
TING DNS	CW designed by	conc par	R.0828	57.001
	MM		project no.	no. du projet
ONS	approved by	approuve par	25 OF 6	65
	tender pro soumission admini	oject manager strateur de projets	drawing no.	dessine no.

DATE PLOTTED: Monday, March 27, 2017 12:18:56 PM




DEFECT No.	DESCRIPTION		
1	ABRASION		
2	BENT TRANSVERSE BAR		
3	BENT TRANSVERSE BAR		




CAD FILE: H:\ISO\476073\12010 Grating System Inspection And Repair Phase 1\Dwgs\Bascule Bridge Deck Inspection GRATING 6-8.dwg

TING ONS	JS drawn by	dessine par	17-03-2 project date	
	CW designed by	conc par		57.001
	MM		project no.	no. du projet
ONIC	approved by	approuve par	26 OF	65
	tender soumission adm	project manager ninistrateur de projets	drawing no.	dessine no.


DATE PLOTTED: Monday, March 27, 2017 12:18:58 PM






i

DATE PLOTTED: Monday, March 27, 2017 12:19:00 PM







DEFECT No.	DESCRIPTION		
1	ABRASION		
2	BENT TRANSVERSE BAR		
3	BENT TRANSVERSE BAR		
4	BENT TRANSVERSE BAR		
5	BENT TRANSVERSE BAR		




	JS drawn by	dessine par	17-03-2 project date	
TING ONS	CW designed by	conc par	R.0828	357.001
	MM approved by	approuve par	project no.	no. du projet
ONS			28 OF	65
	tender pr soumission admir	oject manager istrateur de projets	drawing no.	dessine no.

DATE PLOTTED: Monday, March 27, 2017 12:19:01 PM









CAD FILE: H:\ISO\476073\12010 Grating System Inspection And Repair Phase 1\Dwgs\Bascule Bridge Deck Inspection GRATING 6-8.dwg

TING ONS	JS drawn by	dessine par	17-03-2 project date	
	CW designed by	conc par	R.0828	357.001
	MM		project no.	no. du projet
ONS	approved by	approuve par	29 OF	65
	tender pr soumission admin	oject manager istrateur de projets	drawing no.	dessine no.

DATE PLOTTED: Monday, March 27, 2017 12:19:02 PM




DEFECT No.	DESCRIPTION	
1	ABRASION	
2	BENT TRANSVERSE BAR	



CAD FILE: H:\ISO\476073\12010 Grating System Inspection And Repair Phase 1\Dwgs\Bascule Bridge Deck Inspection GRATING 6-8.dwg


	JS drawn by	dessine par	17-03- project date	
TING ONS	CW designed by	conc par	R.0828	857.001
	MM approved by		project no.	no. du projet
ONS	approved by	approuve par	30 OF	65
	tender p soumission admi	project manager inistrateur de projets	drawing no.	dessine no.

DATE PLOTTED: Monday, March 27, 2017 12:19:02 PM




TING ONS	JS drawn by	dessine par	17-03-2 project date	27 date du projet
	CW designed by	conc par	R.0828	357.001
	MM approved by		project no.	no. du projet
ONS	approved by	approuve par	31 OF	65
	tender pr soumission admir	roject manager iistrateur de projets	drawing no.	dessine no.

DATE PLOTTED: Monday, March 27, 2017 12:19:05 PM




DEFECT No.	DESCRIPTION		
1	ABRASION		
4	BENT TRANSVERSE BAR		



CAD FILE: H:\ISO\476073\12010 Grating System Inspection And Repair Phase 1\Dwgs\Bascule Bridge Deck Inspection GRATING 8-10.dwg


	JS drawn by	dessine par	17-03-2 project date	7 date du projet
TING ONS	CW designed by	conc par	R.0828	57.001
	MM approved by	approuve par	project no.	no. du projet
ONS	tender pro soumission admini	iject manager strateur de projets	32 OF (drawing no.	65 dessine no.

DATE PLOTTED: Monday, March 27, 2017 12:19:07 PM



<u>8-10 - C</u>

1:20







CAD FILE: H:\ISO\476073\12010 Grating System Inspection And Repair Phase 1\Dwgs\Bascule Bridge Deck Inspection GRATING 8-10.dwg

TING ONS	JS drawn by	dessine par	17-03-2 project date	27 date du projet
	CW designed by	conc par	R.0828	357.001
	ММ		project no.	no. du projet
ONS	approved by	approuve par	33 OF	65
	tender p soumission admi	roject manager nistrateur de projets	drawing no.	dessine no.

DATE PLOTTED: Monday, March 27, 2017 12:19:09 PM






DEFECT No.	DESCRIPTION
1	BENT TRANSVERSE BAR
2	BENT TRANSVERSE BAR
3	BENT TRANSVERSE BAR
4	BENT TRANSVERSE BAR
5	BENT TRANSVERSE BAR
6	BENT TRANSVERSE BAR
7	BENT TRANSVERSE BAR
8	BENT TRANSVERSE BAR
9	BENT TRANSVERSE BAR
10	BENT TRANSVERSE BAR
11	BENT TRANSVERSE BAR
12	BENT TRANSVERSE BAR



TING DNS	JS drawn by	dessine par	17-03-2 project date	27 date du projet
	CW designed by	conc par	R.0828	357.001
	MM		project no.	no. du projet
ONS	approved by tender pr soumission admin	approuve par oject manager istrateur de projets	34 OF drawing no.	65 dessine no.

DATE PLOTTED: Monday, March 27, 2017 12:19:11 PM



DEFECT No.	DESCRIPTION	DEFECT No.	DESCRIPTION
1	ABRASION	13	BENT TRANSVERSE BAR
2	BENT TRANSVERSE BAR	14	BENT TRANSVERSE BAR
3	BENT TRANSVERSE BAR	15	BENT TRANSVERSE BAR
4	BENT TRANSVERSE BAR	16	BENT TRANSVERSE BAR
5	BENT TRANSVERSE BAR	17	BENT TRANSVERSE BAR
6	BENT TRANSVERSE BAR	18	BENT TRANSVERSE BAR
7	BENT TRANSVERSE BAR	19	BENT TRANSVERSE BAR
8	BENT TRANSVERSE BAR	20	BENT TRANSVERSE BAR
9	BENT TRANSVERSE BAR	21	BENT TRANSVERSE BAR
10	BENT TRANSVERSE BAR	22	BENT TRANSVERSE BAR
11	BENT TRANSVERSE BAR		
12	BENT TRANSVERSE BAR		




CAD FILE: H:\ISO\476073\12010 Grating System Inspection And Repair Phase 1\Dwgs\Bascule Bridge Deck Inspection GRATING 8-10.dwg


3SC-A3A

TING ONS	JS drawn by	dessine par	17-03-2 project date	.7 date du projet
	CW designed by	conc par	R.0828	57.001
	MM approved by	approuve par	project no.	no. du projet
ONS	approved by	approuve par	35 OF	65
	tender pr soumission admir	oject manager iistrateur de projets	drawing no.	dessine no.

DATE PLOTTED: Monday, March 27, 2017 12:19:13 PM




DEFECT No.	DESCRIPTION		
1	ABRASION		
2	BENT TRANSVERSE BAR		




CAD FILE: H:\ISO\476073\12010 Grating System Inspection And Repair Phase 1\Dwgs\Bascule Bridge Deck Inspection GRATING 8-10.dwg

TING ONS	JS drawn by	dessine par	17-03-2 project date	
	CW designed by	conc par	R.0828	357.001
	MM		project no.	no. du projet
ONS	approved by	approuve par	36 OF	65
	tender p soumission admir	roject manager histrateur de projets	drawing no.	dessine no.

DATE PLOTTED: Monday, March 27, 2017 12:19:15 PM




DEFECT No.	DESCRIPTION		
1	ABRASION		
2	BENT TRANSVERSE BAR		
3	BENT TRANSVERSE BAR		



CAD FILE: H:\ISO\476073\12010 Grating System Inspection And Repair Phase 1\Dwgs\Bascule Bridge Deck Inspection GRATING 8-10.dwg


TING ONS	JS drawn by	dessine par	17-03-2 project date	
	CW designed by	conc par	R.0828	357.001
	MM approved by		project no.	no. du projet
ONS	approved by	approuve par	37 OF	65
	tender pro soumission admini	oject manager strateur de projets	drawing no.	dessine no.

DATE PLOTTED: Monday, March 27, 2017 12:19:17 PM



<u>10-12 - A</u>

1:20






CAD FILE: H:\ISO\476073\12010 Grating System Inspection And Repair Phase 1\Dwgs\Bascule Bridge Deck Inspection GRATING 10-12.dwg

VEVIJS


TING ONS	JS drawn by	dessine par	17-03-2 project date	
	CW designed by	conc par	R.0828	357.001
	MM		project no.	no. du projet
ONS	approved by	approuve par	38 OF	65
	tender soumission adm	project manager inistrateur de projets	drawing no.	dessine no.


DATE PLOTTED: Monday, March 27, 2017 12:19:18 PM



TING ONS	JS drawn by	dessine par	17-03-2 project date	
	CW designed by	conc par	R.0828	357.001
	MM		project no.	no. du projet
ONS	approved by	approuve par	39 OF	65
	tender p soumission admi	project manager nistrateur de projets	drawing no.	dessine no.

DATE PLOTTED: Monday, March 27, 2017 12:19:20 PM







0 -	12	 С
	1:20	

A Services d'architecture et de génie Région de l'Ontario DECK GRATING REPAIRS

	JS drawn by	dessine par	17-03-2 project date	
TING ONS	CW designed by	conc par	R.0828	357.001
	MM approved by		project no.	no. du projet
ONS	approved by	approuve par	40 OF	65
	tender p soumission admi	roject manager nistrateur de projets	drawing no.	dessine no.

DATE PLOTTED: Monday, March 27, 2017 12:19:22 PM







DEFECT No.	DESCRIPTION
1	TEMPORARY STEEL PLATE
2	BENT TRANSVERSE BAR
3	BENT TRANSVERSE BAR
4	BENT TRANSVERSE BAR
5	BENT TRANSVERSE BAR
6	BENT TRANSVERSE BAR
7	BENT TRANSVERSE BAR
8	BENT TRANSVERSE BAR
9	BENT TRANSVERSE BAR
10	BENT TRANSVERSE BAR
11	BENT TRANSVERSE BAR
12	BENT TRANSVERSE BAR
13	BENT TRANSVERSE BAR
14	BENT TRANSVERSE BAR
15	BENT TRANSVERSE BAR
16	BENT TRANSVERSE BAR
17	BENT TRANSVERSE BAR
18	BENT TRANSVERSE BAR

1615 14 12 10 8 6 4 2 0 G C A	∎₩∎	Public Works and Government Services Canada Architectural and Engineering Services Ontario Region Travaux publics et Services gouvernementaux Canada Services d'architecture et de génie	project title titre du projet LASALLE CAUSEWAY BASCULE BRIDGE KINGSTON ONTARIO DECK GRATING REPAIRS	drawing title titre du dessin BRIDGE GRATING DETERIORATIONS
		Région de l'Ontario	DECK ORATING REFAINS	PARSON


	JS drawn by	dessine par	17-03- project date	
TING ONS	CW designed by	conc par	R.082	857.001
	MM approved by	approuve par	project no.	no. du projet
ONS			41 OF	65
	tender soumission ad	project manager Iministrateur de projets	drawing no.	dessine no.

DATE PLOTTED: Monday, March 27, 2017 12:19:23 PM





BENT TRANSVERSE BAR






CAD FILE: H:\ISO\476073\12010 Grating System Inspection And Repair Phase 1\Dwgs\Bascule Bridge Deck Inspection GRATING 10-12.dwg

10 • • • • 0 15

JS drawn by	dessine par	17-03-2 project date	
CW designed by	conc par	R.0828	357.001
MM approved by	approuve par	project no.	no. du projet
		42 OF	65 dessine no.
	CW designed by MM approved by	CW designed by conc par MM	CW designed by conc par MM approved by approuve par 42 OF

DATE PLOTTED: Monday, March 27, 2017 12:19:24 PM



Ontario Region

Travaux publics et Services gouvernementaux Canada

Services d'architecture et de génie Région de l'Ontario

BASCULE BRIDGE

DECK GRATING REPAIRS

KINGSTON

ONTARIO

G 🗖


D C

А


CAD FILE: H:\ISO\476073\12010 Grating System Inspection And Repair Phase 1\Dwgs\Bascule Bridge Deck Inspection GRATING 10-12.dwg

drawing title titre du dessin	JS drawn by	dessine par	17-03-2 project date	27 date du projet
BRIDGE GRATING DETERIORATIONS	CW designed by	conc par		357.001
	MM approved by	approuve par	project no.	no. du projet
PARSONS	approved by	approuve par	43 OF	65
	tender proje soumission administi	ect manager rateur de projets	drawing no.	dessine no.

DATE PLOTTED: Monday, March 27, 2017 12:19:24 PM



DEFECT No.	DESCRIPTION
1	ABRASION
2	BENT TRANSVERSE BAR
3	BENT TRANSVERSE BAR




CAD FILE: H:\ISO\476073\12010 Grating System Inspection And Repair Phase 1\Dwgs\Bascule Bridge Deck Inspection GRATING 10-12.dwg

-


	JS drawn by	dessine par	17-03-2 project date	
TING ONS	CW designed by	conc par	R.0828	357.001
	MM		project no.	no. du projet
ONS	approved by	approuve par	44 OF	65
	tender p soumission admi	roject manager nistrateur de projets	drawing no.	dessine no.


DATE PLOTTED: Monday, March 27, 2017 12:19:26 PM



	JS drawn by	dessine par	17-03- project date	
TING ONS	CW designed by	conc par	R.0828	857.001
	MM approved by		project no.	no. du projet
ONS	approved by	approuve par	45 OF	65
	tender soumission ad	project manager Iministrateur de projets	drawing no.	dessine no.

DATE PLOTTED: Monday, March 27, 2017 12:19:27 PM





DEFECT No.	DESCRIPTION
1	ABRASION
2	BROKEN TRANSVERSE BAR
3	BENT LONGITUDINAL BAR
4	BROKEN TRANSVERSE BAR
5	BENT TRANSVERSE BAR
6	BENT TRANSVERSE BAR
7	BENT TRANSVERSE BAR
8	BENT TRANSVERSE BAR
9	BENT TRANSVERSE BAR
10	BENT TRANSVERSE BAR
11	BENT TRANSVERSE BAR
12	BENT TRANSVERSE BAR
13	BENT TRANSVERSE BAR
14	BENT TRANSVERSE BAR
15	BENT TRANSVERSE BAR
16	BENT TRANSVERSE BAR
17	BENT TRANSVERSE BAR
18	BENT TRANSVERSE BAR
19	BENT TRANSVERSE BAR

G FF		 	
C ==			

🔳 يىڭىر 📕	Public	Works	and
	Govern	ment	Servic

Government Services Canada Architectural and Engineering Services Ontario Region

Travaux publics et Services gouvernementaux Canada Services d'architecture et de génie Région de l'Ontario project title titre du projet LASALLE CAUSEWAY BASCULE BRIDGE KINGSTON ONTARIO DECK GRATING REPAIRS drawing title titre du dessin BRIDGE GRAT


DETERIORATIC

PARS

CAD FILE: H:\ISO\476073\12010 Grating System Inspection And Repair Phase 1\Dwgs\Bascule Bridge Deck Inspection GRATING 12-14.dwg

TING ONS	JS drawn by	dessine par	17-03-2 project date	
	CW designed by	conc par	R.0828	357.001
	MM .		project no.	no. du projet
ONS	approved by	approuve par	46 OF	65
	tender p soumission admi	project manager nistrateur de projets	drawing no.	dessine no.

DATE PLOTTED: Monday, March 27, 2017 12:19:29 PM







0 • * *

TING ONS	JS drawn by	dessine par	17-03-2 project date	
	CW designed by	conc par	R.0828	357.001
	MM		project no.	no. du projet
ONS	approved by	approuve par	47 OF	65
	tender pi soumission admir	roject manager histrateur de projets	drawing no.	dessine no.

DATE PLOTTED: Monday, March 27, 2017 12:19:31 PM








	
DEFECT No.	DESCRIPTION
1	BENT TRANSVERSE BAR
2	BENT TRANSVERSE BAR
3	BENT TRANSVERSE BAR
4	BENT TRANSVERSE BAR
5	BENT TRANSVERSE BAR
6	BENT TRANSVERSE BAR
7	BENT TRANSVERSE BAR
8	BENT TRANSVERSE BAR
9	BENT TRANSVERSE BAR
10	BROKEN TRANSVERSE BAR



DATE PLOTTED: Monday, March 27, 2017 12:19:32 PM








SC-A3A

TING ONS	JS drawn by	dessine par	17-03- project date	
	CW designed by	conc par	R.082	857.001
	MM		project no.	no. du projet
ONS	approved by	approuve par	49 OF	65
	tender soumission adm	project manager ninistrateur de projets	drawing no.	dessine no.

DATE PLOTTED: Monday, March 27, 2017 12:19:34 PM






DEFECT No.	DESCRIPTION
1	ABRASION
2	BENT TRANSVERSE
3	BENT TRANSVERSE
4	BENT TRANSVERSE
5	BENT TRANSVERSE



TING ONS	JS drawn by	dessine par	17-03-2 project date	
	CW designed by	conc par	R.0828	357.001
	MM		project no.	no. du projet
ONS	approved by	approuve par	50 OF	65
	tender pi soumission admir	roject manager nistrateur de projets	drawing no.	dessine no.

DATE PLOTTED: Monday, March 27, 2017 12:19:35 PM



1:20


DEFECT No.	DESCRIPTION	
1	ABRASION	
2	BENT TRANSVERSE	
3	BENT TRANSVERSE	




CAD FILE: H:\ISO\476073\12010 Grating System Inspection And Repair Phase 1\Dwgs\Bascule Bridge Deck Inspection GRATING 12-14.dwg

	JS drawn by	dessine par	17-03-2 project date	.7 date du projet
TING ONS	CW designed by	conc par	R.0828	57.001
	MM		project no.	no. du projet
ONS	approved by	approuve par	51 OF	65
	tender pr soumission admin	oject manager istrateur de projets	drawing no.	dessine no.

DATE PLOTTED: Monday, March 27, 2017 12:19:37 PM








	JS drawn by	dessine par	17-03-2 project date	
TING ONS	CW designed by	conc par	R.0828	357.001
	MM		project no.	no. du projet
	approved by	approuve par	52 OF	65
	tender pr soumission admin	oject manager istrateur de projets	drawing no.	dessine no.

DATE PLOTTED: Monday, March 27, 2017 12:20:02 PM



DEFECT No.	DESCRIPTION	DEFECT No.	DESCRIPTION
1	BENT TRANSVERSE BAR	21	BENT TRANSVERSE BAR
2	BENT TRANSVERSE BAR	22	BENT TRANSVERSE BAR
3	BENT TRANSVERSE BAR	23	BENT TRANSVERSE BAR
4	BENT TRANSVERSE BAR	24	BENT TRANSVERSE BAR
5	BENT TRANSVERSE BAR	25	BENT TRANSVERSE BAR
6	BENT TRANSVERSE BAR	26	BENT TRANSVERSE BAR
7	BENT TRANSVERSE BAR	27	BROKEN TRANSVERSE BAR
8	BENT TRANSVERSE BAR	28	BROKEN TRANSVERSE BAR
9	BENT TRANSVERSE BAR	29	BROKEN TRANSVERSE BAR
10	BENT TRANSVERSE BAR	30	BENT TRANSVERSE BAR
11	BENT TRANSVERSE BAR	31	BENT TRANSVERSE BAR
12	BENT TRANSVERSE BAR	32	BENT TRANSVERSE BAR
13	BENT TRANSVERSE BAR	33	BENT TRANSVERSE BAR
14	BENT TRANSVERSE BAR	34	BENT TRANSVERSE BAR
15	BENT TRANSVERSE BAR	35	BENT TRANSVERSE BAR
16	BENT TRANSVERSE BAR	36	BENT TRANSVERSE BAR
17	BENT TRANSVERSE BAR	37	BENT TRANSVERSE BAR
18	BENT TRANSVERSE BAR	38	ABRASION
19	BENT TRANSVERSE BAR		
20	BENT TRANSVERSE BAR		
L			

▋┿∎	Pu Go
	۸

ublic Works and Sovernment Services Canada Architectural and Engineering Services Ontario Region


Travaux publics et Services gouvernementaux Canada Services d'architecture et de génie Région de l'Ontario

project title titre du projet LASALLE CAUSEWAY BASCULE BRIDGE KINGSTON ONTARIO DECK GRATING REPAIRS

CAD FILE: H:\ISO\476073\12010 Grating System Inspection And Repair Phase 1\Dwgs\Bascule Bridge Deck Inspection GRATING 14-15.dwg

drawing title titre du dessin	JS drawn by d	lessine par	17-03-2 project date	27 date du projet
BRIDGE GRATING DETERIORATIONS	CW designed by c	onc par	R.0828	357.001
	MM approved by a	pprouve par	project no.	no. du projet
PARSONS			53 OF	65
. /	tender project m soumission administrateur	ianager r de projets	drawing no.	dessine no.


DATE PLOTTED: Monday, March 27, 2017 12:20:03 PM




× 2 ¥ () ()

	JS drawn by	dessine par	17-03-2 project date	.7 date du projet
TING ONS	CW designed by	conc par	R.0828	57.001
	MM		project no.	no. du projet
ONS	approved by	approuve par	54 OF	65
	tender pi soumission admir	roject manager histrateur de projets	drawing no.	dessine no.

DATE PLOTTED: Monday, March 27, 2017 12:20:05 PM








0 V Y Y Y

TULO	JS drawn by	dessine par	17-03-2 project date	
TING ONS	CW designed by	conc par		357.001
	MM approved by	approuve par	project no.	no. du projet
ONS	tender p soumission admi	roject manager nistrateur de projets	55 OF drawing no.	65 dessine no.


DATE PLOTTED: Monday, March 27, 2017 12:20:07 PM




121

	JS drawn by	dessine par	17-03-2 project date	
TING ONS	CW designed by	conc par	R.0828	357.001
	MM approved by		project no.	no. du projet
ONS	approved by	approuve par	56 OF	65
	tender p soumission admir	roject manager histrateur de projets	drawing no.	dessine no.

DATE PLOTTED: Monday, March 27, 2017 12:20:09 PM




DEFECT No.	DESCRIPTION		
1	ABRASION		
2	BENT TRANSVERSE BAR		



	JS drawn by	dessine par	17-03-2 project date	
TING DNS	CW designed by	conc par	R.0828	357.001
	MM		project no.	no. du projet
ONS	approved by	approuve par	57 OF	65
	tender p soumission admir	roject manager histrateur de projets	drawing no.	dessine no.

DATE PLOTTED: Monday, March 27, 2017 12:20:11 PM




DEFECT No.	DESCRIPTION
1	ABRASION
2	BENT TRANSVERSE BAR



	JS drawn by	dessine par	17-03-2 project date	
TING ONS	CW designed by	conc par	R.0828	357.001
	MM		project no.	no. du projet
ONS	approved by	approuve par	58 OF	65
	tender p soumission admir	roject manager histrateur de projets	drawing no.	dessine no.

DATE PLOTTED: Monday, March 27, 2017 12:20:13 PM




	Public Works and	project title titre du projet	drawing title titre du dessin
1615 14 12 10 8 6 4 2 0 G C A A A A A A A A A A A A A A A A A A	Public Works and Government Services Canada Architectural and Engineering Services Ontario Region Travaux publics et Services gouvernementaux Canada Services d'architecture et de génie Région de l'Ontario	LASALLE CAUSEWAY BASCULE BRIDGE KINGSTON	BRIDGE GRATII DETERIORATION

1

	JS drawn by	dessine par	17-03-2 project date	
TING ONS	CW designed by	conc par	R.0828	357.001
	MM approved by		project no.	no. du projet
ONS	approved by	approuve par	59 OF	65
	tender p soumission admi	roject manager nistrateur de projets	drawing no.	dessine no.

DATE PLOTTED: Monday, March 27, 2017 12:20:20 PM



1:20	

DEFECT No.	DESCRIPTION
1	ABRASION
2	BENT TRANSVERSE BAR
3	BENT TRANSVERSE BAR
4	BENT TRANSVERSE BAR
5	BROKEN LONGITUDINAL BAR
6	BROKEN LONGITUDINAL BAR
7	BENT TRANSVERSE BAR
8	BENT TRANSVERSE BAR
9	BENT TRANSVERSE BAR
10	BENT TRANSVERSE BAR
11	BENT TRANSVERSE BAR
12	BENT TRANSVERSE BAR
13	BENT TRANSVERSE BAR
14	BENT TRANSVERSE BAR
15	BENT TRANSVERSE BAR
16	BENT TRANSVERSE BAR
17	BENT TRANSVERSE BAR
18	BROKEN TRANSVERSE BAR
19	BENT TRANSVERSE BAR

δ
-A3A
SC-
SC-A

G 🖊 🗖	 	 	 		

-	Publi
715	Gove

Public Works and Government Services Canada Architectural and Engineering Services Ontario Region

Travaux publics et Services gouvernementaux Canada Services d'architecture et de génie Région de l'Ontario project title titre du projet LASALLE CAUSEWAY BASCULE BRIDGE KINGSTON ONTARIO DECK GRATING REPAIRS drawing title titre du dessin BRIDGE GRAT


PARS

DETERIORATIO

CAD FILE: H:\ISO\476073\12010 Grating System Inspection And Repair Phase 1\Dwgs\Bascule Bridge Deck Inspection GRATING 15-16.dwg

	JS drawn by	dessine par	17-03- project date	
TING DNS	CW designed by	conc par	R.0828	857.001
	MM		project no.	no. du projet
ONS	approved by	approuve par	60 OF	65
	tender soumission adm	project manager inistrateur de projets	drawing no.	dessine no.

DATE PLOTTED: Monday, March 27, 2017 12:20:22 PM



DEFECT No.	DESCRIPTION		
1	ABRASION		
2	BENT TRANSVERSE BAR		
3	BENT TRANSVERSE BAR		
4	BENT TRANSVERSE BAR		
5	BROKEN TRANSVERSE BAR		
6	BROKEN TRANSVERSE BAR		

95-09


GSC-A3A

1615 14 12 10 8 6 4 2 0 G C	Public Works and Government Services Canada Architectural and Engineering Services Ontario Region Travaux publics et Services gouvernementaux Canada	project title titre du projet LASALLE CAUSEWAY BASCULE BRIDGE KINGSTON ONTARIO	drawing title titre du dessin BRIDGE GRATIN DETERIORATION
	Services d'architecture et de génie Région de l'Ontario	DECK GRATING REPAIRS	PARSC

CAD FILE: H:\ISO\476073\12010 Grating System Inspection And Repair Phase 1\Dwgs\Bascule Bridge Deck Inspection GRATING 15-16.dwg

ONS	tender pr soumission admir	roject manager iistrateur de projets	61 OF drawing no.	65 dessine no.
	MM approved by	approuve par		
TING DNS	CW designed by	conc par	R.082	857.001 no. du projet
	JS drawn by	dessine par	17-03- project date	


DATE PLOTTED: Monday, March 27, 2017 12:20:24 PM




DEFECT No.	DESCRIPTION
1	BENT TRANSVERSE BAR
2	BENT TRANSVERSE BAR
3	BENT TRANSVERSE BAR
4	BENT TRANSVERSE BAR
5	BENT TRANSVERSE BAR
6	BENT TRANSVERSE BAR
7	BENT TRANSVERSE BAR

1615 14 12 10 8 6 4 2 0	Public Works and Government Services Canada	project title titre du projet LASALLE CAUSEWAY	drawing title titre du dessin	JS drawn by dessine par	17-03-27 project date du projet
	Architectural and Engineering Services Ontario Region Travaux publics et	BASCULE BRIDGE KINGSTON ONTARIO	BRIDGE GRATING DETERIORATIONS	CW designed by conc par	R.082857.001 project no. no. du projet
	Services gouvernementaux Canada Services d'architecture et de génie Région de l'Ontario	DECK GRATING REPAIRS	PARSONS	MM approved by approuve par tender project manager soumission administrateur de projets	62 OF 65 drawing no. dessine no.

DATE PLOTTED: Monday, March 27, 2017 12:20:26 PM




DEFECT No. DESCRIPTION		DESCRIPTION
1 ABRASION		
	2	BENT TRANSVERSE



TING DNS	JS drawn by	dessine par	17-03- project date	
	CW designed by	conc par	R.0828	857.001
	ММ		project no.	no. du projet
ONS	approved by	approuve par	63 OF	65
	tender soumission adm	project manager inistrateur de projets	drawing no.	dessine no.

DATE PLOTTED: Monday, March 27, 2017 12:20:27 PM



DEFECT No.	DESCRIPTION		
1	ABRASION		
2	BENT TRANSVERSE		
3	BENT TRANSVERSE		
4	BENT TRANSVERSE		
5	BENT TRANSVERSE		
6	BENT TRANSVERSE		
7	BENT TRANSVERSE		
8	BENT TRANSVERSE		
9	BENT TRANSVERSE		
10	BENT TRANSVERSE		
11	BENT TRANSVERSE		
12	BENT TRANSVERSE		
13	BENT TRANSVERSE		
14	BENT TRANSVERSE		
15	BENT TRANSVERSE		
16	BENT TRANSVERSE		
17	BENT TRANSVERSE		
18	BENT TRANSVERSE		
19	BENT TRANSVERSE		
20	BENT TRANSVERSE		

1615	14	12	10	8	6	4	2	0
G D								
Č								
A LZ			I				I	

	4	
	11	

0

Public Works and Government Services Canada Architectural and Engineering Services Ontario Region

Travaux publics et Services gouvernementaux Canada Services d'architecture et de génie Région de l'Ontario

project title titre du projet LASALLE CAUSEWAY BASCULE BRIDGE KINGSTON ONTARIO DECK GRATING REPAIRS

drawing title titre du dessin BRIDGE GRAT


PARS

DETERIORATIO

CAD FILE: H:\ISO\476073\12010 Grating System Inspection And Repair Phase 1\Dwgs\Bascule Bridge Deck Inspection GRATING 15-16.dwg

TING DNS	JS drawn by	dessine par	17-03- project date	
	CW designed by	conc par	R.0828	857.001
	MM .		project no.	no. du projet
ONS	approved by	approuve par	63 OF	6₿
	tender p soumission admi	roject manager nistrateur de projets	drawing no.	dessine no.

DATE PLOTTED: Monday, March 27, 2017 12:20:28 PM



DEFECT No.	DESCRIPTION		
1	ABRASION		
2	BENT TRANSVERSE		
3	BENT TRANSVERSE		



TING DNS	JS drawn by	dessine par	17-03-2 project date	
	CW designed by	conc par	R.0828	357.001
	MM approved by	approuve par	project no.	no. du projet
ONS	approved by	approuve par	65 OF	65
	tender p soumission admi	project manager nistrateur de projets	drawing no.	dessine no.

DATE PLOTTED: Monday, March 27, 2017 12:20:30 PM