



Rough Surface Profile - Makes tank cleaning somewhat difficult for scrubbing and wiping.