



Date: September 2, 2021

Title: Variable Refrigerant Volume (VRV-II) System Replacements, New Delhi, India

Solicitation Number: 21-176374

The following supplements and/or supersedes the solicitation document. This addendum forms part of the contract documents and is to be read, interpreted, and coordinated with all other parts. Any change to the cost of the work as a result of this addendum is to be included in the price proposal.

Addendum # 3

4. Appendix A – Statement of Work, Annex A – Existing Equipment, Table 1

DELETE: Table 1 in its entirety.

INSERT: Table 1 (Revision 2) attached to this document.

All other conditions and requirements remain unchanged.

ANNEX A - Existing Equipment

Table 1 - VRV- II Systems to be Replaced by VRV-IV Systems, Q Series, at HCC New Delhi

Revision 2
(31 August 2021)

(Note: changes from last version of Table 1, Rev 1, shown in RED below)

Ref	Outdoor Unit (ODU) Model # & HP	ODU Location	Indoor Unit (IDU)	IDU/Cassette Location	Outdoor Unit		Indoor Unit	
					Tonnage	#	#	#
1	RXY16MY1 16 HP	Club Canada Roof	FXF80LVE	Club Manager office	16	1	1	
				SubTotal Canada Club (Master unit 1a)				1
2	RXY10MY1 10 HP	Club Canada Roof	FXF80LVE	CLO Office	10	1	1	
				SubTotal Canada Club (Slab unit 2 to Master unit 1a)				1
3	RXY10MY1 10 HP	Club Canada Roof	FXF125LVE	Restaurant -1	10	1	1	
			FXF125LVE	Restaurant -2			1	
			FXF80LVE	MPR-A			1	
			FXF80LVE	MPR-A			1	
			FXF80LVE	MPR-B			1	
			FXF80LVE	MPR-B			1	
				SubTotal Canada Club (Slab unit 3 to Master unit 1a)				6
4	RXY8MY1 8 HP	Transport Roof	FX80LVE	TV Room	8	1	1	
			FXA50LVE9	Pantry			1	
			FXA40LVE9	Office Room			1	
				SubTotal Transport				3
5	RXY8MY1 8 HP	B&D Block Lawn	FX100LVE	B block kids play room	8	1	1	
			FX100LVE	B block kids play room			1	
				SubTotal Block B & D				2
6	RXY14MY1 14 HP	Service Building Roof	FXF50LVE	ATM Room	14	1	1	
				SubTotal Service Building (Master unit 1b)				1
7	RXY10MY1 10 HP	Service Building Roof	FXF50LVE	Canteen-1	10	1	1	
			FXF50LVE	Canteen-2			1	
			FXF50LVE	Club Store-1			1	
			FXF50LVE	Club Store-2			1	
			FXF40LVE	Canteen-3			1	
			FXF40LVE	Canteen-4			1	
			FXF40LVE	Club Manager Room			1	
			FXF100LVE	Plant Operator Room			1	
			FXF32LVE	Resource Center			1	
			FXF32LVE	Meeting Room OFC			1	
			FXF63LVE	Store Room OFC			1	
			FXF32LVE	Meeting Room ONC			1	
			FXF25LVE	Annex OFC (added unit from last version of Table 1)			1	
				SubTotal Service Building (Slab unit 2 to Master unit 1b)				13
8	RXY5MY1 5HP	Chancery Roof	FXF63LVE	HSZ Room#383	5	1	1	
			FXF50LVE	HSZ Room#383			1	
				SubTotal Chancery				2
9	RXY12MY1 12HP	CANZA Roof	FXM250LEV	Shopping Hall	12	1	1	
			FXA40LVE	Manager Office Room			1	
			FXA40LVE	Cash Counter			1	
				(deleted unit from last version of Table 1)			0	
				SubTotal Canza				3
Total Count:						9		32