



**RETURN BIDS TO:**

**RETOURNER LES SOUMISSIONS À:**

Public Works and Government Services Canada

See herein for bid submission

instructions/

Voir la présente pour les

instructions sur la présentation

d'une soumission

NA

Alberta

NA

Bid Fax: (418) 566-6167

**LETTER OF INTEREST**

**LETTRE D'INTÉRÊT**

Comments - Commentaires

Vendor/Firm Name and Address

Raison sociale et adresse du

fournisseur/de l'entrepreneur

Issuing Office - Bureau de distribution

Public Works and Government Services Canada

Northern Contaminated Site Program

Canada Place/Place du Canada

10th Floor/10e étage

9700 Jasper Ave/9700 ave Jasper

Edmonton

Alberta

T5J 4C3

<b>Title - Sujet</b> O'Connor Lake Mine Remediation Work	
<b>Solicitation No. - N° de l'invitation</b> EW699-230990/B	<b>Date</b> 2022-10-28
<b>Client Reference No. - N° de référence du client</b> CIRNAC EW699-230990	<b>GETS Ref. No. - N° de réf. de SEAG</b> PW-\$NCS-118-12337
<b>File No. - N° de dossier</b> NCS-2-45048 (118)	<b>CCC No./N° CCC - FMS No./N° VME</b>
<b>Solicitation Closes - L'invitation prend fin</b> <b>at - à 02:00 PM</b> Central Standard Time CST <b>on - le 2022-11-15</b> Heure Normale du Centre HNC	
<b>F.O.B. - F.A.B.</b> <b>Plant-Usine:</b> <input type="checkbox"/> <b>Destination:</b> <input checked="" type="checkbox"/> <b>Other-Autre:</b> <input type="checkbox"/>	
<b>Address Enquiries to: - Adresser toutes questions à:</b> Keenan, Matthew	<b>Buyer Id - Id de l'acheteur</b> ncs118
<b>Telephone No. - N° de téléphone</b> (431) 278-4884 ( )	<b>FAX No. - N° de FAX</b> (418) 566-6167
<b>Destination - of Goods, Services, and Construction:</b> <b>Destination - des biens, services et construction:</b> PWGSC/TPSGC 9700 JASPER PLACE EDMONTON Alberta T5J4C3 Canada	

Instructions: See Herein

Instructions: Voir aux présentes

<b>Delivery Required - Livraison exigée</b> See Herein – Voir ci-inclus	<b>Delivery Offered - Livraison proposée</b>
<b>Vendor/Firm Name and Address</b> <b>Raison sociale et adresse du fournisseur/de l'entrepreneur</b>	
<b>Telephone No. - N° de téléphone</b> <b>Facsimile No. - N° de télécopieur</b>	
<b>Name and title of person authorized to sign on behalf of Vendor/Firm</b> <b>(type or print)</b> <b>Nom et titre de la personne autorisée à signer au nom du fournisseur/</b> <b>de l'entrepreneur (taper ou écrire en caractères d'imprimerie)</b>	
<b>Signature</b>	<b>Date</b>

Information Provided at Optional Pre-Tender Site Visit for O'Connor Mine Bidder's Tour held on September 27, 2022:

#### Head Frame and Waste Rock Pile

- Asbestos Containing Material present on sides of the headframe.
- Open shaft located below the headframe; shaft dimensions are approximately 3.5 m x 3.5 m and 55 m deep; ice plug located 8 m below grade (unknown thickness); open shaft to be plugged with concrete.
- Waste rock piles will be left in place, remove debris and tripping hazards only.
- Limited contaminated soil removal (minor surface staining).

#### South / Southwest Area of Island

- Several buildings in various states of disrepair located here; most have outhouses nearby.
- Roofing material does not contain asbestos.
- Limited amounts of lead painted material may be present.

#### Exploration Trench

- To be partially backfilled with clean material to remove falling hazard.
- Will not be using waste rock as backfill material.
- Wood and other debris within the trench to be removed prior to backfilling.
- Blasting is not permitted.

#### Debris

- A small dump area is located in the centre of the island and contains mostly metal debris and some batteries.
- Hazardous (10 m<sup>3</sup>) and non-hazardous debris (18 m<sup>3</sup>) to be removed offsite for disposal.
- Clean wood to be burned onsite (198 m<sup>3</sup>).
- Concrete to be cut to grade and placed in the exploration trench as backfill (29 m<sup>3</sup>).

#### Access and Logistics

- The site is densely vegetated.
- Suspect historical winter road accessed the site on the south side of the island. If Contractor decides to construct a winter road they will be responsible with all associated regulatory requirements (permits, etc.).
- Historical haul road ran north-south on the island but has been overgrown with vegetation.
- Very little borrow material available onsite.
- Archaeologically significant area located on the south end of the site and will have buffer zone restricting heavy equipment use and excavation in the area.
- Slave Lake Zinc holds mineral rights for the site and could potentially be conducting exploration activities during remediation.

**PROJECT: O'Connor Lake Mine Remediation Work**

**PROJET : Travaux d'assainissement de la mine O'Connor Lake**

NOTIFICATION NO. / N° DE NOTIFICATION : EW699-230990

DATE : 2022-09-27

LOCATION / EMPLACEMENT : Mine O'Connor Lake

[illegible]