

**QUESTIONS AND ANSWERS #1**

**The purpose of this document is to provide answers to questions raised against Request for Proposal T8493-22-0016(1):**

**Question 1:** In the Failure description - Found no distance displayed (frequency in yellow) – found no A2 output & A2 flash failure – Install SB 6 & SB 5 -test and recertified (MPS) – Tested IAW CMMPL 523-0780571 Ed1/Rev20

Could you please verify if you are requesting to have SB 5 & 6 incorporated in addition to the repair?

**Answer 1:** Yes, please incorporate any outstanding Service Bulletins (SB).

**ALL OTHER TERMS AND CONDITIONS REMAIN THE SAME**

**QUESTIONS ET RÉPONSES #1**

**Le but de ce document est de répondre aux questions soulevées reliées à la demande de proposition T8493-22-0016(1) :**

**Question 1:** Dans la description de défaillance – aucune distance affichée (fréquence en jaune) - aucun A2 trouvé hors service et défaillance du flash d'A2-Installer SB 6 & SB 5 – mise à l'essai et recertification (MPS) –mise à l'essai conformément à CMMPL 523-0780571 éd.1/rév.20

Pouvez-vous s.v.p. vérifier si l'inclusion de SB 5 & 6 est demandé en surplus de la réparation?

**Réponse 1:** Oui, s'il vous plaît incorporer tous les bulletins de services (SB) en suspens.

**TOUS LES AUTRES TERMS ET CONDITIONS RESTENT LES MÊMES**