

NOTE :-

1. I.M.S PIPING TO BE WELDED CONSTRUCTION.

CONNECTIONS AT A,B,C,D,E & F TO CORRESPOND TO SAME ON O.M.S PIPING

REFERENCE DRAWINGS

71-10-01 AIR BUBBLER SYSTEM DIAGRAM
71-10-02 ARR'GT AIR BUBBLER SYSTEM PIPING O.M.S.

"AS FITTED"

DISTRIBUTION					
DEPARTMENT	QTY.	DEPARTMENT	QTY.	DEPARTMENT	QTY
Owners	4	Operations Manager		Shipwrights	
Classification	1	Hull - Const. Supt.	1	Rigger	
Shipyard Inspection	4	Outfit Supt.		Joiner	
Chief Engr.	3	Repair Supt.		Pipe Fitter	3
Amp'mer	3	Steel Supt.		Machine Shop	1
Hull D.O	1	Victoria Div.	1		
Machinery D.O	1	Planning	3		
Electrical D.O	1	Loft		Sheet Metal	
Welding Engineer	1	Plater		Electric Shop	
		Welder		Engine Fitter	1

No.	REVISION	BY	DATE
1	DWG. NO CHANGED FROM 71-14-02 TO 71-10-02	RA	6.5
2	POSITION OF CROSS VALVES (AB.08) AND BLANK OFF VALVES & SILENCERS (AB-08 & AB-09) CHANGED AS REQUESTED BY AMPHIMAR	RA	28/7/82
3	NEW DIMENSIONS ADDED IN ACCORDANCE WITH LATEST INFO. FROM AMPHIMAR INTAKE CHANGED FROM SQUARE TO ROUND.	RA	30/8/82
4	REGULATING VALVES ADDED DIFFUSERS MODIFIED AS PER MANUFACTURERS DWG P.C.L. SKETCH #3895.AB.03	RA	27/9/82
5	ADDED ONE 400 ϕ VICTAULIC COUPLING & FOUR 500 ϕ COUPLINGS	A.W.	31/12/82
6	PRESSURE GAUGE & DRAIN ADDED TO AIR BUBBLER TRANSITION	[illegible]	14/1/83
7	"AS FITTED"	[illegible]	31/1/83

Burrard Yarrows Corporation — SHIPBUILDERS, SHIP REPAIRERS, GENERAL ENGINEERS

Vancouver Division P.O. Box 86099, North Vancouver, British Columbia, Canada V7L 4J6
Victoria Division P.O. Box 1030, Victoria, British Columbia, V8W 2S9

DIVISION VANCOUVER / VICTORIA — HULL 101 # 554 — JOB No. 71-10
OWNERS GULF CANADA RESOURCES INC

TITLE
ARRANGEMENT OF AIR BUBBLER SYSTEM PIPING I.M.S.

APPROVALS	REPRESENTS	DATE	DRAWN: D.M.L.
OWNERS		15-7-82	CHECKED
LLYODS		15-7-82	APPROVED
C.S.I.		9-6-82	SCALE 1:25 DATE MAY 6 '82
			DWG. No. 71-10-03 REV. 7