

The Bidders Conference for the **W. G. George 2012** Dry Docking Refit was convened in St. John's on 17 April 2012 with the following officials in attendance:

Name	Rank or Position	Representing
Colleen Dalton	Contracting Officer	PWGCS
Paul Kelly	Vessel Support	CCGS
Wayne Reid	Operation Manager	Dawes Welding & Sons Ltd.
Glenn Burry	President	Burry's Shipyard

The Chairman welcomed everyone in attendance and after introductions stated that the reason for the Bidders Conference is to review the Invitation to Tender Document, the Specifications and to clarify any contentious points that may exist and resolve them to the satisfaction of the Owners and Bidders.

No comments were made regarding the ITT document.

Vessel transfer costs were incorrect in the tender. Find below the correct figures.

Kewitt Offshore Services	\$2,130.00
Newdock	\$3,785.00
Dawes	\$4,196.00
Clareville	\$4,868.00
Theriault & Sons	\$7,706.00

Refit Pre-amble

No issues

HD-01 Services

No issues

HD-02 Drydocking

No issues

HD-03 Propeller Servicing

No issues

HD-04 Hull Inspection

Bidders are to contact supplier of hull coating to request information on application of coatings. If a shelter and heat is required it is to be included in your tender.

HD-05 Seabay Cleaning & Painting

No issues

HD-06 Zinc Anodes. (Supply and Install 16.)

No issues

HD 07 Main Engine Sea Strainer Replacement

No issues

HD 08 Panish Control Replacement

No issues

HD 09 Engine Room Exhaust Fan Replacement

No issues

HD 10 Fire Pump Discharge Pipe

No issues

HD 11 Fuel Tank Cleaning and Inspection

No issues

HD 12 Trim Tab Cylinder Servicing

No issues

HD 13 Main Engine Valve Tappet Adjustment

1.1 Caterpillar FSR allowance \$2,500.00

L-01 Insulation Testing

No issues

L-02 Fire Detection System & Co2 Smothering System

No issues

Pricing Data Sheet CCGS W. G. George Dry Docking Refit 2012.

HD-01 Services

3.1.1 Gangway \$_____

3.1.2 Electrical Shore Power \$_____

Unit cost per kwh. \$_____.

3.1.3 Fire Protection \$_____

3.1.4 Garbage Container \$_____

3.1.5 Oily Water Removal. (80/20 water/oil) \$_____

Unit cost Water. \$_____ 40 liters

Unit cost Oil. \$_____ 10 liters.

3.1.6 Interior Deck Protection. (7.5 sq. Meters) \$_____

3.1.7 Washrooms Facilities. \$_____

3.1.8 Office for CE \$_____

3.1.9 Evacuation Plan \$_____

3.1.10 Vessel Cleaning \$_____

HD-02 Drydocking \$_____

3.1 Unit day cost. \$_____

HD-03 Propeller Servicing \$_____

3.1.3 Refurbishment and Shipping allowance. **\$1,500.00.**

HD-04 Hull Inspection \$_____

3.1.3 Unit cost per sq. Ft. Repair and hull coating. \$_____.

3.1.6 Unit cost per sq. Meter. A. \$_____.

3.1.6 Unit cost per sq. Meter. B. \$_____.

HD-05 Seabay Cleaning & Painting \$_____

1.1 Unit cost per. ½ sq. Meter. \$_____.

HD-06 Zinc Anodes. (Supply and Install 16.) \$_____

HD 07 Main Engine Sea Strainer Replacement	\$_____
HD 08 Panish Control Replacement	\$_____
HD 09 Engine Room Exhaust Fan Replacement	\$_____
HD 10 Fire Pump Discharge Pipe	\$_____
HD 11 Fuel Tank Cleaning	\$_____
HD 12 Trim Tab Cylinder Servicing	\$_____
HD 13 Main Engine Valve Tappet Adjustment	\$_____
1.1 Caterpillar FSR.	\$2,500.00
L-01 Insulation Testing	\$_____
L-02 Fire Detection System & Co2 Smothering System	\$_____
Total Price hst extra	<u>\$_____</u>