

Question 008

H-08, Shower valves

The complete Rada Excel valve itself is no longer available, although spare parts are certainly available for it. This valve is replaced by the Rada 722 series. I'm assuming by you saying Crane/Rada, that you need the built-in concealed version 722.B? Please advise.

Response:

This valve will be acceptable. Regarding the built-in concealment, the valve shall be installed inboard of the shower enclosure for ease of replacement as a whole.

Question 009

H-11 Tow Deck Coating and Inspection

3.1.2 A review of the items indicates the change in Tow Deck Coating and Inspection from 'the application of two coats of primer' to 'two coats of Amercoat 235'. Do you require 2 coats of Primer and 2 coats topcoat?

Response:

Minutes show 2 coats of each.

Question 010

Item 26 Preamble.

What version of Fleet Safety Manual will be used for this refit?

Response:

The new version of the Fleet Safety Manual 4th Edition, Sept 2012 Revision will be used.

There are no significant changes but the latest version must be used where required.