

The Bidders Conference was convened in St. John's, 17 May 2012 with the following officials in attendance:

Name	Rank/Position	Representing	Telephone Number
Colleen Dalton	Supply Specialist	PWGSC	772-4931
Terry Sheppard		PWGSC	772-4614
Phillip Bingley	Project Engineer	CCG	772-4146
Stephane Belzile	C/E	CCG Ann Harvey	685-3914
Chris Woolfrey	Electrical Officer	CCG Ann Harvey	685-3914
Glenn Way	Operations Manager	Burry's Shipyard	466-7725
George Penney	Marine Manager	NewDock	758-6811
Kevin MacKinnon	Estimator	NewDock	758-6808
George Reid	Mechanical Eng.	DF Barnes	579-5041
Derrick English	Welding Supervisor	DF Barnes	579-5041
Cyril Coombs	Welding Supervisor	East Coast Marine	722-8600
Dennis Thorne	General Manager	Marener	725-4703

The Chairman welcomed everyone in attendance and after introductions stated that the reason for the Bidders Conference is to review the Invitation to Tender Document, the Specifications and to clarify any contentious points that may exist and resolve them to the satisfaction of the Owners and Bidders.

The Chairman reviewed the Invitation to Tender with the following comments:

A review of the English document up to page 31 was completed.

Page 01 The Closing Date is 31 May 2012.
Bidders are to fill in page 1, block on the bottom.

Page 05 Bidders indicated that the work schedule is reasonable for the dates given.

Page 08 Public opening is 31 May 2012.

21 attachments are included with the bid package and attachment #3 is not relevant to the refit. It was stated in the meeting for the bidders to disregard attachment #3.

As there were no other questions or comments on the Invitation to Tender, the Specification was reviewed with the following comments.

Specification changes.

H-01 Production Chart & Subcontractor allowance.

No issues

H-02 Fixed Fire Fighting Systems Annual Inspection/Maintenance

Allowance to be removed as per instructions included in attachment #21.

2.2 states that the contractor shall supply.....in this case it is the sub contractor who will supply the required materials and equipment.

H-03 Life rafts Servicing.

No issues

H-04 Fuel tanks Survey

No issues

H-05 Auxiliary Lube Oil Storage Tank.

No issues

H-06 Waste Oil Tank and Purifier Sludge Tank.

No issues

H-07 Void Tanks Survey

3.5 Bidders are to include in their bid the cost to pressure test 1 tank only and to include a unit cost per additional tank.

H-8 Fore peak Tank Survey and tank Level Transducer Installation

No issues

H-9 Cabin 304 Steel Renewal

3.14 Bidders are to include in price to supply and install 3.5 m² of 6mm dex-o-tex underlay.

3.13 Contractor to install 7m of new owner supplied bulkhead lining bottom track.....

H-10 Boiler Feed Tank Survey and repairs.

No issues

H-11 Piping Renewals and Repairs

No issues

E-01 Air Receivers Quinquennial Survey

No issues

E-02 Safety Valves Certification

3.1 1 main air receiver and 1 main air compressor can be done at the same time. All remaining values can be done at the same time.

The valves are to be taken off for servicing and returned within 4 business days.

E-03 Number 2 Boiler

No issues

E-04 P & S Steering Pumps, Cylinders and Control Block Survey

No issues

L-01 Breaker Replacement (6)

3.1 to 3.4 is the responsibility of the main contractor.

3.5 to 3.27 is the responsibility of the sub contractor.

L-02 P & S Steering Pump Motor Survey

No issues

Pricing Data Sheet CCGS Ann Harvey Alongside Refit 2012.

Item	Description	Pricing (including allowances)
H-01	Production Chart & Sub Contractor Allowance	\$
H-02	Fixed Fire Fighting Systems Annual Inspection/Maintenance	\$
H-03	Life Raft Servicing	\$
	3.3 Allowance for subcontractor	\$15,000.00
H-04	Fuel Tanks Survey	\$
	3.2 Unit cost per cubic meter \$ _____	
	3.4 Unit cost per m ² \$ _____	
	3.7 Unit cost per stud \$ _____	
H-05	Auxiliary Lube Oil Storage Tank	\$
	3.2 Unit cost per addtl. 500 ltrs of oil \$ _____	
H-06	Waste Oil Tank and Purifier Sludge Tank	\$
	3.1 Unit cost per cubic meter \$ _____	
H-07	Void Tanks Survey	\$
	3.4 Unit cost per addtl. stud \$ _____	
	3.5 Unit cost per addtl. tank testing \$ _____	
H-08	Fore Peak Tank Survey and Tank Level Transducer Install	\$
	3.3 Unit cost per addtl. cubic meter \$ _____	
	3.7 Unit cost per addtl. m ² \$ _____	
	3.9 Unit cost per manhole cover stud \$ _____	
H-09	Cabin 304 Steel Renewal	\$
	3.11 Allowance for NDT of new welds	\$1,000.00
	3.15 Allowance for new flooring	\$800.00
H-10	Boiler Feed Tank Survey and Repairs	\$
	3.5 Unit cost per m ² for surface prep and coating \$ _____	
	3.6 Unit cost per pit repair \$ _____	
H-11	Piping Renewals and Repairs	\$
E-01	Air Receivers Quinquennial Survey	\$
	3.8 Unit cost per fastener \$ _____	
E-02	Safety Valves Certification	\$
	3.2 Allowance for testing and setting valves	\$5,000.00
E-03	Number 2 Boiler	\$
	3.11 Allowance for repairs to the refractory cement	\$5,000.00
E-04	P & S Steering Pumps, Cylinders & Control Block	\$
L-01	Breaker Replacement (6)	\$
	3.1 Allowance for FSR	\$70,000.00
L-02	P & S Steering Pump Motors Survey	\$
	3.5 Allowance for 3 new couplings	\$500.00
	Total (including allowances)	\$