

CCGS W. Jackman Refit 2015

Bidders Conference Minutes

Attendees:

Colleen Dalton	PWGSC	Supply Specialist	772-4931
Paul Kelly	CCG	Project Manager	772-5334
Francis Dalton	Fermeuse Marine	Manager	771-0243
Jim House	Glovertown Shipyard	Vice President	749-0722
Leon Dowden	Glovertown Shipyard	Manager	533-8720

ITT:

Change 7.23 in the ITT document to 47.2 for aluminum welding.

Refit dates: April 15 - May 13, 2015.

Vessel transfer cost: This cost to be included with bid price.

Glovertown Shipyard: \$6,301.00

Fermeuse Marine: \$2,043.00

Note: The docking certificate required must be current and active. The certificate has to clearly demonstrate the yard can safely handle the displacement weight of the vessel.

HD-1 SERVICES

3.1.2 The contractor will be required to provide a per day rate instead of kilowatt hour.

HD-2 DRY-DOCKING

No issues

HD-3 PROPELLER SERVICING

Allowance included in case the propellers has to go for servicing. The C/E will notify the contractor if this is required once the propellers have been removed.

HD-04 HULL INSPECTION

The lettering is stenciled and the yard will take care of the supply of them.

The Canada symbols are 6" in size.

HD-05 SEABAYS CLEANING & PAINTING

No issues

HD-06 ZINC ANODES

No issues

HD-07 MAIN ENGINE WATER COOLER CLEANING

The main engine coolant is Caterpillar extended life.

HD-08 HULL FENDER REMOVAL AND INSPECTION

Bolts are to re-used.

HD-09 PIPELINE INSPECTION

Include in bid price allowance for \$6,000.00 for inspection and repairs and will be adjusted up or down with 1379.

HD-10 FUEL TANK CLEANING AND INSPECTION

No issues

HD-11 SEA CONNECTION VALVES

No issues

HD-12 STEERING OIL COOLER

No issues

HD-13 STORM VALVE INSPECTION

No issues

HD-14 NEW ZODIAC WINCH

No issues

HD-15 RUDDER TUBE GLAND

No issues

HD-16 MAIN ENGINE STARTING MOTORS

No issues

HD-17 FUEL TANK TOP RENEWAL

No issues

L-1 INSULATION TESTING

No issues

L-2 FIRE DETECTION SYSTEM AND CO2 SMOTHERING SYSTEM

No issues

Pricing Data Sheet

Item #	Description	Price (including allowances)
HD-01	SERVICES	
	3.1.1 ONE GANGWAY	\$
	3.1.2 PER DAY RATE X 28 DAYS FOR SHORE POWER COST FOR ADDTL PER DAY RATE \$ _____	\$
	3.1.3 FIRE PROTECTION	\$
	3.1.4 GARBAGE CONTAINER AND REMOVAL	\$
	3.1.5 DISPOSAL OF OILY WATER COST PER ADDTL 50 LITRES \$ _____	\$
	3.1.6 INTERIOR DECK PROTECTION	\$
	3.1.7 WASHROOM FACILITIES	\$
	3.1.8 OFFICE AND TELEPHONE	\$
	3.1.10 CLEANING OF VESSEL AT THE END OF THE REFIT	\$
	TOTAL SERVICES	\$
HD-02	DRYDOCKING	\$
HD-03	PROPELLER SERVICING 3.1.3 ALLOWANCE FOR REFURBISHMENT AND SHIPPING	\$ \$2,500.00
HD-04	HULL INSPECTION 3.1.3 UNIT COST PER ADDTL F ² \$ _____	\$
HD-05	SEABAY CLEANING & PAINTING 1.1 UNIT COST PER ADDTL 0.5 M ² \$ _____	\$
HD-06	ZINC ANODES	\$
HD-07	MAIN ENGINE WATER COOLER CLEANING	\$
HD-08	HULL FENDER REMOVAL AND INSPECTION	\$
HD-09	PIPELINE INSPECTION ALLOWANCE FOR INSPECTION AND REPAIRS	\$ \$6,000.00
HD-10	FUEL TANK CLEANING AND INSPECTION	\$
HD-11	SEA CONNECTION VALVES	\$
HD-12	STEERING OIL COOLER	\$
HD-13	STORM VALVE INSPECTION	\$
HD-14	NEW ZODIAC WINCH	\$
HD-15	RUDDER TUBE GLAND	\$
HD-16	MAIN ENGINE STARTING MOTORS 3.1.2 ALLOWANCE FOR REFURBISHMENT OF MOTORS	\$ \$2,500.00
HD-17	FUEL TANK TOP RENEWAL	\$
L-1	INSULATION TESTING	\$
L-2	FIRE DETECTION SYSTEM & CO2 SMOTHERING SYSTEM	\$
	TOTAL(HST EXTRA)	\$