	Form of Tender Contract Pack	age 1 - Repair to \	Wharf Subs	structure (Components	
Item	Description	Class of Labour, Materials, Plant and/or Equip.	Quantity	Unit	Unit Price	Amount
1	Mobilization & Demobilization		1	LS		
.0 Lions (Gate Dock Repairs					
1.1	Replace Cap and Install New Posts on CIP Sonatube Footings		1	LS		
1.2	Fresh Head and Install Corbel		1	LS		
1.3	Fresh Head and Install Double Corbel		1	LS		
1.4	Install Steel Bands		2	Each		
					Subtotal	
0 Lions (Gate Dock Concrete Beam Repair		1		1	
2.1	Option A - not jacking the beam					
2.1.1	Investigation, Survey, and Corbel Shop		1	LS		
212	Drawing Preparation	-	1	ıc		
2.1.2	Corbel Material Supply and Fabrication Corbel Shipping and Erection	+	1	LS LS		
2.1.5	Removal of Cracked concrete and corrosion		1	LS		
2.1.4	damaged rebar		1	LS		
2.1.5	Repair interface preparation		1	LS		
2.1.6	Replacement of corroded rebar	†	1	LS		
2.1.7	Forming and grouting for repair		1	LS		
•		•		-	Subtotal	
2.2	Option B - jacking the beam			_		
224	Investigation, Survey, and Corbel Shop		4	1.0		
2.2.1	Drawing Preparation		1	LS		
2.2.2	Corbel Material Supply and Fabrication		1	LS		
2.2.3	Corbel Shipping and Erection		1	LS		
2.2.4	Removal of Cracked concrete and corrosion damaged rebar		1	LS		
2.2.5	Repair interface preparation		1	LS		
2.2.6	Replacement of corroded rebar		1	LS		
2.2.7	Forming and grouting for repair		1	LS		
					Subtotal	
2.3	Provisional Item					
2.3.1	Concrete beam repair crack injection		1	LS		
0 Bridge					1	
3.1	Install Channel Patch		1	LS		
3.2	Move Large Boulder, Install Steel Angle Brackets w/ Lag Bolts to Prevent Shifting		1	LS		
2.2			7	En -l-		
3.3	Install Steel Bands	+	7	Each		
3.4	Fill Undermined Concrete Abutment w/ CIP Concrete		1	LS		
			·	<u> </u>	Subtotal	
0 West I	Dock					
4.1	Install Treated Timber Shims		1	LS		
4.2	Install Steel Bands		11	Each		
4.3	Pile/cap connection		1	Each		
4.4	Fresh Head and Install Double Corbel		2	Each		
4.5	Replace Pile		5	Each		
					Subtotal	
	Market Wharf and Trestle					
0 Public			1	LS		
0 Public 5.1	Install Steel Bands					
	Install Steel Bands Fill Undermined Concrete Abutment w/ CIP Concrete		1	LS		
5.1	Fill Undermined Concrete Abutment w/ CIP		1	LS LS		

6.0 Public Market Boardwalk and Sheet Pile Walls									
6.1	Replace Pedestals		1	LS					
6.2	Restore Riprap Slope Protection in Front of Boardwalk		30	sq.m					
6.3	Restore Riprap Slope Protection in Front of Stairs		6	sq.m					
					Subtotal				
7.0 North	east Seawall and Boardwalk								
7.1	Install Steel Plate Patch - Pile 79		1	LS					
7.2	Install Steel Plate Patch Pile - 106		1	LS					
					Subtotal				
8.0 Pelica	n Bay Marina Boardwalk Removal								
8.1	Boardwalk Removal		1	LS					
8.2	Lentil Sign Relocation		1	LS					
					Subtotal				
9.0 Catho	dic Protection								
9.1	Cathodic Protection of All Outboard Pipe Piles		165	Each					
					Subtotal				
10.0 Mari	time Market Boardwalk								
10.1	Remove riprap and fill that is in conflict with existing dock.		35	cu.m					
	<u> </u>				Subtotal				
Subtotal Repairs, using Option A for Lions Gate Beam Repair									
Contingency (15%) Option B									
Total - Option B									
Total - Provisional Items									