

Solicitation No. - N° de l'invitation
EQ754-152367/A
Client Ref. No. - N° de réf. du client
R.050927.001

Amd. No. - N° de la modif.
009
File No. - N° du dossier
PWL-5-38005

Buyer ID - Id de l'acheteur
pw1003
CCC No./N° CCC - FMS No./N° VME

Question and Answer:

Q: Section 68 in drawing S1.10 shows tie rod stretch from a Anchor Cross Wall to the Face Wall. It seems this tie rod has to form an angle at some point. Please provide details.

A: If the tie rod meets the cross wall or anchor wall at an angle cut and a tapered spacer from 114.3 OD XXS steel pipe and install as bearing washer.