




1 SITE PLAN
1:200

GENERAL NOTES	SITE LEGEND	KEYNOTES
1. WHERE DISTURBED BY THE WORK, PATCH AND REPAIR PAVED AREAS, CURBS AND GROUNDS BEYOND THE LIMITS TO BE REPAIRED. 2. REPAIR PAVING LINES AND MARKER SET SYMBOLS, 75M ON EXISTING RESURFACED LOT	<ul style="list-style-type: none"> MANHOLE COVERS AND CATCH BASINS PARKING METERS LIGHT POSTS DECIDUOUS TREES CONIFEROUS TREES FIRE HYDRANT CAR PLUG-IN ASPHALT REPAIR/FILL ASPHALT SLURRY COAT OVER EXISTING 	<ul style="list-style-type: none"> 1 PATCH/REPAIR EXISTING CONCRETE CURB 2 NEW CONCRETE CURB, DTL 2/42-1 3 NEW CONCRETE WALK WITH ROLLED CURB, DTL 4/42-1 4 NEW ASPHALT REPAIR AT CURB 5 NEW ROLLED CONC. CURB, DTL 4/42-1 6 AND CEOR MATCH TO A FINISHED DEPTH OF 150mm 7 FILL POTHOLE/ DAMAGED PAVEMENT, MATCH LEVEL OF EXISTING PAVED SURFACE 8 ASPHALT SLURRY COAT 9 NEW CONCRETE CURB, DTL 3/42-1 10 NEW CONCRETE WALK AND RAMPS, DTL 2/41-1 11 NEW CONCRETE WALK SEGMENT WITH SQUARE CURB, DTL 3/41-2 SILL 12 NEW ASPHALT PAVING TO MATCH ADJACENT PAVING SURFACE



NRC PBI PARKING LOT REPAIRS			
SASKATOON, SASKATCHEWAN			
FILE: 2853	DATE: JUNE 2015	DRAWN: JG	SCALE: AS NOTED
Rev	Description	Date	
SITE PLAN DETAILS			
DRAWING NUMBER	A1-2		

architects
HDH
henry · downing

2233 Avenue C North
Saskatoon, Saskatchewan S7L 5Z2
E-mail: manager@hdharchitects.ca
Phone: (306) 682-5044 Fax: (306) 686-0082

