



**RETURN BIDS TO:**

**RETOURNER LES SOUMISSIONS À:**

**Bid Receiving - PWGSC / Réception des soumissions  
- TPSGC**  
**11 Laurier St. / 11, rue Laurier**  
**Place du Portage, Phase III**  
**Core 0B2 / Noyau 0B2**  
**Gatineau, Québec K1A 0S5**  
**Bid Fax: (819) 997-9776**

**SOLICITATION AMENDMENT  
MODIFICATION DE L'INVITATION**

The referenced document is hereby revised; unless otherwise indicated, all other terms and conditions of the Solicitation remain the same.

Ce document est par la présente révisé; sauf indication contraire, les modalités de l'invitation demeurent les mêmes.

**Comments - Commentaires**

**Vendor/Firm Name and Address**  
**Raison sociale et adresse du**  
**fournisseur/de l'entrepreneur**

**Issuing Office - Bureau de distribution**  
Industrial Vehicles & Machinery Products Division  
11 Laurier St./11, rue Laurier  
7B1, Place du Portage, Phase III  
Gatineau  
Québec  
K1A 0S5

<b>Title - Sujet</b> TRUCK,LIFT,FORK	
<b>Solicitation No. - N° de l'invitation</b> W8476-165395/A	<b>Amendment No. - N° modif.</b> 001
<b>Client Reference No. - N° de référence du client</b> W8476-165395	<b>Date</b> 2015-11-03
<b>GETS Reference No. - N° de référence de SEAG</b> PW-\$\$HS-610-68149	
<b>File No. - N° de dossier</b> hs610.W8476-165395	<b>CCC No./N° CCC - FMS No./N° VME</b>
<b>Solicitation Closes - L'invitation prend fin</b> <b>at - à 02:00 PM</b> <b>on - le 2015-11-24</b>	
<b>Time Zone</b> <b>Fuseau horaire</b> Eastern Standard Time EST	
<b>F.O.B. - F.A.B.</b> <b>Plant-Usine:</b> <input type="checkbox"/> <b>Destination:</b> <input type="checkbox"/> <b>Other-Autre:</b> <input type="checkbox"/>	
<b>Address Enquiries to: - Adresser toutes questions à:</b> Reynolds, Kevin	<b>Buyer Id - Id de l'acheteur</b> hs610
<b>Telephone No. - N° de téléphone</b> (819) 956-3996 ( )	<b>FAX No. - N° de FAX</b> ( ) -
<b>Destination - of Goods, Services, and Construction:</b> <b>Destination - des biens, services et construction:</b>	

**Instructions: See Herein**

**Instructions: Voir aux présentes**

<b>Delivery Required - Livraison exigée</b>	<b>Delivery Offered - Livraison proposée</b>
<b>Vendor/Firm Name and Address</b> <b>Raison sociale et adresse du fournisseur/de l'entrepreneur</b>	
<b>Telephone No. - N° de téléphone</b> <b>Facsimile No. - N° de télécopieur</b>	
<b>Name and title of person authorized to sign on behalf of Vendor/Firm</b> <b>(type or print)</b> <b>Nom et titre de la personne autorisée à signer au nom du fournisseur/</b> <b>de l'entrepreneur (taper ou écrire en caractères d'imprimerie)</b>	
<b>Signature</b>	<b>Date</b>

**Bidder`s Questions and TA`s Answers**  
**Ref: W 8476-165395 (BT 617)**

**Question 1:**

**Purchase Description**

- (a) Page 4 of 17 Configuration "A" Vehicle Height 3.4.2(e)  
Please advise if a vehicle height of 84 in. would be acceptable as the lowered height of 185 in. lift height is 84 in.
- (b) Page 4 of 17 Configuration "A" Lift Height & Vehicle Height 3.4.2 (d) (e)  
Please advise if a vehicle height of 79.9 would be acceptable with a lift height of 156 in.
- (c) Page 4 of 17 Configuration "C" Vehicle Height 3.4.2(e)  
Please advise if a vehicle height of 98 in. would be acceptable as the lowered height of 216 in. lift height is 98 in

**Answer 1:**

- (a) No - a vehicle height of 84 inches for Configuration "A" will not be acceptable for this application.
- (b) No - a vehicle height of 79.9 inches will not be acceptable for this application. The maximum allowable vehicle height of 78.5" with a lift height of 154" will be acceptable for this application.

Section 1.4 - Requirements Summary Table of the Purchase Description (PD) will be amended to reflect this.

- (c) Yes - a vehicle height of 98 inches for Configuration "C" will be acceptable for this application.

Section 1.4 - Requirements Summary Table of the Purchase Description (PD) will be amended to reflect this.

**Question 2:**

**Purchase Description**

Page 9 of 17 Configuration "A" "B" "C" "D" Fork Tine Position Guide Vehicle Height 3.5 (f)

Please be advised that the installation of the Fork Tine Position Guide in conjunction with an integrated side-shifting fork positioner is very difficult due to movement of the forks when they are being positioned. Installation can be done but would require custom manufacturing and the cost would be excessive. This would also be a very high maintenance item. Please advise if this item could be reviewed.

**Answer 2:**

This requirement can be waived for this application.

Section 3.5(f) - Fork Tine Position Guide of the Purchase Description (PD) will be amended to reflect this.