



**RETURN BIDS TO:**  
**RETOURNER LES SOUMISSIONS À:**  
**Bid Receiving Public Works and Government**  
**Services Canada/Réception des soumissions**  
**Travaux publics et Services gouvernementaux**  
**Canada**  
**800 Burrard Street, Room 219**  
**800, rue Burrard, pièce 219**  
**Vancouver**  
**British Columbia**  
**V6Z 0B9**  
**Bid Fax: (604) 775-9381**

## **SOLICITATION AMENDMENT**

## **MODIFICATION DE L'INVITATION**

The referenced document is hereby revised; unless otherwise indicated, all other terms and conditions of the Solicitation remain the same.

Ce document est par la présente révisé; sauf indication contraire, les modalités de l'invitation demeurent les mêmes.

### **Comments - Commentaires**

**Vendor/Firm Name and Address**  
**Raison sociale et adresse du**  
**fournisseur/de l'entrepreneur**

**Issuing Office - Bureau de distribution**  
Public Works and Government Services Canada -  
Pacific Region  
800 Burrard Street, Room 219  
800, rue Burrard, pièce 219  
Vancouver  
British C  
V6Z 0B9

<b>Title - Sujet</b> West Coast Trail Bridges Repair	
<b>Solicitation No. - N° de l'invitation</b> EZ899-161618/A	<b>Amendment No. - N° modif.</b> 003
<b>Client Reference No. - N° de référence du client</b>	<b>Date</b> 2016-01-04
<b>GETS Reference No. - N° de référence de SEAG</b> PW-\$PWY-026-7692	
<b>File No. - N° de dossier</b> PWY-5-38279 (026)	<b>CCC No./N° CCC - FMS No./N° VME</b>
<b>Solicitation Closes - L'invitation prend fin</b> <b>at - à 02:00 PM</b> <b>on - le 2016-01-12</b>	<b>Time Zone</b> <b>Fuseau horaire</b> Pacific Standard Time PST
<b>F.O.B. - F.A.B.</b> <b>Plant-Usine:</b> <input type="checkbox"/> <b>Destination:</b> <input checked="" type="checkbox"/> <b>Other-Autre:</b> <input type="checkbox"/>	
<b>Address Enquiries to: - Adresser toutes questions à:</b> Liu (PWY), Patty	<b>Buyer Id - Id de l'acheteur</b> pwy026
<b>Telephone No. - N° de téléphone</b> (604) 775-6227 ( )	<b>FAX No. - N° de FAX</b> (604) 775-6633
<b>Destination - of Goods, Services, and Construction:</b> <b>Destination - des biens, services et construction:</b> Parks Canada - Pacific Rim National Park, Vancouver Island, BC	

**Instructions: See Herein**

**Instructions: Voir aux présentes**

<b>Delivery Required - Livraison exigée</b>	<b>Delivery Offered - Livraison proposée</b>
<b>Vendor/Firm Name and Address</b> <b>Raison sociale et adresse du fournisseur/de l'entrepreneur</b>	
<b>Telephone No. - N° de téléphone</b> <b>Facsimile No. - N° de télécopieur</b>	
<b>Name and title of person authorized to sign on behalf of Vendor/Firm</b> <b>(type or print)</b> <b>Nom et titre de la personne autorisée à signer au nom du fournisseur/</b> <b>de l'entrepreneur (taper ou écrire en caractères d'imprimerie)</b>	
<b>Signature</b>	<b>Date</b>

Solicitation No. - N° de l'invitation

EZ899-161618/A

Client Ref. No. - N° de réf. du client

Amd. No. - N° de la modif.

003

File No. - N° du dossier

PWY-5-38279

Buyer ID - Id de l'acheteur

pw026

CCC No./N° CCC - FMS No./N° VME

---

## AMENDMENT 003

Amendment 003 has been raised to incorporate ADDENDUM 002.

All other terms and conditions remain unchanged.

# ADDENDUM

---

Project: West Coast Trail Bridges Repair  
Pacific Rim national Park, Vancouver Island, BC  
Project No.: R.064182.001  
Requisition No.: EZ899-161618/A

**Addendum No.: 002**

January 4, 2016

---

## **GENERAL**

This Addendum forms part of the Contract Documents for **Project No. R.064182.001** and amends the original drawings and Specifications. The following revisions supersede the information contained in the original drawings and Specifications issued to the extent referenced and shall become part thereof. No adjustment to the Contract Price will be considered or allowed due to the Contractor or to any sub-contractor or supplier not being familiar with this Addendum.

## **Questions and Answers:**

Question 1) General instructions 011151 2.2.2 & 2.2.3 note retain services of Lewkowich Engineering and Ryzuk Geotechnical. Section 31000.01 - 3.4.1 - notes "site reviewed by a geotechnical engineer retained by the Departmental Representative." Please clarify if the geotechnical engineers are to be retained by contractor or PWGSC.

Answer 1) The geotechnical engineers will be retained by PWGSC or Parks Canada (Departmental Representative) and are not to be retained by the contractor.

Question 2) Can pictures be provided of all three bridge sites and bridges as they were inspected?

Answer 2) General bridge pictures can be downloaded from the following site:

### **Simple access via Web Browser:**

<https://share-ca.wspgroup.com>

### **Access via FTP client:**

<ftp://share-ca.wspgroup.com>

Username: RJMXYTJQHQ

Password: qGPCISp7

The login above will expire on 2016-02-03 00:00:00 , the site and all its data are deleted automatically after it expires.

Note, the fallen tree (shown on the pictures) was removed from Bridge 92 and the guardrail was temporarily repaired with on-site (existing bridge) material.

Question 3) Drawing S-7 - Details 1A & 1B - can a detail be provided of the Existing Saddle Steel Assembly. Alternatively, pictures of the existing would be adequate - see note above.

Answer 3) Unfortunately, there is no close up picture from the saddle assembly, but the original drawings can be downloaded from the same ftp site as in Answer 2). Note, the existing drawings do not show a clear detail, either.

## ADDENDUM

---

Question 4) Drawing S-7 - is the existing wood crib to be demolished at the south end? Can this remain or is it to be removed?

Answer 4) The existing wood crib to remain in place.

Question 5) Drawing S-8 - Detail 1 - note below reads "Assume Alternate 1 for tender, provide separate price for alternate 2". There is no space provided in the tender form for alternate prices.

Answer 5) Provide price for alternative 1 only. Ignore Alternative 2.

Question 6) Drawing S-9 - Detail 11 - Alaskan Yellow Cedar (AYC) tower poles are to be "treated both sides" - please clarify treatment or clarify note.

Answer 6) Treatment is not required.

Question 7a) Drawing S-9 - Detail 11 - AYC tower poles are to be drilled and site inspected by structural engineer. General Instructions 011151 - 2.2.8 - note one allowance for Structural EOR inspection helicopter transport.

Answer 7a) Allow for 2 site visits for structural engineer of record and pay helicopter costs.

Question 7b) As well, note lists tower pole replacement as a separate price - no space is provided in tender form. Please clarify.

Answer 7b) Include the cost of pole replacement. Ignore the note for separate price.

End of Addendum