

Solicitation No. - N° de l'invitation
EV385-162237/A

Amd. No. - N° de la modif.
004

Buyer ID - Id de l'acheteur
pwz202

Client Ref. No. - N° de réf. du client
Parks EV385-162237

File No. - N° du dossier
PWZ-5-38297

CCC No./N° CCC - FMS No./N° VME

CLARIFICATIONS:

1. In the Wood Treatment section part 3 Execution it says: Incise all timber materials prior to treatment. Does this include the round poles? Round poles are to receive the treatment indicated. If this can be achieved without incising it would considered acceptable.
2. The poles for this project cannot be incised (06 05 73-3.1) and natural peeled (amend #1 2.2). Incised logs must be milled to a uniform round dimension like a telephone pole to ensure proper penetration of incise and treatment.

Delete sentence to 2.2.1 in its entirety. Replace sentence 2.2.1 with the following:

Remove bark from round poles by means of either natural peeling or milling. Ensure the method selected will allow for the proper application of the specified wood treatment.