



RETURN BIDS TO:

RETOURNER LES SOUMISSIONS À:

Travaux publics et Services gouvernementaux
Canada

Place Bonaventure, portail Sud-Est
800, rue de La Gauchetière Ouest
7^{ème} étage

Montréal

Québec

H5A 1L6

FAX pour soumissions: (514) 496-3822

Revision to a Request for a Standing Offer

Révision à une demande d'offre à commandes

Regional Individual Standing Offer (RISO)

Offre à commandes individuelle régionale (OCIR)

The referenced document is hereby revised; unless otherwise indicated, all other terms and conditions of the Offer remain the same.

Ce document est par la présente révisé; sauf indication contraire, les modalités de l'offre demeurent les mêmes.

Comments - Commentaires

Vendor/Firm Name and Address

Raison sociale et adresse du
fournisseur/de l'entrepreneur

Issuing Office - Bureau de distribution

Travaux publics et Services gouvernementaux Canada
Place Bonaventure, portail Sud-Est
800, rue de La Gauchetière Ouest
7^{ème} étage
Montréal
Québec
H5A 1L6

| | | |
|---|--|---|
| Title - Sujet Parts/Repairs batteries Lift truck | | |
| Solicitation No. - N° de l'invitation W3380-15B005/A | | Date 2016-08-24 |
| Client Reference No. - N° de référence du client W3380-15B005 | | Amendment No. - N° modif. 003 |
| File No. - N° de dossier MTA-6-39006 (309) | CCC No./N° CCC - FMS No./N° VME | |
| GETS Reference No. - N° de référence de SEAG PW-\$MTA-309-13907 | | |
| Date of Original Request for Standing Offer Date de la demande de l'offre à commandes originale | | 2016-06-16 |
| Solicitation Closes - L'invitation prend fin at - à 02:00 PM on - le 2016-09-14 | | Time Zone Fuseau horaire Heure Avancée de l'Est HAE |
| Address Enquiries to: - Adresser toutes questions à: Paradis, Mary | | Buyer Id - Id de l'acheteur mta309 |
| Telephone No. - N° de téléphone (514) 496-3874 () | | FAX No. - N° de FAX (514) 496-3822 |
| Delivery Required - Livraison exigée | | |
| Destination - of Goods, Services, and Construction: Destination - des biens, services et construction: MINISTÈRE DE LA DEFENSE NATIONALE Garnison Longue-Pointe 6769, rue Notre-Dame Est Montréal, Québec H1N 3E9 Canada | | |
| Security - Sécurité This revision does not change the security requirements of the Offer. Cette révision ne change pas les besoins en matière de sécurité de la présente offre. | | |

Instructions: See Herein

Instructions: Voir aux présentes

| | | |
|--|--|---|
| Acknowledgement copy required Accusé de réception requis | Yes - Oui <input type="checkbox"/> | No - Non <input type="checkbox"/> |
| The Offeror hereby acknowledges this revision to its Offer. Le proposant constate, par la présente, cette révision à son offre. | | |
| Signature | Date | |
| Name and title of person authorized to sign on behalf of offeror. (type or print) Nom et titre de la personne autorisée à signer au nom du proposant. (taper ou écrire en caractères d'imprimerie) | | |
| For the Minister - Pour le Ministre | | |

THE ABOVE MENTIONED REQUEST FOR STANDING OFFER HAS BEEN AMENDED AS FOLLOWS:

DELETE:

**ANNEX "B"
BASIS OF PAYMENT**

NOTE TO OFFERORS:

1. Firm prices are required for all items in the table below.
All applicable taxes are extra to the prices on the table below.

OFFERS THAT DO NOT MEET THIS REQUIREMENT WILL BE REJECTED.

Period: From the date of issue until December 31, 2017 (Firm years)

Parts and labour as described in Annex A.

TABLE 1

| Description | Period | | Total | Total |
|--|---|---|----------|----------|
| | Date of issue until December 31, 2016 | From January 1 to December 31 2017 | | |
| | YEAR 1 | YEAR 2 | YEAR 1 | YEAR 2 |
| a. Hourly repair rate multiplied by estimated number of hours (regular hours*) *From Monday to Friday between 7am and 4pm | \$ _____ X 100 hrs | \$ _____ X 100 hrs | \$ _____ | \$ _____ |
| b. Hourly repair rate multiplied by estimated number of hours (outside regular hours , including week-ends) | \$ _____ X 100 hrs | \$ _____ X 100 hrs | \$ _____ | \$ _____ |
| c. The batteries listed below are just an example of what we use and is not an exhausted list. Therefore, we have selected these batteries for the financial evaluation. | The estimated number of batteries used in a year is 10 units | The estimated number of batteries used in a year is 10 units | | |
| Model: 18-125-15 Dimension: 38,00 x 17,75 x 30,50 Voltage: 36 volts Amperage -hours : 875 AH Battery cost multiplied by estimated number of batteries | \$ _____ X 2 units | \$ _____ X 2 units | \$ _____ | \$ _____ |
| Model: 18-85-07 Dimension: 25,50 x 8,56 x 23 Voltage: 24 volts Amperage -hours : 225 AH Battery cost multiplied by estimated number of batteries | \$ _____ X 3 units | \$ _____ X 3 units | \$ _____ | \$ _____ |

Solicitation No. - N° de l'invitation
W3380-15B005/A
 Client Ref. No. - N° de réf. du client
W3380-15B005

Amd. No. - N° de la modif.
003
 File No. - N° du dossier
MTA 6-39006

Buyer ID - Id de l'acheteur
MTA 309
 CCC No./N° CCC - FMS No./N° VME

| | | | | |
|---|------------------------------|------------------------------|----------|----------|
| Model: 24-85-19 Dimension: 38,25 x 29,75 x 22,50 Voltage: 48 volts Amperage -hours : 765 AH Battery cost multiplied by estimated number of batteries | \$ _____ X <u>2</u> units | \$ _____ X <u>2</u> units | \$ _____ | \$ _____ |
| Model: 18-125-13 Dimension: 38,00 x 15,50 x 31,00 Voltage: 36 volts Amperage -hours : 750 AH Battery cost multiplied by estimated number of batteries | \$ _____ X <u>3</u> units | \$ _____ X <u>3</u> units | \$ _____ | \$ _____ |

Period: Option year

Parts and labour as described in Annex A.

TABLE 2

| Description | Period | Total |
|---|---|---|
| | From January 1 to December 31 2018 | |
| a. Hourly repair rate multiplied by estimated number of hours (regular hours*) *From Monday to Friday between 7am and 4pm | \$ _____ X <u>100</u> hrs | \$ _____ |
| b. Hourly repair rate multiplied by estimated number of hours (outside regular hours, including week-ends) | \$ _____ X <u>100</u> hrs | \$ _____ |
| c. . The batteries listed below are just an example of what we use and is not an exhausted list. Therefore, we have selected these batteries for the financial evaluation. | The estimated number of batteries used in a year is 10 units. | The estimated number of batteries used in a year is 10 units. |
| Model: 18-125-15 Dimension: 38,00 x 17,75 x 30,50 Voltage: 36 volts Amperage -hours : 875 AH Battery cost multiplied by estimated number of batteries | \$ _____ X <u>2</u> units | \$ _____ |
| Model: 18-85-07 Dimension: 25,50 x 8,56 x 23 Voltage: 24 volts Amperage -hours : 225 AH Battery cost multiplied by estimated number of batteries | \$ _____ X <u>3</u> units | \$ _____ |

Solicitation No. - N° de l'invitation
W3380-15B005/A
Client Ref. No. - N° de réf. du client
W3380-15B005

Amd. No. - N° de la modif.
003
File No. - N° du dossier
MTA 6-39006

Buyer ID - Id de l'acheteur
MTA 309
CCC No./N° CCC - FMS No./N° VME

| | | |
|---|------------------------------|----------|
| Model: 24-85-19 Dimension: 38,25 x 29,75 x 22,50 Voltage: 48 volts Amperage -hours : 765 AH Battery cost multiplied by estimated number of batteries | \$ _____ X <u>2</u> units | \$ _____ |
| Model: 18-125-13 Dimension: 38,00 x 15,50 x 31,00 Voltage: 36 volts Amperage -hours : 750 AH Battery cost multiplied by estimated number of batteries | \$ _____ X <u>3</u> units | \$ _____ |

THE FOLLOWING IS OUR INVENTORY FOR LIFT TRUCKS:

| MANUFACTURER | YEAR | MODEL | SERIAL NUMBER |
|--------------|------|-------------|--------------------|
| BENCO | 2008 | TP-500 | 296.03.09 |
| BENCO | 2005 | TRANSPORTER | 4N1234 |
| BENCO | 2004 | TRANSPORTER | 11460105 |
| BENCO | 2004 | TRANSPORTER | 11290404 |
| BENCO | 2004 | TRANSPORTER | 11280304 |
| CLARK | 2008 | TMX25 | TMX25025019597 |
| CLARK | 2014 | ECX30 | ECX36022799653KF |
| CLARK | 2008 | ESM II-15 | ESX25000939704 |
| CLARK | 2006 | ESM II-15 | ESM24703509580 |
| CLARK | 2004 | TMG15S | TMG24817439570 |
| CLARK | 2002 | TMG 15S | TMG24803959570 |
| CLARK | 2014 | ECX30 | ECX36022809653KF |
| CLARK | 1998 | ECG20 | ECG358-0339-6754FB |
| CLARK | 1998 | ECG20 | ECG35803686754FB |
| CROWN | 2014 | RR5725-45 | 1A425433 |
| CVS FERRARI | 2012 | F478 | ZA9F478H603A26155 |
| CVS FERRARI | 2012 | F478 | ZA9F478H603A26150 |
| DAEWOO | 1999 | G25S | 99-01548 |
| DAEWOO | 2006 | BC30S | CM-00458 |
| DAEWOO | 2004 | G30E | DX-00305 |
| DAEWOO | 2002 | G25E | CX-04254 |
| DAEWOO | 2002 | BC20S | CJ-00182 |
| DAEWOO | 2002 | BC20S | CJ-00181 |
| DAEWOO | 2002 | BC20S | CJ-00185 |
| DAEWOO | 2002 | BC20S | CJ-00188 |

Solicitation No. - N° de l'invitation
W3380-15B005/A
Client Ref. No. - N° de réf. du client
W3380-15B005

Amd. No. - N° de la modif.
003
File No. - N° du dossier
MTA 6-39006

Buyer ID - Id de l'acheteur
MTA 309
CCC No./N° CCC - FMS No./N° VME

| | | | |
|---------------|------|---------|------------------|
| DAEWOO | 2002 | BC25S | CL-00127 |
| DAEWOO | 2003 | G30E | DX-00127 |
| DAEWOO | 2002 | G30E | CX03502 |
| DAEWOO | 2006 | BC30S | CN00459 |
| DAEWOO | 2002 | BC20S | CJ-00187 |
| DAEWOO | 2000 | G20S | CX-00843 |
| DAEWOO | 2000 | G25S | CX-00842 |
| DAEWOO | 2002 | G25E | CX-05013 |
| DAEWOO | 2002 | BC20S | CJ000186 |
| DAEWOO/DOOSAN | 2007 | G30E | MC-00149 |
| DAEWOO/DOOSAN | 2007 | G30E | MC-00147 |
| DAEWOO/DOOSAN | 2007 | G30E | MC-00148 |
| DOOSAN | 2014 | G20E3-5 | FGA07179000778 |
| DOOSAN | 2012 | G30E-5 | FGA09-1790-02003 |
| DOOSAN | 2014 | G30E-5 | FGA09-1790-02746 |
| DOOSAN | 2012 | BC30S-5 | FBA0J-1350-00560 |
| DOOSAN | 2012 | BC30S-5 | FBA0J-1350-00556 |
| DOOSAN | 2012 | BC30S-5 | FBA0J-1350-00555 |
| DOOSAN | 2012 | BC30S-5 | FBA0J-1350-00553 |
| DOOSAN | 2014 | G30E3-5 | FGA09-1790-02748 |
| DOOSAN | 2014 | G30E3-5 | FGA09-1790-02749 |
| DOOSAN | 2012 | G30E-5 | FGA09-1790-01922 |
| DOOSAN | 2010 | G30E-5 | MC-00259 |
| DOOSAN | 2010 | G30P-5 | MM-00676 |
| DOOSAN | 2010 | G30P-5 | MM-00677 |
| DOOSAN | 2014 | G35C-5 | FGA0E-1290-01051 |
| DOOSAN | 2014 | G30E-5 | FGA09-1790-02750 |
| DOOSAN | 2014 | G30E-5 | FGA09-1790-02752 |
| DOOSAN | 2012 | BC30S-5 | FBA0J-1350-00561 |
| DOOSAN | 2012 | BC30S-5 | FBA0J-1350-00575 |
| DOOSAN | 2012 | BC30S-5 | FBA0J-1350-00574 |
| DOOSAN | 2012 | BC30S-5 | FBA0J-1350-00573 |
| DOOSAN | 2012 | B18T-5 | FBA02-1370-01366 |
| DOOSAN | 2012 | BC30S-5 | FBA0J-1350-00562 |
| DOOSAN | 2012 | BC30S-5 | FBA0J-1350-00554 |
| DOOSAN | 2010 | G30E-5 | MC00251 |
| DOOSAN | 2010 | G30E-5 | MC00250 |
| DOOSAN | 2008 | BC30S-5 | LA-00128 |
| DOOSAN | 2008 | BC30S-5 | LA-00127 |
| DOOSAN | 2008 | BC30S-5 | LA-00130 |

Solicitation No. - N° de l'invitation
W3380-15B005/A
Client Ref. No. - N° de réf. du client
W3380-15B005

Amd. No. - N° de la modif.
003
File No. - N° du dossier
MTA 6-39006

Buyer ID - Id de l'acheteur
MTA 309
CCC No./N° CCC - FMS No./N° VME

| | | | |
|--------------|------|--------------|---------------------|
| DOOSAN | 2008 | BC30S-5 | LA-00129 |
| DOOSAN | 2014 | G30E3-5 | FGA09-1790-02744 |
| DOOSAN | 2014 | G30E-5 | FGA09-1790-02751 |
| DOOSAN | 2012 | B18T-5 | FBA02-1370-01339 |
| DOOSAN | 2014 | G30E-5 | FGA09-1790-02747 |
| DOOSAN | 2012 | G30E-5 | FGA09-1790-02004 |
| DREXEL | 2005 | SLT30 | 46502D-30195 |
| DREXEL | 2013 | SLT-30AC | SLT30AC-1307C-07850 |
| DREXEL | 2008 | SL66 | SL66-50-803B-30794 |
| DREXEL | 2008 | SL40 | SL40SE-802D-05317 |
| DREXEL | 2005 | SLT30 | 46502D-30194 |
| EP | 2008 | ES-10-22C | 08090737 |
| HYSTER | 2014 | E65XN | A268N13890M |
| HYSTER | 2013 | W30ZR | B455N02310L |
| HYSTER | 2012 | W30ZR | B455N02200K |
| HYSTER | 2012 | W30ZR | B455N02204K |
| HYSTER | 2012 | W30ZR | B455N02203K |
| HYSTER | 2012 | W30ZR | B455N02202K |
| HYSTER | 2015 | H360-48HD2 | A238E01657N |
| HYSTER | 1991 | H230XL | D7D1849M |
| HYSTER | 2011 | N30ZDRS | A265N02769K |
| HYSTER | 2014 | E65XN | A268N14376M |
| HYSTER | 2014 | E65XN | A268N13889M |
| HYSTER | 2011 | N30ZDRS | A265N02768K |
| HYSTER | 2013 | H70FT | L177V13684L |
| HYUNDAI | 2005 | HBF30C7 | FM0310007 |
| LIFTKING IND | 2005 | CDN10 | LT1345 |
| MANITEX | 2014 | CVS-F25 | A26035 |
| RAYMOND | 2009 | 7400DR32TT | 740-09-AB14714 |
| RAYMOND | 2009 | 7400DR32TT | 740-09-AB14709 |
| RAYMOND | 2001 | RWR300 | RWR-01-00214 |
| RAYMOND | 2001 | RWR300 | RWR-01-00211 |
| RAYMOND | 2011 | 5400-OPC30TT | 540-12-A13518 |
| RAYMOND | 2015 | 5600-OPC30TT | 560-15-A22723 |
| RAYMOND | 2015 | 5600-OPC30TT | 560-15-A22803 |
| RAYMOND | 2015 | 5600-OPC30TT | 560-15-A22802 |
| RAYMOND | 2015 | 5600-OPC30TT | 560-15-A22725 |
| RAYMOND | 2015 | 5600-OPC30TT | 560-15-A22724 |
| RAYMOND | 2015 | 5600-OPC30TT | 560-15-A22722 |
| RAYMOND | 2015 | 5600-OPC30TT | 560-15-A22726 |

Solicitation No. - N° de l'invitation
W3380-15B005/A
Client Ref. No. - N° de réf. du client
W3380-15B005

Amd. No. - N° de la modif.
003
File No. - N° du dossier
MTA 6-39006

Buyer ID - Id de l'acheteur
MTA 309
CCC No./N° CCC - FMS No./N° VME

| | | | |
|---------|------|------------------|---------------|
| RAYMOND | 2014 | 9600-CSR30T 5371 | 960-14-03280 |
| RAYMOND | 2014 | 9600-CSR30T 5371 | 960-14-03281 |
| RAYMOND | 2014 | 9600-CSR30T 5371 | 960-14-03282 |
| RAYMOND | 2013 | 5500-OPC30TT | 550-13-A15965 |
| RAYMOND | 2013 | 5500-OPC30TT | 550-13-A15964 |
| RAYMOND | 2013 | 5500-OPC30TT | 550-13-A15963 |
| RAYMOND | 2012 | 4150-C30TT | 415-12-35856 |
| RAYMOND | 2011 | 5400-OPC30TT | 540-12-A13519 |
| RAYMOND | 2008 | TRT-S30SRT | TRT-07-00127 |
| RAYMOND | 1986 | 76SL100TF | 076-86-0265 |
| RAYMOND | 1995 | 589 SRT | 589-94-00383 |
| RAYMOND | 1995 | 589 SRT | 589-94-00382 |
| RAYMOND | 1995 | 589 SRT | 589-94-00381 |
| RAYMOND | 1995 | 589 SRT | 589-94-00380 |
| RAYMOND | 1995 | 589 SRT | 589-94-00379 |
| RAYMOND | 1995 | 589 SRT | 589-94-00378 |
| RAYMOND | 1995 | 589 SRT | 589-95-00406 |
| RAYMOND | 1995 | 589 SRT | 589-95-00405 |
| RAYMOND | 2007 | 5200-OPC30T | 520-07-02094 |
| SCHAEFF | 2013 | SE80 | KE00039K |
| SCHAEFF | 2013 | SE80 | LT2290SC |
| VTC | 2015 | 500 T | 3107.03.15 |
| VTC | 2015 | 500 T | 3106.03.15 |
| W30ZR | 2014 | HYSTER | B455N02467M |

INSERT: At Part 2: Standard Instruction, Clauses and Conditions

2.1.1 SACC Manual Clause

B4024T No substitute products 2006-08-15
M1004T Condition of material 2011-05-16

Solicitation No. - N° de l'invitation
W3380-15B005/A
Client Ref. No. - N° de réf. du client
W3380-15B005

Amd. No. - N° de la modif.
003
File No. - N° du dossier
MTA 6-39006

Buyer ID - Id de l'acheteur
MTA 309
CCC No./N° CCC - FMS No./N° VME

INSERT:

**ANNEX "B"
BASIS OF PAYMENT**

NOTE TO OFFERORS:

1. Firm prices are required for all items in the table below.
All applicable taxes are extra to the prices on the table below.

OFFERS THAT DO NOT MEET THIS REQUIREMENT WILL BE REJECTED.

Period: From the date of issue until December 31, 2017 (Firm years)

Parts and labour as described in Annex A.

TABLE 1

| Description | Period | | Total | Total |
|---|---|---|----------|----------|
| | Date of issue until December 31, 2016 | From January 1 to December 31 2017 | | |
| | YEAR 1 | YEAR 2 | YEAR 1 | YEAR 2 |
| a. Hourly repair rate multiplied by estimated number of hours (regular hours*) *From Monday to Friday between 7am and 4pm | \$ _____ X <u>100</u> hrs | \$ _____ X <u>100</u> hrs | \$ _____ | \$ _____ |
| b. Hourly repair rate multiplied by estimated number of hours (outside regular hours , including week-ends) | \$ _____ X <u>100</u> hrs | \$ _____ X <u>100</u> hrs | \$ _____ | \$ _____ |
| c. The batteries listed below are just an example of what we use and is not an exhausted list. Therefore, we have selected these batteries for the financial evaluation. | The estimated number of batteries used in a year is 10 units | The estimated number of batteries used in a year is 10 units | | |
| Model: 18-125-15 Dimension: 38,00 x 17,75 x 30,50 Voltage: 36 volts Amperage -hours : 875 AH Battery cost multiplied by estimated number of batteries | \$ _____ X <u>2</u> units | \$ _____ X <u>2</u> units | \$ _____ | \$ _____ |
| Model: 18-85-7 Dimension: 25,50 x 8,56 x 23 Voltage: 36 volts Amperage -hours : 255 AH Battery cost multiplied by estimated number of batteries | \$ _____ X <u>3</u> units | \$ _____ X <u>3</u> units | \$ _____ | \$ _____ |

Solicitation No. - N° de l'invitation
W3380-15B005/A
 Client Ref. No. - N° de réf. du client
W3380-15B005

Amd. No. - N° de la modif.
003
 File No. - N° du dossier
MTA 6-39006

Buyer ID - Id de l'acheteur
MTA 309
 CCC No./N° CCC - FMS No./N° VME

| | | | | |
|---|------------------------------|------------------------------|----------|----------|
| Model: 24-85-19 Dimension: 38,25 x 29,75 x 22,50 Voltage: 48 volts Amperage -hours : 765 AH Battery cost multiplied by estimated number of batteries | \$ _____ X <u>2</u> units | \$ _____ X <u>2</u> units | \$ _____ | \$ _____ |
| Model: 18-125-13 Dimension: 38,00 x 15,50 x 31,00 Voltage: 36 volts Amperage -hours : 750 AH Battery cost multiplied by estimated number of batteries | \$ _____ X <u>3</u> units | \$ _____ X <u>3</u> units | \$ _____ | \$ _____ |

Period: Option year

Parts and labour as described in Annex A.

TABLE 2

| Description | Period | Total |
|---|---|---|
| | From January 1 to December 31 2018 | |
| a. Hourly repair rate multiplied by estimated number of hours (regular hours*) *From Monday to Friday between 7am and 4pm | \$ _____ X <u>100</u> hrs | \$ _____ |
| b. Hourly repair rate multiplied by estimated number of hours (outside regular hours, including week-ends) | \$ _____ X <u>100</u> hrs | \$ _____ |
| c. . The batteries listed below are just an example of what we use and is not an exhausted list. Therefore, we have selected these batteries for the financial evaluation. | The estimated number of batteries used in a year is 10 units. | The estimated number of batteries used in a year is 10 units. |
| Model: 18-125-15 Dimension: 38,00 x 17,75 x 30,50 Voltage: 36 volts Amperage -hours : 875 AH Battery cost multiplied by estimated number of batteries | \$ _____ X <u>2</u> units | \$ _____ |
| Model: 18-85-7 Dimension: 25,50 x 8,56 x 23 Voltage: 36 volts Amperage -hours : 255 AH Battery cost multiplied by estimated number of batteries | \$ _____ X <u>3</u> units | \$ _____ |

Solicitation No. - N° de l'invitation
W3380-15B005/A
Client Ref. No. - N° de réf. du client
W3380-15B005

Amd. No. - N° de la modif.
003
File No. - N° du dossier
MTA 6-39006

Buyer ID - Id de l'acheteur
MTA 309
CCC No./N° CCC - FMS No./N° VME

| | | |
|---|-----------------------|----------|
| Model: 24-85-19 Dimension: 38,25 x 29,75 x 22,50 Voltage: 48 volts Amperage -hours : 765 AH Battery cost multiplied by estimated number of batteries | \$ _____ X 2 units | \$ _____ |
| Model: 18-125-13 Dimension: 38,00 x 15,50 x 31,00 Voltage: 36 volts Amperage -hours : 750 AH Battery cost multiplied by estimated number of batteries | \$ _____ X 3 units | \$ _____ |

THE FOLLOWING IS OUR INVENTORY FOR LIFT TRUCKS:

| MANUFACTURER | YEAR | MODEL | SERIAL NUMBER |
|--------------|------|-------------|--------------------|
| BENCO | 2008 | TP-500 | 296.03.09 |
| BENCO | 2005 | TRANSPORTER | 4N1234 |
| BENCO | 2004 | TRANSPORTER | 11460105 |
| BENCO | 2004 | TRANSPORTER | 11290404 |
| BENCO | 2004 | TRANSPORTER | 11280304 |
| CLARK | 2008 | TMX25 | TMX25025019597 |
| CLARK | 2014 | ECX30 | ECX36022799653KF |
| CLARK | 2008 | ESM II-15 | ESX25000939704 |
| CLARK | 2006 | ESM II-15 | ESM24703509580 |
| CLARK | 2004 | TMG15S | TMG24817439570 |
| CLARK | 2002 | TMG 15S | TMG24803959570 |
| CLARK | 2014 | ECX30 | ECX36022809653KF |
| CLARK | 1998 | ECG20 | ECG358-0339-6754FB |
| CLARK | 1998 | ECG20 | ECG35803686754FB |
| CROWN | 2014 | RR5725-45 | 1A425433 |
| CVS FERRARI | 2012 | F478 | ZA9F478H603A26155 |
| CVS FERRARI | 2012 | F478 | ZA9F478H603A26150 |
| DAEWOO | 1999 | G25S | 99-01548 |
| DAEWOO | 2006 | BC30S | CM-00458 |
| DAEWOO | 2004 | G30E | DX-00305 |
| DAEWOO | 2002 | G25E | CX-04254 |
| DAEWOO | 2002 | BC20S | CJ-00182 |
| DAEWOO | 2002 | BC20S | CJ-00181 |
| DAEWOO | 2002 | BC20S | CJ-00185 |
| DAEWOO | 2002 | BC20S | CJ-00188 |

Solicitation No. - N° de l'invitation
W3380-15B005/A
Client Ref. No. - N° de réf. du client
W3380-15B005

Amd. No. - N° de la modif.
003
File No. - N° du dossier
MTA 6-39006

Buyer ID - Id de l'acheteur
MTA 309
CCC No./N° CCC - FMS No./N° VME

| | | | |
|---------------|------|---------|------------------|
| DAEWOO | 2002 | BC25S | CL-00127 |
| DAEWOO | 2003 | G30E | DX-00127 |
| DAEWOO | 2002 | G30E | CX03502 |
| DAEWOO | 2006 | BC30S | CN00459 |
| DAEWOO | 2002 | BC20S | CJ-00187 |
| DAEWOO | 2000 | G20S | CX-00843 |
| DAEWOO | 2000 | G25S | CX-00842 |
| DAEWOO | 2002 | G25E | CX-05013 |
| DAEWOO | 2002 | BC20S | CJ000186 |
| DAEWOO/DOOSAN | 2007 | G30E | MC-00149 |
| DAEWOO/DOOSAN | 2007 | G30E | MC-00147 |
| DAEWOO/DOOSAN | 2007 | G30E | MC-00148 |
| DOOSAN | 2014 | G20E3-5 | FGA07179000778 |
| DOOSAN | 2012 | G30E-5 | FGA09-1790-02003 |
| DOOSAN | 2014 | G30E-5 | FGA09-1790-02746 |
| DOOSAN | 2012 | BC30S-5 | FBA0J-1350-00560 |
| DOOSAN | 2012 | BC30S-5 | FBA0J-1350-00556 |
| DOOSAN | 2012 | BC30S-5 | FBA0J-1350-00555 |
| DOOSAN | 2012 | BC30S-5 | FBA0J-1350-00553 |
| DOOSAN | 2014 | G30E3-5 | FGA09-1790-02748 |
| DOOSAN | 2014 | G30E3-5 | FGA09-1790-02749 |
| DOOSAN | 2012 | G30E-5 | FGA09-1790-01922 |
| DOOSAN | 2010 | G30E-5 | MC-00259 |
| DOOSAN | 2010 | G30P-5 | MM-00676 |
| DOOSAN | 2010 | G30P-5 | MM-00677 |
| DOOSAN | 2014 | G35C-5 | FGA0E-1290-01051 |
| DOOSAN | 2014 | G30E-5 | FGA09-1790-02750 |
| DOOSAN | 2014 | G30E-5 | FGA09-1790-02752 |
| DOOSAN | 2012 | BC30S-5 | FBA0J-1350-00561 |
| DOOSAN | 2012 | BC30S-5 | FBA0J-1350-00575 |
| DOOSAN | 2012 | BC30S-5 | FBA0J-1350-00574 |
| DOOSAN | 2012 | BC30S-5 | FBA0J-1350-00573 |
| DOOSAN | 2012 | B18T-5 | FBA02-1370-01366 |
| DOOSAN | 2012 | BC30S-5 | FBA0J-1350-00562 |
| DOOSAN | 2012 | BC30S-5 | FBA0J-1350-00554 |
| DOOSAN | 2010 | G30E-5 | MC00251 |
| DOOSAN | 2010 | G30E-5 | MC00250 |
| DOOSAN | 2008 | BC30S-5 | LA-00128 |
| DOOSAN | 2008 | BC30S-5 | LA-00127 |
| DOOSAN | 2008 | BC30S-5 | LA-00130 |

Solicitation No. - N° de l'invitation
W3380-15B005/A
Client Ref. No. - N° de réf. du client
W3380-15B005

Amd. No. - N° de la modif.
003
File No. - N° du dossier
MTA 6-39006

Buyer ID - Id de l'acheteur
MTA 309
CCC No./N° CCC - FMS No./N° VME

| | | | |
|--------------|------|--------------|---------------------|
| DOOSAN | 2008 | BC30S-5 | LA-00129 |
| DOOSAN | 2014 | G30E3-5 | FGA09-1790-02744 |
| DOOSAN | 2014 | G30E-5 | FGA09-1790-02751 |
| DOOSAN | 2012 | B18T-5 | FBA02-1370-01339 |
| DOOSAN | 2014 | G30E-5 | FGA09-1790-02747 |
| DOOSAN | 2012 | G30E-5 | FGA09-1790-02004 |
| DREXEL | 2005 | SLT30 | 46502D-30195 |
| DREXEL | 2013 | SLT-30AC | SLT30AC-1307C-07850 |
| DREXEL | 2008 | SL66 | SL66-50-803B-30794 |
| DREXEL | 2008 | SL40 | SL40SE-802D-05317 |
| DREXEL | 2005 | SLT30 | 46502D-30194 |
| EP | 2008 | ES-10-22C | 08090737 |
| HYSTER | 2014 | E65XN | A268N13890M |
| HYSTER | 2013 | W30ZR | B455N02310L |
| HYSTER | 2012 | W30ZR | B455N02200K |
| HYSTER | 2012 | W30ZR | B455N02204K |
| HYSTER | 2012 | W30ZR | B455N02203K |
| HYSTER | 2012 | W30ZR | B455N02202K |
| HYSTER | 2015 | H360-48HD2 | A238E01657N |
| HYSTER | 1991 | H230XL | D7D1849M |
| HYSTER | 2011 | N30ZDRS | A265N02769K |
| HYSTER | 2014 | E65XN | A268N14376M |
| HYSTER | 2014 | E65XN | A268N13889M |
| HYSTER | 2011 | N30ZDRS | A265N02768K |
| HYSTER | 2013 | H70FT | L177V13684L |
| HYUNDAI | 2005 | HBF30C7 | FM0310007 |
| LIFTKING IND | 2005 | CDN10 | LT1345 |
| MANITEX | 2014 | CVS-F25 | A26035 |
| RAYMOND | 2009 | 7400DR32TT | 740-09-AB14714 |
| RAYMOND | 2009 | 7400DR32TT | 740-09-AB14709 |
| RAYMOND | 2001 | RWR300 | RWR-01-00214 |
| RAYMOND | 2001 | RWR300 | RWR-01-00211 |
| RAYMOND | 2011 | 5400-OPC30TT | 540-12-A13518 |
| RAYMOND | 2015 | 5600-OPC30TT | 560-15-A22723 |
| RAYMOND | 2015 | 5600-OPC30TT | 560-15-A22803 |
| RAYMOND | 2015 | 5600-OPC30TT | 560-15-A22802 |
| RAYMOND | 2015 | 5600-OPC30TT | 560-15-A22725 |
| RAYMOND | 2015 | 5600-OPC30TT | 560-15-A22724 |
| RAYMOND | 2015 | 5600-OPC30TT | 560-15-A22722 |
| RAYMOND | 2015 | 5600-OPC30TT | 560-15-A22726 |

Solicitation No. - N° de l'invitation
W3380-15B005/A
Client Ref. No. - N° de réf. du client
W3380-15B005

Amd. No. - N° de la modif.
003
File No. - N° du dossier
MTA 6-39006

Buyer ID - Id de l'acheteur
MTA 309
CCC No./N° CCC - FMS No./N° VME

| | | | |
|---------|------|------------------|---------------|
| RAYMOND | 2014 | 9600-CSR30T 5371 | 960-14-03280 |
| RAYMOND | 2014 | 9600-CSR30T 5371 | 960-14-03281 |
| RAYMOND | 2014 | 9600-CSR30T 5371 | 960-14-03282 |
| RAYMOND | 2013 | 5500-OPC30TT | 550-13-A15965 |
| RAYMOND | 2013 | 5500-OPC30TT | 550-13-A15964 |
| RAYMOND | 2013 | 5500-OPC30TT | 550-13-A15963 |
| RAYMOND | 2012 | 4150-C30TT | 415-12-35856 |
| RAYMOND | 2011 | 5400-OPC30TT | 540-12-A13519 |
| RAYMOND | 2008 | TRT-S30SRT | TRT-07-00127 |
| RAYMOND | 1986 | 76SL100TF | 076-86-0265 |
| RAYMOND | 1995 | 589 SRT | 589-94-00383 |
| RAYMOND | 1995 | 589 SRT | 589-94-00382 |
| RAYMOND | 1995 | 589 SRT | 589-94-00381 |
| RAYMOND | 1995 | 589 SRT | 589-94-00380 |
| RAYMOND | 1995 | 589 SRT | 589-94-00379 |
| RAYMOND | 1995 | 589 SRT | 589-94-00378 |
| RAYMOND | 1995 | 589 SRT | 589-95-00406 |
| RAYMOND | 1995 | 589 SRT | 589-95-00405 |
| RAYMOND | 2007 | 5200-OPC30T | 520-07-02094 |
| SCHAEFF | 2013 | SE80 | KE00039K |
| SCHAEFF | 2013 | SE80 | LT2290SC |
| VTC | 2015 | 500 T | 3107.03.15 |
| VTC | 2015 | 500 T | 3106.03.15 |
| W30ZR | 2014 | HYSTER | B455N02467M |

INSERT: At Part 2: Standard Instruction, Clauses and Conditions

2.1.1 SACC Manual Clause

B4024T No substitute products 2006-08-15
M1004T Condition of material 2011-05-16

- All other terms and conditions remain the same.