

TENDER ADDENDUM

**Richmond Landing Shoreline Access
Ceremonial Landing
(Pier, Dock and Gangway)
Tender File #AL1665
September 14, 2016
ADDENDUM NO: 2**

ADDENDA À LA SOUMISSION

**Accès au rivage – Débarcadère Richmond
Débarcadère protocolaire
(Pilier, plate-forme et pont de service)
Dossier de soumission de la CCN no. AL1665
Le 14 septembre 2016
ADDENDA NO: 2**

The following shall be read in conjunction with and shall form an integral part of the Tender/Proposal and Contract Documents:

1. Attached is the sign in sheet to the non-mandatory site visit held on September 9, 2016.
2. Delete hand hole details E-27(NCC) and sheet no. 870.1 on drawings C11 and C11F.
3. The following reports are provided for information:
 - 2016 Environmental Effects Analysis
 - 2013 Screening Level Risk Assessment
 - 2016 Annual Groundwater and Surface Water Monitoring
 - 2016 Geotechnical
4. Daily water levels since April 14, 2015 are provided for information.
5. Various specification sections have been revised. All revisions are shown in track mode:
 - 01 01 00 – General Requirements
 - 01 35 30 – Health and Safety Requirements
 - 26 05 34 – Conduits, Conduit Fastening and Fittings
 - 31 23 10 – Earth Excavation and Backfilling
6. The following specification section is added:
 - 01 35 13.43 – Special Project Procedures for Contaminated Sites
7. On drawing C-01, Plan view, the note “Top Elev. 42.39 +or-“ is deleted.
8. The depth of the granular stone crushed base under the pier footing is 300 mm.

Ce qui suit doit être interprété comme faisant partie intégrante de la proposition/appeal d'offres et des documents relatifs au contrat :

1. En annexe est la feuille de présence pour la visite de site non obligatoire du 9 septembre 2016.
2. Supprimer les détails des trous d'hommes E-27 (NCC) et la feuille no. 870.1 sur les dessins C11 et C11F.
3. Les rapports en annexe à titre d'information :
 - 2016 Environmental Effects Analysis
 - 2013 Screening Level Risk Assessment
 - 2016 Annual Groundwater and Surface Water Monitoring
 - 2016 Geotechnical
4. Les niveaux journaliers d'eau depuis 14 avril 2015 en annexe à titre d'information.
5. Diverses sections de spécifications ont été révisées. Toutes les révisions sont soulevées en mode de révision :
 - 01 01 00 – Exigences générales
 - 01 35 30 – Santé et sécurité
 - 26 05 34 – Conduits, fixations et raccords de conduits
 - 31 23 10 – Travaux d'excavation dans la terre et de remblayage après excavation
6. Les spécifications suivantes sont ajoutées :
 - 01 35 13.43 – Procédures spéciales – Sites contaminés
7. Sur le dessin C-01, la note “Partie Supérieure De L'Elev. A 42.39” est supprimée.
8. L'épaisseur de la couche de base en pierre concassée granulaire sous la semelle du pilier est de 300 mm.

- | | |
|---|---|
| <p>9. The clear stone filter around the drains, as shown on drawing C-01, "Typical Section", should read as 0.05³.</p> <p>10. The strut pier connection details are similar to those for the gangway connections shown on drawing C-06. Minimum stud embedment is to be 150 mm.</p> <p>11. On drawing C-06, delete the note "Note: 90 degree connection plate..." on the "Plan of WT Brace Support Between Framing Angles."</p> <p>12. On drawing C-04, Section C, the galvanized bolts to secure the bollard to the top of the concrete pier are to have an embedment of 150 mm and are to be secured with an approved epoxy. Contractor to submit product information for the epoxy for approval.</p> <p>13. All costs for the work of salvaging the bollard, removing the base to the bollard below the collar, drilling for anchor bolts, galvanizing and, installing the bollard on the pier, complete with anchor bolts, shall be included in the lump sum price for the item "Pier Construction".</p> <p>14. On drawing C-04, Plan: Geometry view, note that there is no solar lighting required on the pier.</p> | <p>9. Le filtre en pierres de décantation autour des drains, tel qu'indiqué sur le dessin C-01, devrait être 0.05³.</p> <p>10. Les détails de la connexion entre le support et le pilier ressemblent à celles des connexions de la passerelle indiqués sur le dessin C-06. L'encastrement minimum des poteaux doit être de 150 mm.</p> <p>11. Sur le dessin C-06, supprimer la note "Plaque De Raccordement ..." sur le "Plan Du Support D'Entretoise De L'Ensemble <<WT>> Entre Les Cornières D'Ossature".</p> <p>12. Sur le dessin C-04, Section C, les boulons galvanisés fixant le bollard au sommet du pilier en béton doivent avoir un encastrement de 150 mm et doivent être fixés avec une résine époxy approuvée. L'entrepreneur doit soumettre les informations concernant le produit époxy aux fins d'approbation.</p> <p>13. Tous les coûts des travaux de récupération du bollard, enlèvement de la base jusqu'au bollard en-dessous du col, perçage pour les boulons de scellement, galvanisation, et installation du bollard sur le pilier, y compris les boulons de scellement, doivent être compris dans la somme forfaitaire pour l'item "Construction du pilier".</p> <p>14. Sur le dessin C-04, Plan : Vue Géométrie, noté qu'il n'y a pas d'éclairage solaire requis sur le pilier.</p> |
|---|---|

Allan Lapensée
Senior Contract Officer
Procurement Services

Allan Lapensée
Agent principal des contrats
Services d'approvisionnement