

File # 201700569

Question 3

The dry sprinkler 'winterization' is marked to be performed twice a year. Is this an oversight because it also reads that it should be performed with the 2nd fire alarm inspection in the fall?

Answer 3

It is an error where dry sprinkler 'winterization' is marked as '2' under the **Annual Frequency** column. Dry sprinkler 'winterization' is to be performed **once per year in the fall** in conjunction with the fire alarm system inspection.
